

15/5/2010

INS. CASE OWNER:

Lynn

CC 4

TAXA1900

2501

E 932

LKK:

IDAC:

Surveyor:

STEVE

DOI:

ASSIGNMENT


12/1/10

Date / Time:

12/1/10

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SQL 663R

Claim No. :

990101E / 97250

Name of Insured :

MM W M M M M M

Policy No. :

PA1900000000

Insured Tel No. :

HP:

Make / Model :

TOYOTA

Excess Sec II :\$

D.O.A :

25/1/10

Place of Accident :

BOUN LAY RD TO JONGMAY

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :


Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SJT 7238



INSRS:

WSP:

Tel :

Liability :

RMKS:

Tan Chong



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	12/1/10
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Others:	<input checked="" type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by: Steve

Repair Cost: PIP \$5862.30 (6 days) Reduction: \$3612.06 % 38 Email Call

FINAL SETTLEMENT Date/Time: 14/2/10 Confirm with: Lawrence / Lynn Email Call

Final Liability: % (Agreed / Assessed) BOLA S/N No. : 17

Repair Cost: (W/L) \$6272.66

Loss of Rental (LOR): \$ (days)

Loss of Use (LOU): \$300.00 (\$50 x 6 days)

Loss of Income (LOI): \$ (\$ x days)

LOR only LOU only LOR + LOU LOR + LO [Tick only one]

GIA/LTA Search \$2.00

Medical: \$

Disbursement: \$ (e.g. Tow/ Independent)

Legal Cost: \$

Total: \$6574.66 **Global Sum \$:**

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: \$6574.66 Name 1: Tan Chong Motor Sales Pte Ltd

Payee 2: (Strike if N.A.) \$ Name 2:

Payee 3: (Strike if N.A.) \$ Name 3:

COPY SENT 14/2/10



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19002501/Epb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 12-02-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGL 663R	Veh. Inspected	SJT 723Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	12/02/2019
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/01/2019	Inspection Date	13/02/2019
Survey held at	TAN CHONG MOTOR SALES PTE LTD 911 BUKIT TIMAH ROAD SINGAPORE 589623		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 529623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SJT723Z

NETT ITEM	0.00
LESS 20.00%)	0.00
NETT AMOUNT	0.00
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	0.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	0.00
TOTAL LABOUR CHARGES	6175.00
TOTAL SPARE PARTS CHARGES	0.00
TOTAL CHARGES	6175.00
ADD 7 % GST	432.25
GRAND TOTAL	6607.25

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJT723Z

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS	60.00	.00
* 2 PSC	PULL/STRAIGHTEN CHASSIS	350.00	.00 X
3 RCI	REPLACE REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST	120.00	.00
* 4 RISCOF	REMOVE/INSTALL SEAT & CUSHION CARPET (PARTIAL)	120.00	.00 X
5 RPI	PERFORM RUST PROOFING & TREATMENT FOR 2X AFFECTED PANEL	240.00	.00
6 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	.00
7 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY 3XAREA PANEL	300.00	.00
8 SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	.00
9 ZZ/001	TRANSFER MECHANICAL PART FOR REAR TAILGATE	60.00	.00
10 ZZ/002	CHECK LIGHTING	48.00	.00
11 ZZ/003	RENEW REAR WINDSCREEN	180.00	.00
12 ZZ/004	REPAIR REAR FENDER RH & LH SIDE, REAR PANFLOOR, RENEW REAR TAILGATE, RR BUMPER & RR END PANEL	1500.00	.00 1250
13 ZZ/005	S/PAINT REAR BUMPER, RR END PANEL, RR TAILGATE, RR PANFLOOR, RR FENDER RH & LH SIDE	1400.00	.00 1000
14 ZZ/006	AS PER AGREED LUMP SUM REPAIR		
15 ZZ/007	LIMIT REPAIR \$6500.00		
TOTAL LABOUR CHARGES		4593.00	6500.00
ADDITIONAL DISCOUNT(5.00%)			325.00
FINAL LABOUR CHARGES			6175.00

3463
 - 5%
 3289.85

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJT7232

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 GLASS-TAIL GATE	K0300-1JY0A	1875.50 /		X
2 DOOR BACK	K0100-ED0MM	1198.90 /		X
3 BRKT LIC LAMP	96252-AA000	63.50 X		X
4 EMBLEM-REAR	90892-EE10A	80.90 /		X
5 EMBLEM-REAR	90890-ED000	59.70 /		X
6 WEATHER STRIP	90830-1U600	71.20 /		X
7 HANDLE ASSY BACK DOOR	90606-1JY3B	135.70 X		X
8 STRIKER-TAIL GA	90570-AX000	31.70 X		X
9 STAY-REAR BUMPE RH	85212-AX010	43.30 /		X
10 ENERGY ABSORDER	85090-1JY0A	37.00 /		X
11 BRKT-RR BUMPER	85227-ED000	33.30 /		X
12 BRKT-RR BUMPER RH	85226-ED000	33.30 /		X
13 STAY-REAR BUMPE LH	85213-AX010	43.30 /		X
14 BUMPER SET-RR	85022-1JY0J	532.40 /		X
15 SENSOR-REVERSE	SENSOR			250.00 / X
16 SUNDRIES	NPN			70.00 ⁵⁰ X
17 A LOCK LIFT	90502-EY10D	116.70 /		X
18 PANEL-REAR UPPE	79110-1JY0A	434.40 /		X
19 CLIP(10X1.3)	01553-09321	13.00 /		X
20 FINISHER-LUGGAG SIDE LH	84951-ED000	415.80 /		X
21 CLIP(10X1.2)	01553-10501	12.00 /		X
22 BOARD ASSY	84908-ED01A	336.00 X		X
23 MASK-KICKING PL	84994-ED000	63.00 X		X
24 PLATE-LUGGAGE	84992-ED000	83.60 X		X

P- 2292.45
 N- 280
 L- 3289.85
 S 86230

4584.90 - 280
 -50%
 2292.45

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJT723Z

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
		0.00	0.00	0.00
SUB TOTAL		0.00	0.00	0.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)				
GRAND TOTAL		0.00	0.00	0.00
OVERALL TOTAL		0.00		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before enter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Vivian

IG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0085/2019
DATE : 08-FEB-2019

DS => Steve(LKK)

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN: MOTOR CLAIM MANAGER VALENCIA

ZHR

OWNER'S NAME : MDM YONG YAN YI
ADDRESS : BLK 613 CLEMENTI WEST ST 1
#06-350
S(120613)
TELEPHONE NO : 96658860/67763162

Recommend Repair (6 Pay)

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SGL563R
VEHICLE NO : SJ77232
MODEL CODE : PDUARDAC11EYAA--03
MODEL/YEAR : LATIO 1.5 A/T SPORTS BASE (1)
ENGINE NO : HR15155748B
CHASSIS NO : JN1FAAC1120010772
MILEAGE : 1 KM
DATE IN : 09/02/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 25/01/2019

LOU => \$60 x 6
=> \$360.00

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0085/2019
DATE : 08-FEB-2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : MDM YONG YAN YI
ADDRESS : BLK 613 CLEMENTI WEST ST 1
#06-350
S(120613)
TELEPHONE NO : 96685860/67763162

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SGL663R
VEHICLE NO : SJT723Z
MODEL CODE : FDUARDAC11EYAA--DB
MODEL/YEAR : LATIO 1.5 A/T SPORTS BASE (I)
ENGINE NO : HR15155748B
CHASSIS NO : JN1FAAC11Z0010772
MILEAGE : 1 KM
DATE IN : 08/02/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 25/01/2019

DIRECT SETTLEMENT
OWNER CLAIMING LOSS OF USE / RENTAL
~~CAR AT WORKSHOP~~ / CAR NOT AT WORKSHOP
KINDLY REVERT TO ME ASAP 8/2/2019
EMAIL : zuhri@tanchong.com
OFFICE : 67038916 FAX : 64697472

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJT723Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS	60.00	/
2	PSC	PULL/STRAIGHTEN CHASSIS	350.00	9x
3	RCI	REPLACE REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST	120.00	/
4	RISCCP	REMOVE/INSTALL SEAT & CUSHION CARPET (PARTIAL)	120.00	9x
5	RPI	PERFORM RUST PROOFING & TREATMENT FOR 2X AFFECTED PANEL	240.00	120 /
6	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	/
7	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY 3XAREA PANEL	300.00	/
8	SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	/
9	ZZ/001	TRANSFER MECHANICAL PART FOR REAR TAILGATE	60.00	/
10	ZZ/002	CHECK LIGHTING	48.00	/
11	ZZ/003	RENEW REAR WINDSCREEN	180.00	/
12	ZZ/004	REPAIR REAR FENDER RH & LH SIDE, REAR PANFLOOR, RENEW REAR TAILGATE, RR BUMPER & RR END PANEL	1500.00	1500 1250 /
13	ZZ/005	S/PAINT REAR BUMPER, RR END PANEL, RR TAILGATE, RR PANFLOOR, RR FENDER RH & LH SIDE	1400.00	1300 /
TOTAL LABOUR CHARGES			4583.00	

Rigid Exhaust pipe 120 ✓

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

Steve (LKK)
 12/2/19
 L/S
 6 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJT723Z

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 SENSOR-REVERSE / BR	SENSOR			250.00
2 SUNDRIES / NEC	NPN			70.00 30/
3 EMBLEM-REAR / NEC	90892-EE10A	80.90		
4 EMBLEM-REAR / NEC	90890-ED000	59.70		
5 WEATHER STRIP 2 / CR4	90830-1U600	71.20		
6 STRIKER-TAIL GA X NAI	90570-AX000	31.70		
7 HANDLE ASSY BACK DOOR 3xNN	90606-1JY3B	135.70		
8 A LOCK LIFT 8 / DT	90502-EY10D	116.70		
9 DOOR BACK / DD	K0100-ED0MM	1198.90		
10 GLASS-TAIL GATE / NEC	K0300-1JY0A	1875.50		
11 STAY-REAR BUMPE RH / DR	85212-AX010	43.30		
12 STAY-REAR BUMPE LH / DR	85213-AX010	43.30		
13 PANEL-REAR UPPE P / DD	79110-1JY0A	434.40		
14 BRKT-RR BUMPER RH / DR	85226-ED000	33.30		
15 BRKT-RR BUMPER LH / DR	85227-ED000	33.30		
16 ENERGY ABSORBER 2 / CR4	85090-1JY0A	37.00		
17 CLIP(10X1.3) / NEC	01553-09321	13.00		
18 BRKT LIC LAMP 2xNN	96252-AA000	63.50		
19 BUMPER SET-RR / DD	85022-1JY0J	532.40		
20 FINISHER-LUGGAG SIDE LH X NAI	84951-ED000	415.80		
21 CLIP(10X1.2) / NEC	01553-10501	12.00		
22 BOARD ASSY 2xNN	84908-ED01A	336.00		
23 MASK-KICKING PL 2x NAI	84994-ED000	63.00		
24 PLATE-LUGGAGE 2xNN	84992-ED000	83.60		

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJT723Z

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
SUB TOTAL		5714.20	0.00	320.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1142.84	0.00	0.00
GRAND TOTAL		4571.36	0.00	320.00
OVERALL TOTAL		4891.36		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJT723Z

TOTAL LABOUR CHARGES	4583.00
TOTAL SPARE PARTS CHARGES	4891.36

GRAND TOTAL	9474.36 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1254E
Vehicle Details	
Vehicle No.:	SJT723Z
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jan 2019
Vehicle Make:	NISSAN
Vehicle Model:	LATIO SPORT BASE 1.5L AT ABS D/AB 2WD 5D
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	HR15155748B
Chassis No.:	JN1FAAC11Z0010772
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,927.00
Original Registration Date:	23 Sep 2009
First Registration Date:	23 Sep 2009
Transfer Count:	0
Actual ARF Paid:	\$16,927.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Sep 2019
PARF Rebate Amount:	\$8,463.00
Intended COE Rebate Details	
COE Expiry Date:	22 Sep 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$15,019.00
COE Rebate Amount:	\$988.00
Total Rebate Amount:	\$9,451.00

The information contained herein is correct as at 26 Jan 2019

OK

SATISFACTORY NOTE

TAN CHONG MOTOR SALES PTE LTD (TCMS)

AUTOLUTION INDUSTRIAL PTE LTD (AIPL)

TC AUTOCLINIC PTE LTD (TCAC)

TYPE OF CLAIM:

DATE: _____

OWN DAMAGE (OD)

OWNER NAME: MOH YONG YAN YI

OWN DAMAGE (OD) & UNINSURED LOSS (EXCESS & LOSS OF USAGE) VIA TCMS / AIPL / TCAC

NRIC NO.: _____

ADDRESS: 613 CLEMENTI WEST ST1

THIRD PARTY THROUGH TCMS / AIPL / TCAC

06-350

S(120613)

THIRD PARTY - OWNER DIRECT CLAIM AGAINST THIRD PARTY INSURANCE

WINDSCREEN / GLASS (W/S)

VEHICLE MODEL: NISSAN LATIO 15

INSURANCE CO.: AICT - AXA

REGN. NO.: SJT 723 Z

CLAIM NO.: _____

CHASSIS NO.: _____


POLICY NO.: JP - SGL663R

DATE OF ACCIDENT: <u>25.1.2019</u>	DATE RECEIVED: <u>15.2.2019</u>	DATE COMPLETED: <u>21.2.2019</u>
------------------------------------	---------------------------------	----------------------------------

We / I hereby confirmed that the accident repair carried out by Tan Chong Motor Sales Pte Ltd / Autolution Industrial Pte Ltd / TC AutoClinic Pte Ltd and that all necessary repairs as resulted of the accident of the above vehicle have been completed to our / my satisfaction and that We / I have no futher claim whatsoever against the above Company in repect thereof. Terms and Conditions as stipulated in the overleaf applies.

We / I have taken delivery of my car after all necessary repair carried out by Tan Chong Motor Sales Pte Ltd / Autolution Industrial Pte Ltd / TC AutoClinic Pte Ltd on* _____

Note: In the event of an Own Damage Claim, your Insurance Company may under policy terms & conditions, or as standard Industrial Practice, increase the loading on your premium during Insurance Policy renewal. Your NCD [Non Claim Discount] may also be affected, subject to business policy of respective Insurance Company.



(NAME / SIGNATURE OF INSURED)

FOOTNOTE:

TCMS / AIPL / TCAC* WILL CLAIM ON BEHALF OF OWNER THROUGH TCMS'S LEGAL AID

DEPOSIT PAID BY OWNER

OWNER WILL MAKE CLAIM AGAINST THIRD PARTY INSURANCE COMPANY

DOCUMENTS RETURNED TO OWNER

TCMS / AIPL / TCAC* WILL CLAIM ON BEHALF OF OWNER UNINSURED LOSS. (EXCESS PAYMENT & LOSS OF USAGE)

INSURANCE CO. COPY

* Delete When Necessary