

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJT723Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS	60.00	/
2	PSC	PULL/STRAIGHTEN CHASSIS	350.00	97
3	RCI	REPLACE REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST	120.00	/
4	RISCCP	REMOVE/INSTALL SEAT & CUSHION CARPET (PARTIAL)	120.00	7X
5	RPI	PERFORM RUST PROOFING & TREATMENT FOR 2X AFFECTED PANEL	240.00	1200 /
6	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	/
7	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY 3XAREA PANEL	300.00	/ /
8	SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	/
9	ZZ/001	TRANSFER MECHANICAL PART FOR REAR TAILGATE	60.00	/
10	ZZ/002	CHECK LIGHTING	48.00	/
11	ZZ/003	RENEW REAR WINDSCREEN	180.00	/
12	ZZ/004	REPAIR REAR FENDER RH & LH SIDE, REAR PANFLOOR, RENEW REAR TAILGATE, RR BUMPER & RR END PANEL	1500.00	1500 / 1250 /
13	ZZ/005	S/PAINT REAR BUMPER, RR END PANEL, RR TAILGATE, RR PANFLOOR, RR FENDER RH & LH SIDE	1400.00	1900 /
TOTAL LABOUR CHARGES			4583.00	

Ripped Exhaust pipe 120 ✓

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

Steve (LKK)
 12/2/19
 L/S
 6 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJJ7232

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 SENSOR-REVERSE / BR	SENSOR			250.00
2 SUNDRIES / NEC	NPN			70.00 30/
3 EMBLEM-REAR / NEC	90892-EE10A	80.90		
4 EMBLEM-REAR / NEC	90890-ED000	59.70		
5 WEATHER STRIP / CR4	90830-1U600	71.20		
6 STRIKER-TAIL GA X NAI	90570-AX000	31.70		
7 HANDLE ASSY BACK DOOR ? X NN	90606-1JY3B	135.70		
8 A LOCK LIFT P / BT	90502-EY10D	116.70		
9 DOOR BACK / DD	K0100-ED0MM	1198.90		
10 GLASS-TAIL GATE / NEC	K0300-1JY0A	1875.50		
11 STAY-REAR BUMPE RH / DR	85212-AX010	43.30		
12 STAY-REAR BUMPE LH / DR	85213-AX010	43.30		
13 PANEL-REAR UPPE P / DD	79110-1JY0A	434.40		
14 BRKT-RR BUMPER RH / DR	85226-ED000	33.30		
15 BRKT-RR BUMPER LH / DR	85227-ED000	33.30		
16 ENERGY ABSORBER E / CR4	85090-1JY0A	37.00		
17 CLIP(10X1.3) / NEC	01553-09321	13.00		
18 BRKT LIC LAMP ? X NN	96252-AA000	63.50		
19 BUMPER SET-RR / DD	85022-1JY0J	532.40		
20 FINISHER-LUGGAG SIDE LH X NAI	84951-ED000	415.80		
21 CLIP(10X1.2) / NEC	01553-10501	12.00		
22 BOARD ASSY ? X NN	84908-ED01A	336.00		
23 MASK-KICKING PL P X NAI	84994-ED000	63.00		
24 PLATE-LUGGAGE ? X NN	84992-ED000	83.60		

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJT723Z

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
SUB TOTAL		5714.20	0.00	320.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1142.84	0.00	0.00
GRAND TOTAL		4571.36	0.00	320.00
OVERALL TOTAL		4891.36		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJT723Z

TOTAL LABOUR CHARGES	4583.00
TOTAL SPARE PARTS CHARGES	4891.36

GRAND TOTAL	9474.36 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.