

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0085/2019
DATE : 08-FEB-2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : MDM YONG YAN YI
ADDRESS : BLK 613 CLEMENTI WEST ST 1
#06-350
S(120613)
TELEPHONE NO : 96685860/67763162

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SGL663R
VEHICLE NO : SJT723Z
MODEL CODE : FDUARDAC11EYAA--DB
MODEL/YEAR : LATIO 1.5 A/T SPORTS BASE (I)
ENGINE NO : HR15155748B
CHASSIS NO : JN1FAAC11Z0010772
MILEAGE : 1 KM
DATE IN : 08/02/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 25/01/2019

DIRECT SETTLEMENT
OWNER CLAIMING LOSS OF USE / RENTAL
~~CAR AT WORKSHOP / CAR NOT AT WORKSHOP~~
KINDLY REVERT TO ME ASAP 8/2/2019
EMAIL : zuhri@tanchong.com
OFFICE : 67038916 FAX : 64697472

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGT723Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS	60.00	/
2	PSC	PULL/STRAIGHTEN CHASSIS	350.00	?
3	RCI	REPLACE REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST	120.00	X
4	RISCCP	REMOVE/INSTALL SEAT & CUSHION CARPET (PARTIAL)	120.00	?
5	RPI	PERFORM RUST PROOFING & TREATMENT FOR 2X AFFECTED PANEL	240.00	1200 /
6	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	/
7	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY 3XAREA PANEL	300.00	200 /
8	SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	/
9	ZZ/001	TRANSFER MECHANICAL PART FOR REAR TAILGATE	60.00	/
10	ZZ/002	CHECK LIGHTING	48.00	/
11	ZZ/003	RENEW REAR WINDSCREEN	180.00	/
12	ZZ/004	REPAIR REAR FENDER RH & LH SIDE, REAR PANFLOOR, RENEW REAR TAILGATE, RR BUMPER & RR END PANEL	1500.00	1500 ✓ 1250 /
13	ZZ/005	S/PAINT REAR BUMPER, RR END PANEL, RR TAILGATE, RR PANFLOOR, RR FENDER RH & LH SIDE	1400.00	1000 /
TOTAL LABOUR CHARGES			4583.00	

Repd Exhaust pipe 120 ✓

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

Stem (LKK)
 12/2/19
 L/S
 6 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJT723Z

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	SENSOR-REVERSE / BR	SENSOR		250.00
2	SUNDRIES / NEC	NPN		70.00 30/
3	EMBLEM-REAR / NEC	90892-EE10A	80.90	
4	EMBLEM-REAR / NEC	90890-ED000	59.70	
5	WEATHER STRIP 2 / CR4	90830-1U600	71.20	
6	STRIKER-TAIL GA X NAI	90570-AX000	31.70	
7	HANDLE ASSY BACK DOOR ?	90606-1JY3B	135.70	
8	A LOCK LIFT P / DT	90502-EY10D	116.70	
9	DOOR BACK / DD	K0100-ED0MM	1198.90	
10	GLASS-TAIL GATE / NEC	K0300-1JY0A	1875.50	
11	STAY-REAR BUMPE RH / BR	85212-AX010	43.30	
12	STAY-REAR BUMPE LH / BR	85213-AX010	43.30	
13	PANEL-REAR UPPE P / DD	79110-1JY0A	434.40	
14	BRKT-RR BUMPER RH / BR	85226-ED000	33.30	
15	BRKT-RR BUMPER LH / BR	85227-ED000	33.30	
16	ENERGY ABSORBER 2 / CR4	85090-1JY0A	37.00	
17	CLIP(10X1.3) / NEC	01553-09321	13.00	
18	BRKT LIC LAMP ?	96252-AA000	63.50	
19	BUMPER SET-RR / DD	85022-1JY0J	532.40	
20	FINISHER-LUGGAG SIDE LH X NAI	84951-ED000	415.80	
21	CLIP(10X1.2) / NEC	01553-10501	12.00	
22	BOARD ASSY ?	84908-ED01A	336.00	
23	MASK-KICKING PL P X NAI	84994-ED000	63.00	
24	PLATE-LUGGAGE ? Rm on 7/1/19	84992-ED000	83.60	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJT723Z

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
SUB TOTAL		5714.20	0.00	320.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1142.84	0.00	0.00
GRAND TOTAL		4571.36	0.00	320.00
OVERALL TOTAL		4891.36		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJT723Z

TOTAL LABOUR CHARGES 4583.00
TOTAL SPARE PARTS CHARGES 4891.36

GRAND TOTAL 9474.36 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
 affected vehicle. Should we require further labour
 charges & spare parts in the process of repairs, we
 shall inform you accordingly.