

ASS. REC. BY:

REF:

CS/SM019002504/71td3ⁿ²

Special Instruction:

Surveyor:

Merimen

Taufik

ASSIGNMENT (Office)

From (Person):

Huang Shiang Yi

of

SMO

Date/Time:

12/2/19 @ 2.56pm

Estimated Cost:

Bill to:

OD / IT / WS / TT RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFM 4981C

Insured:

CB 71282

at Workshop m/s

Auto wheels

Tel:

91928963

of

No.1 Bukit Batok Crescent

Policy No:

D18MTSCB4000144

Claim No:

CMTD1900789

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/02/2019

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

4:08pm @ 12/2/19

Person Contacted:

Jawis

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SFM 4981C - X
	CB 71282 - X
13/2@13:59	- Revised via merimen. preli aduce.
	lump sum \$2900/- (Red: 4379.78! 60%)

SYNOPSIS

Tynjala

REF:

Samps

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

425k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SFM 4981C Yr Regn: 20/2 March

Type: M/Car/ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Camry

cc

1498

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading:

2157854

T/Radio: Insured / Std / NI / NA

Eng/No:

Ct/No:

MR053BK40705/687

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

7 1/2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

44mm

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

12/2/17 @ 1730

Survey held at

Auto wheels BPS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1) 14 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$)

TP
2900/-

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation

) \$ + P5 \$

) Photos

) Others

TOTAL

250
10

260

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hwang Shiang Yi

Date: 13 Feb 2019

Preliminary Advice

Insured Vehicle No	: CB7128Z	Accident Date	: 08/02/2019
TP Vehicle No	: SFM4981C	Assignment Date	: 12/02/2019
Make	: TOYOTA CAMRY	Est. Duration of Repair	: 5.00
Date of Inspection	: 12/02/2019		
Inspection At	: AUTO WHEELS MOTORWORKS PTE LTD (HQ) NO.1 BUKIT BATOK CRESCENT, #02-40 WCEGA PLAZA SINGAPORE 658064		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,279.78
Revised Amount	:S\$	3,798.05
Check Items (Estimated)	:S\$	415.58
Total	:S\$	4,213.63

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Survey on "WP"

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Feb 2019		12 Feb 2019 14:56 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LOO CHIN TECK, ID: S1186207A, Tel: +6596228063, Email: NOEMAIL			
Main Claimant:	LIM SIEW LING, ID: S7211503A			
Vehicle Reg. No.:	SFM4981C	Date of Loss:	08/02/2019 13:00 - :59	
Claim Type:	TP / CMTD1900789	Policy/Cover Note No.:	D18MTSCBU000144 (Comprehensive)	
Vehicle Reg. No. (Insured):	CB7128Z	Policy No. (Claimant):		
		Excess:		
Repairer:	Auto Wheels Motorworks Pte Ltd (HQ) No.1 Bukit Batok Crescent, #02-40 WCEGA PLAZA, 658064 Bukit Batok - Tel: 97684247			
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/02/2019]			
Driver/Custodian (Insured):	LOO CHIN TECK (62 / Male), NRIC: S1186207A, Tel: +6596228063			
Adj Asg. Remarks:	PIC: Louis Ong 91928963 VEH IN			

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Louis Ong <louisongautowheels@yahoo.com>
Sent: Thursday, 11 April 2019 8:25 PM
To: Taufikh (LKKAuto); Denise Tay (LKKAuto)
Cc: SUR
Subject: Re: Finalize for vehicle SFM4981C Lumpsum \$3,050.00 with 5 repair days before GST.

Hi,

We accept the amount.

Thanks

Auto Wheels Motorworks PTE LTD
Louis Ong
91928963

On Thursday, 11 April 2019, 11:20:02 am GMT+8, Denise Tay (LKKAuto) <denisetay@lkkauto.com> wrote:

Dear Louis,

Re-counter offer at lump sum \$2,900. 5days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Louis Ong <louisongautowheels@yahoo.com>
Sent: Saturday, 6 April 2019 1:09 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 1503A

Vehicle Details

Vehicle No.: SFM4981C
Vehicle to be Exported: No
Intended Deregistration Date: 13 Feb 2019
Vehicle Make: TOYOTA
Vehicle Model: CAMRY 2.0 AUTO ABS
AIRBAG
Primary Colour: Beige
Manufacturing Year: 2009
Engine No.: 1AZE153931
Chassis No.: MR053BK4107051684
Maximum Power Output: 108.0 kW (144 bhp)
Open Market Value: \$27,271.00
Original Registration Date: 17 Mar 2010
First Registration Date: 17 Mar 2010
Transfer Count: 2
Actual ARF Paid: \$27,271.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 16 Mar 2020
PARF Rebate Amount: \$14,999.00

Intended COE Rebate Details

COE Expiry Date: 16 Mar 2020
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$26,389.00
COE Rebate Amount: \$2,880.00
Total Rebate Amount: \$17,879.00

The information contained herein is correct as at 13 Feb 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 08/02/2019 16:14
 Date Of Accident 08/02/2019 13:45
 Exact Location Of Accident ALONG HILLCREST RD
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SFM4981C
Insured/Policyholder
 Name Of Registered Owner LIM SIEW LING
 NRIC No S7211503A
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-96772432
 Alternative Phone No OFFICE-96772432

Vehicle Particulars

Manufacturer TOYOTA
 Model CAMRY

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
 PRIVATE CAR

Vehicle Category

Insurance Company

Name of Insurance Company LIBERTY INSURANCE PTE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number SI18V05249/VPC/R00
 Cover Note Number

Driver

Name of Driver LIM BOON POH
 NRIC No S0246195A
 Date Of Birth 06/11/1951
 Occupation INDOOR
 Date Of Driving Pass 20/09/1973
 Driving Experience 45 YEARS AND 4 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-96772432
 Fax Number
 Contact Number
 EMail Address NOEMAIL

BLK 260 BT BATOK EAST AVE 4 #08-285

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured PARENT

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : --
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: WILL PASSED TO W/SHOP FOR TP CLAIM

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number CB7128Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category BUS

Name of Driver

NRIC/Passport Number S1186207A

Contact Number 96228063

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



Car A - SIM 4981C
Car B - CB 7128Z

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While in the small road, with 2 exit lane, ^{at 12.30pm} ~~waiting~~ to exit to Dunearn road, coming out from Raffles Girl Primary School. The other vehicle, CB 7128Z, beside the other lane suddenly come into my lane and knock my front right side of my vehicle. I had pre-horn him to avoid the accident but was too late. The driver, Mr. Loo Chin Teck, IC 1186207A, come down out and admit his fault for driving carelessly to my lane and ask me to claim from his insurance company, Sompo.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC BUKIT BATOK (VAC)

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: SOMPO INSURANCE

DATE: 11/2/2019
 VEHICLE NO: SFM4981C
 MODEL: TOYOTA CAMRY
 YEAR: 2010
 ACCIDENT DATE: 8/2/3019
 TYPE OF CLAIM: TP
 CLAIM ADVISOR: LOUIS (91928963)
 EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
BONNET	1	\$ 956.40 R x
FRONT GRILLE	1	\$ 329.10 Cna
FRONT EMBLEM	1	\$ 65.30 ner
FRONT BUMPER	1	\$ 779.60 de - 581.45 nn
FRONT BUMPER RETAINER	2	\$ 50.70 101.40 RH ner, LH x
FRONT BUMPER BRACKET	2	\$ 2790 155.80 RH ner, LH x nn
FRONT BUMPER CENTRE LOWER GRILLE	1	\$ 196.40 x }
FRONT BUMPER SPONGE	1	\$ 165.70 x }
FRONT REINFORCEMENT	1	\$ 395.20 x }
SUPPORT PANEL	1	REPAIR
FRONT NUMBER PLATE GARNISH	1	\$ 178.40 x nn
HEADLAMP	1	\$ 1,032.20 Cna 1032.20
RH FOGLAMP	1	\$ 387.50 x nn
RH FOGLAMP COVER	1	\$ 178.40 R nn
RH FOGLAMP CHROME LINING	1	\$ 167.40 act
RH FRONT FENDER	1	\$ 497.40 buer
RH FRONT FENDER INNER PANEL	1	RESTORE R

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: SOMPO INSURANCE

DATE: 11/2/2019
VEHICLE NO: SFM4981C
MODEL: TOYOTA CAMRY
YEAR: 2010
ACCIDENT DATE: 8/2/3019
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

RH FRONT FENDER INNER SHIELD	1	\$	197.80 <i>de</i>
WIPER TANK	1	\$	<i>nn</i> 176.30 ?
WIPER TANK MOTOR	1	\$	<i>nn</i> 199.40 ?

TOTAL:	\$	6,159.70
DISCOUNT 25%:	\$	1,539.93
	\$	<u>4,619.78</u>

S/NET

FRONT NUMBER PLATE	1	\$	100.00 <i>X nn.</i>
FRONT BUMPER CLIPS	10	\$	<i>30.00 net</i>
FRONT GRILLE CLIPS	10	\$	<i>30.00 10 net</i>
RH FRONT FENDER INNER SHIELD CLIPS	10	\$	<i>30.00 10 net</i>
TOTAL:	\$	<u>30.00</u>	

LABOUR

	PRICE
LABOUR FOR FACILITATE REPAIR	\$ <i>1,200.00 600</i>
TO RESPRAY AFFECTED AREAS - BONNET	\$ <i>300.00 200</i>
TO RESPRAY AFFECTED AREAS - FRONT BUMPER	\$ <i>300.00 200</i>
TO RESPRAY AFFECTED AREAS - RH FRONT FENDER AND INNER PANEL	\$ <i>300.00 200</i>

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: SOMPO INSURANCE

DATE: 11/2/2019
VEHICLE NO: SFM4981C
MODEL: TOYOTA CAMRY
YEAR: 2010
ACCIDENT DATE: 8/2/3019
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

TO RESPRAY AFFECTED AREAS - SUPPORT PANEL
TO CHECK AND RECONNECT ALL NECESSARY WIRING
SUNDARIES
RUST PROOFING

\$	250.00	600-
\$	100.00	30-
\$	80.00	20- X (W/B)
\$	100.00	30-
TOTAL: \$	2,630.00	

TOTAL: \$	7,279.78
7% GST: \$	509.58
\$	7,789.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


13/2/19

Tanfer 9749549
WP

12/2/19 @ 530pm

tanfer@lkkauto.com

5 days

Warranty

Resurvey after repair

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: SOMPO INSURANCE

DATE: 11/2/2019
VEHICLE NO: SFM4981C
MODEL: TOYOTA CAMRY
YEAR: 2010
ACCIDENT DATE: 8/2/2019
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION

QTY

LIST PRICE

PARTS

BONNET	1	\$	R 956.40 R
FRONT GRILLE	1	\$	- 329.10 C
FRONT EMBLEM	1	\$	- 65.30 W
FRONT BUMPER	1	\$	- 779.60 de
FRONT BUMPER RETAINER	2	\$	50.70 101.40 RH-LH-X
FRONT BUMPER BRACKET	2	\$	77.90 155.80 RH-LH-X
FRONT BUMPER CENTRE LOWER GRILLE	1	\$	X 196.40 X
FRONT BUMPER SPONGE	1	\$	X 165.70 X
FRONT REINFORCEMENT	1	\$	X 395.20 X
SUPPORT PANEL	1		REPAIR
FRONT NUMBER PLATE GARNISH	1	\$	X 178.40 X
HEADLAMP	2	\$	- 1,032.20 C
RH FOGLAMP	1	\$	X 387.50 X
RH FOGLAMP COVER	1	\$	X 178.40 ?
RH FOGLAMP CHROME LINING	1	\$	- 167.40 ant
RH FRONT FENDER	1	\$	- 497.40 bu
RH FRONT FENDER INNER PANEL	1		RESTORE

2,999.60

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: SOMPO INSURANCE

DATE: 11/2/2019
VEHICLE NO: SFM4981C
MODEL: TOYOTA CAMRY
YEAR: 2010
ACCIDENT DATE: 8/2/3019
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

RH FRONT FENDER INNER SHIELD	1	\$	197.80 <i>de</i>
WIPER TANK	1	\$	176.30 ? X
WIPER TANK MOTOR	1	\$	199.40 ? X

TOTAL:	\$	6,159.70	<i>3,197.40</i>
DISCOUNT 25%:	\$	1,539.93	<i>799.35</i>
	\$	<u>4,619.78</u>	<i>2,398.05</i>

S/NET

FRONT NUMBER PLATE	1	\$	100.00 X
FRONT BUMPER CLIPS	10	\$	30.00 <i>net</i>
FRONT GRILLE CLIPS	10	\$	30.00 <i>10 net</i>
RH FRONT FENDER INNER SHIELD CLIPS	10	\$	30.00 <i>10 net</i>
TOTAL:	\$	<u>30.00</u>	<i>(50)</i>

LABOUR

LABOUR FOR FACILITATE REPAIR
TO RESPRAY AFFECTED AREAS - BONNET
TO RESPRAY AFFECTED AREAS - FRONT BUMPER
TO RESPRAY AFFECTED AREAS - RH FRONT FENDER AND INNER PANEL

PRICE

\$	1,200.00	<i>600</i>
\$	300.00	<i>200</i>
\$	300.00	<i>200</i>
\$	300.00	<i>200</i>

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: SOMPO INSURANCE

DATE: 11/2/2019
VEHICLE NO: SFM4981C
MODEL: TOYOTA CAMRY
YEAR: 2010
ACCIDENT DATE: 8/2/2019
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

TO RESPRAY AFFECTED AREAS - SUPPORT PANEL
TO CHECK AND RECONNECT ALL NECESSARY WIRING
SUNDARIES
RUST PROOFING

\$	250.00	600-
\$	100.00	30-
\$	80.00	20-
\$	100.00	30-
TOTAL: \$	2,630.00	1380
TOTAL: \$	7,279.78	3,828.05
7% GST: \$	509.58	
\$	7,789.36	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfer 9749549
WP
12/2/19 @ 530pm
tanfer@lkkauto.com
5 days
Ls: 3,050
5 days
Lumpsum
Resurvey after repair

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19002504/T1TD3N2

Date: 15/04/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTSCBU000144
Claimant Vehicle No :	SFM4981C	Insured Vehicle No :	CB7128Z
Date of Loss:	08/02/2019	Nature of Claim:	TP
		Claim No:	CMTD1900789

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFM4981C	Engine No:	1AZE153931
Make & Model:	TOYOTA CAMRY, 2.0 (A)	Chassis No:	MR053BK4107051684
Reg. Date:	17/03/2010 (Man. Year: 2009)	Odometer:	157854 km
Colour:	Beige		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,889.77	2,299.44	2,590.33	52.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	1,360.00	1,190.00	46.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,439.77	3,659.44	3,780.33	50.81
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	7,439.77	2,900.00	4,539.77	61.02
+ GST 7.00/7.00% (S\$)	520.78	203.00	317.78	61.02
Nett Amount (S\$)	7,960.55	3,103.00	4,857.55	61.02

INSPECTION

Date of Assignment: 12/02/2019
 Date Inspected: 12/02/2019 Inspected At:

Auto Wheels Motorworks Pte Ltd (HQ)
 No.1 Bukit Batok Crescent, #02-40
 WCEGA PLAZA
 Singapore 658064

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Apr 2019)
Parts:	143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFM4981C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	956.40 FL	*- FL
2	1		*FRONT GRILLE	Cracked	329.10 FL	*329.10 FL
3	1		*FRONT EMBLEM	Necessary	65.30 FL	*65.30 FL
4	1		*FRONT BUMPER	Deformed	779.60 FL	*581.45 FL
5	1		*FRONT BUMPER RETAINER	Os Necessary/Ns Not Necessary	101.40 FL	*50.70 FL
6	1		*FRONT BUMPER BRACKET	Os Necessary/Ns Not Necessary	155.80 FL	*77.90 FL
7	1		*FRONT BUMPER CENTRE LOWER GRILLE	Not Necessary	196.40 FL	*- FL
8	1		*FRONT BUMPER SPONGE	Not Necessary	165.70 FL	*- FL
9	1		*FRONT REINFORCEMENT	Not Necessary	395.20 FL	*- FL
10	1		*SUPPORT PANEL (NPA)	Repair	0.00 FL	*- FL
11	1		*FRONT NUMBER PLATE GARNISH	Not Necessary	178.40 FL	*- FL
12	1		*HEADLAMP	Cracked	1,032.20 FL	*1,032.20 FL
13	1		*RH FOGLAMP	Not Necessary	387.50 FL	*- FL
14	1		*RH FOGLAMP COVER	Not Necessary	178.40 FL	*- FL
15	1		*RH FOGLAMP CHROME LINING	Cut	167.40 FL	*167.40 FL
16	1		*RH FRONT FENDER	Buckled	497.40 FL	*497.40 FL
17	1		*RH FRONT FENDER INNER PANEL (NPA)	Repair	0.00 FL	*- FL
18	1		*RH FRONT FENDER INNER SHIELD	Deformed	197.80 FL	*197.80 FL
19	1		*WIPER TANK	Not Necessary	176.30 FL	*- FL
20	1		*WIPER TANK MOTOR	Not Necessary	199.40 FL	*- FL
21	1		*FRONT NUMBER PLATE	Not Necessary	100.00 FS	*- FS
22	10		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
23	10		*FRONT GRILLE CLIPS	Necessary	30.00 FS	*10.00 FS
24	10		*RH FRONT FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*10.00 FS
25	1		*SUNDARIES	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,429.70	3,049.25
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,539.93	749.81
Total Parts (\$\$)	4,889.77	2,299.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR FACILITATE REPAIR	New	1,200.00	600.00
2	TO RESPRAY AFFECTED AREAS-BONNET	New	300.00	200.00
3	TO RESPRAY AFFECTED AREAS-FRONT BUMPER	New	300.00	200.00
4	TO RESPRAY AFFECTED AREAS-RH FRONT FENDER AND INNER PANEL	New	300.00	200.00
5	TO RESPRAY AFFECTED AREAS-SUPPORT PANEL	New	250.00	100.00
6	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	100.00	30.00
7	RUST PROOFING	New	100.00	30.00
Gross Labour Cost (\$\$)			2,550.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >