
Estimated Cos	: Kanaliah Kanis		Bill to:	
OD/TP/WS	HTP RES / OD RES / E	ON INVINVIG		Insured:
	m/s			
		Person Contacted.	Excess: _	TP IP ST PS 2018 D.O.A. 8 10 20 H.O.D. Endorment Vehicle IN LOUT
Date/Time	Action/Instruction () Estimate		
	MCW 9025-X	1/-1	0	returned of some
		12/4	O DAG	

New cases (14 cases)
Rohaizal (LKKAuto) Main apy



From:

Kamaliah KAMIS (SPF) < Kamaliah_KAMIS@spf.gov.sg>

Sent:

Friday, 1 February 2019 7:01 PM

To:

Rohaizal (LKKAuto)

Cc:

Bryan Ang (LKKAuto); SPF-TP FAIT; Jun Yan TAN (SPF); Mohammed Feroz HUSSIEN

(SPF); Syed Zayid MUHAMMAD (SPF)

Subject:

Mechanical Inspection Report Request

Hi Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the 14 vehicles below:

a) Case IAFP-IB-20190114 - Mechanical Inspection of Motor Van GBH5120M (TP/IP/64329/2018)

On 21 November 2018 at about 12.25 pm, Police incident was created regarding an accident along Blk 268 Bukit Batok East Avenue 4 involving a motor van and pedestrian. Preliminary investigation revealed that motor van was turning right from the car park of Blk 265 Bukit Batok East Avenue 5, into the main road of Bukit Batok East Avenue 4. While making the right turn, pedestrian crossed from motor van's left to right side which resulted in the collision. As a result of the collision, pedestrian was conveyed by ambulance to National University Hospital (NUH) in an unconscious state as she sustained head injuries. She succumbed to her injuries in hospital and pronounced dead on 24 November 2018 at 12.57pm by Dr Sukhen.

Vehicle to be inspected: GBH5120M (Potential Defendant)

IO In-Charge: DOC Saleha

- b) Case IAFP-IB-20190114 Mechanical Inspection of Motorcycle, JNU3125 (TP/IP/57195/2018)
- c) Case IAFP-IB-20190114 Mechanical Inspection of Motorcycle, JSR3079 (TP/IP/57195/2018)
- d) Case IAFP-IB-20190114 Mechanical Inspection of Motorcycle, MCW9025 (TP/IP/57195/2018)

On 8 October 2018 (Monday) at about 5.36 a.m., the Deceased was riding his motorcycle along Woodlands Crossing and as he was approaching the entrance into the dedicated motorcycle lane, he collided into the temporary barricade. Due to the impact, the Deceased veered to the left and collided into the 1st Involved Party's motorcycle. As a result of the collision, the Deceased, 1st Involved Party and his pillion were flung off their motorcycles and skidded along the road. At the time, the 2st Involved Party was riding a distance behind when the collision occurred. He applied the emergency brakes, which resulted in him losing control of his motorcycle and skidded. The Deceased was pronounced dead at the scene by the attending paramedic at 5.58 a.m. All the Involved Parties were conveyed to Khoo Teck Puat Hospital conscious.

Vehicles to be inspected: JNU3125 (Deceased)

Vehicles to be inspected: JSR3079 (1st involved party)

Vehicles to be inspected: MCW9025 (2nd involved party)

10 In-Charge: DOC Saleha

e) Case IAFP-IB-20190114 - Mechanical Inspection of Motor taxi SHD9754H (TP/IP/53269/2018)

On 17 September 2018 at about 2.26pm, motor taxi was travelling straight on lane 2 of 2 lanes along Telok Blangah Way towards Lower Delta road. As he was driving he claimed that his vision was blurred and about 2 seconds later he felt an impact and saw pedestrian flung. Taxi driver claimed that he did not see pedestrian beforehand and did not know where pedestrian was crossing from. As a result of the accident, pedestrian