

22/03/2002

ASS. REC. BY:

REF:

CS/MSG19002513/AGvd30

Special Instruction:

Surveyor:

Gao Chang

ASSIGNMENT (Office)

From (Person):

Monica Chung

of

MSG

Date/Time:

11/2/19 @ 4:05pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SMC 7818S

Insured:

SIX 388L

at Workshop m/s

TK Motor Workshop

Tel:

67466896

of

1 Kaki Bkt Ave 6 #02-56 Autobay

Policy No.:

Claim No.:

584318

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

03/02/2019

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

10:50am 3/2/19

Person Contacted:

Kenny

Vehicle IN ☒ OUT

Date/Time

Action/Instruction

☒

Estimate

SMC 7818S-X

SIX 388L-NA/AG19002224/K4

D.O.A: 3/2/19

13/2/19

Informed Monica pending workshop est by merimen

12/7/19

Adrian confirmed LS \$2800 (Red 4827-30, 639)

12/7/19

Send preli revised via merimen

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMC78185 Yr Regn: 2010 / May.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Harrier c.c. 2362Colour: White A/C: Insured / Std / NI / NASp. Reading 124269 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: AU300110602Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/65R17R: 225/65R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 12/02/19Survey held at T.K.Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP MSIG.

RECEIVED 15 JUL 2019

MV: 35K.PV: 19.9KNett: 15.1K.

Date/Time, File Pass to?

Date/Time, File Return to?

1) 12/7 - typist

3) _____

5) _____

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Date:

15011161

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Feb 2019		11 Feb 2019 16:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LOH TECK YONG, ID: S8008960J, Tel: +6591195801, Email: NOEMAIL		
Main Claimant:	CHEN XING JU, ID: S8210484D		
Vehicle Reg. No.:	SMC7818S	Date of Loss:	03/02/2019 20:00 - :59 [104 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 584318	Policy/Cover Note No.:	29073231 (Comprehensive) Coverage: 24/02/2018 - 10/05/2019
Vehicle Reg. No. (Insured):	SJX388L	Policy No. (Claimant):	
		Excess:	
Repairer:	Tk Motor Workshop (HQ) Blk 1 Kaki Bukit Ave 6 #02-56, Autobay @ Kaki Bt, 417883 Kaki Bukit - Tel: 67466896		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/02/2019]		
Driver/Custodian (Insured):	LOH TECK YONG (38 / Male), NRIC: S8008960J, Tel: +6591195801		
Adj Asg. Remarks:	on WP, LIAB 100% SJE AGREE LKK PLS CONTACT 9627 3323		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
-----	--	-------	---

Attn:	Monica Chung Pei Zhen	Date:	12 Jul 2019
-------	-----------------------	-------	-------------

Preliminary Advice

Insured Vehicle No	: SJX388L	Accident Date	: 03/02/2019
TP Vehicle No	: SMC7818S	Assignment Date	: 11/02/2019
Make	: TOYOTA HARRIER	Est. Duration of Repair	: 4
Date of Inspection	: 12/02/2019		
Inspection At	: TK MOTOR WORKSHOP (HQ) BLK 1 KAKI BUKIT AVE 6 #02-56, AUTOBAY @ KAKI BT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,627.30
Revised Amount	:S\$	2,800.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,800.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

View Sent Message

This mail is associated with :

***SMC7818S (584318)**

[SJX388L]

TP

CHEN XING JU

Feb 3 2019 8:00PM

[LOH TECK YONG]

Tk Motor Workshop

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **13/02/2019 13:35 PM.**

To MSIG_CPZ

Subject TP SURVEY SMC 7818S

Dear Monica,

Please be informed that we have inspected the vehicle SMC 7818S on 12/2/2019.

We are pending estimate from repairer.

Best Regards,

Veron Chen

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0484D
Vehicle Details	
Vehicle No.:	SMC78185
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER 2.4G A
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	2AZB433848
Chassis No.:	ACU300110602
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$30,179.00
Original Registration Date:	10 May 2010
First Registration Date:	10 May 2010
Transfer Count:	2
Actual ARF Paid:	\$30,179.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 May 2020
PARF Rebate Amount:	\$16,598.00
Intended COE Rebate Details	
COE Expiry Date:	09 May 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$26,389.00
COE Rebate Amount:	\$3,267.00
Total Rebate Amount:	\$19,865.00

The information contained herein is correct as at 13 Feb 2019

OK



Full Panoramic Roof And Full Electric Seats.



Posted: 18-Jan-2019

Tags: 2008 Toyota Harrier, 2008 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

DIRECT OWNER



☐ Toyota Harrier 2.4A (COE till 06/2023)

\$40,800

\$9,360 /yr

24-Jun-2008

2,362 cc

-

SUV

Available

Elegant Silver SUV, Low Mileage Done, Low Maintenance Cost, Very Well Maintained, Flexible In-house Loan Packages Available.

Prime Motor & Leasing



Posted: 26-Jan-2019

Tags: 2008 Toyota Harrier, 2008 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota



☐ Toyota Harrier 2.4A G (COE till 08/2028)

\$64,800

\$6,820 /yr

15-Aug-2008

2,362 cc

157,000 km

SUV

Available

Car In Good Condition. PQP Renewal 10 Years. Nice Number (8228) Don't Worry!



Posted: 14-Jan-2019

Tags: 2008 Toyota Harrier, 2008 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota



☐ Toyota Harrier 2.4A GL (COE till 12/2028)

\$58,800

\$5,980 /yr

09-Dec-2008

2,362 cc

129,000 km

SUV

Available

Well Maintained Harrier. Original Condition With All Wear And Tear Parts Changed. New Leather Seats. Quiet Smooth Engine And Undercarriage. High Loan And Trade In Available.



Posted: 09-Feb-2019

Tags: 2008 Toyota Harrier, 2008 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota



Insurance renewal at cheaper price!

We'll find you the cheapest car insurance quotes from over 10 Insurers. Make your choice on zero excess and own workshop. Everything done at the comfort of your own home. Roadside assistance & claims support completely free.

Find out more!



☐ Toyota Harrier 2.4A GL (New 10-yr COE)

\$58,000

\$5,800 /yr

20-Feb-2009

2,362 cc

154,985 km

SUV

Available

Full Lexus Conversion. Well Maintained Elegant Black Unit. Original Condition With All Wear And Tear Parts Changed. New Leather Seats. Quiet Smooth Engine And Undercarriage. High Loan And Trade In Ava...



Posted: 15-Jan-2019

Tags: 2009 Toyota Harrier, 2009 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

PREMIUM AD



☐ Toyota Harrier 2.4A G (New 10-yr COE)

\$59,888

\$5,980 /yr

26-Feb-2009

2,362 cc

106,250 km

SUV

Available

Well Maintained Condition! Trade In And Loan Available! Call/WhatsApp Now To Arrange For An Appointment!

Monster Motors Pte Ltd



Posted: 12-Feb-2019

Tags: 2009 Toyota Harrier, 2009 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

PREMIUM AD



☐ Toyota Harrier 2.4A GL (New 10-yr COE)

\$66,800

\$6,670 /yr

10-Mar-2009

2,362 cc

-

SUV

Available

New Paint, Low Depreciation And High Perf For Harrier! Best Valued SUV In The Market! Excellent Condition! Call Us Now! Very High In-house Loan Available.



Posted: 22-Jan-2019

Tags: 2009 Toyota Harrier, 2009 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota



☐ Toyota Harrier 2.4A G (New 10-yr COE)

\$58,900

\$5,890 /yr

26-Jun-2009

2,362 cc

151,501 km

SUV

Available

(We Assure 100% Genuine Mileage), Converted To Lexus RX350, Tip Top Condition. New Paint. Road Tax Till Jun'19. Option To Renew 5 Years COE.



Posted: 09-Feb-2019

Tags: 2009 Toyota Harrier, 2009 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota



☐ Toyota Harrier 2.4A GL

\$28,000

\$13,240 /yr

30-Dec-2009

2,362 cc

116,000 km

SUV

Available

New Road Tax! Full Lexus Conversion. Well Maintained By Previous Owner. Hesitate No More! Call Our Friendly Sales Consultant To Book An Appointment Now!



Posted: 21-Jan-2019

Tags: 2009 Toyota Harrier, 2009 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

PREMIUM AD



☐ Toyota Harrier 2.4A GL

\$51,800

\$14,950 /yr

10-Jun-2011

2,362 cc

-

SUV

Available

ABWIN (1994) Pte Ltd



Posted: 06-Jan-2019

Tags: 2011 Toyota Harrier, 2011 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota



☐ Toyota Harrier Hybrid 3.3A

\$96,800

\$13,380 /yr

23-Sep-2014

2,493 cc

-

SUV

Available

Fuel Type: Petrol-Electric

Elegant White, Powerful Drive With 194 BHP, Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, Very Well Maintained, Flexible In-House Loan Packages Available.

SHORTLISTED HISTORY

Compare

10 Sin Ming Drive Singapore 575701
www.lta.gov.sg

28 Jun 2018

Our ref 2806180203N057018665

CHEN XING JU
APT BLK 315A PUNGGOL WAY
#12-641
SINGAPORE 821315

Dear Sir/Madam

NOTIFICATION ON SUCCESSFUL REPLACEMENT OF VEHICLE REGISTRATION NO. SJX252U WITH VEHICLE REGISTRATION NO. SMC7818S

You may be pleased to know that your application of 28 Jun 2018 for replacement of registration number is approved.

2. The details of the vehicle after the transaction are as follows:

Vehicle Registration No. : SMC7818S (Previously SJX252U)
Vehicle Make : TOYOTA
Vehicle Model : HARRIER 2.4G A
Chassis No. : ACU300110602
Engine No./ Motor No. : 2AZB433848 / -

3. Please change the number plates on your existing vehicle (ie. Chassis No. : ACU300110602, Engine No./ Motor No. : 2AZB433848 / -) to display the new/ replacement registration number, SMC7818S by 01 Jul 2018. It is an offence to keep or use a vehicle without displaying the correct vehicle registration number assigned. The penalty for first offence is a fine not more than \$1,000 or imprisonment of not more than 3 months. For second or subsequent offence, the fine is not more than \$2,000 or imprisonment of not more than 6 months.

4. Please contact our customer service officers on tel: 1800-CALL LTA (1800-2255 582) if you have any questions. You can either quote the Business Transaction Reference No. 20180628121749909986 or the vehicle registration number when making your enquiry.

Accident Sketch Plan



Yours sincerely

NG LAY CHOO (MS)
DEPUTY DIRECTOR, VRL SERVICE OPERATIONS
VEHICLE SERVICES GROUP
LAND TRANSPORT AUTHORITY

(This is a computer-generated notice that requires no signature.)

From 15 February 2017, you do not need to display road tax disc on the windscreen of your vehicle. LTA has stopped issuing physical road tax discs as part of our efforts to streamline our processes. Please ensure that your original motor insurance certificate is readily available in your vehicle at all times. If you are driving into Malaysia, you are advised to carry printed proof of the validity of your road tax in your vehicle.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	07/02/2019 19:07
Date Of Accident	03/02/2019 20:00
Exact Location Of Accident	PUNGGOL WAY NEAR BUS STOP OF B/261 PUNGGOL
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMC7818S
Insured/Policyholder	
Name Of Registered Owner	CHEN XING JU
NRIC No	S8210484D
Email Address	KENNETHCHENXINGJU@GMAIL.COM
Mobile Phone No	(LOCAL) +65-84888437
Alternative Phone No	OTHERS-84888437
Vehicle Particulars	
Manufacturer	TOYOTA
Model	-
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800054672
Cover Note Number	
Driver	
Name of Driver	CHEN XING JU
NRIC No	S8210484D
Date Of Birth	12/04/1982
Occupation	INDOOR
Date Of Driving Pass	10/04/2002
Driving Experience	16 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84888437
Fax Number	
Contact Number	OTHERS-84888437
Email Address	KENNETHCHENXINGJU@GMAIL.COM

Address	BLK 315A PUNGGOL WAY #12-641
Postcode	821315
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : NIL GENDER: : FEMALE
Passenger 2	NAME: : NIL GENDER: : FEMALE
Passenger 3	NAME: : NIL GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SENGKANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 2 SENGKANG SQUARE #01-02 SINGAPORE , POSTCODE: 545025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800 - 3438999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE POLICE REPORT : T/20190204/2115 / T/20190204/2117 / F/20190204/7027 /

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJX388L
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

CHEN XING JU

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

7/2/19
12.30pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:


7/2/19
12.30pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I, Chen Xing Jun, SP210484D, am the driver of vehicle, SMC7818S, together with my 3 passengers, Goh Pei Wan, S903570A, Chan Ku Zhong Kedric, T1310297F & Chen Yi Xin Ashley, T1537371C at the point of this accident. At around 8.30pm, our vehicle, SMC7818S, came to a stop behind a vehicle (In front of Bus Stop no. 65149 along Pungol way). A few seconds later, we felt a strong impact followed by a lurching from the rear of our vehicle. My son, Kedric Chan, was thrown off the rear seat. His head hit the front passenger seat and fell onto the carpet. My wife was thrown forward by the strong impact with her hand raised daughter, Ashley Chan, and the back of her head hit the rear passenger seat headrest. I was also thrown forward by the strong impact and the back of my head hit the driver seat headrest. On the next day, I brought my son and daughter, Kedric Chan & Ashley Chan, to Raffles Medical @ Raffles Place for a checkup. I was given 5 days MC. Separately, my wife went to Raffles Medical @ Changi Business Park for checkup and was given 1 day MC.

pls Refer to the Police Report
T/20190204/2115
T/20190204/2117
F/20190204/7027

DECLARATION

I/We declare the foregoing particulars are true in every respect.

J. U. Chan
Policyholder's Signature
Date & Time:

J. U. Chan
Driver's Signature
(If driver is not the policyholder)
Date & Time:

... 7/2/2019
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20190204/2115

1 of 3

Report No. T/20190204/2115

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
04/02/2019 16:01

Vide Report No.:

Station Diary No.:
175

Informant's Particulars

Name of Informant:
CHEN XING JU

Address:
APT BLK 315A PUNGGOL WAY #12-641 SINGAPORE
821315

ID Type / ID No.:
NRIC NO / S8210484D

Contact No.:
Home/Office: Mobile: 84888437

Nationality:
SINGAPORE CITIZEN

Email:

Sex: Age: Date of Birth:
Male 36 12/04/1982

Type of Informant:
Driver

Race:
Chinese

Language:

Institution / School Name:

Occupation:
MANAGER

Driving Licence Information:
Class: 2B,2A,3

Date of Expiry:

General Information of the Accident

Type of
Accident:

Injury
Others

Drink
Drive:
No

Date/Time of
Accident:
03/02/2019 20:00

Type of Location:
Straight Road

Location:
Along Road 1
PUNGGOL WAY

Near to the bus stop of B/261 Punggol

Weather:
Clear

Road Surface:
Dry

Road Speed Limit:

Traffic Flow:
Dual Carriage Way

Traffic Control:

Traffic Volume:
Moderate

Type of Collision:
Between Moving Vehicles - Head To Rear

Anyone conveyed by
ambulance:
No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJX388L	Car	AUDI		Grey	Seriously Damaged	1
SMC7818S	Car	TOYOTA	HARRIER 2.4G A	White	Seriously Damaged	3

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMC7818S	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1800054672	15/05/2018	14/05/2019



**SINGAPORE
POLICE FORCE**



T/20190204/2115

2 of 3

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

Report No. T/20190204/2115

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	CHEN XING JU	ID No.	S8210484D
Related Vehicle	SMC7818S (Car)	Contact No.	84888437
Hospital/Clinic	RAFFLES MEDICAL.	Class of Driving Licence & Expiry Date	Class: 2B, 2A, 3 Date of Expiry: NIL
Date Treatment	04/02/2019	Date Discharge	04/02/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On the 03/02/2019 at about 2030hs, I was driving my vehicle bearing the registration plate number SMC7818S along Punggol Way and was driving along the bus lane. Upon reaching the bus stop of Soo Teck LRT, I slowly came to a stop as in front of my vehicle there was bus. While waiting for the aforesaid bus to move off, suddenly one vehicle bearing the registration plate number SJX388L collided to the rear of my vehicle. I then alighted from my vehicle and checked if anyone was injured.

I wish to state that there were no visible injuries found on us. The driver and I then exchanged particulars and also agreed to proceed with insurance claims.

The bumper of my rear vehicle was seriously damaged.

On the 04/02/2019 at 1200hrs, I felt sore and pain on the my back and the back of my neck.

I am lodging this report for insurance claims.



**SINGAPORE
POLICE FORCE**



T/20190204/2115

3 of 3

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

Report No. T/20190204/2115

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /
Sgt 1 TENG WEI KANG

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
SSI 2 SITIMARSITA BINTE BOHARI
Contact No.: 65476219

Signature Of Informant:

Date/Time:
04/02/2019 16:01

Classification Of Case:

SN 085

Authentication Stamp
NP168



Signature:

Singapore Police Force

Accident Sketch Plan



T K MOTOR WORKSHOP

LKK Adrian

1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL:96273323 FAX: 68442641
CO. REG NO :53049097L

4/17 MSIG Ins
US : 5 day.

DATE: 26/2/2019

CHEN XING JU
BLK 315A PUNGGOL WAY #12-641
SINGAPORE 821315

By Hand: 13/5/2019
Veron.

DEAR SIR

ACCIDENT DATE:03/02/2019
ESTIMATE COST OF REPAIRS BILL TO TOYOTA CAR NO:SMC7818S

1 PC REAR BOOTLID	new	S\$ 1,578.20	1,578.20	+
1 PC REAR BOOTLID LOCK	new	349.40	349.40	+
1 PC REAR BOOTLID RUBBER	new	195.60	195.60	+
4 PC REAR BOOTLID EMBLEM	new	397.10	397.10	+
2 PC REAR TAILLAML SIDE GARNISH	new	178.40	178.40	+
1 PC REAR END PANEL	new	678.60	678.60	+
1 PC REAR END PANEL GARNISH	cracked.	278.40	278.40	✓
1 PC REAR BUMPER	Deformed	860.40	860.40	✓
1 PC REAR BUMPER SPONGE	cracked.	208.40	208.40	✓
1 PC REAR BUMPER REINFORCEMENT BEAM	Bent	429.60	429.60	✓
2 PC REAR BUMPER REFLECTOR	cracked	322.40	322.40	✓
8 PC REAR BUMPER CLIP	new	30.40	30.40	✓
4 PC REAR BUMPER SIDE RETAINER	new	180.40	180.40	✓
1 PC REAR BUMPER REVERSE SENSOR	Damaged. S.N. 200	200.00	200.00	S/NETT ✓
TO CHECK WRING .		50.00	50.00	30
TO SPRAY PAINTING (PEARL WHITE)		800.00	800.00	600
TO REMOVE & REFIX REAR INTERIOR UPHOSLY.		80.00	80.00	40
TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION.		80.00	80.00	x.
TO MEASURE,DRILL THE REPLACED BUMPER,POSITION & REINSTALL REAR REVERSE SENSOR ,CONTRAL UNIT,CHECK & TEST FOR FUNCTIONING		80.00	80.00	50
TO LABOUR CHARGE FOR PANEL BEATING,WELDING REMOVING ALL DAMAGED PARTS & REPLACING OF THE NEW PARTS ETC.		650.00	650.00	50

TOTAL S\$

7,627.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

total: 3300.32
L/S: 2.8K.
04 Days.

28K

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Feb 2019		11 Feb 2019 16:05 Edit Adj Rpt	S\$2,800.00 Edit Estimates	S\$2,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	LOH TECK YONG , ID: S8008960J, Tel: +6591195801, Email: NOEMAIL								
Main Claimant:	CHEN XING JU , ID: S8210484D								
Vehicle Reg. No.:	SMC7818S	Date of Loss:	03/02/2019 20:00 - :59 [104 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 584318	Policy/Cover Note No.:	29073231 (Comprehensive) Coverage: 24/02/2018 - 10/05/2019						
Vehicle Reg. No. (Insured):	SJX388L	Policy No. (Claimant):							
		Excess:							
Repairer:	Tk Motor Workshop (HQ) Blk 1 Kaki Bukit Ave 6 #02-56, Autobay @ Kaki Bt, 417883 Kaki Bukit - Tel: 67466896								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 13/03/2019]								
Driver/Custodian (Insured):	LOH TECK YONG (38 / Male) , NRIC: S8008960J, Tel: +6591195801 Email: NOEMAIL								
Adj Asg. Remarks:	on WP. LIAB 100% SJE AGREE LKK PLS CONTACT 9627 3323								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMC7818S (584318)
[SJX388L]
TP
CHEN XING JU
Feb 3 2019 8:00PM
[LOH TECK YONG]
Tk Motor Workshop

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports								1 per page		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	08/02/19 15:24	Accident Statement From:SC - Reg. No: SJX388L, Claimant: LOH TECK YONG							Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	12/07/19 15:18	Adjuster Immediate Advice							Load HTM	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	13/02/19 13:38	General View							Load JPG	<input checked="" type="checkbox"/>
2	13/02/19 13:38	General View							Load JPG	<input checked="" type="checkbox"/>
3	13/02/19 13:38	General View							Load JPG	<input checked="" type="checkbox"/>
4	13/02/19 13:38	General View							Load JPG	<input checked="" type="checkbox"/>
5	13/02/19 13:38	General View							Load JPG	<input checked="" type="checkbox"/>
6	13/02/19 13:38	General View							Load JPG	<input checked="" type="checkbox"/>
7	13/02/19 13:38	General View							Load JPG	<input checked="" type="checkbox"/>
8	13/02/19 13:38	General View							Load JPG	<input checked="" type="checkbox"/>
9	13/02/19 13:38	General View							Load JPG	<input checked="" type="checkbox"/>
10	13/02/19 13:38	General View							Load JPG	<input checked="" type="checkbox"/>
11	13/02/19 13:38	General View							Load JPG	<input checked="" type="checkbox"/>
12	13/02/19 13:38	General View							Load JPG	<input checked="" type="checkbox"/>
13	13/02/19 13:38	General View							Load JPG	<input checked="" type="checkbox"/>
14	12/07/19 13:27	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>
15	12/07/19 13:27	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>
16	12/07/19 13:27	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>
17	12/07/19 13:27	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>
18	12/07/19 13:27	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>
19	12/07/19 13:27	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>
20	12/07/19 13:27	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>
21	12/07/19 13:27	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>
22	12/07/19 13:27	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>
23	12/07/19 13:27	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>
24	12/07/19 13:27	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>
25	12/07/19 13:27	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>
26	12/07/19 13:27	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>
27	12/07/19 13:27	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>
28	12/07/19 13:27	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>
29	12/07/19 13:27	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>
30	12/07/19 13:27	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>
31	12/07/19 13:27	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>
32	12/07/19 13:27	Reinspection Photo							Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	12/07/19 13:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	12/07/19 13:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	12/07/19 13:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	12/07/19 13:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	12/07/19 13:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	12/07/19 13:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	12/07/19 13:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	12/07/19 13:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	12/07/19 13:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	12/07/19 13:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	12/07/19 13:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	12/07/19 13:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	12/07/19 13:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	12/07/19 13:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	12/07/19 13:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	12/07/19 13:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	12/07/19 13:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	12/07/19 13:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	12/07/19 13:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	12/07/19 13:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/02/19 15:24	police report From: SC - Reg. No: SJX388L, Claimant: LOH TECK YONG	Load PDF	
2	11/02/19 09:16	SJE AGREE LKK	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19002513/AGVD3E2

Date: 01/08/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29073231

Claimant Vehicle No : SMC7818S

Insured Vehicle No : SJX388L

Date of Loss: 03/02/2019

Nature of Claim: TP

Claim No: 584318

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMC7818S

Make & Model: TOYOTA HARRIER, 2.4 (A)

Engine No: 2AZB433848

Reg. Date: 10/05/2010 (Man. Year: 2010)

Chassis No: ACU300110602

Colour: White

Odometer: 124269 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65 R17

Rear Tyre Size: 225/65 R17

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,887.30	2,230.32	3,656.98	62.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,740.00	1,270.00	470.00	27.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,627.30	3,500.32	4,126.98	54.11
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	7,627.30	2,800.00	4,827.30	63.29

INSPECTION

Date of Assignment: 11/02/2019

Date Inspected: 12/02/2019 Inspected At:

Tk Motor Workshop (HQ)

Blk 1 Kaki Bukit Ave 6 #02-56, Autobay @

Kaki Bt

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Aug 2019)
Parts:	M1-SUV	TOYOTA HARRIER 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC7818S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Repair	1,578.20 F	*- FL
2	1		*REAR BOOTLID LOCK	Not Necessary	349.40 F	*- FL
3	1		*REAR BOOTLID RUBBER	Not Necessary	195.60 F	*- FL
4	1		*REAR BOOT LID EMBLEM (4PCS)	Necessary	397.10 F	*397.10 FL
5	2		*REAR TAILLAMP SIDE GARNISH	Not Necessary	178.40 F	*- FL
6	1		*REAR END PANEL	Repair	678.60 F	*- FL
7	1		*REAR END PANEL GARNISH	Cracked	278.40 F	*278.40 FL
8	1		*REAR BUMPER	Deformed	860.40 F	*860.40 FL
9	1		*REAR BUMPER SPONGE	Cracked	208.40 F	*208.40 FL
10	1		*REAR BUMPER REINFORCEMENT BEAM	Bent	429.60 F	*429.60 FL
11	2		*REAR BUMPER REFLECTOR	Cracked	322.40 F	*322.40 FL
12	8		*REAR BUMPER CLIP	Necessary	30.40 F	*30.40 FL
13	4		*REAR BUMPER SIDE RETAINER	Necessary	180.40 F	*180.40 FL
14	1		*REAR BUMPER REVERSE SENSOR	Damaged	200.00 FS	*200.00 FS
					Sub Total (S\$)	5,887.30 2,907.10
					- List Item Discount on L Items 0.00/25.00% (S\$)	0.00 676.78
					Total Parts (S\$)	5,887.30 2,230.32

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO SPRAY PAINTING (PEARL WHITE)	New	800.00	600.00
3	TO REMOVE & REFIX REAR INTERIOR UPHOSLY	New	80.00	40.00
4	TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION	New	80.00	0.00
5	TO MEASURE, DRILL THE REPLACED BUMPER, POSITION & REINSTALL REAR REVERSE SENSOR, CONTRAL UNIT, CHECK & TEST FOR FUNCTIONING	New	80.00	50.00
6	TO LABOUR CHARGE FOR PANEL BEATING, WELDING REMOVING ALL DAMAGED PARTS & REPLACING OF THE NEW PARTS ETC	New	650.00	550.00
Gross Labour Cost (S\$)			1,740.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >