

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0181/2019/GW
Date : 12-Feb-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle : YN 4176 E

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Leow Ban Leong
Address : 28 Saraca Road
Singapore 807374
Telephone : HP +65 97644638
Type of Claim : Third Party Claims
Policy No. : 1800080290
Vehicle No : **SLN 7633 L**
Model Code : Audi Q7 3.0 TFSI QU
Model / Year : Jun-~~18~~ / 18
Engine No : CRE 223785
Chassis No : WAUZZZ4M2JD027562
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 7-Feb-19
Place of Accident : CTE Twds City (Near Braddell)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLN 7633 L.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00 ✓	
2	To dismantle and renew rear bumper assy. Re-organize crash management components. Reinstall all parts removed.	\$ 1,200.00 803	
3	To respray rear bumper, mid bumper and both rear arch covers.	\$ 2,200.00 1800.	$700 + 700 = 1400$ $200 + 200 = 400$ <u>1800.</u>
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 3,952.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 7633 L.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Repl</i>	\$ 1,121.00	<i>f</i>
2	REAR BUMPER MID <i>Repl</i>	\$ 1,740.00	<i>✓</i>
3	REAR BUMPER FIXING PARTS <i>new</i>	\$ 188.00	<i>x</i>
4	REAR BUMPER SPOILER <i>Repl</i>	\$ 1,151.00	<i>✓</i>
5	REAR BUMPER SPOILER TRIM <i>Repl</i>	\$ 97.00	<i>✓ ?</i>
7	REAR BUMPER SENSOR <i>new Repl. 1 piece</i>	2 \$ 462.00	<i>231</i>
8	REAR BUMPER SEAL RING <i>new</i>	4 \$ 12.00	<i>x</i>
9	TAIL LIGHT-LH/RH <i>?</i>	2 \$ 652.00	<i>?</i>
10	REAR BUMPER CARRIER <i>?</i>	\$ 1,238.00	<i>?</i>
11	REAR BUMPER HOLDING STRAP <i>new</i>	\$ 166.00	<i>x</i>
12	REAR BUMPER GUIDE SECTION-CENTER <i>new</i>	\$ 129.00	<i>x</i>
13	REAR LID CONTROL UNIT FOR OPENING <i>?</i>	\$ 350.00	<i>?</i>
14	REAR LID SENSOR LINE FOR TAILGATE <i>?</i>	\$ 190.00	<i>?</i>
15	REAR WHEEL COVER-RH/LH <i>new</i>	2 \$ 688.00	<i>✓</i>
16	SUNDRIES	\$ 300.00	<i>?</i>
TOTAL SPARE PARTS		\$ 8,484.00	
TOTAL LABOUR		\$ 3,952.00	
GRAND TOTAL		\$ 12,436.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling.
Surveyed Date : 19/02/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : not authorized, 03 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant