

2/15/200

ASS. REC. BY:

REF: C/TPD19002501/PC

Special Instruction:

Survivor:

ASSIGNMENT (Office)

From (Person): Kamalish Konde

of SPP

Date/Time: 1/2/2019

Estimated Cost:

Bill to:

OD+TP+WS+TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: STH 9201S

Insured:

at Workshop m/s

Tel:

of

Policy No: MHASPP06000013266

Claim No: TP/IP/66301/2018

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A 6/1/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction ()	Estimate
	STH 9201S - X	

[Handwritten signature]

(11) SJH9201S

j) Case IAFP-IB-20190114 - Mechanical Inspection of Motor Car, SLW9010Z (TP/IP/70101/2018)

On 22 December 2018 at about 1202hrs, driver of motor car SLW 9010 Z was making a right turn from Kallang-Paya Lebar Expressway into Tampines Road when he claimed to have lost the function of the accelerator and brake of his motor when an error message "Chassis Control Error" appeared on the dashboard of his motor car. It resulted in the said motor car meeting into an accident with a motor van and thereafter mounted the left kerb and collided into a lamppost before coming to a stop.

Vehicles to be inspected: SLW9010Z (Defendant)

IO In-Charge: IO Syed Zayid

k) Case IAFP-IB-20190114 - Mechanical Inspection of Motor Taxi, SHD2783U (TP/IP/66301/2018)

On 30 November 2018 at about 0758hrs, driver of motor taxi, SHD2783U was travelling along PIE (AP), slip road into CTE (SLE) when he was involved in an accident. Driver claimed that there was a mechanical fault to his motor taxi.

Vehicles to be inspected: SHD2783U (Defendant)

IO In-Charge: IO Feroz

l) Case IAFP-IB-20190114 - Mechanical Inspection of Motor Car, SJH9201S (TP/IP/66301/2018)

On 6 January 2019 at about 0557hrs, driver of motor car, SJH 9201 S was driving on lane 1 of 3 on Seletar Expressway towards Bukit Timah Expressway when he suddenly felt his front engine portion was vibrating and his vehicle suddenly swerved towards the left and collided onto a car and a van. He claims that his vehicle gear box have an issue albeit it occurs rarely, at times when he engaged 'Park' mode, he is unable to shift it to 'Drive' mode and he have to switched off and on his engine again to move it. He also claims that he has problem with his vehicle suspension and he felt vibrations to his vehicle engine just prior to the accident. After the accident, he spotted that his left rear tyre was punctured. He too suspected that the tyre has burst prior to the accident and due to the punctured tyre, his vehicle swerved towards the left.

Vehicles to be inspected: SJH9201S (Defendant)

IO In-Charge: IO Jeff Tan

m) Case IAFP-IB-20190114 - Mechanical Inspection of Motorcycle, FX8854C (TP/IP/70099/2018)

On 22 December 2018, Saturday at about 6.59 am, the accused was riding along CTE (SLE), 13.2km on lane 2 of the 4-lanes road, together with his girlfriend who was also his pillion. The accused mentioned that he made a left lane changed from lane 2 to lane 3. While doing so, the accused claimed that he rode over some road depression which caused him to lose his balance and skidded. Due to the accident, the accused (conscious) and the deceased (unconscious) were conveyed by an ambulance to Sengkang General Hospital. On 23 December at 1.17 pm, the deceased succumbed to her injuries and was pronounced dead by Doctor Vrushal in Ward 23 Bed 23 of Khoo Teck Puat Hospital.

Vehicles to be inspected: FX8854C (Defendant)

IO In-Charge: SIO Kamaliah