

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 4171H

DATE 11/2/2019 11:53

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 544.50
	Front Bumper Bracket Top (LH)			\$ 22.40
	Front Bumper Bracket (LH)			\$ 24.60
	Frt Wheel Hub Cap, LH			\$ 107.10
	SUB TOTAL			\$ 698.60
	LESS 20%			\$ 139.72
	DISCOUNTED TOTAL			\$ 558.88
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 600.00
	Towing Fee			\$ 60.00
	Frt Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 1,140.00
	ESTIMATE TOTAL			\$ 1,698.88
<p> NAK LKK 11/2/19 1635 3 DAYS LIS CHECK ITEMS & PHOTOS AFTER REPAIR PHOTOS </p>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: