



Scope Of Work
Home Team Agency

98576861 Kong

Steve (LKK) 14/2/19 4:00 PM

P/P

Resumy before & aftl spy
"without prejudice"

15 days

[Signature]
18/2/19

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR:	SMRT	VEH TYPE:	UNMARKED	UNIT:	CNB SUP 'F'
VEH NO:	QX1286H / SLL9124L	REPAIR TYPE:	ACCIDENT		
VEH MAKE/MODEL:	MAZDA 3	ODOMETER:	26174		

Reference No.	1286/CNB/4W/18/11/01
---------------	----------------------

iLMS No.	-
----------	---

S/N	Front PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	Front Bumper / <i>DO</i>		1		665.50	665.50
1.2	Front RH Bumper Retainer / <i>BR</i>		1		33.88	33.88
1.3	Radiator Grill / <i>BR</i>		1		350.90	350.90
1.4	Front RH Bumper Lower Grill Cover / <i>MIS</i>		1		36.30	36.30
1.5	Front LH Bumper Lower Grill Cover / <i>MIS</i>		1		36.30	36.30
1.6	Front Number Plate / <i>BT</i>		1		60.50	60.50

Remarks:		Parts Total:	\$	1,183.38
-----------------	--	---------------------	----	----------

S/N	Front LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	Front Bumper:		5	340.00 ✓
	Remove & Replace Front Bumper			
	Remove & Replace Front RH Bumper Retainer			
	Putty & Spray Paint for Front Complete Bumper			
1.2	Radiator Grill, Front Bumper Lower Grill Cover :		1	68.00 ✓
	Remove & Replace Radiator Grill			
	Replace Front RH Bumper Lower Grill Cover			
	Replace Front LH Bumper Lower Grill Cover			
	Labour Total:	\$	408.00	

Front TOTAL : \$ 1,591.38

S/N	Rear PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	Rear Bumper / <i>DO</i>		1		701.80	701.80
1.2	Rear RH Bumper Tow Eye Cover / <i>BR</i>		1		33.88	33.88
1.3	Rear LH Bumper Tow Eye Cover / <i>BR</i>		1		33.88	33.88

Remarks:		Parts Total:	\$	769.56
-----------------	--	---------------------	----	--------

S/N	Rear LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	Rear Bumper:		5	340.00 ✓
	Remove & Replace Rear Bumper			
	Remove & Re-Install back Reverse Sensor onto new Rear Bumper			
	Putty & Spray Paint for Rear Complete Bumper			
1.2	Rear Bumper Tow Eye Cover:		1	68.00 ✓
	Remove & Replace Rear RH Bumper Tow Eye Cover			
	Remove & Replace Rear LH Bumper Tow Eye Cover			
	Putty & Spray Paint for Rear RH Bumper Tow Eye Cover			
	Putty & Spray Paint for Rear LH Bumper Tow Eye Cover			
	Labour Total:	\$	408.00	

Rear TOTAL : \$ 1,177.56

2 Additional Services				
2.1	Towing Service From Station to Workshop (SOR 10)	176.80	1	176.80 ✓
2.2	Return Service From Workshop to Station (SOR 9)	61.20	1	61.20 ✓
	SUB-TOTAL		2	238.00

Front & Rear GRAND TOTAL : \$ 3,006.94

Contractor shall complete the entire repair within 15 working days upon approval date . (Include parts awaiting time)

Verification of Scope of Work		
Contractor QC	Vetted By:	Approved By:

Name:	KONG SEW KUI	Name:		Name:	
Date:	22.01.2019	Date:		Date:	
Sign:		Sign:		Sign:	

Verification of Completed Repairs

Contractor QC		Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager	
Name:		Name:		Name:	
Date:		Date:		Date:	
Sign:		Sign:		Sign:	

All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: