



萬 春 摩 哆 BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GSTReg. No. 351915/00A

GST Regn No. 35191500A

11/02/2019

Lonpac Insurance Berhad
100 Beach Road
#19-00 Shaw Tower
Singapore 189702

Attn: Motor Claims Dept.

Dear Sir/Madam

QUOTATION FOR REPAIRS OF VEHICLE NO. SFT 6119 B

MODEL: BMW 523i

DATE OF ACCIDENT: 01/02/2019

YOUR INSURED VEHICLE NO. SJX 9279 J

1 pc	LH rear door	\$ 1,615.00	btw
1 pc	LH rear door rubber	175.75	?
1 pc	LH rocker panel	389.50	Ry
1 pc	LH sport rim	600. 800.00	atw
		\$ 2,980.25	

LABOUR CHARGES:

To knocking and straightening of all necessary damaged parts.

To changing of above part.

To putty and spray painting on accident damaged parts.

1,200.00	700
1,000.00	600
\$ 5,180.25	

Yours faithfully,

Perinday

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfer 97495719
WP
12/2/19 21020
lumpsum
Resurvey after repair
surellment.com
5 days.