

Surveyor

## ASSIGNMENT (Office)

From (Person)

Chang Baun Sen

of

CTI

Date/Time

11/2/2019 @ 11:57am

Estimated Cost

Bill to:

OD / ☒ WS / TT RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JPV 5613

Insured:

SJM 2147K

at Workshop m/s

Torque 5

Tel:

9147 8488

of

# 1cekki Bkt Ave 4 # 01-49 premier

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A.

31/01/2019

CA / REV / REP. / REV 24 HRS

hup

13/2/19

H.O.D. Endorsement:

Date/Time:

2:56pm @ 12/2/19

Person Contacted:

Stephanie

Vehicle

☒ IN ☐ OUT

| Date/Time | Action/Instruction (✓) Estimate           |
|-----------|-------------------------------------------|
| 12/2/19   | estimate not yet ready arrange on 13/2/19 |
|           | JPV 5613 - NA/CTI 19002112/h4             |
|           | 9M 2147K - NA/CTI 19002112/h4             |
|           |                                           |
|           |                                           |
|           |                                           |
|           |                                           |

D.O.A. = 31/1/2019

D.O.A. = 31/1/2019

CTI

VEHICLE INSPECTION

13/2/19

Veh No: JPV 5613

In Regn: 28/01/2014

Type: ☒ Car ☐ M/Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover

Truck / Trailer or

Make: HONDA CITY 1.5L

CC: 1497

Colour: WHITE

A/C: Insured / Std / NI / NA

Sp Reading: 85340

T/Cable: Insured / Std / NI / NA

Eng No: L15A75611590

C/N: PMHGM2660DD211597

Gen. Cond: Good ☒ Fair ☐ Poor ☐ BurntSteering: ☒ Normal ☐ Jammed ☐ Leaked ☐ Burnt orBrake: ☒ Normal ☐ Jammed ☐ Leaked ☐ Burnt orMod: Nil ☒ 8 Rims ☐ STD A/Rim or

Tyre Size: F: 185/55/16 MIC

R: 185/55/16 BS

☒ BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 7 mm R/Bal: 7 mm

L/Bal: 7 mm L/Bal: 7 mm

D.O.A: 31/1/19 D.O.I: 13/2/19

Survey held at: Torque 5

Des. of Damages: ☒ Front ☒ Rear ☐ O/S ☐ N/S ☐ UIC ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Form No:

Date:

Estimated by:

CD: ☒ WS / TP RES / OD RES / EVA / INV / MY

Vehicle No:

JPV 5613

Engine No:

Torque 5

Address: 8 Kalki Bkt Ave 4 # or 49 premier

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

Client's Record:

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

8

days

Res: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS <sup>up</sup>

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time:

Action / Instruction:

Range 19,000/- 20,000/-

18/04/19 Confirmed L/S \$10,100/- @ 8 days with LTG -  
(\$13,945 - 50 - Red - 58%.)

RECEIVED 13 MAY 2019

Termin <sup>hui</sup>  
13/2/19

Date/Time: File Photo(s):

13/05/19

If

Typ. 24

Date/Time: File Return(s):



Prelim. Report



Final Report

Days Of Repair:

8

Resurvey No. of Trip:

2

Add Fee:



Site Insp: 15



Interview: 15



Test Insp: 15



Workshop: 15

Survey Fee:

Transportation:

1. Car / 2. Truck:

1. Truck:

1. Other:

1. Other:

1. Other:

Report Format:

Lump Sum / L/S + 15

10/00/- L/S

220

220

## Shirley Hiew (LKK Auto)

---

**From:** Torque 5 Assessment <assessment@torque5.com>  
**Sent:** Friday, 10 May 2019 2:54 PM  
**To:** 'Shirley Hiew (LKK Auto)'  
**Cc:** 'Torque 5 Assessment'; claims@torque5.com; sam.chang@torque5.com  
**Subject:** RE: JPV 5613 - After Repair Photo & Finalisation .

Dear Shirley ,



We hereby confirm the COR \$10100 with 08 days .

Thank you .

*Warmest Regards,*

*Lucas Chow*

Assessor | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

Mobile (65) 8131 6518

Email [lucas.chow@torque5.com](mailto:lucas.chow@torque5.com)

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54  
Premier @ KB, Singapore 415875

[www.torque5.com](http://www.torque5.com)



---

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]  
**Sent:** Friday, May 10, 2019 10:24 AM  
**To:** 'Torque 5 Assessment'  
**Cc:** claims@torque5.com; sam.chang@torque5.com; Admin A; Admin-D (LKKAuto)  
**Subject:** RE: JPV 5613 - After Repair Photo & Finalisation .

Dear Lucas,

Please re- confirm final fig \$ 10,100.00 (lump sum) @ 8 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



**From:** Shirley Hiew (LKK Auto)

[mailto:ShirleyHiew@lkkauto.com]  
**Sent:** Thursday, 18 April 2019 4:24 PM  
**To:** 'Torque 5 Assessment' <assessment@torque5.com>  
**Cc:** claims@torque5.com; sam.chang@torque5.com; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>  
**Subject:** RE: JPV 5613 - After Repair Photo & Finalisation .

Dear Lucas,

Please confirm final fig \$ 9,350.00 (lump sum) @ 8 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Torque 5 Assessment [mailto:assessment@torque5.com]  
**Sent:** Tuesday, 26 February 2019 2:16 PM  
**To:** Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>  
**Cc:** 'Torque 5 Assessment' <assessment@torque5.com>; claims@torque5.com; sam.chang@torque5.com  
**Subject:** JPV 5613 - After Repair Photo & Finalisation .

Dear All,



Please kindly check the attach and confirm the finalise amount .

Thank You .

*Warmest Regards,*

*Lucas Chow*

Assessor | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

Mobile (65) 8131 6518

Email [lucas.chow@torque5.com](mailto:lucas.chow@torque5.com)

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54  
Premier @ KB, Singapore 415875

[www.torque5.com](http://www.torque5.com)



**Nivitha (LKK Auto)**

---

**From:** Shu Pei (LKKAuto) <shupe@lkkauto.com>  
**Sent:** Tuesday, 12 February 2019 11:57 AM  
**To:** assignments  
**Subject:** FW: Accident involving JPV5613 & SJM2147K on 31/01/2019 (PRE-REPAIR SURVEY REQUEST)  
**Attachments:** image013.wmz; image034.emz

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupe@lkkauto.com](mailto:shupe@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Tuesday, 12 February 2019 11:56 AM  
**To:** Torque 5 Assessment <assessment@torque5.com>  
**Cc:** Admin A <admin-a@lkkauto.com>  
**Subject:** RE: Accident involving JPV5613 & SJM2147K on 31/01/2019 (PRE-REPAIR SURVEY REQUEST)

Without Prejudice

Dear Sir,

We will appoint.

Dear LKK,

Pri pls.

Regards,

**Chong Boon Sen**

Claims Executive

Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

From: Torque 5 Assessment [mailto:assessment@torque5.com]  
Sent: Tuesday, 12 February, 2019 10:28 AM  
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
Cc: assessment@torque5.com  
Subject: RE: Accident involving JPV5613 & SJM2147K on 31/01/2019 (PRE-REPAIR SURVEY REQUEST)

Without Prejudice

Dear Sir/ Mdm,

We refer to the above matter and your email below.

Thank you for your reply.

We are agreeable to your list of surveyor – **Marcus Chua from LKK Auto Consultants** as the SJE for this matter.



Kindly make the necessary arrangements.

Warmest Regards,

*Heng Lee Yi*

Administrative Assistant | Motor Claims Department

Hotline (65) 6452 4457 Ext:111 | Fax (65) 6452 4584

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54  
Premier @ KB, Singapore 415875

[www.torque5.com](http://www.torque5.com)



**From:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>

**Sent:** Tuesday, 12 February, 2019 10:29 AM

**To:** Torque 5 Assessment <[assessment@torque5.com](mailto:assessment@torque5.com)>

**Subject:** RE: Accident involving JPV5613 & SJM2147K on 31/01/2019 (PRE-REPAIR SURVEY REQUEST)

**Without Prejudice**

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.



|                            |
|----------------------------|
| ADRIAN LING                |
| Kelvin Ang                 |
| SEE CHEW SENG              |
| MOHD FADHILAH BIN<br>OSMAN |
| XING QUO QIANG             |
| KENNETH KONG               |
| SIMON HO                   |
| CHUA WEIJIE                |
| MARCUS CHUA                |
| HENRY NG                   |

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

**Chong Boon Sen**

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 63896171  
Fax: 62247175  
Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

**From:** Torque 5 Assessment [<mailto:assessment@torque5.com>]  
**Sent:** Tuesday, 12 February, 2019 10:14 AM  
**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>  
**Cc:** [assessment@torque5.com](mailto:assessment@torque5.com)  
**Subject:** FW: Accident involving JPV5613 & SJM2147K on 31/01/2019 (PRE-REPAIR SURVEY REQUEST)  
**Importance:** High

## **\*\* IMMEDIATE ASSISTANCE NEEDED \*\***

Dear Team,

Kindly note that we had not heard or gotten any reply from your side for the above mentioned accident.  
Due to the delay in the survey of the vehicle, we will be claiming for Loss of Rental/Use for the period of delay.



Do revert for the arrangement for the survey to prevent any further delay.  
Thank you.

*Warmest Regards,*  
**Heng Lee Yi**  
Administrative Assistant | Motor Claims Department

Hotline (65) 6452 4457 Ext:111 | Fax (65) 6452 4584

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54  
Premier @ KB, Singapore 415875

[www.torque5.com](http://www.torque5.com)



**From:** Torque 5 Assessment <[assessment@torque5.com](mailto:assessment@torque5.com)>

**Sent:** Monday, 11 February, 2019 3:03 PM

**To:** 'Chong Boon Sen' <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com); 'Elaine Cheong' <[elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)>

**Cc:** [claims@torque5.com](mailto:claims@torque5.com); [assessment@torque5.com](mailto:assessment@torque5.com)

**Subject:** RE: Accident involving JPV5613 & SJM2147K on 31/01/2019 (PRE-REPAIR SURVEY REQUEST)

**Importance:** High

## **\*\* IMMEDIATE ASSISTANCE NEEDED \*\***

Dear Team,

Kindly note that we had not heard or gotten any reply from your side for the above mentioned accident. Due to the delay in the survey of the vehicle, we will be claiming for Loss of Rental/Use for the period of delay. Do revert for the arrangement for the survey to prevent any further delay.



Thank you.

Warmest Regards,

*Heng Lee Yi*

Administrative Assistant | Motor Claims Department

Hotline (65) 6452 4457 Ext:111 | Fax (65) 6452 4584

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54  
Premier @ KB, Singapore 415875

[www.torque5.com](http://www.torque5.com)





**From:** Torque 5 Assessment <[assessment@torque5.com](mailto:assessment@torque5.com)>

**Sent:** Friday, 1 February, 2019 10:33 AM

**To:** 'Chong Boon Sen' <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com); 'Elaine Cheong' <[elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)>

**Cc:** [assessment@torque5.com](mailto:assessment@torque5.com); [sam.chang@torque5.com](mailto:sam.chang@torque5.com); [claims@torque5.com](mailto:claims@torque5.com)

**Subject:** Accident involving JPV5613 & SJM2147K on 31/01/2019 (PRE-REPAIR SURVEY REQUEST)


Without Prejudice

Dear Sir/ Mdm,

We refer to the above matter.

We represent our client, Cheah Kian Soon, to notify you of the aforesaid accident involving our client's vehicle JPV 5613 and your insured's vehicle SJM 2147 K on 31/01/2019.

Please find enclosed our client's GIA report for your necessary action.



This serves as a **NOTICE** that we are claiming against SJM 2147 K for damages, costs and disbursements.

Please let us know within **2 working days** from today, your client's and your intention to conduct a pre-repair survey of our client's vehicle, along with your list of at least **ten (10) motor surveyors**.

If we do not receive any reply from you within the stipulated timeline, we shall proceed to appoint our own surveyor and proceed with the necessary repair for our client's vehicle without further reference to your insured or you.

**Premises for the Pre-repair inspection:** 8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

**Contact Person:** Lucas (8131 6518)

**Contact Email:** [assessment@torque5.com](mailto:assessment@torque5.com)

VEH IN (Date & Time)

: 01/02/2019

**PRS ACKNOWLEDGEMENT**Appointed Surveyor  
(Name & Signature)

Date &amp; Time of Inspection

Kindly cc a copy of this letter to your insured for his/her acknowledgement.

We look forward to hearing from you soon.

To avoid incurrence of any unnecessary cost on both our end, kindly confirm liability status within 7 days from this to minimize time wastage and incurrence of any unnecessary cost(s) on both our end, we seek your kind advice, within 7 days working days, on liability status for subject claim. If we do not hear from you within the stipulated period, we shall proceed with the purchase of your insured GIA



report and this cost or any other cost incurred for confirmation of liability status shall be included in our LOD for reimbursement purpose.

Warmest Regards,

*Heng Lee Yi*

Administrative Assistant | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

Address: 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54  
Premier @ KB, Singapore 415875

[www.torque5.com](http://www.torque5.com)



This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



# SINGAPORE POLICE FORCE

Vehicle in.



T/20190131/2140

Police Station Of Origin:  
Geylang N.P.C  
132 Paya Lebar Road SINGAPORE 409014  
Tel No: 1800-8486999

1 of 3

Report No. T/20190131/2140

## REPORT OF A TRAFFIC ACCIDENT

|                                            |            |                                                                |                              |
|--------------------------------------------|------------|----------------------------------------------------------------|------------------------------|
| Date/Time Report Made:<br>31/01/2019 18:00 |            | Vide Report No.:<br>E/20190131/0103                            | Station Diary No.:<br>80     |
| <b>Informant's Particulars</b>             |            |                                                                |                              |
| Name of Informant:<br>CHEAH KIAN SOON      |            | Address:<br>APT BLK 97 GEYLANG BAHRU #02-3174 SINGAPORE 330097 |                              |
| ID Type / ID No.:<br>FIN NO / G6521834N    |            | Contact No.:<br>Home/Office:                                   | Mobile: 84810206             |
| Nationality:<br>MALAYSIAN                  |            | Email:                                                         |                              |
| Sex:<br>Male                               | Age:<br>29 | Date of Birth:<br>16/05/1989                                   | Type of Informant:<br>Driver |
| Race:<br>Chinese                           |            | Language:                                                      | Institution / School Name:   |
| Occupation:<br>CONSTRUCTION                |            | Driving Licence Information:<br>Class: Date of Expiry:         |                              |

## General Information of the Accident


|                                                                                                                                                     |                                  |                                    |                                            |                                    |
|-----------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|------------------------------------|--------------------------------------------|------------------------------------|
| Type of Accident:                                                                                                                                   | Non-Injury<br>Attended by Police | Drink Drive:<br>No                 | Date/Time of Accident:<br>31/01/2019 14:45 | Type of Location:<br>Straight Road |
| Location:<br>Along Road 1 Traveling Toward Road 2<br>PAN ISLAND EXPRESSWAY<br>STEVENS ROAD<br>PIE (TUAS) 19.3KM NEAR LP951<br>Lamp Post Number: 951 |                                  |                                    |                                            |                                    |
| Weather:<br>Clear                                                                                                                                   |                                  | Road Surface:<br>Dry               | Road Speed Limit:                          |                                    |
| Traffic Flow:<br>One Way                                                                                                                            |                                  | Traffic Control:<br>Not Controlled | Traffic Volume:<br>Moderate                |                                    |
| Type of Collision:<br>Between Moving Vehicles - Head On                                                                                             |                                  |                                    | Anyone conveyed by ambulance:<br>No        |                                    |

## Details of Vehicle Involved

| Vehicle No. | Type | Make   | Model                | Color  | Condition         | No of Passenger |
|-------------|------|--------|----------------------|--------|-------------------|-----------------|
| JPV5613     | Car  | HONDA  | CITY 1.5A            | White  | Seriously Damaged | 0               |
| SJF8604E    | Car  | TOYOTA | WISH 1.8X A          | Black  | Slightly Damaged  | 0               |
| SJM2147K    | Car  | HONDA  | HONDA CIVIC 1.8L 5AT | Silver | Slightly Damaged  | 0               |



SINGAPORE  
POLICE FORCE



T/20190131/2140

Police Station Of Origin:  
Geylang N.P.C  
132 Paya Lebar Road SINGAPORE 409014  
Tel No: 1800-8486999

2 of 3

Report No. T/20190131/2140

CONTINUATION OF REPORT

Brief Details.

Vide E/20190131/0103.

On 31 Jan 2019 at about 1445hrs, I was driving my Malaysian car (JPV5613) from Geylang Bahru to Jurong Point. While I was driving on Lane 1, on the right most lane of the expressway (PIE towards Tuas) 19.3km near lamp post 951 when the car ( SJF8604E) in front of me had suddenly slowed down. I then managed to stop without colliding onto the front car. However I heard and felt an impact on the rear of my vehicle which caused my vehicle to surge forward and collide with the front car. I then discovered my car being collided in between the two cars, SJF8604E and SJM2147K).

I checked on my vehicle and there was several damages which include front and back bumper damaged. I was not injured and there was no passenger with me.



**SINGAPORE  
POLICE FORCE**



T/20190131/2140

Police Station Of Origin:  
Geylang N.P.C  
132 Paya Lebar Road SINGAPORE 409014  
Tel No: 1800-8486999

3 of 3

Report No. T/20190131/2140

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
G /  
Sgt 2 NUR JANNAH BINTE MOHAMED HUSNI

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:

TP / GI /



SINGAPORE  
POLICE FORCE

Contact No.:

Authentication Stamp

NP168

SIGNATURE

Signature Of Informant:

Date/Time:  
31/01/2019 18:00

Classification Of Case:

V.A) JPVSGIB

V.B) SJM247K

V.C) SJFSGOHE

On the stated date and time, I vehicle 'M' was travelling on the stated venue. I was travelling straight in my lane, the front car suddenly stop hence I applied my brakes and eventually came to a stop. Moments later I felt an huge impact on my vehicle rear portion, the impact caused my entire vehicle to propel forward and collided onto vehicle 'C' rear portion.

I/We declare the foregoing particulars are true in every respect.

*James*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# JABATAN PENGANGKUTAN JALAN MALAYSIA

## PERAKUAN PENDAFTARAN KENDERAAN

NO. PENDAFTARAN: **JPV5613**

No. Siri B **5950055**  
**JUOSHAYM**

Name Pemunya Berdaftar : **CHEAH KIAN SOON**

**890516085613**  
**[MAL]**

Alamat : **05-25 BLOK D P/PURI SRI AKASIA JLN PERSIARAN  
T/WANGSA UTAMA TAMAN TAMPOI INDAH  
81200 JOHOR BAHRU JOHOR**

|                    |                                      |             |   |
|--------------------|--------------------------------------|-------------|---|
| No. Enjin          | <b>L15A75611590</b>                  | B.D.M/B.G.K | - |
| No. Casis          | <b>PMHGM2660DD211597</b>             | B.T.T.      | - |
| Buatan             | <b>HONDA</b>                         | Berat Kerb  | - |
| Nama Model         | <b>CITY E 1.5L I-VTEC</b>            | B.T.M.      | - |
| Keupayaan Enjin    | <b>1497 S.P.</b>                     | B.G.1       | - |
| Bahan Bakar        | <b>PETROL</b>                        | B.G.2       | - |
| Warna              | <b>PUTIH</b>                         | B.G.3       | - |
| Kelas Kegunaan     | <b>PERSENDIRIAN-MOTOKAR INDIVIDU</b> | B.G.4       | - |
| Jenis Badan        | <b>MOTOKAR</b>                       | B.G.5       | - |
| Tahun Dibuat       | <b>2014</b>                          | B.G.6       | - |
| Tarikh Pendaftaran | <b>28/01/2014</b>                    | B.G.7       | - |
| Status Pemunya     | <b>PERSENDIRIAN</b>                  | B.G.8       | - |
| Muatan Tempat      |                                      | B.G.9       | - |
| Duduk              | <b>5</b>                             | B.G.10      | - |
| Kadar Lesen        |                                      | B.G.11      | - |
| Kenderaan Motor    | <b>6 bulan RM45.00</b>               | B.G.12      | - |
|                    | <b>12 bulan RM90.00</b>              |             |   |

Tandatangan Pemunya Berdaftar

Perakuan Pendaftaran ini dikeluarkan  
oleh Pengerah JPJ Negeri **JPJ NEGERI JOHOR**

PEMASANGAN TEMPATAN

UNTUK KEGUNAAN PEJABAT

HAK MILIK DITUNTUT OLEH: PUBLIC BANK BERHAD NO SIRI: H05/510701/14

### NOTA PENTING

Simpan perakuan ini di tempat yang selamat. Jika perakuan ini hilang, anda dikehendaki melaporkan kepada balai polis dengan segera dan memohon salinan perakuan pendaftaran daripada Pengerah Jabatan Pengangkutan Jalan (JPJ).

Semak butir-butir kenderaan di muka ini dan laporkan dengan segera kepada Pengerah JPJ jika terdapat sebarang perubahan.

Lesen kenderaan motor yang sah hendaklah sentiasa dipamerkan. Anda boleh membarui lesen 60 hari sebelum tempohnya tamat.

Anda dikehendaki melaporkan secara bertulis dengan segera kepada Pengerah JPJ sekiranya kenderaan anda tidak berlesen.

5. Jika anda menjual kenderaan, serahkan perakuan pendaftaran ini kepada pembeli. Anda dan pembeli dikehendaki mengisi dan mengemukakan borang JPJK3/JPJK3A kepada Pengerah JPJ dalam tempoh tujuh hari dari tarikh penjualan itu.

6. Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran milikan telah disempurnakan dan kenderaan telah didaftarkan dengan nama pemilik baru.

7. Jika alamat anda bertukar, kemukakan perakuan pendaftaran ini kepada Pengerah JPJ dalam tempoh tujuh hari dari tarikh pertukaran itu.

# BAYARAN-BAYARAN

|    |                                                                                                                                          |    |
|----|------------------------------------------------------------------------------------------------------------------------------------------|----|
| 1  | 0101011 28/01/2014 11:23:25 VEL01001 N SAFIAH<br>03418 * 2 JPV5612<br>2353070 RM50.00 2103030 RM150.00<br>RM200.00                       | 11 |
| 2  | 0101011 26/12/2013 11:21:56 VEL03004 N SAFIAH<br>030655 1 0 JPV5613 27/01/2015<br>2600000RM*****200.00 2610000RM*****10.00 RM*****210.00 | 12 |
| 3  | 006371 23/01/2015 13:19:06 VEL02504 N MYEG<br>004616 7 0 JPV5613 27/01/2016<br>2203000RM*****90.00 RM*****90.00                          | 13 |
| 4  |                                                                                                                                          | 14 |
| 5  |                                                                                                                                          | 15 |
| 6  |                                                                                                                                          | 16 |
| 7  |                                                                                                                                          | 17 |
| 8  |                                                                                                                                          | 18 |
| 9  |                                                                                                                                          | 19 |
| 10 |                                                                                                                                          | 20 |

## PERTUKARAN-PERTUKARAN MILIKAN DAN ALAMAT

|   |                         |                             |
|---|-------------------------|-----------------------------|
| 1 | No. K.P./Def. Naga/Sykt | Terdengar Pemunya Berdaftar |
| 2 | No. K.P./Def. Naga/Sykt | Terdengar Pemunya Berdaftar |
| 3 | No. K.P./Def. Naga/Sykt | Terdengar Pemunya Berdaftar |
| 4 | No. K.P./Def. Naga/Sykt | Terdengar Pemunya Berdaftar |
| 5 | No. K.P./Def. Naga/Sykt | Terdengar Pemunya Berdaftar |

## REKOD-REKOD PEMERIKSAAN

|   |   |    |
|---|---|----|
| 1 | 5 | 9  |
| 2 | 6 | 10 |
| 3 | 7 | 11 |
| 4 | 8 | 12 |

|                                                                                                                                                                                                                                                                                                                                                                  |                                                                                                                                |                                                                                                                                                                                                                                                                                                                                                                                                |                                                                                                                                                   |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|
| The Insured / Pemegang Polisi<br><b>CHEAH KIAN SOON</b>                                                                                                                                                                                                                                                                                                          |                                                                                                                                | Policy No. / No. Polisi<br><b>JVD6426311 01-01</b>                                                                                                                                                                                                                                                                                                                                             |                                                                                                                                                   |
| 05-25 BLOK D P/PURI SRI AKASIA<br>JALAN PERSIARAN TITIWANGSA UTA<br>TAMAN TAMPOI INDAH<br>81200 JOHOR BAHRU                                                                                                                                                                                                                                                      |                                                                                                                                | Account No. / No. Akaun<br><b>C99200-00</b>                                                                                                                                                                                                                                                                                                                                                    |                                                                                                                                                   |
| Occupation / Pekerjaan<br><b>OTHERS</b>                                                                                                                                                                                                                                                                                                                          |                                                                                                                                | Type of Cover / Jenis Perlindungan<br><b>COMPREHENSIVE</b>                                                                                                                                                                                                                                                                                                                                     |                                                                                                                                                   |
| I.C. No. / No. Kad Pengenalan<br><b>890516085613</b>                                                                                                                                                                                                                                                                                                             |                                                                                                                                | Period of Insurance / Tempoh Insurans<br>From / Dari <b>00:00:01 AM 28-01-2019</b> To / Hingga <b>27-01-2020</b>                                                                                                                                                                                                                                                                               |                                                                                                                                                   |
| Hire Purchase Owner / Pemilik Sewa Beli<br><b>PUBLIC BANK BERHAD</b>                                                                                                                                                                                                                                                                                             |                                                                                                                                | Premium / Premium<br>Ali Rider / Semua Penunggang<br>NCD / Diskaun Tanpa Tuntutan 55.00%<br>Wef / Berkuatkuasa dari 28-01-2019                                                                                                                                                                                                                                                                 |                                                                                                                                                   |
| Make & Type of Body / Buatan & Jenis Badan<br><b>HONDA CITY / 4D SEDAN</b>                                                                                                                                                                                                                                                                                       |                                                                                                                                | Optional Cover<br>Legal Liability Of Passengers / Liabiliti Penumpang Di<br>Sisi Undang-Undang Kerana Perbuatan Cua<br>Legal Liability To Passengers / Liabiliti Dari Segi<br>Undang-Undang Kepada Penumpang<br>Windscreen Damage (Tempered/Laminated Glass Inclusive<br>Labour Cost) / Kerosakan Cermin Kenderaan (Penggubahan<br>Cermin / Cermin Berlapis Termasuk Kos Buruh) RM<br>1,200.00 |                                                                                                                                                   |
| Registration No. /<br>No. Pendaftaran<br><b>JPV5613</b>                                                                                                                                                                                                                                                                                                          | Excess / Lebihan<br><b>0.00</b>                                                                                                | Regn. Card No. / No. Kad<br>Pendaftaran<br><b>B5950055</b>                                                                                                                                                                                                                                                                                                                                     | RM 1,440.08<br>0.00<br>792.04<br>648.04<br>7.50<br>33.75<br>180.00                                                                                |
| Carrying or Seating<br>Capacity Incl. Driver /<br>Muatan Tempat Duduk<br>Termasuk Pemandu<br><b>5</b>                                                                                                                                                                                                                                                            | Tonnage / C.C. / Watt<br>Tan / Keupayaan Enjin<br><b>1497.00 CC</b><br>Year of Manufacture /<br>Tahun Diperbuat<br><b>2014</b> | Sum Insured / Jumlah<br>Diinsuranskan (RM)<br><b>42,000.00</b><br>(Agreed Value)                                                                                                                                                                                                                                                                                                               | Gross Premium / Premium Kasar<br>Service Tax / Cukai Perkhidmatan 6%<br>Stamp Duty / Duti Setem                                                   |
| Engine/Motor No. / No. Enjin/Motor<br><b>L15A75611590</b>                                                                                                                                                                                                                                                                                                        | Chassis No. / No. Casis<br><b>PMHGM2660DD211597</b>                                                                            | Trailer / Treler<br><b>-</b>                                                                                                                                                                                                                                                                                                                                                                   | 869.29<br>52.16<br>10.00                                                                                                                          |
| Only The Extensions, Endorsement And / Or Warranties Indicated Below Apply To<br>This Policy. / Hanya Lanjutan, Endorsemen dan / atau Warranti sepertimana yang<br>dinyatakan di bawah ini boleh diguna pakai dalam polisi ini.<br><b>2, 100, 15, 72, 89, 87 (AGREED VALUE)</b>                                                                                  |                                                                                                                                |                                                                                                                                                                                                                                                                                                                                                                                                |                                                                                                                                                   |
| Endorsement 87 (Agreed Value) will not apply in the event any changes to the<br>sum insured is made after policy inception                                                                                                                                                                                                                                       |                                                                                                                                |                                                                                                                                                                                                                                                                                                                                                                                                |                                                                                                                                                   |
| Subject to IMPORTANT NOTICE: Your duty as the Owner of the vehicle as attached.                                                                                                                                                                                                                                                                                  |                                                                                                                                |                                                                                                                                                                                                                                                                                                                                                                                                | Total Due / Jumlah Berbayar<br>RM 931.45                                                                                                          |
| Named Driver / Pemandu Yang Dinamakan<br><b>THE POLICYHOLDER</b>                                                                                                                                                                                                                                                                                                 |                                                                                                                                |                                                                                                                                                                                                                                                                                                                                                                                                | Total Due (OTC) / Jumlah Berbayar Di Kaunter<br>RM 931.45                                                                                         |
| Geographical Area : Malaysia , Republic of Singapore and Negara Brunei Darussalam. / Kawasan Geografi : Malaysia, Republik Singapura dan<br>Negara Brunei Darussalam.<br>Limitations as to Use / Authorised Driver : As described in the Certificate of Insurance. / Had Penggunaan / Pemandu Yang Diberi Kuasa : Seperti<br>yang tercatat dalam Sijil Insurans. |                                                                                                                                |                                                                                                                                                                                                                                                                                                                                                                                                |                                                                                                                                                   |
| Replacing Cover Note No. /<br>Gantian No. Nota<br>Perlindungan<br>Renewal of Policy No. /<br>Pembaharuan No. Polisi<br>Date of Proposal or<br>Declaration /<br>Tarikh Cadangan atau<br>Pengisytiharan                                                                                                                                                            | <b>V7445150</b><br><b>27-12-2018</b>                                                                                           | Issued By / Dikeluarkan Oleh :<br><b>SAGITO MOTOR (M) SDN BHD</b><br><b>47 JALAN TANJONG</b><br><b>TAMAN DATO PENGGAWA BARAT</b><br><b>81200 JOHOR BAHRU</b><br>Tel : 0072382000<br>Fax : 0072372020                                                                                                                                                                                           | For / untuk<br><b>AmGeneral Insurance Berhad</b><br><br><b>AmGeneral Insurance</b><br><br>Authorised Signature /<br>Tandatangan Yang Diberi Kuasa |
| Date of Issue / Time<br>Tarikh Dikeluarkan / Waktu                                                                                                                                                                                                                                                                                                               | <b>27-12-2018 11:07:36 AM</b><br><b>210210271218K885</b>                                                                       |                                                                                                                                                                                                                                                                                                                                                                                                |                                                                                                                                                   |



**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
Co. & GST Reg. No.: 201313221G

## ESTIMATION REPORT

**Vehicle No** : JPV5613  
**Make & Model** : HONDA, CITY E 1.5L I-  
VTEC, PMHGM2660DD211597  
**Year of Manufacture** : 2014

**Estimation No.** : E19020001  
**DOA** : 31/01/2019

| No                                | Description                     | Qty  | U/P  | Amt          |
|-----------------------------------|---------------------------------|------|------|--------------|
| <b><u>Section: List Items</u></b> |                                 |      |      |              |
| 1                                 | Rear bumper                     | 1.00 | 0.00 | 0.00 DDV     |
| 2                                 | Rear bumper lower garnish       | 1.00 | 0.00 | 0.00 DLV     |
| 3                                 | Rear bumper retainer (LH)       | 1.00 | 0.00 | 0.00         |
| 4                                 | Rear bumper retainer (RH)       | 1.00 | 0.00 | 0.00 } NEC ✓ |
| 5                                 | Rear bumper reflector (LH)      | 1.00 | 0.00 | 0.00         |
| 6                                 | Rear bumper reflector (RH)      | 1.00 | 0.00 | 0.00 } CRAV  |
| 7                                 | Rear bumper bracket (LH)        | 1.00 | 0.00 | 0.00 } ?     |
| 8                                 | Rear bumper bracket (RH)        | 1.00 | 0.00 | 0.00 } ?     |
| 9                                 | Reverse sensor                  | 4.00 | 0.00 | 0.00 CUTV    |
| 10                                | Reverse sensor harness wire set | 1.00 | 0.00 | 0.00 - NEC ✓ |
| 11                                | Bootlid                         | 1.00 | 0.00 | 0.00 DDV     |
| 12                                | Bootlid emblem - Logo           | 1.00 | 0.00 | 0.00         |
| 13                                | Bootlid emblem - City           | 1.00 | 0.00 | 0.00 } NEC ✓ |
| 14                                | Bootlid emblem - I/TEC          | 1.00 | 0.00 | 0.00         |
| 15                                | Bootlid chrome garnish          | 1.00 | 0.00 | 0.00 ?       |
| 16                                | Bootlid lock                    | 1.00 | 0.00 | 0.00 JAM ✓   |
| 17                                | Bootlid lock catch              | 1.00 | 0.00 | 0.00 NNX     |
| 18                                | Bootlid insulator               | 1.00 | 0.00 | 0.00 NNX     |
| 19                                | Bootlid hinge (LH)              | 1.00 | 0.00 | 0.00         |
| 20                                | Bootlid hinge (RH)              | 1.00 | 0.00 | 0.00 } RX    |
| 21                                | Bootlid rubber beading          | 1.00 | 0.00 | 0.00 TN ✓    |
| 22                                | License lamp (LH)               | 1.00 | 0.00 | 0.00         |
| 23                                | License lamp (RH)               | 1.00 | 0.00 | 0.00 } NNX   |
| 24                                | Tail lamp (LH)                  | 1.00 | 0.00 | 0.00 ?       |
| 25                                | Tail lamp (RH)                  | 1.00 | 0.00 | 0.00 CRAV    |
| 26                                | Tail lamp gasket (LH)           | 1.00 | 0.00 | 0.00 NNX     |

Continue on next page...



**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
Co. & GST Reg. No.: 201313221G

## ESTIMATION REPORT

**Vehicle No** : JPV5613  
**Make & Model** : HONDA,CITY E 1.5L I-  
VTEC,PMHGM2660DD211597  
**Year of Manufacture** : 2014

**Estimation No.** : E19020001  
**DOA** : 31/01/2019

| No | Description                   | Qty  | U/P  | Amt                    |
|----|-------------------------------|------|------|------------------------|
| 27 | Tail lamp gasket (RH)         | 1.00 | 0.00 | 0.00 NNX               |
| 28 | Tail lamp inner panel (LH)    | 1.00 | 0.00 | 0.00 NNX               |
| 29 | Tail lamp inner panel (RH)    | 1.00 | 0.00 | 0.00 ?                 |
| 30 | End panel                     | 1.00 | 0.00 | 0.00 BTV               |
| 31 | End panel top garnish         | 1.00 | 0.00 | 0.00 DLV               |
| 32 | Spare tyre top board          | 1.00 | 0.00 | 0.00 ?                 |
| 33 | Spare tyre panel              | 1.00 | 0.00 | 0.00 ?                 |
| 34 | Rear fender (RH)              | 1.00 | 0.00 | 0.00 <del>NRX</del> RX |
| 35 | Rear fender inner trim (LH)   | 1.00 | 0.00 | 0.00 NNX               |
| 36 | Rear fender inner trim (RH)   | 1.00 | 0.00 | 0.00 DIS ✓             |
| 37 | Rear seat (LH)                | 1.00 | 0.00 | 0.00 } ?               |
| 38 | Rear seat (RH)                | 1.00 | 0.00 | 0.00 } ?               |
| 39 | Rear exhaust muffler          | 1.00 | 0.00 | 0.00 }                 |
| 40 | Rear exhaust heat shield      | 1.00 | 0.00 | 0.00 } ?               |
| 41 | Exhaust mid pipe              | 1.00 | 0.00 | 0.00 }                 |
| 42 | Rear chassis member (RH)      | 1.00 | 0.00 | 0.00 NNX               |
| 43 | Front bumper                  | 1.00 | 0.00 | 0.00 BRV               |
| 44 | Front bumper retainer (LH)    | 1.00 | 0.00 | 0.00 } NECV            |
| 45 | Front bumper retainer (RH)    | 1.00 | 0.00 | 0.00 }                 |
| 46 | Front bumper lower garnish    | 1.00 | 0.00 | 0.00 BRV               |
| 47 | Front bumper towing cap       | 1.00 | 0.00 | 0.00 <del>CRA</del> NI |
| 48 | Radiator grille               | 1.00 | 0.00 | 0.00 CRA ✓             |
| 49 | Radiator grille emblem - Logo | 1.00 | 0.00 | 0.00 NECV              |
| 50 | Fog lamp (LH)                 | 1.00 | 0.00 | 0.00 }                 |
| 51 | Fog lamp (RH)                 | 1.00 | 0.00 | 0.00 } ?               |
| 52 | Fog lamp garnish (LH)         | 1.00 | 0.00 | 0.00 }                 |
| 53 | Fog lamp garnish (RH)         | 1.00 | 0.00 | 0.00 }                 |

Continue on next page...



# Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
Co. & GST Reg. No.: 201313221G

## ESTIMATION REPORT

Vehicle No : JPV5613  
Make & Model : HONDA,CITY E 1.5L I-  
VTEC,PMHGM2660DD211597  
Year of Manufacture : 2014

Estimation No. : E19020001  
DOA : 31/01/2019

| No | Description                    | Qty  | U/P  | Amt                          |
|----|--------------------------------|------|------|------------------------------|
| 54 | Front bumper reinforcement     | 1.00 | 0.00 | 0.00 BT✓                     |
| 55 | Front bumper bracket (LH)      | 1.00 | 0.00 | 0.00                         |
| 56 | Front bumper bracket (RH)      | 1.00 | 0.00 | 0.00 } reinforcement bracket |
| 57 | Bonnet                         | 1.00 | 0.00 | 0.00 DD✓                     |
| 58 | Bonnet lock                    | 1.00 | 0.00 | 0.00 BT✓                     |
| 59 | Bonnet hinge (LH)              | 1.00 | 0.00 | 0.00                         |
| 60 | Bonnet hinge (RH)              | 1.00 | 0.00 | 0.00 } NNX                   |
| 61 | Bonnet insulator               | 1.00 | 0.00 | 0.00                         |
| 62 | Bonnet air duct                | 1.00 | 0.00 | 0.00 } NNX                   |
| 63 | Bonnet weather strip (LH)      | 1.00 | 0.00 | 0.00                         |
| 64 | Bonnet weather strip (RH)      | 1.00 | 0.00 | 0.00 } NEC✓                  |
| 65 | Bonnet nozzle (LH)             | 1.00 | 0.00 | 0.00                         |
| 66 | Bonnet nozzle (RH)             | 1.00 | 0.00 | 0.00 } NNX                   |
| 67 | Head lamp (LH)                 | 1.00 | 0.00 | 0.00 ?                       |
| 68 | Head lamp (RH)                 | 1.00 | 0.00 | 0.00 CRA✓                    |
| 69 | Head lamp bracket (LH)         | 1.00 | 0.00 | 0.00                         |
| 70 | Head lamp bracket (RH)         | 1.00 | 0.00 | 0.00 } ?                     |
| 71 | Head lamp panel (LH)           | 1.00 | 0.00 | 0.00                         |
| 72 | Head lamp panel (RH)           | 1.00 | 0.00 | 0.00                         |
| 73 | Front fender (LH)              | 1.00 | 0.00 | 0.00 DD✓ NNX                 |
| 74 | Front fender (RH)              | 1.00 | 0.00 | 0.00 DD✓                     |
| 75 | Front fender inner shield (LH) | 1.00 | 0.00 | 0.00 NNX                     |
| 76 | Front fender inner shield (RH) | 1.00 | 0.00 | 0.00 ?                       |
| 77 | Front fender QTR garnish (LH)  | 1.00 | 0.00 | 0.00 NNX                     |
| 78 | Front fender QTR garnish (RH)  | 1.00 | 0.00 | 0.00 Cut✓                    |
| 79 | Front door (RH)                | 1.00 | 0.00 | 0.00 R X                     |
| 80 | Front door checker (RH)        | 1.00 | 0.00 | 0.00 NNX                     |

Continue on next page...



**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
Co. & GST Reg. No.: 201313221G

## ESTIMATION REPORT

**Vehicle No** : JPV5613  
**Make & Model** : HONDA, CITY E 1.5L I-  
VTEC, PMHGM2660DD211597  
**Year of Manufacture** : 2014

**Estimation No.** : E19020001  
**DOA** : 31/01/2019

| No | Description                      | Qty  | U/P  | Amt  |       |
|----|----------------------------------|------|------|------|-------|
| 81 | Front door hinge bottom          | 1.00 | 0.00 | 0.00 | } NNX |
| 82 | Front door hinge upper           | 1.00 | 0.00 | 0.00 |       |
| 83 | Front support top panel          | 1.00 | 0.00 | 0.00 | BT ✓  |
| 84 | Front support panel top garnish  | 1.00 | 0.00 | 0.00 | DL ✓  |
| 85 | A/C condenser                    | 1.00 | 0.00 | 0.00 | BT ✓  |
| 86 | Radiator                         | 1.00 | 0.00 | 0.00 | ?     |
| 87 | A/C condenser discharge pipe     | 1.00 | 0.00 | 0.00 | } ?   |
| 88 | A/C condenser return pipe        | 1.00 | 0.00 | 0.00 |       |
| 89 | Radiator fan motor & cowling set | 1.00 | 0.00 | 0.00 | } ?   |
| 90 | A/C fan motor & cowling set      | 1.00 | 0.00 | 0.00 |       |
| 91 | Radiator spare tank              | 1.00 | 0.00 | 0.00 | } ?   |
| 92 | Wiper tank                       | 1.00 | 0.00 | 0.00 |       |
| 93 | Wiper tank motor                 | 1.00 | 0.00 | 0.00 | NNX   |
| 94 | Radiator bracket (LH)            | 1.00 | 0.00 | 0.00 | } ?   |
| 95 | Radiator bracket (RH)            | 1.00 | 0.00 | 0.00 |       |
| 96 | A/C condenser bracket (LH)       | 1.00 | 0.00 | 0.00 |       |
| 97 | A/C condenser bracket (RH)       | 1.00 | 0.00 | 0.00 | } ?   |
| 98 | Front bumper undercover          | 1.00 | 0.00 | 0.00 |       |

**Amt** S\$ 0.00  
**Discount (0.00%)** S\$ 0.00  
**Subtotal** S\$ 0.00

### Section: Special Nett Items

|     |                                |      |       |                              |
|-----|--------------------------------|------|-------|------------------------------|
| 99  | Rear bumper clip set           | 1.00 | 50.00 | <del>50.00</del> 30.00 NEC ✓ |
| 100 | Bootlid insulator clip set     | 1.00 | 50.00 | <del>50.00</del> NNX         |
| 101 | Bootlid logo emblem            | 1.00 | 90.00 | 90.00 NEC ✓                  |
| 102 | Tail lamp clip set (LH) & (RH) | 1.00 | 40.00 | <del>40.00</del> 20 NEC ✓    |
| 103 | End panel top garnish clip set | 1.00 | 30.00 | <del>30.00</del> 20 NEC ✓    |

Continue on next page...



**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
Co. & GST Reg. No.: 201313221G

## ESTIMATION REPORT

**Vehicle No** : JPV5613  
**Make & Model** : HONDA,CITY E 1.5L I-  
VTEC,PMHGM2660DD211597  
**Year of Manufacture** : 2014

**Estimation No.** : E19020001  
**DOA** : 31/01/2019

| No  | Description                             | Qty  | U/P    | Amt    |         |
|-----|-----------------------------------------|------|--------|--------|---------|
| 104 | Rear fender inner trim clip set (LH)    | 1.00 | 45.00  | 45.00  | NEC NN. |
| 105 | Rear fender inner trim clip set (RH)    | 1.00 | 45.00  | 45.00  | NEC ✓   |
| 106 | Trolley                                 | 1.00 | 200.00 | 200.00 | NNX     |
| 107 | End panel sealant                       | 1.00 | 50.00  | 50.00  | } NEC ✓ |
| 108 | Spare tyre panel sealant                | 1.00 | 50.00  | 50.00  |         |
| 109 | Spare tyre panel insulator matt         | 1.00 | 280.00 | 280.00 | e ?     |
| 110 | Rear exhaust mounting set               | 1.00 | 180.00 | 180.00 | ?       |
| 111 | Rear number plate                       | 1.00 | 60.00  | 60.00  | NNX     |
| 112 | Front number plate & casing             | 1.00 | 50.00  | 50.00  | BR ✓    |
| 113 | Front bumper clip set                   | 1.00 | 50.00  | 50.00  | NEC ✓   |
| 114 | Support panel top garnish clip set      | 1.00 | 30.00  | 30.00  | NEC ✓   |
| 115 | Front bumper under cover clip set       | 1.00 | 45.00  | 45.00  | ?       |
| 116 | Bonnet insulator clip set               | 1.00 | 35.00  | 35.00  | NNX     |
| 117 | Bonnet air duct clip set                | 1.00 | 35.00  | 35.00  | NNX     |
| 118 | Front fender inner shield clip set (LH) | 1.00 | 45.00  | 45.00  | NNX     |
| 119 | Front fender inner shield clip set (RH) | 1.00 | 45.00  | 45.00  | ?       |
| 120 | Horn                                    | 1.00 | 120.00 | 120.00 | ?       |
| 121 | Engine coolant                          | 1.00 | 100.00 | 100.00 | ?       |
| 122 | A/C condenser o'ring set                | 1.00 | 30.00  | 30.00  | NEC     |
| 123 | Auto transmission fluid 1 Litre         | 1.00 | 60.00  | 60.00  | ?       |

**Amt** S\$ 1,815.00  
**Discount (0.00%)** S\$ 0.00  
**Subtotal** S\$ 1,815.00

### Section: Labour Items

|     |                                   |      |        |        |       |
|-----|-----------------------------------|------|--------|--------|-------|
| 124 | To R&R rear bumper reverse sensor | 1.00 | 80.00  | 80.00  | 60.00 |
| 125 | To check wiring & lighting system | 1.00 | 100.00 | 100.00 | 60.00 |
| 126 | To conduct head lamp focus        | 1.00 | 100.00 | 100.00 | 50.00 |

Continue on next page...



**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
Co. & GST Reg. No.: 201313221G

## ESTIMATION REPORT

**Vehicle No** : JPV5613  
**Make & Model** : HONDA,CITY E 1.5L I-  
VTEC,PMHGM2660DD211597  
**Year of Manufacture** : 2014

**Estimation No.** : E19020001  
**DOA** : 31/01/2019

| No  | Description                                | Qty  | U/P      | Amt                         |
|-----|--------------------------------------------|------|----------|-----------------------------|
| 127 | To R&R rear trims,garnish & seat assy      | 1.00 | 200.00   | <del>200.00</del> 100.00    |
| 128 | To R&R rear exhaust assy                   | 1.00 | 250.00   | <del>250.00</del> 120.00    |
| 129 | To R&R fuel tank to cut & weld             | 1.00 | 350.00   | <del>350.00</del> NNX       |
| 130 | To R&R radiator, a/c condenser assy        | 1.00 | 350.00   | <del>350.00</del> 150.00    |
| 131 | To vacuum & top up 134a refrigerants.      | 1.00 | 120.00   | 120.00 ✓                    |
| 132 | To straighten rear RH chassis member       | 1.00 | 350.00   | <del>350.00</del> NNX       |
| 133 | To repair, replace & realign damaged areas | 1.00 | 2,000.00 | 2,000.00 1400.00            |
| 134 | To spray painting on affected areas        | 1.00 | 1,800.00 | <del>1,800.00</del> 1200.00 |
| 135 | To car wash & polish vehicle after repair  | 1.00 | 150.00   | <del>150.00</del> NNX       |
| 136 | To perform water seepage test after repair | 1.00 | 180.00   | <del>180.00</del> NNX       |
| 137 | Sundries                                   | 1.00 | 50.00    | 50.00 NEC                   |

**Amt** S\$ 6,080.00  
**Discount (0.00%)** S\$ 0.00  
**Subtotal** S\$ 6,080.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Repair day 8

? Photo

Lump sum repair

13/2/19 1300

TTCIM

**List Items Subtotal** S\$ 0.00  
**Special Nett Items Subtotal** S\$ 1,815.00  
**Labour Items Subtotal** S\$ 6,080.00  
**Total** S\$ 7,895.00



Torque 5 Pte Ltd  
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
Co. & GST Reg. No.: 201313221G

## ESTIMATION REPORT

Vehicle No : JPV5613  
Make & Model : HONDA, CITY E 1.5L I-  
VTEC, PMHGM2660DD211597  
Year of Manufacture : 2014

Estimation No. : E19020001  
DOA : 31/01/2019

| No                         | Description                               | Qty  | U/P  | Amt                                  |
|----------------------------|-------------------------------------------|------|------|--------------------------------------|
| <b>Section: List Items</b> |                                           |      |      |                                      |
| 1                          | Rear bumper                               | 1.00 | 564  | 0.00 564.00 DDV                      |
| 2                          | Rear bumper lower garnish                 | 1.00 | 9280 | 0.00 9280.00 DLV                     |
| 3                          | Rear bumper retainer (LH)                 | 1.00 | 20   | 0.00 20.00 0.00                      |
| 4                          | Rear bumper retainer (RH)                 | 1.00 | 20   | 0.00 20.00 0.00                      |
| 5                          | Rear bumper reflector (LH)                | 1.00 | 60   | 0.00 47.20 0.00                      |
| 6                          | Rear bumper reflector (RH)                | 1.00 | 60   | 0.00 47.20 0.00                      |
| 7                          | Rear bumper bracket (LH)                  | 1.00 | 22   | 0.00 22.00 0.00                      |
| 8                          | Rear bumper bracket (RH)                  | 1.00 | 22   | 0.00 22.00 0.00                      |
| 9                          | Reverse sensor <i>€ 250.00 (original)</i> | ★ 2  | 400  | 0.00 500.00 <sup>SN</sup> 0.00 CUTV  |
| 10                         | Reverse sensor harness wire set           | 1.00 |      | 0.00 <del>240.00</del> 0.00 - NEC XN |
| 11                         | Bootlid                                   | 1.00 | 495  | 0.00 495.00 0.00 DDV                 |
| 12                         | Bootlid emblem - Logo                     | 1.00 | 25   | 0.00 25.80 0.00                      |
| 13                         | Bootlid emblem - City                     | 1.00 | 23   | 0.00 22.20 0.00                      |
| 14                         | Bootlid emblem - IVTEC                    | 1.00 | 40   | 0.00 23.50 0.00                      |
| 15                         | Bootlid chrome garnish                    | 1.00 | 108  | 0.00 108.00 0.00 ? CUTV              |
| 16                         | Bootlid lock                              | 1.00 | 79   | 0.00 75.00 0.00 JAMV                 |
| 17                         | Bootlid lock catch                        | 1.00 |      | 0.00 0.00 NNX                        |
| 18                         | Bootlid insulator                         | 1.00 |      | 0.00 0.00 NNX                        |
| 19                         | Bootlid hinge (LH)                        | 1.00 |      | 0.00 0.00                            |
| 20                         | Bootlid hinge (RH)                        | 1.00 |      | 0.00 0.00                            |
| 21                         | Bootlid rubber beading                    | 1.00 | 100  | 0.00 74.40 0.00 TNV                  |
| 22                         | License lamp (LH)                         | 1.00 |      | 0.00 0.00                            |
| 23                         | License lamp (RH)                         | 1.00 |      | 0.00 0.00                            |
| 24                         | Tail lamp (LH)                            | 1.00 | 277  | 0.00 215.00 0.00 ? CRAV              |
| 25                         | Tail lamp (RH)                            | 1.00 | 277  | 0.00 215.00 0.00 CRAV                |
| 26                         | Tail lamp gasket (LH)                     | 1.00 |      | 0.00 0.00 NNX                        |

Continue on next page...

2542.1

3104.20



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
Co. & GST Reg. No.: 201313221G

## ESTIMATION REPORT

Vehicle No : JPV5613  
Make & Model : HONDA, CITY E 1.5L I-  
VTEC, PMHGM2660DD211597  
Year of Manufacture : 2014

Estimation No. : E19020001  
DOA : 31/01/2019

| No   | Description                         | Qty         | U/P         | Amt           |
|------|-------------------------------------|-------------|-------------|---------------|
| 27   | Tail lamp gasket (RH)               | 1.00        | 0.00        | -0.00 NNX     |
| 28   | Tail lamp inner panel (LH)          | 1.00 160    | 0.00        | 0.00 NNX      |
| 29   | Tail lamp inner panel (RH)          | 1.00 160    | 0.00 160.00 | 0.00 ? DDV    |
| 30   | End panel                           | 1.00 430    | 0.00 430.00 | 0.00 BTV      |
| 31   | End panel top garnish               | 1.00 89     | 0.00 89.00  | 0.00 DLV      |
| 32   | Spare tyre top board                | 1.00 92     | 0.00 92.00  | 0.00 ? DISV   |
| 33   | Spare tyre panel                    | 1.00 612    | 0.00        | 0.00 ? DDV RX |
| 34   | Rear fender (RH)                    | 1.00        | 0.00        | 0.00 ? RX     |
| * 35 | Rear fender inner trim (LH)         | 1.00 120    | 0.00 120.00 | 0.00 ? RX CUT |
| * 36 | Rear fender inner trim (RH)         | 1.00 120    | 0.00 120.00 | 0.00 ? DISV   |
| 37   | Rear seat (LH) COVER (local repair) | 1.00 380    | 0.00 380.00 | 0.00 ? RX     |
| 38   | Rear seat (RH) COVER (local repair) | 1.00 380    | 0.00 380.00 | 0.00 ? RX     |
| * 39 | Rear exhaust muffler                | 1.00 592    | 0.00 592.00 | 0.00 BTV      |
| * 40 | Rear exhaust heat shield            | 1.00        | 0.00        | 0.00 ? RX     |
| * 41 | Exhaust mid pipe                    | 1.00        | 0.00        | 0.00 RX       |
| 42   | Rear chassis member (RH)            | 1.00        | 0.00        | 0.00 NNX      |
| 43   | Front bumper                        | 1.00 598.70 | 0.00 459.80 | 0.00 BRV      |
| 44   | Front bumper retainer (LH)          | 1.00 44.50  | 0.00 39.00  | 0.00 } NECV   |
| 45   | Front bumper retainer (RH)          | 1.00 44.50  | 0.00 39.00  | 0.00 } NECV   |
| 46   | Front bumper lower garnish          | 1.00 198    | 0.00 198.00 | 0.00 BRV      |
| 47   | Front bumper towing cap             | 1.00        | 0.00        | 0.00 CAAV NNA |
| 48   | Radiator grille                     | 1.00 170    | 0.00 170.00 | 0.00 CRAV     |
| 49   | Radiator grille emblem - Logo       | 1.00 40     | 0.00 21.60  | 0.00 NECV     |
| 50   | Fog lamp (LH)                       | 1.00 375    | 0.00 200.00 | 0.00 } BRV    |
| 51   | Fog lamp (RH)                       | 1.00 375    | 0.00 200.00 | 0.00 } BRV    |
| 52   | Fog lamp garnish (LH)               | 1.00 33     | 0.00 37.00  | 0.00 }        |
| 53   | Fog lamp garnish (RH)               | 1.00 33     | 0.00 37.00  | 0.00 }        |

Continue on next page...

3182.40

4056.20



**Torque 5 Pte Ltd**  
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
 Co. & GST Reg. No.: 201313221G

## ESTIMATION REPORT

**Vehicle No** : JPV5613  
**Make & Model** : HONDA,CITY E 1.5L I-  
 VTEC,PMHGM2660DD211597  
**Year of Manufacture** : 2014

**Estimation No.** : E19020001  
**DOA** : 31/01/2019

| No | Description                    | Qty  | U/P   | Amt             |
|----|--------------------------------|------|-------|-----------------|
| 54 | Front bumper reinforcement     | 1.00 | 192   | 0.00 192.00 BT✓ |
| 55 | Front bumper bracket (LH)      | 1.00 | 0.00  | 0.00            |
| 56 | Front bumper bracket (RH)      | 1.00 | 0.00  | 0.00            |
| 57 | Bonnet                         | 1.00 | 523   | 0.00 482.70 DD✓ |
| 58 | Bonnet lock                    | 1.00 | 223   | 0.00 89.10 BT✓  |
| 59 | Bonnet hinge (LH)              | 1.00 | 0.00  | 0.00            |
| 60 | Bonnet hinge (RH)              | 1.00 | 0.00  | 0.00            |
| 61 | Bonnet insulator               | 1.00 | 0.00  | 0.00            |
| 62 | Bonnet air duct                | 1.00 | 0.00  | 0.00            |
| 63 | Bonnet weather strip (LH)      | 1.00 | 23    | 0.00 28.60      |
| 64 | Bonnet weather strip (RH)      | 1.00 | 23    | 0.00 28.60      |
| 65 | Bonnet nozzle (LH)             | 1.00 | 0.00  | 0.00            |
| 66 | Bonnet nozzle (RH)             | 1.00 | 0.00  | 0.00            |
| 67 | Head lamp (LH)                 | 1.00 | 410   | 0.00 344.70     |
| 68 | Head lamp (RH)                 | 1.00 | 410   | 0.00 344.70     |
| 69 | Head lamp bracket (LH)         | 1.00 | 50    | 0.00 37.50      |
| 70 | Head lamp bracket (RH)         | 1.00 | 50    | 0.00 37.50      |
| 71 | Head lamp panel (LH)           | 1.00 | 390   | 0.00 -0.00      |
| 72 | Head lamp panel (RH)           | 1.00 | 390   | 0.00 35.20      |
| 73 | Front fender (LH)              | 1.00 | 325   | 0.00 0.00       |
| 74 | Front fender (RH)              | 1.00 | 325   | 0.00 325.00 DD✓ |
| 75 | Front fender inner shield (LH) | 1.00 | 0.00  | 0.00            |
| 76 | Front fender inner shield (RH) | 1.00 | 0.00  | 0.00            |
| 77 | Front fender QTR garnish (LH)  | 1.00 | 58.70 | 0.00 0.00       |
| 78 | Front fender QTR garnish (RH)  | 1.00 | 58.70 | 0.00 58.70      |
| 79 | Front door (RH)                | 1.00 | 0.00  | 0.00            |
| 80 | Front door checker (RH)        | 1.00 | 0.00  | 0.00            |

Continue on next page...

2054.10

3162.60



**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
Co. & GST Reg. No.: 201313221G

## ESTIMATION REPORT

**Vehicle No** : JPV5613  
**Make & Model** : HONDA,CITY E 1.5L I-  
VTEC,PMHGM2660DD211597  
**Year of Manufacture** : 2014

**Estimation No.** : E19020001  
**DOA** : 31/01/2019

| No | Description                      | Qty  | U/P     | Amt             |          |
|----|----------------------------------|------|---------|-----------------|----------|
| 81 | Front door hinge bottom          | 1.00 | 0.00    | <del>0.00</del> | } NNx    |
| 82 | Front door hinge upper           | 1.00 | 0.00    | <del>0.00</del> |          |
| 83 | Front support top panel          | 1.00 | 317.00  | 317.00          | BT ✓     |
| 84 | Front support panel top garnish  | 1.00 | 88.50   | 88.50           | DL ✓     |
| 85 | A/C condenser                    | 1.00 | 490.00  | 490.00          | BT ✓     |
| 86 | Radiator                         | 1.00 | 1409.20 | 1019.00         | ? BT ✓   |
| 87 | A/C condenser discharge pipe     | 1.00 | 112.30  | 33.00           | } ? BT ✓ |
| 88 | A/C condenser return pipe        | 1.00 | 124.60  | 29.00           |          |
| 89 | Radiator fan motor & cowling set | 1.00 | 590.00  | 350.00          | } ? BR ✓ |
| 90 | A/C fan motor & cowling set      | 1.00 | 490.00  | 350.00          |          |
| 91 | Radiator spare tank              | 1.00 | 0.00    | <del>0.00</del> | } ? NNx  |
| 92 | Wiper tank                       | 1.00 | 0.00    | <del>0.00</del> |          |
| 93 | Wiper tank motor                 | 1.00 | 0.00    | <del>0.00</del> | NNx      |
| 94 | Radiator bracket (LH)            | 1.00 | 0.00    | <del>0.00</del> | } ? NNx  |
| 95 | Radiator bracket (RH)            | 1.00 | 0.00    | <del>0.00</del> |          |
| 96 | A/C condenser bracket (LH)       | 1.00 | 0.00    | <del>0.00</del> |          |
| 97 | A/C condenser bracket (RH)       | 1.00 | 0.00    | <del>0.00</del> |          |
| 98 | Front bumper undercover          | 1.00 | 28.00   | 28.00           | ? BR ✓   |

Parts discount Less 20%

**Amt** S\$ 0.00 1999.20  
**Discount (0.00%)** S\$ 0.00  
**Subtotal** S\$ 0.00  
2710.50

### Section: Special Nett Items

|     |                                |      |       |                  |        |
|-----|--------------------------------|------|-------|------------------|--------|
| 99  | Rear bumper clip set           | 1.00 | 50.00 | 30.00            | NECV ✓ |
| 100 | Bootlid insulator clip set     | 1.00 | 50.00 | <del>50.00</del> | NNx    |
| 101 | Bootlid logo emblem            | 1.00 | 90.00 | 90.00            | NECV ✓ |
| 102 | Tail lamp clip set (LH) & (RH) | 1.00 | 40.00 | <del>40.00</del> | NECV   |
| 103 | End panel top garnish clip set | 1.00 | 30.00 | <del>30.00</del> | NECV   |

Continue on next page...

160.00



## Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
Co. & GST Reg. No.: 201313221G

### ESTIMATION REPORT

Vehicle No : JPV5613  
Make & Model : HONDA,CITY E 1.5L I-  
VTEC,PMHGM2660DD211597  
Year of Manufacture : 2014

Estimation No. : E19020001  
DOA : 31/01/2019

| No  | Description                             | Qty  | U/P    | Amt    |        |
|-----|-----------------------------------------|------|--------|--------|--------|
| 104 | Rear fender inner trim clip set (LH)    | 1.00 | 45.00  | 45.00  | NNN    |
| 105 | Rear fender inner trim clip set (RH)    | 1.00 | 45.00  | 45.00  | NECV   |
| 106 | Trolley                                 | 1.00 | 200.00 | 200.00 | NNX    |
| 107 | End panel sealant                       | 1.00 | 50.00  | 50.00  | NECV   |
| 108 | Spare tyre panel sealant                | 1.00 | 50.00  | 50.00  |        |
| 109 | Spare tyre panel insulator matt         | 1.00 | 280.00 | 280.00 | ?NEC   |
| 110 | Rear exhaust mounting set               | 1.00 | 180.00 | 180.00 | ?80.00 |
| 111 | Rear number plate                       | 1.00 | 60.00  | 60.00  | NNX    |
| 112 | Front number plate & casing             | 1.00 | 50.00  | 50.00  | BRV    |
| 113 | Front bumper clip set                   | 1.00 | 50.00  | 50.00  | NECV   |
| 114 | Support panel top garnish clip set      | 1.00 | 30.00  | 30.00  | NECV   |
| 115 | Front bumper under cover clip set       | 1.00 | 45.00  | 45.00  | ?NECV  |
| 116 | Bonnet insulator clip set               | 1.00 | 35.00  | 35.00  | NNX    |
| 117 | Bonnet air duct clip set                | 1.00 | 35.00  | 35.00  | NNX    |
| 118 | Front fender inner shield clip set (LH) | 1.00 | 45.00  | 45.00  | NNX    |
| 119 | Front fender inner shield clip set (RH) | 1.00 | 45.00  | 45.00  | ?NEC   |
| 120 | Horn                                    | 1.00 | 120.00 | 120.00 | ?SCRV  |
| 121 | Engine coolant                          | 1.00 | 100.00 | 100.00 | ?NEC   |
| 122 | A/C condenser o'ring set                | 1.00 | 30.00  | 30.00  | NECV   |
| 123 | Auto transmission fluid 1 Litre         | 1.00 | 60.00  | 60.00  | ?NECV  |

Amt S\$ 1,815.00  
Discount (0.00%) S\$ 0.00  
Subtotal S\$ 1,815.00

680

#### Section: Labour Items

|     |                                   |      |        |        |       |
|-----|-----------------------------------|------|--------|--------|-------|
| 124 | To R&R rear bumper reverse sensor | 1.00 | 80.00  | 80.00  | 60.00 |
| 125 | To check wiring & lighting system | 1.00 | 100.00 | 100.00 | 60.00 |
| 126 | To conduct head lamp focus        | 1.00 | 100.00 | 100.00 | 50.00 |

Continue on next page...

120.00

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
 Co. & GST Reg. No.: 201313221G

**ESTIMATION REPORT**

**Vehicle No** : JPV5613  
**Make & Model** : HONDA,CITY E 1.5L I-  
 VTEC,PMHGM2660DD211597  
**Year of Manufacture** : 2014

**Estimation No.** : E19020001  
**DOA** : 31/01/2019

| No  | Description                                | Qty  | U/P      | Amt                              |
|-----|--------------------------------------------|------|----------|----------------------------------|
| 127 | To R&R rear trims,garnish & seat assy      | 1.00 | 200.00   | <del>200.00</del> 140.00         |
| 128 | To R&R rear exhaust assy                   | 1.00 | 250.00   | <del>250.00</del> 120.00         |
| 129 | To R&R fuel tank to cut & weld             | 1.00 | 350.00   | <del>350.00</del> NNX            |
| 130 | To R&R radiator, a/c condenser assy        | 1.00 | 350.00   | <del>350.00</del> 150.00         |
| 131 | To vacuum & top up 134a refrigerants.      | 1.00 | 120.00   | 120.00 ✓                         |
| 132 | To straighten rear RH chassis member       | 1.00 | 350.00   | <del>350.00</del> NNX            |
| 133 | To repair, replace & realign damaged areas | 1.00 | 2,000.00 | <del>2,000.00</del> 1400.00      |
| 134 | To spray painting on affected areas        | 1.00 | 1,800.00 | <del>1,800.00</del> 1200.00      |
| 135 | To car wash & polish vehicle after repair  | 1.00 | 150.00   | <del>150.00</del> NNX            |
| 136 | To perform water seepage test after repair | 1.00 | 180.00   | <del>180.00</del> NNX            |
| 137 | Sundries                                   | 1.00 | 50.00    | <del>50.00</del> NEC NNX         |
|     |                                            |      |          | <b>Amt</b> S\$ 6,080.00          |
|     |                                            |      |          | <b>Discount (0.00%)</b> S\$ 0.00 |
|     |                                            |      |          | <b>Subtotal</b> S\$ 6,080.00     |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair day 8

? Photo

Lump sum repair

13/2/19 1300

TTCIM

  
 25/3/19

24045.50

|                       |                     |
|-----------------------|---------------------|
| List Items Subtotal   | S\$ 0.00            |
| Special Nett Items    | S\$                 |
| Subtotal              | 1,815.00            |
| Labour Items Subtotal | S\$                 |
|                       | 6,080.00            |
| <b>Total</b>          | <b>S\$ 7,895.00</b> |

24356.20



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
 Co. & GST Reg. No.: 201313221G

## SUPPLEMENTARY REPORT

Vehicle No : JPV5613  
 Make & Model : HONDA, CITY E 1.5L I-  
 VTEC, PMHGM2660DD211597  
 Year of Manufacture : 2014

Estimation No. : E19020010  
 DOA : 31/01/2019

| No                         | Description                     | Qty  | U/P    | Amt                              |
|----------------------------|---------------------------------|------|--------|----------------------------------|
| <b>Section: List Items</b> |                                 |      |        |                                  |
| 1                          | Support panel lower air duct    | 1.00 | 228.00 | 228.00                           |
| 2                          | Reverse sensor harness wire set | 1.00 | 360.00 | 360.00                           |
|                            |                                 |      |        | <b>Amt</b> S\$ 588.00            |
|                            |                                 |      |        | <b>Discount (0.00%)</b> S\$ 0.00 |
|                            |                                 |      |        | <b>Subtotal</b> S\$ 588.00       |

285.00

Resurvey 14/2/19

1545 hrs

Parts

TTCim Lin

2542.10

3182.40

2054.10

2710.50

285.00

10774.10

2154.82

8619.28

160.00

680.00

120.00

3090.00

4050.00

8619.28

12669.28

@20% 2533.86

10135.42

labour

Parts 8619.28

SN 840.00

Labour 3210.00

12669.28

@20% 2533.86

10135.42

L/S 10100/2

TTCim Lin

29/4/19

List Items Subtotal S\$ 588.00  
 Total S\$ 588.00

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |                      |               |                                                      |                                                       |                                                 |             |                                                                 |
|--------------------------|----------------------|---------------|------------------------------------------------------|-------------------------------------------------------|-------------------------------------------------|-------------|-----------------------------------------------------------------|
| Case                     | Notified             | Est Submitted | Adj Assigned                                         | Adj Rpt                                               | Adj Submitted                                   | Ins Auth'ed | Status                                                          |
| Main                     | 04 Jun 2019<br>10:58 |               | 18 Mar 2019<br>17:47<br><a href="#">Edit Adj Rpt</a> | <b>S\$10,100.00</b><br><a href="#">Edit Estimates</a> | <b>S\$10,100.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main                                                                                                                                                                          | Reference | Claim Details                                                                             | Documents  | Show All |         |             |              |            |       |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|-------------------------------------------------------------------------------------------|------------|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by Insurer]</span>                                                                                        |           |                                                                                           |            |          |         |             |              |            |       |
| Insured: -, Co. Reg. No.: -                                                                                                                                                   |           |                                                                                           |            |          |         |             |              |            |       |
| Main Claimant: <b>CHEAH KIAN SOON</b>                                                                                                                                         |           |                                                                                           |            |          |         |             |              |            |       |
| Vehicle Reg. No.: <b>JPV5613</b>                                                                                                                                              |           | Date of Loss: 31/01/2019 00:00 - :59<br>[60 Months and 3 Days From LTA Reg Date (Man Yr)] |            |          |         |             |              |            |       |
| Claim Type: <b>TP</b>                                                                                                                                                         |           | Policy/Cover Note No.:                                                                    |            |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured): <b>SJM2147K</b>                                                                                                                                   |           | Policy No. (Claimant):                                                                    |            |          |         |             |              |            |       |
|                                                                                                                                                                               |           | Excess: S\$0.00                                                                           |            |          |         |             |              |            |       |
| Repairer: <b>Torque 5 Pte Ltd (Kaki Bukit)</b> No. 8 Kaki Bukit Ave 4,, #01-50, 415875 Kaki Bukit - Tel: 64524457                                                             |           |                                                                                           |            |          |         |             |              |            |       |
| Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]                                          |           |                                                                                           |            |          |         |             |              |            |       |
| Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Lim Teow Guan</b> ] ... [Final Rpt due 27/03/2019]                                     |           |                                                                                           |            |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>                                                 |           |                                                                                           |            |          |         |             |              |            |       |
| There are no mail for this case.                                                                                                                                              |           |                                                                                           |            |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |           |                                                                                           |            |          |         |             |              |            |       |
| Due Date                                                                                                                                                                      | Priority  | Type                                                                                      | Task Group | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                                                                                   |           |                                                                                           |            |          |         |             |              |            |       |

## Claim Documents

\*JPV5613  
[SJM2147K]  
TP  
CHEAH KIAN SOON  
Jan 31 2019 12:00AM  
[-]  
Torque 5 Pte Ltd

|                  |                 |                                   |               |  |                    |  |      |                                                                                       |                                              |                                     |
|------------------|-----------------|-----------------------------------|---------------|--|--------------------|--|------|---------------------------------------------------------------------------------------|----------------------------------------------|-------------------------------------|
| Upload Documents |                 |                                   | Upload Photos |  | Compose New Letter |  | View |                                                                                       | View in Browser                              |                                     |
| Photos/Images    |                 |                                   |               |  |                    |  |      | 3 per page                                                                            |                                              | <input checked="" type="checkbox"/> |
| No               | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |               |  |                    |  |      | Thumbnail                                                                             | Print                                        |                                     |
| 1                | 13/05/19 13:17  | General View                      |               |  |                    |  |      |    | Load JPG <input checked="" type="checkbox"/> |                                     |
| 2                | 13/05/19 13:17  | General View                      |               |  |                    |  |      |    | Load JPG <input checked="" type="checkbox"/> |                                     |
| 3                | 13/05/19 13:17  | General View                      |               |  |                    |  |      |    | Load JPG <input checked="" type="checkbox"/> |                                     |
| 4                | 13/05/19 13:17  | General View                      |               |  |                    |  |      |    | Load JPG <input checked="" type="checkbox"/> |                                     |
| 5                | 13/05/19 13:17  | General View                      |               |  |                    |  |      |    | Load JPG <input checked="" type="checkbox"/> |                                     |
| 6                | 13/05/19 13:17  | General View                      |               |  |                    |  |      |    | Load JPG <input checked="" type="checkbox"/> |                                     |
| 7                | 13/05/19 13:18  | General View                      |               |  |                    |  |      |    | Load JPG <input checked="" type="checkbox"/> |                                     |
| 8                | 13/05/19 13:18  | General View                      |               |  |                    |  |      |    | Load JPG <input checked="" type="checkbox"/> |                                     |
| 9                | 13/05/19 13:18  | General View                      |               |  |                    |  |      |    | Load JPG <input checked="" type="checkbox"/> |                                     |
| 10               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |   | Load JPG <input checked="" type="checkbox"/> |                                     |
| 11               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 12               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 13               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 14               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 15               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 16               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 17               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 18               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 19               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 20               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 21               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 22               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 23               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 24               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 25               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 26               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 27               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 28               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 29               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 30               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 31               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 32               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 33               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 34               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 35               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 36               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |
| 37               | 13/05/19 13:18  | General View                      |               |  |                    |  |      |  | Load JPG <input checked="" type="checkbox"/> |                                     |

| Photos/Images |                 |                                   | 3 per page                                                                                     | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 38            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 39            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 40            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 41            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 42            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 43            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 44            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 45            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 46            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 47            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 48            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 49            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 50            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 51            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 52            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 53            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 54            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 55            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 56            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 57            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 58            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 59            | 13/05/19 13:18  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 60            | 13/05/19 13:18  | General View                      |  Load JPG  | <input checked="" type="checkbox"/> |
| 61            | 13/05/19 13:18  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 62            | 13/05/19 13:18  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 63            | 13/05/19 13:18  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 64            | 13/05/19 13:18  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 65            | 13/05/19 13:18  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 66            | 13/05/19 13:18  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 67            | 13/05/19 13:18  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 68            | 13/05/19 13:18  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 69            | 13/05/19 13:18  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 70            | 13/05/19 13:18  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 71            | 13/05/19 13:18  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 72            | 13/05/19 13:18  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 73            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 74            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 75            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 76            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 77            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 78            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 79            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 80            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 81            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 82            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 83            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 84            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 85            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 86            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 87            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images |                 |                                   | 3 per page                                                                                     | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 88            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 89            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 90            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 91            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 92            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 93            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 94            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 95            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 96            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 97            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 98            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 99            | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 100           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 101           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 102           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 103           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 104           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 105           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 106           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 107           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 108           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 109           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG  | <input checked="" type="checkbox"/> |
| 110           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 111           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 112           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 113           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 114           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 115           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 116           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 117           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 118           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 119           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 120           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 121           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 122           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 123           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 124           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 125           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 126           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 127           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 128           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 129           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 130           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 131           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 132           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 133           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 134           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 135           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 136           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 137           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images |                 |                                   | 3 per page                                                                                     | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 138           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 139           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 140           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 141           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 142           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 143           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 144           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 145           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 146           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 147           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 148           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 149           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 150           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 151           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 152           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 153           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 154           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 155           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 156           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 157           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 158           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 159           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG  | <input checked="" type="checkbox"/> |
| 160           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 161           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 162           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 163           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 164           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 165           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 166           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 167           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 168           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 169           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 170           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 171           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 172           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 173           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 174           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 175           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 176           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 177           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 178           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 179           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 180           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 181           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 182           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 183           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 184           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 185           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 186           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 187           | 13/05/19 13:18  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images |                 |                                   | 3 per page                                                                            | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|---------------------------------------------------------------------------------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                             | Print                               |
| 188           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 189           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 190           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 191           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 192           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 193           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 194           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 195           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 196           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 197           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 198           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 199           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 200           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 201           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 202           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 203           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 204           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 205           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 206           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 207           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 208           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 209           | 13/05/19 13:18  | Reinspection Photo                |    | <input checked="" type="checkbox"/> |
| 210           | 13/05/19 13:18  | Reinspection Photo                |   | <input checked="" type="checkbox"/> |
| 211           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 212           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 213           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 214           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 215           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 216           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 217           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 218           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 219           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 220           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 221           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 222           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 223           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 224           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 225           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 226           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 227           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 228           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 229           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 230           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 231           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 232           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 233           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 234           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 235           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 236           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |
| 237           | 13/05/19 13:18  | Reinspection Photo                |  | <input checked="" type="checkbox"/> |

| Photos/Images |                 |                                                    | 3 per page                                                                                     | <input checked="" type="checkbox"/> |
|---------------|-----------------|----------------------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                  | Thumbnail                                                                                      | Print                               |
| 238           | 13/05/19 13:18  | Reinspection Photo                                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 239           | 13/05/19 13:18  | Reinspection Photo                                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 240           | 13/05/19 13:18  | Reinspection Photo                                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 241           | 13/05/19 13:18  | Reinspection Photo                                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 242           | 13/05/19 13:18  | Reinspection Photo                                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 243           | 13/05/19 13:18  | Reinspection Photo                                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 244           | 13/05/19 13:18  | Reinspection Photo                                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 245           | 13/05/19 13:18  | Reinspection Photo                                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 246           | 13/05/19 13:18  | Reinspection Photo                                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 247           | 13/05/19 13:18  | Reinspection Photo                                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 248           | 13/05/19 13:18  | Reinspection Photo                                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 249           | 13/05/19 13:18  | Reinspection Photo                                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 250           | 13/05/19 13:18  | Reinspection Photo                                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 251           | 13/05/19 13:18  | Reinspection Photo                                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 252           | 13/05/19 13:19  | Reinspection Photo                                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 253           | 13/05/19 13:19  | Reinspection Photo                                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 254           | 13/05/19 13:19  | Reinspection Photo                                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 255           | 13/05/19 13:19  | Reinspection Photo                                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 256           | 13/05/19 13:19  | Reinspection Photo                                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 257           | 13/05/19 13:19  | Reinspection Photo                                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 258           | 13/05/19 13:19  | Reinspection Photo                                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 259           | 13/05/19 13:19  | Reinspection Photo                                 |  Load JPG  | <input checked="" type="checkbox"/> |
| 260           | 13/05/19 13:19  | Reinspection Photo                                 |  Load JPG | <input checked="" type="checkbox"/> |
| 261           | 13/05/19 13:20  | Reinspection Photo                                 |  Load JPG | <input checked="" type="checkbox"/> |
| 262           | 13/05/19 13:20  | Reinspection Photo                                 |  Load JPG | <input checked="" type="checkbox"/> |
| 263           | 13/05/19 13:20  | Reinspection Photo                                 |  Load JPG | <input checked="" type="checkbox"/> |
| 264           | 13/05/19 13:20  | Reinspection Photo                                 |  Load JPG | <input checked="" type="checkbox"/> |
| 265           | 13/05/19 13:20  | Reinspection Photo                                 |  Load JPG | <input checked="" type="checkbox"/> |
| 266           | 13/05/19 13:20  | Reinspection Photo                                 |  Load JPG | <input checked="" type="checkbox"/> |
| 267           | 13/05/19 13:20  | Reinspection Photo                                 |  Load JPG | <input checked="" type="checkbox"/> |
| 268           | 13/05/19 13:20  | Reinspection Photo                                 |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation |                 |                                                    | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
| No            | Finalized On    | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail                                                                                      | Print                               |
| 1             | 18/03/19 17:47  | PR1 CONTACT                                        |  Load PDF |                                     |
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                  | Thumbnail                                                                                      | Print                               |
| 1             | 04/06/19 11:02  | Supplementary                                      |  Load PDF |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST                                                                                                                                |  | Reset | Save | Print |
|----------------------------------------------------------------------------------------------------------------------------------------------------|--|-------|------|-------|
| There are no document checklists configured.                                                                                                       |  |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>          |  |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |  |       |      |       |



## LKK Auto Consultants Pte Ltd (Co Reg No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119002535/BSD3E2

Date: 04/06/2019

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

Claimant Vehicle  
No : JPV5613

Insured Vehicle No : SJM2147K

Date of Loss: 31/01/2019

Nature of Claim: TP Claim No: N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: JPV5613

Make &amp; Model: HONDA CITY, 1.5 (A)

Reg. Date: 28/01/2014 (Man. Year: 2014)

Colour: White

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: L15A75611590

Chassis No: PMHGM2660DD211597

Odometer: 85340 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |               |                  |                  |
|-------------------|---------------|------------------|------------------|
| Front Tyre Size:  | 185/55 R16    | Rear Tyre Size:  | 185/55 R16       |
| Front Left Side:  | Michelin 7 mm | Rear Left Side:  | Bridgestone 7 mm |
| Front Right Side: | Michelin 7 mm | Rear Right Side: | Bridgestone 7 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                           | Repairer's       | Adjuster's       | Difference       | Diff %       |
|------------------------------------------|------------------|------------------|------------------|--------------|
| Parts                                    | 18,326.70        | 9,625.28         | 8,701.42         | 47.48        |
| Miscellaneous Items                      | 0.00             | 0.00             | 0.00             |              |
| Labour                                   | 6,030.00         | 3,210.00         | 2,820.00         | 46.77        |
| Paintwork Labour                         | 0.00             | 0.00             | 0.00             |              |
| Towing                                   | 0.00             | 0.00             | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>24,356.70</b> | <b>12,835.28</b> | <b>11,521.42</b> | <b>47.30</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>10,100.00</b> |                  |              |
| <b>(S\$)</b>                             | <b>24,356.70</b> | <b>10,100.00</b> | <b>14,256.70</b> | <b>58.53</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>            | <b>1,704.97</b>  | <b>707.00</b>    | <b>997.97</b>    | <b>58.53</b> |
| <b>Nett Amount (S\$)</b>                 | <b>26,061.67</b> | <b>10,807.00</b> | <b>15,254.67</b> | <b>58.53</b> |

## INSPECTION

Date of Assignment: 18/03/2019

Date Inspected: 13/02/2019 Inspected At:

Torque 5 Pte Ltd (Kaki Bukit)  
No. 8 Kaki Bukit Ave 4, #01-50  
Singapore 415875

Estimated Period of Repair: 8.0 days

**Adjuster:** Lim Teow Guan

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

|               |                                                                                                                                                                              |                                                      |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------|
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 04 Jun 2019)        |
| Parts:        | 143                                                                                                                                                                          | HONDA CITY 1.5 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                    |
| Print Code:   | (Unsubmitted, no print-code for JPV5613)                                                                                                                                     |                                                      |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                      |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                      |

## Recommended Parts

| No. | Qty | Part No. | Particulars                            | Condition     | Repairer's  | Amount     |
|-----|-----|----------|----------------------------------------|---------------|-------------|------------|
| 1   | 1   |          | *REAR BUMPER                           | Dented        | 564.00 F    | *564.00 FL |
| 2   | 1   |          | *REAR BUMPER LOWER GARNISH             | Dislodged     | 92.80 F     | *92.80 FL  |
| 3   | 1   |          | *REAR BUMPER RETAINER (LH)             | Necessary     | 20.00 F     | *20.00 FL  |
| 4   | 1   |          | *REAR BUMPER RETAINER (RH)             | Necessary     | 20.00 F     | *20.00 FL  |
| 5   | 1   |          | *REAR BUMPER REFLECTOR (LH)            | Cracked       | 60.00 F     | *47.20 FL  |
| 6   | 1   |          | *REAR BUMPER REFLECTOR (RH)            | Cracked       | 60.00 F     | *47.20 FL  |
| 7   | 1   |          | *REAR BUMPER BRACKET (LH)              | Not Necessary | 22.00 F     | *- FL      |
| 8   | 1   |          | *REAR BUMPER BRACKET (RH)              | Not Necessary | 22.00 F     | *- FL      |
| 9   | 1   |          | *REVERSE SENSOR<br>(4PCS)              | Cut-2PCS ONLY | 1,120.00 FS | *500.00 FS |
| 10  | 1   |          | *BOOTLID                               | Dented        | 495.00 F    | *495.00 FL |
| 11  | 1   |          | *BOOTLID EMBLEM - LOGO                 | Necessary     | 25.00 F     | *22.80 FL  |
| 12  | 1   |          | *BOOTLID EMBLEM - CITY                 | Necessary     | 23.00 F     | *22.20 FL  |
| 13  | 1   |          | *BOOTLID EMBLEM - IVTEC                | Necessary     | 40.00 F     | *23.50 FL  |
| 14  | 1   |          | *BOOTLID CHROME GARNISH                | Cut           | 108.00 F    | *108.00 FL |
| 15  | 1   |          | *BOOTLID LOCK                          | Jammed        | 79.00 F     | *75.00 FL  |
| 16  | 1   |          | *BOOTLID LOCK CATCH (NPA)              | Not Necessary | 0.00 F      | *- FL      |
| 17  | 1   |          | *BOOTLID INSULATOR (NPA)               | Not Necessary | 0.00 F      | *- FL      |
| 18  | 1   |          | *BOOTLID HINGE (LH) (NPA)              | Repair        | 0.00 F      | *- FL      |
| 19  | 1   |          | *BOOTLID HINGE (RH) (NPA)              | Repair        | 0.00 F      | *- FL      |
| 20  | 1   |          | *BOOTLID RUBBER BEADING                | Torn          | 100.00 F    | *74.40 FL  |
| 21  | 1   |          | *LICENSE LAMP (LH) (NPA)               | Not Necessary | 0.00 F      | *- FL      |
| 22  | 1   |          | *LICENSE LAMP (RH) (NPA)               | Not Necessary | 0.00 F      | *- FL      |
| 23  | 1   |          | *TAIL LAMP (LH)                        | Cracked       | 277.00 F    | *215.00 FL |
| 24  | 1   |          | *TAIL LAMP (RH)                        | Cracked       | 277.00 F    | *215.00 FL |
| 25  | 1   |          | *TAIL LAMP GASKET (LH) (NPA)           | Not Necessary | 0.00 F      | *- FL      |
| 26  | 1   |          | *TAIL LAMP GASKET (RH) (NPA)           | Not Necessary | 0.00 F      | *- FL      |
| 27  | 1   |          | *TAIL LAMP INNER PANEL (LH)            | Not Necessary | 160.00 F    | *- FL      |
| 28  | 1   |          | *TAIL LAMP INNER PANEL (RH)            | Dented        | 160.00 F    | *160.00 FL |
| 29  | 1   |          | *END PANEL                             | Bent          | 430.00 F    | *430.00 FL |
| 30  | 1   |          | *END PANEL TOP GARNISH                 | Dislodged     | 89.00 F     | *89.00 FL  |
| 31  | 1   |          | *SPARE TYRE TOP BOARD                  | Distorted     | 92.00 F     | *92.00 FL  |
| 32  | 1   |          | *SPARE TYRE PANEL                      | Repair        | 612.00 F    | *- FL      |
| 33  | 1   |          | *REAR FENDER (RH) (NPA)                | Repair        | 0.00 F      | *- FL      |
| 34  | 1   |          | *REAR FENDER INNER TRIM (LH)           | Cut           | 120.00 F    | *120.00 FL |
| 35  | 1   |          | *REAR FENDER INNER TRIM (RH)           | Distorted     | 120.00 F    | *120.00 FL |
| 36  | 1   |          | *REAR SEAT (LH) COVER (LOCAL REPAIR) } | Dented        | 380.00 FS   | *180.00 FS |
| 37  | 1   |          | *REAR SEAT (RH) COVER (LOCAL REPAIR) } |               | 380.00 FS   | *- FS      |
| 38  | 1   |          | *REAR EXHAUST MUFFLER                  | Bent          | 592.00 F    | *592.00 FL |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                              | Condition     | Repairer's | Amount       |
|-----|-----|----------|----------------------------------------------------------|---------------|------------|--------------|
| 39  | 1   |          | *REAR EXHAUST HEAT SHIELD (NPA)                          | Repair        | 0.00 F     | *- FL        |
| 40  | 1   |          | *EXHAUST MID PIPE (NPA)                                  | Repair        | 0.00 F     | *- FL        |
| 41  | 1   |          | *REAR CHASSIS MEMBER (RH) (NPA)                          | Not Necessary | 0.00 F     | *- FL        |
| 42  | 1   |          | *FRONT BUMPER                                            | Broken        | 598.70 F   | *459.80 FL   |
| 43  | 1   |          | *FRONT BUMPER RETAINER (LH)                              | Necessary     | 44.50 F    | *38.00 FL    |
| 44  | 1   |          | *FRONT BUMPER RETAINER (RH)                              | Necessary     | 44.50 F    | *38.00 FL    |
| 45  | 1   |          | *FRONT BUMPER LOWER GARNISH                              | Broken        | 198.00 F   | *198.00 FL   |
| 46  | 1   |          | *FRONT BUMPER TOWING CAP (NPA)                           | Not Necessary | 0.00 F     | *- FL        |
| 47  | 1   |          | *RADIATOR GRILLE                                         | Cracked       | 170.00 F   | *170.00 FL   |
| 48  | 1   |          | *RADIATOR GRILLE EMBLEM - LOGO                           | Necessary     | 40.00 F    | *21.60 FL    |
| 49  | 1   |          | *FOG LAMP (LH)                                           | Broken        | 375.00 F   | *200.00 FL   |
| 50  | 1   |          | *FOG LAMP (RH)                                           | Broken        | 375.00 F   | *200.00 FL   |
| 51  | 1   |          | *FOG LAMP GARNISH (LH)                                   | Broken        | 38.00 F    | *37.00 FL    |
| 52  | 1   |          | *FOG LAMP GARNISH (RH)                                   | Broken        | 38.00 F    | *37.00 FL    |
| 53  | 1   |          | *FRONT BUMPER REINFORCEMENT                              | Bent          | 192.00 F   | *192.00 FL   |
| 54  | 1   |          | *FRONT BUMPER BRACKET (LH) (REINFORCEMENT BRACKET) (NPA) | Not Necessary | 0.00 F     | *- FL        |
| 55  | 1   |          | *FRONT BUMPER BRACKET (RH) (REINFORCEMENT BRACKET) (NPA) | Not Necessary | 0.00 F     | *- FL        |
| 56  | 1   |          | *BONNET                                                  | Dented        | 523.00 F   | *482.70 FL   |
| 57  | 1   |          | *BONNET LOCK                                             | Bent          | 223.00 F   | *89.10 FL    |
| 58  | 1   |          | *BONNET HINGE (LH) (NPA)                                 | Not Necessary | 0.00 F     | *- FL        |
| 59  | 1   |          | *BONNET HINGE (RH) (NPA)                                 | Not Necessary | 0.00 F     | *- FL        |
| 60  | 1   |          | *BONNET INSULATOR (NPA)                                  | Not Necessary | 0.00 F     | *- FL        |
| 61  | 1   |          | *BONNET AIR DUCT (NPA)                                   | Not Necessary | 0.00 F     | *- FL        |
| 62  | 1   |          | *BONNET WEATHER STRIP (LH)                               | Necessary     | 28.60 F    | *28.60 FL    |
| 63  | 1   |          | *BONNET WEATHER STRIP (RH)                               | Necessary     | 28.60 F    | *28.60 FL    |
| 64  | 1   |          | *BONNET NOZZLE (LH) (NPA)                                | Not Necessary | 0.00 F     | *- FL        |
| 65  | 1   |          | *BONNET NOZZLE (RH) (NPA)                                | Not Necessary | 0.00 F     | *- FL        |
| 66  | 1   |          | *HEAD LAMP (LH)                                          | Cracked       | 410.00 F   | *344.70 FL   |
| 67  | 1   |          | *HEAD LAMP (RH)                                          | Cracked       | 410.00 F   | *344.70 FL   |
| 68  | 1   |          | *HEAD LAMP BRACKET (LH)                                  | Broken        | 50.00 F    | *37.50 FL    |
| 69  | 1   |          | *HEAD LAMP BRACKET (RH)                                  | Broken        | 50.00 F    | *37.50 FL    |
| 70  | 1   |          | *HEAD LAMP PANEL (LH)                                    | Repair        | 390.00 F   | *- FL        |
| 71  | 1   |          | *HEAD LAMP PANEL (RH)                                    | Bent          | 390.00 F   | *85.00 FL    |
| 72  | 1   |          | *FRONT FENDER (LH)                                       | Not Necessary | 325.00 F   | *- FL        |
| 73  | 1   |          | *FRONT FENDER (RH)                                       | Dented        | 325.00 F   | *325.00 FL   |
| 74  | 1   |          | *FRONT FENDER INNER SHIELD (LH) (NPA)                    | Not Necessary | 0.00 F     | *- FL        |
| 75  | 1   |          | *FRONT FENDER INNER SHIELD (RH) (NPA)                    | Not Necessary | 0.00 F     | *- FL        |
| 76  | 1   |          | *FRONT FENDER QTR GARNISH (RH)                           | Cut           | 58.70 F    | *58.70 FL    |
| 77  | 1   |          | *FRONT DOOR (RH) (NPA)                                   | Repair        | 0.00 F     | *- FL        |
| 78  | 1   |          | *FRONT DOOR CHECKER (RH) (NPA)                           | Not Necessary | 0.00 F     | *- FL        |
| 79  | 1   |          | *FRONT DOOR HINGE BOTTOM (NPA)                           | Not Necessary | 0.00 F     | *- FL        |
| 80  | 1   |          | *FRONT DOOR HINGE UPPER (NPA)                            | Not Necessary | 0.00 F     | *- FL        |
| 81  | 1   |          | *FRONT SUPPORT TOP PANEL                                 | Bent          | 317.00 F   | *317.00 FL   |
| 82  | 1   |          | *FRONT SUPPORT PANEL TOP GARNISH                         | Dislodged     | 88.50 F    | *88.50 FL    |
| 83  | 1   |          | *A/C CONDENSER                                           | Bent          | 490.00 F   | *490.00 FL   |
| 84  | 1   |          | *RADIATOR                                                | Bent          | 1,409.20 F | *1,019.00 FL |
| 85  | 1   |          | *A/C CONDENSER DISCHARGE PIPE                            | Bent          | 112.30 F   | *39.00 FL    |
| 86  | 1   |          | *A/C CONDENSER RETURN PIPE                               | Bent          | 124.60 F   | *29.00 FL    |
| 87  | 1   |          | *SET RADIATOR FAN MOTOR & COWLING                        | Broken        | 590.00 F   | *350.00 FL   |
| 88  | 1   |          | *SET A/C FAN MOTOR & COWLING                             | Broken        | 490.00 F   | *350.00 FL   |
| 89  | 1   |          | *RADIATOR SPARE TANK (NPA)                               | Not Necessary | 0.00 F     | *- FL        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                     | Condition     | Repairer's | Amount     |
|-----|-----|----------|-------------------------------------------------|---------------|------------|------------|
| 90  | 1   |          | *WIPER TANK (NPA)                               | Not Necessary | 0.00 F     | *- FL      |
| 91  | 1   |          | *WIPER TANK MOTOR (NPA)                         | Not Necessary | 0.00 F     | *- FL      |
| 92  | 1   |          | *RADIATOR BRACKET (LH) (NPA)                    | Not Necessary | 0.00 F     | *- FL      |
| 93  | 1   |          | *RADIATOR BRACKET (RH) (NPA)                    | Not Necessary | 0.00 F     | *- FL      |
| 94  | 1   |          | *A/C CONDENSER BRACKET (LH) (NPA)               | Not Necessary | 0.00 F     | *- FL      |
| 95  | 1   |          | *A/C CONDENSER BRACKET (RH) (NPA)               | Not Necessary | 0.00 F     | *- FL      |
| 96  | 1   |          | *FRONT BUMPER UNDERCOVER                        | Broken        | 28.00 F    | *28.00 FL  |
| 97  | 1   |          | *SET REVERSE SENSOR HARNESS WIRE                | Not Necessary | 300.00 F   | *- FL      |
| 98  | 1   |          | *SET REAR BUMPER CLIP                           | Necessary     | 50.00 FS   | *30.00 FS  |
| 99  | 1   |          | *SET BOOTLID INSULATOR CLIP                     | Not Necessary | 50.00 FS   | *- FS      |
| 100 | 1   |          | *BOOTLID LOGO EMBLEM                            | Necessary     | 90.00 FS   | *90.00 FS  |
| 101 | 1   |          | *SET TAIL LAMP CLIP (LH) & (RH)                 | Necessary     | 40.00 FS   | *20.00 FS  |
| 102 | 1   |          | *SET END PANEL TOP GARNISH CLIP                 | Necessary     | 30.00 FS   | *20.00 FS  |
| 103 | 1   |          | *SET REAR FENDER INNER TRIM CLIP (LH)           | Not Necessary | 45.00 FS   | *- FS      |
| 104 | 1   |          | *SET REAR FENDER INNER TRIM CLIP (RH)           | Necessary     | 45.00 FS   | *30.00 FS  |
| 105 | 1   |          | *TROLLEY                                        | Not Necessary | 200.00 FS  | *- FS      |
| 106 | 1   |          | *END PANEL SEALANT }                            | Necessary     | 50.00 FS   | *60.00 FS  |
| 107 | 1   |          | *SPARE TYRE PANEL SEALANT }                     |               | 50.00 FS   | *- FS      |
| 108 | 1   |          | *SPARE TYRE PANEL INSULATOR MAT                 | Necessary     | 280.00 FS  | *180.00 FS |
| 109 | 1   |          | *SET REAR EXHAUST MOUNTING                      | Necessary     | 180.00 FS  | *80.00 FS  |
| 110 | 1   |          | *REAR NUMBER PLATE                              | Not Necessary | 60.00 FS   | *- FS      |
| 111 | 1   |          | *FRONT NUMBER PLATE & CASING                    | Broken        | 50.00 FS   | *40.00 FS  |
| 112 | 1   |          | *SET FRONT BUMPER CLIP                          | Necessary     | 50.00 FS   | *30.00 FS  |
| 113 | 1   |          | *SET SUPPORT PANEL TOP GARNISH CLIP             | Necessary     | 30.00 FS   | *30.00 FS  |
| 114 | 1   |          | *SET FRONT BUMPER UNDER COVER CLIP              | Necessary     | 45.00 FS   | *30.00 FS  |
| 115 | 1   |          | *SET BONNET INSULATOR CLIP                      | Not Necessary | 35.00 FS   | *- FS      |
| 116 | 1   |          | *SET BONNET AIR DUCT CLIP                       | Not Necessary | 35.00 FS   | *- FS      |
| 117 | 1   |          | *SET FRONT FENDER INNER SHIELD CLIP (LH)        | Not Necessary | 45.00 FS   | *- FS      |
| 118 | 1   |          | *SET FRONT FENDER INNER SHIELD CLIP (RH)        | Necessary     | 45.00 FS   | *30.00 FS  |
| 119 | 1   |          | *HORN                                           | Scratched     | 120.00 FS  | *40.00 FS  |
| 120 | 1   |          | *ENGINE COOLANT                                 | Necessary     | 100.00 FS  | *60.00 FS  |
| 121 | 1   |          | *SET A/C CONDENSER ORING                        | Necessary     | 30.00 FS   | *30.00 FS  |
| 122 | 1   |          | *AUTO TRANSMISSION FLUID 1 LITRE                | Necessary     | 60.00 FS   | *40.00 FS  |
| 123 | 1   |          | *SUPPORT PANEL LOWER AIR DUCT                   | Cracked       | 228.00 F   | *135.00 FL |
| 124 | 1   |          | *SET REVERSE SENSOR HARNESS WIRE (LOCAL REPAIR) | Necessary     | 360.00 FS  | *150.00 FS |
| 125 | 1   |          | *SUNDRIES                                       | Not Necessary | 50.00 FS   | *- FS      |
| 126 | 1   |          | *FRONT FENDER QTR GARNISH (LH)                  | Not Necessary | 58.70 F    | *- FL      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 18,326.70 11,614.10  
 - List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 1,988.82

Total Parts (\$\$) 18,326.70 9,625.28

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                | Lab.Type | Repairer's      | Amount          |
|--------------------------------|--------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                            |          |                 |                 |
| 1                              | TO R&R REAR BUMPER REVERSE SENSOR          | New      | 80.00           | 60.00           |
| 2                              | TO CHECK WIRING & LIGHTING SYSTEM }        | New      | 100.00          | 60.00           |
| 3                              | TO CONDUCT HEAD LAMP FOCUS }               | New      | 100.00          | 0.00            |
| 4                              | TO R&R REAR TRIMS, GARNISH & SEAT ASSY     | New      | 200.00          | 100.00          |
| 5                              | TO R&R REAR EXHAUST ASSY                   | New      | 250.00          | 120.00          |
| 6                              | TO R&R FUEL TANK TO CUT & WELD             | New      | 350.00          | 0.00            |
| 7                              | TO R&R RADIATOR, A/C CONDENSER ASSY        | New      | 350.00          | 150.00          |
| 8                              | TO VACUUM & TOP UP 134A REFRIGERANTS       | New      | 120.00          | 120.00          |
| 9                              | TO STRAIGHTEN REAR RH CHASSIS MEMBER       | New      | 350.00          | 0.00            |
| 10                             | TO REPAIR, REPLACE & REALIGN DAMAGED AREAS | New      | 2,000.00        | 1,400.00        |
| 11                             | TO SPRAY PAINTING ON AFFECTED AREAS        | New      | 1,800.00        | 1,200.00        |
| 12                             | TO CAR WASH & POLISH VEHICLE AFTER REPAIR  | New      | 150.00          | 0.00            |
| 13                             | TO PERFORM WATER SEEPAGE TEST AFTER REPAIR | New      | 180.00          | 0.00            |
| <b>Gross Labour Cost (S\$)</b> |                                            |          | <b>6,030.00</b> | <b>3,210.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >