

ASS. REC. BY:

REF:

08/C7119002537/Usd3/12

Special Instruction:

Surveyor:

MARCUS

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

C71

Date/Time: 11/2/19 @ 5:50pm

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJJ1685X

Insured:

SJT 9354X

at Workshop m/s

Joo Hak Kee

Tel:

6743 1913

of

3007 ubi Road 1 # 01-406

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 01/02/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12/2/19 @ 9:14am

Person Contacted:

Grace

Vehicle: ~~IN~~ / OUT

Date/Time

Action/Instruction (☒) Estimate

SJJ1685X - CS/MSG17018384/Aqbn2

DUA: 22/4/17

SJT 9354X - ~~X~~

REF: CTI

ASSIGNMENT

Date: 12/02/19

Veh No: SJJ1685X Page: 9 of 9

Type: Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or: CA /
Make: Toyota ALLION cc: 1496

Colour: Red AC: Insured / Std / NI / NA

Sp. Reading: 135709 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 27 T260303 / 284

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front: R/Bal: 6 mm Rear: 6 mm

L/Bal: 6 mm D.O.A. D.O.I. 12/2/19

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The D/C / Chassis frame / Body Structure affected due to collision.

Estimated Cost

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJJ 1685X
Joo Huk Kee

at Workshop no:

3007 Ubi Road 1 #01-406

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

48

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repair:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS.

1 up cor 1/9/2028

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

214 30896

27/2/19 2/5 @ 5850 confirmed with grace.
(\$ 10,506.65 Red - 64%)

RECEIVED 28 FEB 2019

Date/Time, File Pass to?

28/02/19

1)

Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / LB: 5,850/- 45

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp. (\$

☐ Interview (\$

☐ Tech. Inv. (\$

☐ Weekend (\$

Survey Fee:

Transportation:

1. 500.00

2. Hotel:

3. Other:

4. TOTAL:

220

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Monday, 11 February 2019 5:50 PM
To: assignments
Subject: FW: New Third Party Claim - SJJ1685X / SJJ9354X on 01/02/2019

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Grace Lim <grace@jkh.com.sg>
Sent: Monday, 11 February 2019 5:33 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: Re: New Third Party Claim - SJJ1685X / SJJ9354X on 01/02/2019

Dear Boon Sen,

Name of Workshop: Joo Hak Kee Auto Pte Ltd
Contact: 67431913

Cheers,

Grace Lim

Joo Hak Kee Auto Pte Ltd

3007 Ubi Road 1 #01-406 Singapore 408701

O: 6743 1913 | F: 6743 5234 | E: grace@jkh.com.sg

On Mon, Feb 11, 2019 at 5:12 PM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without Prejudice

Dear Grace,

Pls provide necessary workshop contact details etc.

Dear LKK,

Pls pri.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Grace Lim [mailto:grace@jhk.com.sg]

Sent: Monday, 11 February, 2019 4:59 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: New Third Party Claim - SJJ1685X / SJT9354X on 01/02/2019

Dear Boon Sen,

kindly arrange for Mr Marcus Chua from LKK, thanks!

Cheers,

Grace Lim

Joo Hak Kee Auto Pte Ltd

3007 Ubi Road 1 #01-406 Singapore 408701

O: 6743 1913 | F: 6743 5234 | E: grace@ihk.com.sg

On Mon, Feb 11, 2019 at 4:56 PM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Grace Lim [mailto:grace@jhk.com.sg]
Sent: Monday, 11 February, 2019 4:51 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Re: New Third Party Claim - SJJ1685X / SJT9354X on 01/02/2019

Dear Boon Sen,

Happy Chinese New Year!

Dropping in a second reminder to follow up on the list of surveyor pls?

Vehicle is alr in workshop, thanks!

Cheers,

Grace Lim

Joo Hak Kee Auto Pte Ltd

3007 Ubi Road 1 #01-406 Singapore 408701

O: 6743 1913 | F: 6743 5234 | E: grace@jhk.com.sg

On Mon, Feb 11, 2019 at 10:48 AM Grace Lim <grace@jhk.com.sg> wrote:

Dear Sir/Mdm,

Kindly please arrange pre-repair survey for the above and if possible would like to do direct settlement. Car is already in workshop.

Please provide us your list of surveyors for our selection.

Attached are the accident report for your reference and we're currently in the midst of preparing the estimate.

Thank you.

Cheers,

Grace Lim

Joo Hak Kee Auto Pte Ltd

3007 Ubi Road 1 #01-406 Singapore 408701

O: 6743 1913 | F: 6743 5234 | E: grace@jhk.com.sg

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



Owned This Car With Loan Amount As Shown, Monthly Only \$647, High Loan Available, Good Condition, No Repair Needed, Free Road Tax 2019, Call To Make Appointment Now.

Creative Auto

Posted: 29-Jan-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



Toyota Allion 1.5A (COE till 01/2029) \$52,999 \$5,340 /yr 13-Jan-2009 1,496 cc 110,600 km

New 10-Yr COE, Fuel Efficient & Easy To Maintain! Changed New Aircon Compressor, Condenser, Cooling Coil, Absorber, Alternator, Iro Back, Stabilizer Link, Gearbox Gasket. Service Every 8...

Posted: 28-Jan-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



Toyota Allion 1.5A (COE till 02/2028) \$51,800 \$5,720 /yr 14-Apr-2008 1,496 cc 135,608 km

Just Arrived! Nice Plate Number Of 5888 Well Maintained By Previous Owner! High Loan With High Trade In Available. Price Negotiable. Visit Our Showroom Today.

Car House Pte Ltd

Posted: 25-Jan-2019 Tags: 2008 Toyota Allion, 2008 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



Toyota Allion 1.5A (COE till 01/2024) \$29,800 \$6,070 /yr 09-Jan-2009 1,496 cc 130,000 km

Full Loan Amount Stated. Monthly At \$698. Per Day \$24 Only! Cheaper Than Rental! Pristine Exterior With Well Kept Interior. Warranty Extra Peace Of Mind. One Of The Most Popular Japanese...

Creative Auto

Posted: 18-Jan-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



Toyota Allion 1.5A (New 5-yr COE) \$30,800 \$6,160 /yr 29-Dec-2008 1,496 cc 97,000 km

100% Immediate Loan Approval Package! Additional 6 Months Warranty And Road Tax For You! 1 Doctor Owner Unit With No Accident Zero Repairs Needed! Priced Lowest In The Market! Superbly We...

Posted: 12-Jan-2019 Tags: 2008 Toyota Allion, 2008 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



Toyota Allion 1.5A (New 5-yr COE) \$31,800 \$6,360 /yr 13-Jan-2009 1,496 cc 83,000 km

100% Approval Rate! Zero Repair Needed. Weekend Point To Point Car With Low Mileage Done. Nicely Done Up New Pearl White Paint. Rental Unit! Free 6 Months Road Tax, 1st Grooming And Serv...

Posted: 12-Jan-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



Sell to direct buyers at the price you want!

Make the choice to sell only if the price meets your expectations. Contact our agents to find out how to list on consignment.

Find out more!



Toyota Allion 1.5A (New 5-yr COE) \$31,600 \$6,320 /yr 05-Feb-2009 1,496 cc -

Excellent And Original Condition, Well Maintained Interior And Exterior, With New 5 Years COE, Call Now For Viewing.

Posted: 30-Dec-2018 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



Toyota Allion 1.5A (COE till 09/2023) \$31,000 \$6,700 /yr 29-Sep-2008 1,496 cc -

Just Arrived! Well Maintained By Previous Owner! High Loan With High Trade In Available. Price Negotiable. Call Now Or Visit Our Show

Posted: 28-Dec-2018 Tags: 2008 Toyota Allion, 2008 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota

Compare

Save this search criteria, to get email alerts whenever a match is found.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4966G
Vehicle Details	
Vehicle No.:	SJJ1685X
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	ALLION 1.5 A
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	1NZD160460
Chassis No.:	NZT2603031284
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$14,571.00
Original Registration Date:	02 Sep 2008
First Registration Date:	02 Sep 2008
Transfer Count:	2
Actual ARF Paid:	\$14,571.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	01 Sep 2028
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$32,339.00
COE Rebate Amount:	\$30,896.00
Total Rebate Amount:	\$30,896.00

The information contained herein is correct as at 12 Feb 2019

OK



JOO HAK KEE AUTO PTE LTD

裕合记汽车私人有限公司

SINCE 1986

ATTN: MOTOR CLAIMS DEPARTMENT
OWNER: CHUA CHONG MENG VINCENT
INSURER: NTUC INCOME INSURANCE CO-OPERATIVE LTD
POLICY NO: 5083745596-02
REFERENCE: TP CLAIM
DOA: 01/02/2019

REPAIR ESTIMATE

Est. No. : E19020001
Date : 11/02/2019
Vehicle Num. : SJJ1685X
Make/Model : TOYOTA ,ALLION
Chassis/Eng# : NZT2603031284

No	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	FRONT BUMPER <i>Dis</i> ✓	1.00	0.00	0.00
2	FRONT BUMPER RH FOG LAMP <i>320</i> ✓	1.00	0.00	0.00
3	FRONT BUMPER RH FOG LAMP COVER <i>320</i> ✓	1.00	0.00	0.00
4	FRONT BUMPER SPONGE <i>To...</i> ✓	1.00	0.00	0.00
5	FRONT BUMPER REINFORCEMENT <i>Bel</i> ✓	1.00	0.00	0.00
6	FRONT BUMPER SIDE RETAINER <i>Bel</i> ✓	2.00	0.00	0.00
7	FRONT BUMPER CLIPS (SET) <i>neu</i> ✓	1.00	0.00	0.00
8	FRONT BUMPER LOWER GRILLE <i>14 X</i>	1.00	0.00	0.00
9	FRONT GRILLE <i>one</i> ✓	1.00	0.00	0.00
10	FRONT LOGO EMBLEM <i>neu</i> ✓	1.00	0.00	0.00
11	RH HEADLAMP <i>320</i> ✓	1.00	0.00	0.00
12	WIPER WASHER TANK <i>Dis</i> ✓	1.00	0.00	0.00
13	WIPER WASHER MOTOR <i>Daye</i> ✓	1.00	0.00	0.00
14	FRONT SUPPORT PANEL <i>24/7.11</i> ✓	1.00	0.00	0.00
15	BONNET <i>320</i> ✓	1.00	0.00	0.00
16	BONNET INNER LOCK <i>neu</i> ✓	1.00	0.00	0.00
17	BONNET BLACK STICKER (SET) <i>neu 1505.2</i>	1.00	0.00	0.00
18	STEERING RACK & PINION <i>R X</i>	1.00	0.00	0.00
19	RH FRONT FENDER <i>320</i> ✓	1.00	0.00	0.00
20	RH FRONT FENDER <i>inner shield To...</i> ✓	1.00	0.00	0.00
21	INNER SHIELD	1.00	0.00	0.00
22	RH FRONT FENDER <i>Repaired X</i>	1.00	0.00	0.00
23	INNER SHIELD CLIPS (SET) <i>neu</i> ✓	1.00	0.00	0.00
24	RH FRONT DOOR <i>R X</i>	1.00	0.00	0.00

Surveyed by/Company :

Contact Number :

Date/Time :

Licensed Automotive Surveyor's Sign :

Continue on next page...

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: CHUA CHONG MENG VINCENT
 INSURER: NTUC INCOME INSURANCE CO-OPERATIVE LTD
 POLICY NO: 5083745596-02
 REFERENCE: TP CLAIM
 DOA: 01/02/2019

REPAIR ESTIMATE

Est. No. : E19020001
 Date : 11/02/2019
 Vehicle Num. : SJJ1685X
 Make/Model : TOYOTA ,ALLION
 Chassis/Eng# : NZT2603031284

No	Description	Qty	U/P	Amt
25	RH FRONT FENDER HOUSING PANEL <i>2 X</i>	1.00	0.00	0.00
26	RH FRONT SPORTS RIM <i>647 3505.0</i>	1.00	0.00	0.00
27	RH FRONT TYRE <i>8ul X</i>	1.00	0.00	0.00
28	RH FRONT SHOCK ABSORBER <i>1 1 X</i>	1.00	0.00	0.00
29	RH FRONT KNUCKLE ARM <i>1 1 X</i>	1.00	0.00	0.00
30	RH FRONT WHEEL HUB WITH BEARING <i>1 1 X</i>	1.00	0.00	0.00
31	RH FRONT LOWER ARM <i>1 1 X</i>	1.00	0.00	0.00
32	STABILIZER BAR <i>1 1 X</i>	1.00	0.00	0.00
33	STABILIZER BAR RH LINK <i>1 1 X</i>	1.00	0.00	0.00

Amt S\$ 0.00
 Discount (25.00%) S\$ 0.00
 Subtotal S\$ 0.00

Section: LABOUR

34	TO PANEL BEAT AND RENEWAL OF ALL DAMAGED PARTS	1.00	1,560.00	1,560.00 <i>800</i>
35	TO PUTTY & SPRAY PAINTING ON ACCIDENT DAMAGED PROTION	1.00	1,440.00	1,440.00 <i>1000</i>
36	TO ANTI-RUST	1.00	150.00	150.00 <i>80</i>
37	TO WIRING	1.00	60.00	60.00 <i>30</i>
38	TO ALIGN HEAD LAMP	1.00	60.00	60.00 <i>✓</i>
39	TO PERFORM 4 WHEEL ALIGNMENT	1.00	120.00	120.00 <i>✓</i>
40	TO REMOVE AND REINSTALL RADIATOR & AIRCON CONDENSER	1.00	160.00	160.00 <i>✓</i>
41	TO TOP UP AIR CON GAS	1.00	120.00	120.00 <i>✓</i>
42	TO REMOVE AND REINSTALL RH FRONT DOOR	1.00	80.00	1780.00 <i>X</i>
43	TO REMOVE AND REINSTALL UNDERCARRIAGE	1.00	350.00	350.00 <i>120</i>

Continue on next page...

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: CHUA CHONG MENG VINCENT
 INSURER: NTUC INCOME INSURANCE CO-OPERATIVE LTD
 POLICY NO: 5083745596-02
 REFERENCE: TP CLAIM
 DOA: 01/02/2019

REPAIR ESTIMATE

Est. No. : E19020001
Date : 11/02/2019
Vehicle Num. : SJJ1685X
Make/Model : TOYOTA ,ALLION
Chassis/Eng# : NZT2603031284

No	Description	Qty	U/P	Amt
				Amt S\$ 4,100.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 4,100.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LIST ITEMS Subtotal S\$ 0.00
LABOUR Subtotal S\$ 4,100.00
Total S\$ 4,100.00

Joo Hak Kee Auto Pte. Ltd.

BLK 3007 UBI ROAD 1 #01-406, SINGAPORE 408701
 BLK 3014 UBI ROAD 1 #01-324, SINGAPORE 408702

TEL: 6743 1913 FAX: 6743 5234
 EMAIL: admin@jhk.com.sg

CO/GST REG NO: 201300082W
 WEBSITE: www.jhk.com.sg

bizSAFE

Not Authorized
 16th
 2/5 35810/
 5 day.
 The phl. Office
 12/2/19

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: CHUA CHONG MENG VINCENT
 INSURER: NTUC INCOME INSURANCE CO-OPERATIVE LTD
 POLICY NO: 5083745596-02
 REFERENCE: TP CLAIM
 DOA: 01/02/2019

REPAIR ESTIMATE

Est. No. : E19020001
 Date : 11/02/2019
 Vehicle Num. : SJJ1685X
 Make/Model : TOYOTA ALLION
 Chassis/Eng# : NZT2603031284

No	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	FRONT BUMPER	1.00	1,044.35	1,044.35 ✓
2	FRONT BUMPER RH FOG LAMP	1.00	210.25	210.25 ✓
3	FRONT BUMPER RH FOG LAMP COVER	1.00	69.10	69.10 ✓
4	FRONT BUMPER SPONGE	1.00	100.40	100.40 ✓
5	FRONT BUMPER REINFORCEMENT	1.00	397.10	397.10 ✓
6	FRONT BUMPER SIDE RETAINER	2.00	65.90	131.80 ✓
7	FRONT BUMPER CLIPS (SET)	1.00	12.10	12.10 ✓
8	FRONT BUMPER LOWER GRILLE	1.00	145.10	145.10 X
9	FRONT GRILLE	1.00	349.10	349.10 ✓
10	FRONT LOGO EMBLEM	1.00	65.90	65.90 ✓
11	RH HEADLAMP	1.00	809.10	809.10 ✓
12	WIPER WASHER TANK	1.00	124.10	124.10 ✓
13	WIPER WASHER MOTOR	1.00	210.10	210.10 ✓
14	FRONT SUPPORT PANEL	1.00	819.10	819.10 ✓
15	BONNET	1.00	707.10	707.10 ✓
16	BONNET INNER LOCK	1.00	76.30	76.30 ✓
17	BONNET BLACK STICKER (SET)	1.00	180.00	180.00 ✓
18	STEERING RACK & PINION	1.00	5,640.45	5,640.45 X
19	RH FRONT FENDER	1.00	701.10	701.10 ✓
20	INNER SHIELD	1.00	124.90	124.90 ✓
21	RH FRONT FENDER	1.00	124.90	124.90 X
22	INNER SHIELD CLIPS (SET)	1.00	12.90	12.90 ✓
23	RH FRONT DOOR	1.00	1,004.95	1,004.95 X
24	RH FRONT FENDER HOUSING PANEL	1.00	606.10	606.10 X

Continue on next page...

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: CHUA CHONG MENG VINCENT
 INSURER: NTUC INCOME INSURANCE CO-OPERATIVE LTD
 POLICY NO: 5083745596-02
 REFERENCE: TP CLAIM
 DOA: 01/02/2019

REPAIR ESTIMATE

Est. No. : E19020001
 Date : 11/02/2019
 Vehicle Num. : SJJ1685X
 Make/Model : TOYOTA ,ALLION
 Chassis/Eng# : NZT2603031284

No	Description	Qty	U/P	Amt
25	RH FRONT SPORTS RIM	1.00	280.00	280.00 ✓
26	RH FRONT TYRE	1.00	125.00	125.00 X
27	RH FRONT SHOCK ABSORBER	1.00	517.10	517.10 X
28	RH FRONT KNUCKLE ARM	1.00	499.10	499.10 ✓
29	RH FRONT WHEEL HUB WITH BEARING	1.00	210.10	210.10 ✓
30	RH FRONT LOWER ARM	1.00	599.40	599.40 X
31	STABILIZER BAR	1.00	266.10	266.10 X
32	STABILIZER BAR RH LINK	1.00	124.10	124.10 X
33	SPARE TANK JOINT	1.00	55.00	55.00 X

Amt S\$ 16,342.20
 Discount (25.00%) S\$ 999.99
 Subtotal S\$ 15,342.21
 16,342.20
 999.99
 15,342.21

Section: LABOUR

34	TO PANEL BEAT AND RENEWAL OF ALL DAMAGED PARTS	1.00	1,560.00	1,560.00 800
35	TO PUTTY & SPRAY PAINTING ON ACCIDENT DAMAGED PROTION	1.00	1,440.00	1,440.00 1000
36	TO ANTI-RUST	1.00	150.00	150.00 80
37	TO WIRING	1.00	60.00	60.00 30
38	TO ALIGN HEAD LAMP	1.00	60.00	60.00 ✓
39	TO PERFORM 4 WHEEL ALIGNMENT	1.00	120.00	120.00 ✓
40	TO REMOVE AND REINSTALL RADIATOR & AIRCON CONDENSER	1.00	160.00	160.00 } 100
41	TO TOP UP AIR CON GAS	1.00	120.00	120.00 X
42	TO REMOVE AND REINSTALL RH FRONT DOOR	1.00	80.00	80.00 11
43	TO REMOVE AND REINSTALL UNDERCARRIAGE	1.00	350.00	350.00 120

Continue on next page...

13,287.73
 1,862.



JOO HAK KEE AUTO PTE LTD

裕合记汽车私人有限公司

SINCE 1986

ATTN: MOTOR CLAIMS DEPARTMENT
OWNER: CHUA CHONG MENG VINCENT
INSURER: NTUC INCOME INSURANCE CO-OPERATIVE LTD
POLICY NO: 5083745596-02
REFERENCE: TP CLAIM
DOA: 01/02/2019

REPAIR ESTIMATE

Est. No. : E19020001
Date : 11/02/2019
Vehicle Num. : SJJ1685X
Make/Model : TOYOTA ,ALLION
Chassis/Eng# : NZT2603031284

No	Description	Qty	U/P	Amt
				Amt S\$ 4,100.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 4,100.00



Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal S\$ 12,256.65
LABOUR Subtotal S\$ 4,100.00
Total S\$ 16,356.65

BLK 3007 UBI ROAD 1 #01-406, SINGAPORE 408701
BLK 3014 UBI ROAD 1 #01-324, SINGAPORE 408702

TEL: 6743 1913 FAX: 6743 5234
EMAIL: admin@jhk.com.sg

CO/GST REG NO: 201300082W
WEBSITE: www.jhk.com.sg

bizSAFE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119002537/USD3N2

Date: 01/03/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SJJ1685X	Insured Vehicle No :	SJT9354X
Date of Loss:	01/02/2019	Nature of Claim:	TP
		Claim No:	DMPCSN30909118011

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ1685X	Engine No:	1NZD160460
Make & Model:	TOYOTA ALLION, 1.5 (A)	Chassis No:	NZT2603031284
Reg. Date:	02/09/2008 (Man. Year: 2008)	Odometer:	135709 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,256.65	5,078.74	7,177.91	58.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,100.00	2,250.00	1,850.00	45.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,356.65	7,328.74	9,027.91	55.19
Approved Total (Overridden) (\$\$)		5,850.00		
(\$\$)	16,356.65	5,850.00	10,506.65	64.23
+ GST 7.00/7.00% (\$\$)	1,144.97	409.50	735.47	64.23
Nett Amount (\$\$)	17,501.62	6,259.50	11,242.12	64.23

INSPECTION

Date of Assignment:	28/02/2019		
Date Inspected:	12/02/2019	Inspected At:	Joo Hak Kee Auto Pte Ltd (HQ) Blk 3007 Ubi Road 1, #01-406 Singapore 408701
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Mar 2019)
Parts: 143	TOYOTA ALLION 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJJ1685X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,044.35 FL	*682.00 FL
2	1		*FRONT BUMPER RH FOG LAMP	Broken	210.25 FL	*210.25 FL
3	1		*FRONT BUMPER RH FOG LAMP COVER	Broken	69.10 FL	*69.10 FL
4	1		*FRONT BUMPER SPONGE	Torn	100.40 FL	*100.40 FL
5	1		*FRONT BUMPER REINFORCEMENT	Bent	397.10 FL	*397.10 FL
6	2		*FRONT BUMPER SIDE RETAINER	Bent	131.80 FL	*131.80 FL
7	1		*SET FRONT BUMPER CLIPS	Necessary	12.10 FL	*12.10 FL
8	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	145.10 FL	*- FL
9	1		*FRONT GRILLE	Cracked	349.10 FL	*349.10 FL
10	1		*FRONT LOGO EMBLEM	Necessary	65.90 FL	*65.90 FL
11	1		*RH HEADLAMP	Broken	809.10 FL	*809.10 FL
12	1		*WIPER WASHER TANK	Distorted	124.10 FL	*124.10 FL
13	1		*WIPER WASHER MOTOR	Damaged	210.10 FL	*210.10 FL
14	1		*FRONT SUPPORT PANEL	Bent/Twisted	819.10 FL	*819.10 FL
15	1		*BONNET	Buckled	707.10 FL	*707.10 FL
16	1		*BONNET INNER LOCK	Twisted	76.30 FL	*76.30 FL
17	1		*SET BONNET BLACK STICKER	Necessary	180.00 FL	*180.00 FL
18	1		*STEERING RACK & PINION	Repair	5,640.45 FL	*- FL
19	1		*RH FRONT FENDER	Buckled	701.10 FL	*701.10 FL
20	1		*INNER SHIELD	Torn	124.90 FL	*124.90 FL
21	1		*RH FRONT FENDER	Repeated	124.90 FL	*- FL
22	1		*SET INNER SHIELD CLIPS	Necessary	12.90 FL	*12.90 FL
23	1		*RH FRONT DOOR	Repair	1,004.95 FL	*- FL
24	1		*RH FRONT FENDER HOUSING PANEL	Repair	606.10 FL	*- FL
25	1		*RH FRONT SPORTS RIM	Cut	280.00 FL	*280.00 FL
26	1		*RH FRONT TYRE	Serviceable	125.00 FL	*- FL
27	1		*RH FRONT SHOCK ABSORBER	Not Necessary	517.10 FL	*- FL
28	1		*RH FRONT KNUCKLE ARM	Bent	499.10 FL	*499.10 FL
29	1		*RH FRONT WHEEL HUB WITH BEARING	Necessary	210.10 FL	*210.10 FL
30	1		*RH FRONT LOWER ARM	Not Necessary	599.40 FL	*- FL
31	1		*STABILIZER BAR	Not Necessary	266.10 FL	*- FL
32	1		*STABILIZER BAR RH LINK	Not Necessary	124.10 FL	*- FL
33	1		*SPARE TANK JOINT	Not Necessary	55.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	16,342.20	6,771.65
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,085.55	1,692.91
Total Parts (\$\$)	12,256.65	5,078.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT AND RENEWAL OF ALL DAMAGED PARTS	New	1,560.00	800.00
2	TO PUTTY & SPRAY PAINTING ON ACCIDENT DAMAGED PORTION	New	1,440.00	1,000.00
3	TO ANTI-RUST	New	150.00	80.00
4	TO WIRING }	New	60.00	30.00
5	TO ALIGN HEAD LAMP }	New	60.00	0.00
6	TO PERFORM 4 WHEEL ALIGNMENT	New	120.00	120.00
7	TO REMOVE AND REINSTALL RADIATOR & AIRCON CONDENSER }	New	160.00	100.00
8	TO TOP UP AIR CON GAS }	New	120.00	0.00
9	TO REMOVE AND REINSTALL RH FRONT DOOR	New	80.00	0.00
10	TO REMOVE AND REINSTALL UNDERCARRIAGE	New	350.00	120.00
Gross Labour Cost (\$\$)			4,100.00	2,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >