

ASS. REC. BY:

REF:

es/FCI19002543/KISd3/n2

Special Instruction:

Surveyor:

KALVIN

ASSIGNMENT (Office)

From (Person):

Jocanne Yong

of

FCI

Date/Time: 3:33 pm @ 12/2/19

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 69452

Insured:

SHC 8607L

at Workshop m/s

Premier Automotive

Tel:

6544 6689

of

23 chengi south Ave 2 #01-02

Policy No:

Claim No:

D19000958MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/02/2019

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

4:22 pm @ 12/2/19

Person Contacted:

GUY

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 69452 - NA/INC09005153/W/

D.O.A. 8/3/2009

SHC 8607L - CS3/FCI17024389/d3XX

D.O.A. 13/10/17

13/2/19

Email preli revised to FCI

Surveyor: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHC 6495Z Yr Regn: 164, 215
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA optima C.C. 1.6L

Colour: Silver A/C: Ins / Std / NI / NA

Sp. Reading: 313295 T/Radio: Ins / Std / NI / NA

Eng/No: _____

C/No: KNAH M44MF5 639214

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In / Jammed / Leaked / Burnt or

Brake: In / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/65R16

R: 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 1/2/19 D.O.I. 12/4/19

Survey held at Premier

Des. of Damages: Frl / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
18/2/19	Chk 4/5 \$1700/3hr. FCI
	(\$1,377.10 Rd - 45%)

RECEIVED 18 FEB 2019

Date/Time, File Pass to?

18/02/19

1) Typist

Date/Time, File Return to?

2) _____

Report Format:

Lump Sum / I.B.I: (\$ 1,700/- 45)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS: \$ _____

Photos

Others

TOTAL

130
50
50
29
259

MOTOR SURVEY ASSIGNMENT

Date	11-02-2019	Our Ref No. D19000958MFSH
Accident Date	01-02-2019	Claim Type. Third Party
Insured Vehicle	SHC8607L	Third Party Vehicle. SHC6945Z
Survey Location	23 CHANGI SOUTH AVENUE 2 #01-02	
Contact Person.	GARY SHI	
Contact No.	65446676/ 65446689	Fax No. 61241511
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 13 February 2019 12:26 PM
To: 'CWS Motor Claims'
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000958MFSH/1, SHC 6945Z
Attachments: SHC 6945Z PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHC 6945Z
Date of survey: 12/2/2019
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler **on behalf of Shirley**

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 12 February 2019 4:23 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000958MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 12 February 2019 3:33 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joaneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000958MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19000958MFSH

Our ref: CS/FCI19002543/K1sd3

DATE: 13/2/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6945Z


We thank you for your instruction on 12/2/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12/2/2019 at the premises of M/s PREMIER AUTOMOTIVE SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$3,077.10
Revised Estimate Amount	: S\$2,145.90
"Check" Items Amount	: S\$
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s body



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kalvin Ang
Technical Investigator
Technical Investigation & Reconstructionist (SAE-A)

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	16 Oct 2015 / 09:03:31	Receipt No.:	AACCK001-AX239-151016-000011
Asset Type:	Vehicle	Transaction Amount:	\$68,676.00
Asset ID:	SHC6945Z	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20151016090331832259		
Vehicle No.:	SHC6945Z		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	16 Oct 2015		
Original Registration Date:	16 Oct 2015		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5639214		
Engine No.:	D4FDFH314133		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2015		
Open Market Value:	\$22,212.00		
Minimum PARF Benefit:	\$13,858.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	16 Oct 2015 09:03:31		
COE No.:	2015101601003629W		
COE Expiry Date:	15 Oct 2023		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$45,439.00		
Lifespan Expiry Date:	15 Oct 2023		

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

11-Feb-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6945 Z

1 pc	Front o/s door	\$ 761.00
2 pcs	Front o/s door hinges @ \$34.00	\$ 68.00
1 pc	O/s wing mirror assy	\$ 590.00
		\$ 1,419.00
	Less 10%	\$ 141.90
		\$ 1,277.10

S/NETT

1 set	o/s door stickers	\$ 100.00
	Sundry	\$ 50.00
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00
	To dismantle / refit inner components of the front o/s door into new shell door	\$ 150.00
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the o/s windscreen pillar, etc.	\$ 300.00
	To putty and spray painting on front o/s door, o/s windscreen pillar, o/s wing mirror cover	\$ 400.00
	To apply rustproofing on the repaired and replaced panels.	\$ 120.00
		\$ 3,077.10

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Ka Li 16/19
12/2/19 1645L
3 Dyr.
4/5
After Repair ph

...hence notify
...the following:
...survey
...information
...date

Acknowledged by Reparer
Signature:
Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19002543/K1sd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 18-02-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8607L	Veh. Inspected	SHC 6945Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000958MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	12/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5639214	Colour	SILVER	
Odometer	313295	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/02/2019	Inspection Date	12/02/2019	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6945Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT O/S DOOR	DENTED	761.00	761.00
2	FRONT O/S DOOR HINGES @\$34.00	SERVICEABLE	68.00	-
1	O/S WING MIRROR ASSY	BROKEN	590.00	590.00
	LESS 10% DISCOUNT		-141.90	-135.10
			1,277.10	1,215.90
	<u>SPECIAL NETT ITEMS</u>			
1	SET O/S DOOR STICKERS (SN)	NECESSARY	100.00	100.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			150.00	120.00
	<u>LABOUR</u>			
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO DISMANTLE/REFIT INNER COMPONENTS OF THE FRONT O/S DOOR INTO NEW SHELL DOOR.		150.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE O/S WINDSCREEN PILLAR, ETC.		600.00	300.00
	TO PUTTY AND SPRAY PAINTING ON FRONT O/S DOOR, O/S WINDSCREEN PILLAR, O/S WING MIRROR COVER.		600.00	410.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	50.00
			1,650.00	810.00
	GRAND TOTAL		3,077.10	2,145.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,700.00

Report Ref No. CS/FCI19002543/K1sd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.