

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 50474
Date Estimated : 13/03/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Liang Jizhi (LONG JIZHI)
Blk 463B Sembawang Drive
#13-377

Singapore 752463

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD8282A	5H46076	31/03/2017	216d G TOURER	0

DESCRIPTION

To replace tail panel.

VALUE

3,400.00

Painting tail panel and trunk floor.

1145 1,273.00

To carry out body cavity preservation.
(For cut panel).

451 531.00

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230 271.00

Sundries.

70.00

Total Labour 1: 5,545.00

DESCRIPTION

TAIL PANEL

BLIND RIVET AVIBVLB

SCREW (SF PLUS M5X15)

(DG/SL) BODY ADHESIVE K5B (195ML)

PUNCH RIVET N5

(DG) CLEANER R1 (100ML)

PUNCH RIVET N4

(S/L) SEAM SEAL 300ML

QTY PRIC

1 592.25

20 0.55

8 0.55

1 326.80

10 0.55

1 26.15

10 0.55

1 33.80

VALUE

bt 592.25

11.00

4.40

326.80

5.50

26.15

5.50

33.80

Total Parts : 1,005.40

Inthiran 13/3/19

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X**E S T I M A T E**

Estimate No. : **b1 50474**
Date Estimated : **13/03/2019**
Prepared By : **Inthiran A/L Thurasamy**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD8282A	5H46076	31/03/2017	216d G TOURER	0

Labour 1	:	5,545.00
Parts	:	1,005.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	458.53
Grand Total	:	7,008.93

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



11/04 @ 10 am

Survey before 12 pm

Active request car rental with BMW

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

11 FEB 2019

Estimate No. : b1 50053
Date Estimated : 11/02/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- **ESTIMATE REPAIR FOR** -
Liang Jizhi (LONG JIZHI)
Blk 463B Sembawang Drive
#13-377

Singapore 752463

- **ACCOUNT** - **121**
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD8282A	5H46076	31/03/2017	216d G TOURER	0

DESCRIPTIONVALUE

To replace rear bumper, tailgate and attachments.

1720 2,550.00

Painting rear bumper and tailgate.

1730 1,923.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To carry out body cavity preservation.
(Per panel).

600 118.00

Sundries.

7 80.00

Total Labour 1: **4,848.00**DESCRIPTIONQTY PRICVALUE

BOOTLID

1 1,204.35

bt 1,204.35

REAR BUMPER CARRIER

1 458.10

bt 458.10

SUPPORT

1 45.30

45.30

RR BUMPER LH INNER SIDE GUIDE

1 67.55

67.55

RR BUMPER RH INNER SIDE GUIDE

1 67.55

67.55

REAR BUMPER TRIM STRIP (CHROM)

1 107.75

ant 107.75

REAR BUMPER PANEL PRIMED (LINES PDC

1 1,029.50

del 1,029.50

SET MOUNTS PDC SENSOR REAR

1 60.35

60.35

REAR BUMPER TOWING FLAP EYE PRIMED

1 42.85

7 42.85

GROMMET

2 0.75

1.50

PLAQUE 74MM

1 71.25

71.25

REAR RH LIGHT IN THE TRUNK LID

1 255.65

photo 255.65

(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)

2 131.55

263.10

Total Parts : **3,674.80**



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 50053**
Date Estimated : **11/02/2019**
Prepared By : **Inthiran A/L Thurasamy**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD8282A	5H46076	31/03/2017	216d G TOURER	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date & Time 11/3/19 11:40 Excess S\$

Surveyor's Name Tan Jih R Sign [Signature]

Surveyor's Tel 97495449 Authorised Yes / No

Authorised Date WP Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail tanjih.r@hwa.com

No. of Working Days Recommended 5 days + 5 = 10 days

Labour 1	:	4,848.00
Parts	:	3,674.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	596.60
Grand Total	:	9,119.40

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **