

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Feb 2019 Edit Reg		12 Feb 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LIM GECK NGOH , ID: S0175062C									
Main Claimant: KRONOS SERVICES , Co. Reg. No.: -									
Vehicle Reg. No.: GBJ2112X		Date of Loss: 07/02/2019 09:00 - :59 [9 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 5789616116SG		Policy/Cover Note No.: 2100201385-08 (Comprehensive)							
Vehicle Reg. No. (Insured): SJW5641C		Policy No. (Claimant): AVCPSB0095171900							
		Excess:							
Repairer: My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park, 408934 Ubi - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com									
Claimant's Insurer: Allied World Assurance Company, Ltd (HQ) - Tel: 62201188									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/02/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (28/02/2019): Re: SJW5641C - No OI GIA Report - AIG_SG (14/02/2019): No OI GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

***GBJ2112X (5789616116SG)**
[SJW5641C]
TP
KRONOS SERVICES
Feb 7 2019 9:00AM
[LIM GECK NGOH]
My Car Consultant Pte Ltd

Documents Checklist

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_docview&domainid=1&objid=791386&extid=294729&corole... 1/2

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG19002555/GBA3S2**Date:** 13/08/2020**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100201385-08
Claimant Vehicle No :	GBJ2112X	Insured Vehicle No :	SJW5641C
Date of Loss:	07/02/2019	Nature of Claim:	TP
		Claim No:	5789616116SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ2112X		
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Engine No:	1KD2834444
Reg. Date:	29/01/2019 (Man. Year: 2018)	Chassis No:	JTFHT02P800246886
Colour:	Silver	Odometer:	2162 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	12/02/2019	
Date Inspected:	19/02/2019	Inspected At: My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	2.0 days	

Adjuster: XING GUO QIANG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	0.00 F	*- F
F=Franchise part.						
				Total Parts (\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >