



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date: 12 February 2019
 Vehicle: SKA4882J
 Make / Model: HONDA/JAZZ
 Chassis: JHMGD18507S221980

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR BUMPER / <i>re</i>	1	\$ 540.80	495.5
2	TOW COVER X <i>no</i>	1	\$ 17.40	X
3	REAR BUMPER SIDE RETAINER - <i>re.</i>	2	\$ 39.80	/
4	REAR END PANEL ?	1	\$ 465.80	365.9?
5	REAR END PANEL TOP GARNISH X <i>nn</i>	1	\$ 107.90	X
6	REAR LH TAILLAMP - <i>re</i>	1	\$ 306.30	236.2
7	REAR LH TAILLAMP PANEL ?	1	\$ 228.40	146?
8	REAR LH FENDER - <i>buc</i>	1	\$ 837.40	692.5
9	REAR LH FENDER INNER TRIM ?	1	\$ 298.00	?
10	REAR LH FENDER INNER SHIELD - <i>re.</i>	1	\$ 49.90	/
11	REAR LH FENDER AIR GRILLE / <i>re.</i>	1	\$ 61.00	48
12	TAILGATE X <i>repair</i>	1	\$ 908.00	X
13	TAILGATE EMBLEM-JAZZ - <i>re</i>	1	\$ 51.00	42
14	TAILGATE GLASS MOULDING X	2	\$ 110.00	X
15	TAILGATE LOCK X	1	\$ 196.00	X
16	TAILGATE LOCK STRIKER X	1	\$ 59.00	X
17	REAR AXLE BEAM X	1	\$ 1,050.00	X
18	REAR LH SHOCK ABSORBER X	1	\$ 513.20	X
19	REAR LH WHEEL HUB AND BEARING / <i>re</i>	1	\$ 290.00	X
			\$ 6,129.90	1603.9
			Less 20%	\$ 1,225.98
				\$ 4,903.92
				1283.12
S/NETT ITEMS				
20	REAR BUMPER CLIP - <i>re</i>	1 SET	\$ 40.00	30
21	REAR REVERSE SENSOR - <i>re</i>	1 SET	\$ 400.00	200
22	REAR FENDER INNER TRIM CLIP - <i>re</i>	1 SET	\$ 20.00	/
23	JOINT SELANT ?	1	\$ 150.00	? 40
24	WINDSCREEN SEALANT X <i>nn</i>	1	\$ 150.00	X
25	RIM ?	1	\$ 600.00	300
			\$ 1,360.00	550
			Parts Total:	\$ 6,263.92
Labour to:				
25	CHECK REAR WIRING AND LIGHTNING SYSTEM		\$ 60.00	30
26	REMOVE, REFIT REAR LINING, TRIM AND GARNISH		\$ 200.00	60
27	REMOVE AND RENEW REAR REVERSE SENSOR		\$ 150.00	40
28	REFIT REAR WINDSCREEN		\$ 150.00	X
29	TRANSFER PARTS. ATTACHMENT FROM OLD TAILGET TO NEW		\$ 200.00	X
30	CHECK REAR WHEEL ALIGNMENT		\$ 150.00	60
31	REMOVE AND RENEW REAR UNDERCARRIAGE PARTS		\$ 200.00	50
32	PANEL BEATING ON AFFECTED AREAS		\$ 1,200.00	800
33	SPRAY PAINTING ON AFFECTED AREAS		\$ 1,000.00	600

\$	150.00
\$	3,460.00
Grand total:	\$ 9,723.92

60

17.00

2 Days.

Lumpsum repair

After repair photos.

Eno Qiang - 82880282

13/2/19.

3533.12

20% 2800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: