



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date: 12 February 2019
 Vehicle: SKA4882J
 Make / Model: HONDA/JAZZ
 Chassis: JHMGD18507S221980

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR BUMPER <i>- RL</i>	1	\$ 540.80	495.50
2	TOW COVER <i>X NN</i>	1	\$ 17.40	X
3	REAR BUMPER SIDE RETAINER <i>- RL</i>	2	\$ 39.80	/
4	REAR END PANEL <i>X RL</i>	1	\$ 465.80	365.9 X
5	REAR END PANEL TOP GARNISH <i>X NN</i>	1	\$ 107.90	X
6	REAR LH TAILLAMP <i>- RL</i>	1	\$ 306.30	236.2
7	REAR LH TAILLAMP PANEL <i>- RL</i>	1	\$ 228.40	146.7 X
8	REAR LH FENDER <i>- RL</i>	1	\$ 837.40	692.5
9	REAR LH FENDER INNER TRIM <i>- RL</i>	1	\$ 298.00	X
10	REAR LH FENDER INNER SHIELD <i>- RL</i>	1	\$ 49.90	X
11	REAR LH FENDER AIR GRILLE <i>- RL</i>	1	\$ 61.00	48
12	TAILGATE <i>X repair RL</i>	1	\$ 908.00	X
13	TAILGATE EMBLEM-JAZZ <i>- RL</i>	1	\$ 51.00	42
14	TAILGATE GLASS MOULDING <i>X</i>	2	\$ 110.00	X
15	TAILGATE LOCK <i>X</i>	1	\$ 196.00	X
16	TAILGATE LOCK STRIKER <i>X NN</i>	1	\$ 59.00	X
17	REAR AXLE BEAM <i>X NN</i>	1	\$ 1,050.00	X
18	REAR LH SHOCK ABSORBER <i>X</i>	1	\$ 513.20	X
19	REAR LH WHEEL HUB AND BEARING <i>- RL</i>	1	\$ 290.00	X
			\$ 6,129.90	1607.9
			Less 20%	\$ 1,225.98
				\$ 4,903.92
S/NETT ITEMS				
20	REAR BUMPER CLIP <i>- RL</i>	1 SET	\$ 40.00	30
21	REAR REVERSE SENSOR <i>- RL</i>	1 SET	\$ 400.00	200
22	REAR FENDER INNER TRIM CLIP <i>- RL</i>	1 SET	\$ 20.00	/
23	JOINT SELANT <i>X NN</i>	1	\$ 150.00	? 40 X
24	WINDSCREEN SEALANT <i>X NN</i>	1	\$ 150.00	X
25	RIM <i>3 cut</i>	1	\$ 600.00	300
			\$ 1,360.00	550
			Parts Total:	\$ 6,263.92
Labour to:				
25	CHECK REAR WIRING AND LIGHTNING SYSTEM		\$ 60.00	30
26	REMOVE, REFIT REAR LINING, TRIM AND GARNISH		\$ 200.00	60
27	REMOVE AND RENEW REAR REVERSE SENSOR		\$ 150.00	40
28	REFIT REAR WINDSCREEN		\$ 150.00	X
29	TRANSFER PARTS. ATTACHMENT FROM OLD TAILGET TO NEW		\$ 200.00	X
30	CHECK REAR WHEEL ALIGNMENT		\$ 150.00	60
31	REMOVE AND RENEW REAR UNDERCARRIAGE PARTS		\$ 200.00	50
32	PANEL BEATING ON AFFECTED AREAS		\$ 1,200.00	800
33	SPRAY PAINTING ON AFFECTED AREAS		\$ 1,000.00	600

			\$ 150.00	60
		17.00	\$ 3,460.00	
		Grand total:	\$ 9,723.92	

2 Days.

Lump sum repair

After repair photos.

Eno Qiang - 82880282

13/2/19.

3533.12

20%: 2800

L/S = \$ 2,800

7 repair days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: