



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 5034A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	LHR SPORT RIM (K3 L 15" SSW021) (SN)	CUT	320.00	320.00
1	SUNDRIES (SN)	NECESSARY	30.00	20.00
1	FILM-ANTI CHIPPG LH (SN)	CUT	27.00	27.00
			377.00	367.00
	<b><u>LABOUR</u></b>			
	REPAIR & RE-ALIGN LHR DOOR & LHR FENDER.		1,650.00	1,100.00
	RESPRAY LHR DOOR & LHR FENDER.		840.00	840.00
	RENEW LHR SPORT RIM & TRANSFER TYRE.		50.00	30.00
	REMOVE & REFIT TRIM, CARPET & SEAT TO FACILITATE REPAIR.	NOT NECESSARY	120.00	-
	CHECK WIRING ELECTRICAL SYSTEM.		30.00	30.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		200.00	200.00
	APPLY ANTI CORROSION ON AFFECTED AREAS.		80.00	40.00
			2,970.00	2,240.00
	<b>GRAND TOTAL</b>		<b>3,347.00</b>	<b>2,607.00</b>
	<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>			<b>2,607.00</b>

Report Ref No. CS/INC19002572/T1sd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.