

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4494R

DATE : 11.02.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI SONATA

FAX : 6542 6039

India

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Fender (RH) Bnc		\$	593.00
	Front Fender Shield (RH) defmed		\$	174.90
	Front Fender Mudflap (RH) cnt / defmed		\$	16.20
	Front Door (RH) Bnc		\$	2,256.40
	Front Door Rubber defmed		\$	290.50
	Front Door Gear / Regulator (RH) 2 wt		\$	625.00
	Front Door Hinge Upper (RH) 2 WH		\$	51.10
	Front Door Hinge Lower (RH) 2 WH		\$	51.10
	Front Door Check (RH) 2 WH		\$	105.50
	Front Door Trim Board (RH) 2 WH		\$	1,147.00
	Front Door Protector (RH) Bt		\$	78.25
	Door Centre Pillar Outer (RH) Devedd		\$	2,527.80
	Rocker Panel Outer Garnish wt		\$	463.40
	Front Windscreen Glass CRACK		\$	1,017.80
	Front Windscreen Moulding 2 Hlec		\$	113.30
	Front Windscreen Pillar Outer(RH) 2 Bnc		\$	1,766.20
	Front Wheel Rim (RH) 2 distntnl		\$	325.30
	Front Wheel Hub Cap (RH) broken		\$	145.00
	Front Wheel Bearing 2 Dem		\$	540.50
	Front Shock Absorber (Assy) (RH) 2 distntnl		\$	342.20
	Front Shock Absorber Mounting (RH) WH		\$	108.80
	Front Shock Absorber Fork (RH) 2 distntnl		\$	203.30
	Front Suspension Upper Arm (RH) 2 distntnl		\$	240.00
	Front Drive Shaft (RH) 2 Dem		\$	1,030.80
	Rack & Pinion Assy 2 Dem		\$	2,093.00
	STG Tie End 2 distntnl		\$	66.50
	Stabilizer Bar 2 distntnl		\$	252.30
	Stabilizer Bar Bush (RH) WH		\$	16.40
	Stabilizer Bar Link 2 distntnl		\$	78.30
	Stabilizer Bracket WH		\$	24.00
	Front Suspension Lower Arm (RH) 2 distntnl		\$	685.20
	Knuckle Arm (RH) 2 distntnl broken		\$	558.60
	Engine Under Cover WH		\$	334.60
	Engine Crossmember 2 distntnl		\$	2,143.70
	SUB TOTAL		\$	20,465.95
	LESS 20%		\$	4,093.19
	DISCOUNTED TOTAL		\$	16,372.76

SHD 4494R

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Fender Advertisement Logo (RH) <i>Hec</i>			\$ 100.00	Nett ✓
	Front Door Comfort Logo (RH) <i>Hec</i>			\$ 75.00	Nett ✓
	Front Door Advertisement Logo (RH) <i>Hec</i>			\$ 100.00	Nett ✓
	Front Windscreen Sealant <i>Hec</i>			\$ 46.00	Nett ✓
	Front Tyre (RH) <i>Hw</i>			\$ 216.00	Nett X
				\$ 537.00	
	Rear Fender (RH) <i>Deated</i>			\$ 2,171.40	✓
	Rear Fender Inner Lining (RH) <i>Hw</i>			\$ 169.30	X
	Rear Windscreen Moulding <i>Hec</i>			\$ 60.00	✓
	Rear Door (RH) <i>Bot</i>			\$ 2,201.10	✓
	Rear Door Rubber (RH) <i>Hec</i>			\$ 280.50	✓
	Rear Door Protector(RH) <i>Hw</i>			\$ 56.90	X
	Rear Tyre Rim (RH) <i>2 distanced</i>			\$ 325.30	2 ✓
	Rear Wheel Hup-Cap (RH) <i>distanced</i>			\$ 145.00	✓
	Rear Wheelbearing ING & Hub <i>2 Dist</i>			\$ 384.60	2 ✓
	Rear Trailing Arm (RH) <i>2 distanced</i>			\$ 192.00	2 ✓
	Rear Assist (RH) <i>2 distanced</i>			\$ 145.70	2 ✓
	Rear Shock Absorber (RH) <i>2 distanced</i>			\$ 276.30	2 ✓
	Rear Shock Absorber Mounting (RH) <i>Hw</i>			\$ 81.30	X
	Rear Crossmember <i>Hw</i>			\$ 1,140.40	X
	Stabilizer Bar <i>2 distanced</i>			\$ 199.60	2 ✓
	Stabilizer Link <i>2 distanced</i>			\$ 85.90	2 ✓
	Rear Upper Arm (RH) <i>2 distanced</i>			\$ 335.75	2 ✓
	Rear Lower Arm (RH) <i>2 distanced</i>			\$ 353.80	2 ✓
	Rear Knuckle Arm (RH) <i>2 distanced</i>			\$ 550.80	2 ✓
	SUB TOTAL			\$ 9,155.65	
	LESS 20%			\$ 1,831.13	
	DISCOUNTED TOTAL			\$ 7,324.52	
	Rear Fender Advertisement Logo (RH) <i>Hec</i>			\$ 100.00	Nett ✓
	Rear Windscreen Sealant <i>Hec</i>			\$ 46.00	Nett ✓
	Rear Door Advertisement Logo (RH) <i>Hec</i>			\$ 100.00	Nett ✓
	Rear Door Tel No. Sticker (RH) <i>Hec</i>			\$ 10.00	Nett ✓
	Rear Tyre (RH) <i>Hw</i>			\$ 216.00	Nett X
				\$ 472.00	

SHD 4494R

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 2,400.00 1100/-
	Spray Painting Charge			\$ 1,750.00 900/-
	Wiring Charge			\$ 100.00 44
	Tuff Kote			\$ 150.00 40/-
	Towing Charge			\$ 50.00 24
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 44
	Remove/Refix Undercarriage (RR)			\$ 200.00 150/-
	Transfer of Door		\$ 120.00	\$ 240.00 120/-
	Remove/Refix Undercarriage (FRT)			\$ 200.00 150/-
	Four Wheel Alignment			\$ 120.00 60/-
	Remove/Refix Dashboard			\$ 450.00 ?
	Remove/Refix Front Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Cushion & Upholstery Front			\$ 90.00 44
	TOTAL LABOUR			\$ 6,260.00
	ESTIMATE TOTAL			\$ 30,966.28
	13/02/2019 @ 1530w Not Actual 2/Sum 14 days 19an LKK Auto  LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

REPAIR ESTIMATE*

FAX : 6542 6039

Page 1 of 1