



CHEW MOTOR PTE. LTD.

J Kaki Bukit Avenue 6, Blk A #01-11 At Tobay@Kaki Bukit Singapore 417883

Tel: 6509 5545 Fax: 6509 5567

Website: www.chewmotor.com

Registration No : 201718369R

AKG

12/02/2019

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

TP ALA. KDY2318027479.
~~After~~ Sale.

16500

Accident date: 09/02/2019

Estimated repair cost for vehicle no: GBF9168K TOYOTA DYNA 3.0 M 17

CHASSIS: KDY2318027479

S/n	Qty	Items	U/price	Amount
1	1	Rear Tailgate <i>Denied</i>	<i>14 OR</i>	\$1,714.40 <i>1455</i>
3	1	Rear Tailgate Dyna Sticker <i>new</i>		\$40.00 ✓
4	2	Rear Tailgate Top Side Handle <i>Not new</i>	\$187.30	\$374.60 ✓
5	2	Rear Tailgate Lower Side Lock <i>RH Bent</i>	\$171.40	\$342.80 <i>171.40</i>
6	2	Rear Tailgate Lower Side Hinge <i>Bent</i>	\$181.70	\$363.40 <i>126</i>
7	2	Rear Tailgate Lower Side Bracket <i>RH Bent</i>	\$168.60	\$337.20 <i>168.60</i>
8	4	Rear Tailgate Lower Side Rubber Stopper <i>2 pieces Bent</i>	\$31.20	\$124.80 <i>62.40</i>
9	1	Rear Tailgate Lower Member <i>Denied</i>		\$750.00 <i>485</i>
10	2	Rear Tailgate Lower Member Reflector <i>cracked</i>	\$73.00	\$146.00 ✓
11	2	Rear Tail Lamp <i>LH ok, RH cracked</i>	\$327.50	\$655.00 ✓
12	2	Rear Tail Lamp Panel <i>RH Bent</i>	\$374.45	\$748.90 <i>374.45</i>
13	2	Rear Tail Lamp Side Reflector <i>Not new</i>	\$75.00	\$150.00 ✓
14	1	Rear Number Plate Lamp <i>cracked</i>		\$131.35 ✓
15	1	Rear Number Plate Panel <i>Bent</i>		\$127.30 ✓
16	1	Rear Spare Tyre Lock <i>Damaged</i>		\$283.00 ✓
17	1	Rear Exhaust <i>Bent</i>	<i>921</i>	\$980.10 <i>585</i>
18	2	Rear Exhaust Mounting <i>low</i>	\$61.10	\$122.20 <i>35</i>
19	1	Rear Centre Exhaust <i>Bent</i>		\$678.10 ✓
20	1	Rear Floor Panel <i>Repair</i>		\$10,000.00 ✓

Subtotal:- \$18,069.15

5532.60

4149.45

S/N	QTY	ITEMS / Special Nett	U/PRICE	AMOUNT
21	1	Rear Tailgate 70km/H Sticker <i>Nett</i>		\$30.00-15
22	1	Rear Tailgate Body Sticker <i>Nett</i>		\$550.00-200
23	1	Rear Tailgate Aluminium Cover <i>Nett</i>		\$450.00 X
24	100	Rear Tailgate & Floor Panel Aluminium Rivet <i>Nett</i>	\$3.50	\$350.00 X
25	1	Rear Number Plate <i>Carbide</i>		\$50.00 ✓
26	1	Rear Step Panel Bracket <i>Best</i>		\$550.00 200
27	1	Rear Spare Tyre Lock Member <i>Best</i>		\$380.00 ✓
28	1	Rear Floor Panel Aluminium Cover <i>Hot on</i>		\$950.00 ✓
29	1	Rear storage Box <i>Dented</i>		500 350
Subtotal:-				\$3,310.00

1195

Labour charges

To remove & refit rear & centre exhaust	\$380.00	160
To remove & refit aluminium box	\$450.00	X
To remove & refit floor box & repair chassis frame	\$2,800.00	500
To check wiring	\$100.00	30
Towing fee	\$150.00	X
Tuff kote	\$150.00	60
Panel beating	\$2,000.00	1000
Spray painting	\$1,600.00	850
Subtotal:-		\$7,630.00

Total:- \$29,009.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 8144.45
N/S: 65K
08 days

65K
08 days