



新福德車廠私人有限公司

QBE

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

14/02/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPQBE.

Asher.

Accident date: 11/02/2019

Estimated repair cost for vehicle no: SJX9618P TOYOTA PREMIO 1.8X A '09

CHASSIS: ZRT2603042689

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Repair</i>		\$805.00
2	1	Rear Boot Lid Emblem Logo		\$53.00
3	1	Rear Boot Lid Premio Logo		\$60.00
4	1	Rear Boot Lid X Logo		\$60.00
5	1	Rear Boot Lid Center Chrome Moulding <i>new</i>		\$289.00
6	2	Rear Boot Lid Side Reflector <i>new</i>	\$226.00	\$452.00
7	1	Rear Boot Lid Inner Lock <i>new</i>		\$375.00
8	1	Rear Boot Lid Inner Rubber		\$190.00
9	2	Rear Tail Lamp <i>new</i>	\$455.00	\$910.00
10	1	Rear Bumper <i>Defend</i>		\$497.00
11	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00
12	2	Rear Bumper Side Retainer <i>new</i>	\$85.00	\$170.00
13	1	Rear Bumper Reverse Sensor (Special Nett) <i>Pangd</i>		\$350.00
14	1	Rear End Panel <i>Repair</i>		\$555.00
15	1	Rear End Panel Top Garnish <i>Defend</i>		\$178.00
16	1	Rear Spare Tyre Panel Top Cover <i>new</i>		\$225.00

Subtotal :- \$5,221.00

1048

S.N. 200

786

Labour charges

To remove & refit reverse sensor		\$450.00 50
To check wiring		\$100.00 30
Tuff kote		\$150.00 X
Towing fee	880	\$150.00 X,
Panel beating		\$800.00 300
Spray painting		\$800.00 600

Subtotal :- \$2,450.00

Total:- \$7,671.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 1966
A/S: 1.31k (Nett Value)
04 Days.
✓

05 Days