



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

12 February 2019

REG NO.: SLV 6148 K
MAKE/MODEL: VOLKSWAGEN GOLF

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(S\$)
	<u>LIST ITEMS</u>	
1	Rear boot lid 1088.30	\$ 1,178.30
2	Rear boot hinges	\$ 494.00 X
2	Rear boot lamps	\$ 586.40 X
1	Rear boot lock	\$ 198.00
1	Rear boot logo	\$ 125.00
1	Rear boot rubber	\$ 354.00
2	Rear taillamps 455.01 x 2 = 910.02	\$ 1,398.00
1	Rear end panel 955 1066.45	\$ 1,339.00
1	Rear end panel inner garnish	\$ 215.00
1	Rear bumper 1388.62	\$ 1,430.00
2	Rear bumper brackets	\$ 250.00 X
1	Rear bumper inner frame pad	\$ 130.00 X
1	Rear bumper inner sponge	\$ 125.00 X
1	Rear bumper lower diffuser 397.60	\$ 785.00
2	Rear bumper reflectors	\$ 136.00
1	Rear bumper reinforcement	\$ 767.00 X
2	Rear bumper side retainers	\$ 172.00
4	Rear bumper "PDC" sensors 185 x 2 = 390	\$ 1,060.00 2pc
2	Rear number plate lamps 42	\$ 84.00 1pc
1	Rear spare tyre board	\$ 215.00 X
1	Rear spare tyre panel	\$ 985.00 X
1	Rear exhaust silencer	\$ 825.00 X
2	Rear exhaust mountings	\$ 150.00 X
2	Rear fender inner trims	\$ 470.00 X
1	Front bonnet	\$ 1,013.20 X
1	Front bonnet lock	\$ 176.60
1	Front bonnet rubber	\$ 80.40 X
2	Front headlamps 1068.80	\$ 2,137.60 1pc
2	Front headlamp panels	\$ 251.00 X
2	Front headlamp lower brackets 75.80	\$ 151.60 1pc
2	Front headlamp nozzle pens	\$ 390.00 X
2	Front headlamp nozzle covers	\$ 116.00 X
1	Front grille with chrome assy 645.30	\$ 1,148.00
		\$ 18,936.10

c/f:

\$ 18,936.10

LIST ITEMS

1	Front grille logo	\$ cm	165.00	—
1	Front bumper	\$ DJS	1,072.00	—
1	Front bumper clip (1 set)	\$ mer	50.00	—
2	Front bumper fog lamps	\$ 11	465.60	X
2	Front bumper fog lamp covers 156	\$ olssca	312.00	100
1	Front bumper inner sponge	\$ 70.11	135.00	—
1	Front bumper lower grille 184	\$ 70.11	285.00	—
1	Front bumper reinforcement 505.10	\$ 311	562.10	—
2	Front bumper side retainers	\$ 311	81.60	—
4	Front bumper PDC sensors 215x2=430	\$ slush	1,060.00	2pc
1	Front support panel 866.00	\$ cm	1,045.90	—
1	Air con condenser	\$ 11	836.00	X
1	Radiator	\$ 11	945.00	X
			\$ 25,951.30	
Less 10%			\$ 2,595.13	
			\$ 23,356.17	

12094.19
10884.77

SPECIAL NETT ITEMS

1	Rear bumper clip (1 set)	\$ 11	80.00	50
1	Rear number plate	\$ cm	50.00	40
1	Rear reverse camera	\$ 11	480.00	X
1	Front number plate with holder	\$ cm	50.00	40
			\$ 660.00	

S/N

LABOUR CHARGES

1	To check wiring and reset headlamps focussing.	\$	80.00	30
2	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	
3	To remove and refit inner garnishes.	\$	180.00	80
4	To remove and refit rear reverse sensor and camera.	\$	150.00	50
5	To transfer boot lid mechanism and wiring assembly to assist repair.	\$	120.00	60
6	To remove, replace air-con condenser and conduct leakage test.	\$	180.00	100
7	To remove, refit and replace exhaust silencer and mountings.	\$ 11	150.00	X
8	To apply undercoating.	\$	200.00	80
9	Panel beating.	\$	2,000.00	1400
10	To re-spray painting on the affected areas.	\$	1,800.00	1600
			\$ 4,940.00	

14414.77

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 28,956.17