

(5/20/2018)

INS. CASE OWNER:

CC 4 / III 1900 2660, K 6639

LKK:

IDAC:

Surveyor:

KSC

DOI:

ASSIGNMENT

15/1/19

Date / Time:

15/1/19

Registered in Merimen:

12/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKM 7224X

Name of Insured:

TOL

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A.:

5/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

SKM 21W MONO

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

MTC140W156

Policy No.:

MLO 20015

Make / Model:

Hyundai

Place of Accident:

DISHAM ST 2V opp B1K 462

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SDB 5505u

INSRS:
WSP:
Tel:
Liability:
RMKS:

Man's united

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time		STAGE	DATE / PIC
		Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup):	☐
		After call ltr to OI:	☐
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☐
		Towing Invoice:	☐
		LTA / GIA:	☐
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☒
		LOD:	☒
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by: KSC
Repair Cost:	FF \$52,928.00	(4 days) Reduction:	48 %
FINAL SETTLEMENT	Date/Time: 12-04-19	Confirm with: RUPH	Email ☒ Call ☐
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	21
Repair Cost:	\$53,433.05	Q10 REAR ENDORSE TP	
Loss of Rental (LOR):	\$5 -	(4 days)	
Loss of Use (LOU):	\$5,300.00	(5.50 x 6 days)	
Loss of Income (LOI):	\$5 -	(5 x days)	
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐		[Tick only one]	
GIA/LTA Search:	\$5 -		
Medical:	\$5 -		
Disbursement:	\$5 -	(e.g. Tow/Independent)	
Legal Cost:	\$5 -		
Total:	\$53,433.05	Global Sum \$5:	
FINAL PAYMENT	Date/Time: 12-04-19	Confirm with: RUPH	Email ☒ Call ☐
Payee 1:	\$53,433.05	Name 1:	PURVIS UNID AUTO RE-INT
Payee 2: (Strike if N.A.)	\$5	Name 2:	
Payee 3: (Strike if N.A.)	\$5	Name 3:	

ASS. REC. BY:

REF:

T2 /

2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SDB 55054 Yr Regn: 12, 14Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Honda Vezel c.c. 1486Colour: M.P. White A/C: Insured / Std / NI / NASp. Reading: 45560 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RUI 1014988Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orMod: Nil / S/Rlm / STD / Rlm orTyre Size: F: 215/60R16

R: _____

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 5/2/19 D.O.I. 15/2/19

Survey held at _____

Des. of Damages: Frt / Rear O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/ File pass to

Data/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Data/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend IS (\$ _____)

Survey Fee: _____

Transportation: _____

S - RS - SI _____

Flares _____

Others _____

TOTAL _____

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHA7234X
Accident Date : 05-Feb-2019

No. : 05922

Date : 12-Feb-2019

Our Ref : 219024 (III) / CHAN

PAGE : 1

ADIMOOLAM CHANDARA SEGARAN
BLK 263 BISHAN ST 22
#04-264
Singapore 570263

*Not Withash
Resony After Paint
82928.08*

ESTIMATED COST OF REPAIR FOR HONDA VEZEL SDB5505U

1 pc Tail gate		Rs 975.50	✓
1 pc Tail gate rubber		Rs 96.80	✓
1 pc Tail gate lock		Rs 177.10	✓
1 pc Tail gate "VEZEL" emblem		Rs 43.00	✓
2 pcs Tail gate lamp	@ S\$294.60	Rs 589.20	X X
1 pc Rear bumper fascia		Rs 463.50	✓
2 pcs Rear bumper side	@ S\$153.20	Rs 306.40	X
2 pcs Rear bumper reflector	@ S\$141.10	Rs 282.20	X
1 pc Rear w/s glass moulding		Rs 128.00	✓
1 pc Rear end panel		Rs 411.90	X R
1 pc End panel top garnish		Rs 92.30	X X
1 pc End panel outer antenel sensor		Rs 95.00	X X
1 pc Tail gate closed pocket		Rs 35.00	X
		3,695.90	1629.00
	Less 20% :	739.18	327.50
			134.90
1 pc Rear w/s glass sealant		Rs 2,956.72	
1 pc Rear bumper reverse sensor(set		Rs 60.00	sn
1 pc Rear no.plate with box		Rs 300.00	sn
		Rs 50.00	sn X
To remove & refix rear windscreen glass and conduct water leak test.		120.00	150.00
To remove roof lining, front and rear seats, trim board and carpet		120.00	60.00

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHA7234X

Page : 2

To apply undersealing

NK 60.00 X

To putty and spray replaced parts

4401 900.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

500 1,000.00 Z

Total : S\$ 5,596.72

=====

Singapore Dollars Five Thousand Five Hundred
and Ninety Six and Cents Seventy Two Only

P 1311.20

SPSN 90.00

SN 288.40

L 1120.00

2809.60

2928.08

~~2809.60~~

@ 4 Days

Kennerth pls confirm 7ks.

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHA7234X (INDIA)

Date : 16-02-2019

Accident Date : 05-02-2019

Our Ref : 219024/ CHAN

ADIMOOLAM CHANDARA SEGARAN

C/O ALAN'S UNITED AUTO PTE LTD

SUPPLEMENTARY ITEM PRICE FOR HONDA VEZEL SDB5505U

1 PC REAR BUMPER LOWER CHROME MOULDING

 \$90.00 SN ✓

Singapore Dollars Ninety Only

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHA7234X
Accident Date : 05-Feb-2019

No. : 05922

Date : 12-Feb-2019

Our Ref : 219024 (III) / CHAN

PAGE : 1

ADIMOOLAM CHANDARA SEGARAN
BLK 263 BISHAN ST 22
#04-264
Singapore 570263

*Not Withheld
Resony After Paint*

ESTIMATED COST OF REPAIR FOR HONDA VEZEL SDB5505U

1 pc Tail gate
1 pc Tail gate rubber
1 pc Tail gate lock
1 pc Tail gate "VEZEL" emblem
2 pcs Tail gate lamp
1 pc Rear bumper fascia
2 pcs Rear bumper side
2 pcs Rear bumper reflector
1 pc Rear w/s glass moulding
1 pc Rear end panel
1 pc End panel top garnish
1 pc End panel outer antenel sensor
1 pc Tail gate closed pocket

@ S\$294.60

@ S\$153.20

@ S\$141.10

As 975.50 ✓
As 96.80 *50% sn*
As 177.10 ✓
As 43.00 ✓
As 589.20 ?
As 463.50 ✓
Sn 306.40 X
Sn 282.20 X
As 128.00 ✓
As 411.90 ?
As 92.30 ?
As 95.00 ?
Sn 35.00 X

3,695.90

Less 20% : 739.18

1 pc Rear w/s glass sealant
1 pc Rear bumper reverse sensor(set
1 pc Rear no.plate with box

As 2,956.72
40% sn 60.00 sn
Shot 200% sn 300.00 sn
Sn 50.00 sn X

To remove & refix rear windscreen
glass and conduct water leak test.

120%
150.00

To remove roof lining, front and
rear seats, trim board and carpet

120.00 *60%*

UK Auto Consultants hereby notify
the Repairer of the following:
• To ensure follow-up survey painting
• To display damaged parts during survey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No legal modification is allowed
• Supplementary AS-1001 must be completed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHA7234X

Page : 2

To apply undersealing	60.00 ?
To putty and spray replaced parts	4401 900.00
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts	1,000.00 ?
Total :	S\$ 5,596.72 =====

Singapore Dollars Five Thousand Five Hundred
and Ninety Six and Cents Seventy Two Only

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SDB5505U
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Chassis No.:	RU11014988
Propellant:	Petrol
Engine No.:	L15B3515003
Engine Capacity:	1496 cc
Maximum Power Output:	96.0 kW (128 bhp)
Maximum Laden Weight:	1465 kg
Unladen Weight:	1190 kg
Year Of Manufacture:	2014
Original Registration Date:	30 Dec 2014
Lifespan Expiry Date:	-
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium:	\$65,889.00
COE Expiry Date:	29 Dec 2024
Road Tax Expiry Date:	29 Dec 2019
PARF Eligibility Expiry Date:	29 Dec 2024
Inspection Due Date:	29 Dec 2019
Intended Transfer Date:	14 Feb 2019
CO2 Emission:	126.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$10,000.00
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

[OK](#)
[Print](#)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	13 Feb 2019 14:29	Clim Veh Model Changed	(204808) HONDA VEZEL 1.5 (A).	[A] Lau Shu Pei
2	13 Feb 2019 14:29	Clim Created	Reg No: SDB5505U, Acct Date: 2019/02/05, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ), Workshop: Alan's United Auto Pte Ltd (HQ)	[A] Lau Shu Pei
3	13 Feb 2019 14:29	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	13 Feb 2019 14:29	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/02/22	[A] Lau Shu Pei
5	13 Feb 2019 14:29	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.	[A] Lau Shu Pei
6	13 Feb 2019 14:29	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
7	13 Feb 2019 14:29	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Lau Shu Pei
8	13 Feb 2019 15:37	Clim Registration Modified	Pol No:->MCOM0015.	[I] Pool Chin Han Daniel
9	14 Feb 2019 13:47	Adj Mandate Request	Cur.Req:0.00:PODS: LIABILITY: 100% REMARK: B:27 OID REAR ENDED TP	[A] Asher Sng Rong Yi
10	14 Feb 2019 14:22	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/02/22, Mandate Remarks: Agreed to do direct settlement. Please revert with your quantum advice	[I] Sundari Nagarajan
11	14 Feb 2019 14:22	Adj Mandate Set	Approved:0.00:Agreed to do direct settlement. Please revert with your quantum advice	[I] Sundari Nagarajan
12	21 Mar 2019 10:22	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
13	21 Mar 2019 10:22	Clim Dtl Modified	JPJ Reg. Date: -> 2014/12/30.	[A] JOANNE LEE KHANG MIN
14	21 Mar 2019 10:22	Clim Details Notified		[A] JOANNE LEE KHANG MIN
15	25 Mar 2019 12:53	Adj Mandate Request	Cur.Req:3493.05:PODS: LIABILITY: 100% QUANTUM: (a) COR w/GST: \$3,133.05 + (b) LOU: \$360.00 (6days x \$60) Total: a+b = \$3,493.05 VEH MODEL: HONDA VEZEL 1496cc PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF ANY.	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2091899	21/03/2019 10:22	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SDB5505U	SHA7234X	10.70

Print Received Message

This mail is associated with :

***SDB5505U (MCT19020156)
[SHA7234X]**

TP

ADIMOOLAM CHANDARA SEGARAN
Feb 5 2019 11:00PM
[COMFORT TRANSPORTATION PTE LTD]
Alan's United Auto Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 26/03/2019 09:45 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3493.05) - SDB5505U - Claim Handler: Pool Chin Han Daniel

Approved:3493.05:

CkK

ADIMOOLAM CHANDARA SEGARAN
c/o Blk 7 Sin Ming Industrial Estate
#01-76
Singapore 575642

Date: 27-2-2019

INDIA INTERNATIONAL INSURANCE PTE LTD
MOTOR CLAIMS DEPT.
64 CECIL STREET
#04-00/#05-00
IOB BUILDING
SINGAPORE 049711

Dear Sir / Madam

ACCIDENT INVOLVING MOTOR VEHICLES SDB 55054 AND SHA7234X
ALONG BISHAN STREET 22 ON 05-02-2019

I / We, the owner of Vehicle No. SDB 55054 which was involved in the above accident.

My / Our vehicle sustained damages as a result of the above said accident and I / we are now claiming against you for the followings:-

- | | | |
|--|---|-------------------|
| 1. Costs of repair | - | \$3133.05 |
| 2. Loss-of-Use/Rental fees (6 day (5 day)) | - | \$ 300.00 |
| 3. Police / GIA report / LTA fees | - | |
| 4. Surveyor report fees | - | |
| 5. Others | - | |
| Total: | | <u>\$13433.05</u> |

Please advise whether you are now prepare to settle my claims as outlined above.

I / We hereby authorise my / our repairers, M/s Alan's United Auto Pte. Ltd. and/or their representatives to negotiate/compromise settlement of my / our above claim on my / our behalf. If there is a settlement I / we further authorise you to pay whatever settlement sum to my / our repairers being the outstanding repair bill and incidentals due to them.

Your kind attention and prompt settlement is much appreciated.

Yours faithfully,



LKK

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT19020156
Claimant Ref: SDB 5505U

We/I, ALAN'S UNITED AUTO PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 3,133.05 (repair cost), S\$ 300.00 (loss of use/rental), S\$ — (search fee), vehicle no. SDB 5505U that was damaged pursuant to the accident which occurred on 05/02/2019 (date) at BISHAN ST 22 (location) involving vehicle no. SHA 7234X (insured vehicle). This is pursuant to the inspection conducted on 15/02/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner ADIMOOLAM CHANDARA SEGARAN ("the third party claimant") of vehicle no. SDB 5505U to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SDB 5505U (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 3,433.05 to ALAN'S UNITED AUTO PTE LTD

Dated this 12th day of APRIL 2019

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

NRIC:

Address:

Nationality:

Occupation:

WITNESS:

Signature:



KSC

Signed by appointed Surveyor

Name:

NRIC:

Address:

Nationality:

Occupation:

LKK AUTO CONSULTANTS PTE LTD

192607188R

51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK

#02-25 SINGAPORE 408833

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 15689

Date : 26-Feb-2019

PAGE : 1

Vehicle Insured : SHA7234X

Accident Date : 05-Feb-2019

Our Ref : 219024 (III) / CHAN

INDIA INTERNATIONAL INSURANCE PTE LTD

FINAL REPAIR COST FOR HONDA VEZEL SDB5505U

=====

1 pc	Tail gate	975.50
1 pc	Tail gate lock	177.10
1 pc	Tail gate "VEZEL" emblem	43.00
1 pc	Rear bumper fascia	463.50
1 pc	Rear w/s glass moulding	128.00

1,787.10

Less 20% : 357.42

	1,429.68	
1 pc	Tail gate rubber	48.40 sn
1 pc	Rear bumper lower chrome	90.00 sn
1 pc	Rear w/s glass sealant	40.00 sn
1 pc	Rear bumper reverse sensor(set	200.00 sn

To remove & refix rear windscreen glass and conduct water leak test. 120.00

To remove roof lining, front and rear seats, trim board and carpet 60.00

To putty and spray replaced parts 440.00

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts 500.00

2,928.08

Add 7% GST : 204.97

Total : S\$ 3,133.05

=====

Singapore Dollars Three Thousand One Hundred and Thirty Three and Cents Five Only

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Feb 2019 Edit Reg		12 Feb 2019 00:00 Edit Adj Rpt	\$52,928.08 Edit Estimates	\$52,928.08 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	ADIMOOLAM CHANDARA SEGARAN, ID: S1490296A								
Vehicle Reg. No.:	SDB5505U	Date of Loss:	05/02/2019 23:00 - :59 [49 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19020156	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	SHA7234X	Policy No. (Claimant):	5087175303-02						
		Excess:							
Repairer:	Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76, 575642 Sin Ming - Tel: 6453 8686								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pool Chin Han Daniel]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 22/02/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (26/03/2019): Alert - Adj Mandate Approved (\$3493.05) - SDB5505U - Claim Handler: Pool Chin H... - III_SG (14/02/2019): Alert - Adj Mandate Approved (\$0.00) - SDB5505U - Claim Handler: Pool Chin Han ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDB5505U (MCT19020156)
[SHA7234X]
TP
ADIMOOLAM CHANDARA SEGARAN
Feb 5 2019 11:00PM
[COMFORT TRANSPORTATION PTE LTD]
Alan's United Auto Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/03/19 12:50	General View		Load JPG	☒
2	25/03/19 12:50	General View		Load JPG	☒
3	25/03/19 12:50	General View		Load JPG	☒
4	25/03/19 12:50	General View		Load JPG	☒
5	25/03/19 12:50	General View		Load JPG	☒
6	25/03/19 12:50	General View		Load JPG	☒
7	25/03/19 12:50	General View		Load JPG	☒
8	25/03/19 12:50	General View		Load JPG	☒
9	25/03/19 12:50	General View		Load JPG	☒
10	25/03/19 12:50	General View		Load JPG	☒
11	25/03/19 12:50	General View		Load JPG	☒
12	25/03/19 12:50	Odometer Reading		Load JPG	☒
13	25/03/19 12:50	General View		Load JPG	☒
14	25/03/19 12:50	Chassis Number		Load JPG	☒
15	25/03/19 12:51	Reinspection Photo		Load JPG	☒
16	25/03/19 12:51	Reinspection Photo		Load JPG	☒
17	25/03/19 12:51	Reinspection Photo		Load JPG	☒
18	25/03/19 12:51	Reinspection Photo		Load JPG	☒

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/02/19 14:29	EMAIL FROM III DO 12022019		Load PDF	
2	13/02/19 14:29	TP EST & GIA REPORT		Load PDF	
3	18/02/19 17:33	TP ESTIMATE- MARKED		Load PDF	
4	21/03/19 10:29	WORKSHOP INVOICE		Load PDF	
5	21/03/19 10:29	LOD		Load PDF	
6	06/05/19 16:17	DISCHARGE VOUCHER		Load PDF	
7	06/05/19 16:17	AUTHORISATION TO ACT FORM		Load PDF	

No

Finalized On

India International Insurance Pte Ltd (HQ)

Thumbnail

Print

1	13/02/19 15:36	Singapore Accident Statement IV SHA7234X		Load PDF	
---	----------------	--	--	----------	--

Documents Checklist

DOCUMENTS CHECKLIST				Reset	Save	Print
There are no document checklists configured.						

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

	^ v
--	--------

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19002610/KEB3Q2

Date: 06/05/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle
No : SDB5505U

Insured Vehicle No : SHA7234X

Date of Loss: 05/02/2019

Nature of Claim:

TP

Claim No: MCT19020156

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDB5505U

Make & Model: HONDA VEZEL, 1.5 (A)

Engine No: L15B3515003

Reg. Date: 30/12/2014 (Man. Year: 2014)

Chassis No: RU11014988

Colour: Metallic Pearl White

Odometer: 45560 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,456.72	1,808.08	1,648.64	47.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,230.00	1,120.00	1,110.00	49.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,686.72	2,928.08	2,758.64	48.51
+ GST 7.00/7.00% (S\$)	398.07	204.97	193.10	48.51
Nett Amount (S\$)	6,084.79	3,133.05	2,951.74	48.51
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
Nett Liability (S\$)		3,433.05		

INSPECTION

Date of Assignment: 12/02/2019

Date Inspected: 15/02/2019 Inspected At:

Alan's United Auto Pte Ltd (HQ)
Blk 7 Sin Ming Industrial Estate, #01-76
Singapore 575642

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Mar 2019)
Parts: M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SDB5505U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	975.50 FL	*975.50 FL
2	1		*TAIL GATE RUBBER (50%)	Cut	77.44 FS	*48.40 FS
3	1		*TAIL GATE LOCK	Dented	177.10 FL	*177.10 FL
4	1		*TAIL GATE VEZEL EMBLEM	Necessary	43.00 FL	*43.00 FL
5	2		*TAIL GATE LAMP	Serviceable	589.20 FL	*- FL
6	1		*REAR BUMPER FASCIA	Bent	463.50 FL	*463.50 FL
7	2		*REAR BUMPER SIDE	Serviceable	306.40 FL	*- FL
8	2		*REAR BUMPER REFLECTOR	Serviceable	282.20 FL	*- FL
9	1		*REAR W/S GLASS MOULDING	Necessary	128.00 FL	*128.00 FL
10	1		*REAR END PANEL	Repair	411.90 FL	*- FL
11	1		*END PANEL TOP GARNISH	Serviceable	92.30 FL	*- FL
12	1		*END PANEL OUTER ANTENEL SENSOR	Serviceable	95.00 FL	*- FL
13	1		*TAIL GATE CLOSED POCKET	Serviceable	35.00 FL	*- FL
14	1		*REAR W/S GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
15	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
16	1		*REAR NO.PLATE WITH BOX	Serviceable	50.00 FS	*- FS
17	1		*REAR BUMPER LOWER CHROME MOULDING	Dented	90.00 FS	*90.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,176.54	2,165.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	719.82	357.42
Total Parts (\$\$)	3,456.72	1,808.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	150.00	120.00
2	TO REMOVE ROOF LINING,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET	New	120.00	60.00
3	TO APPLY UNDERSEALING	New	60.00	0.00
4	TO PUTTY AND SPRAY REPLACED PARTS	New	900.00	440.00
5	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	1,000.00	500.00
Gross Labour Cost (S\$)			2,230.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >