

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHA7234X
Accident Date : 05-Feb-2019

No. : 05922

Date : 12-Feb-2019

Our Ref : 219024 (III) / CHAN

PAGE : 1

ADIMOOLAM CHANDARA SEGARAN
BLK 263 BISHAN ST 22
#04-264
Singapore 570263

*Not Withheld
Resurvey After Paint*

ESTIMATED COST OF REPAIR FOR HONDA VEZEL SDB5505U

- =====
- | | | |
|-------|--------------------------------|-------------|
| 1 pc | Tail gate | |
| 1 pc | Tail gate rubber | |
| 1 pc | Tail gate lock | |
| 1 pc | Tail gate "VEZEL" emblem | |
| 2 pcs | Tail gate lamp | @ S\$294.60 |
| 1 pc | Rear bumper fascia | |
| 2 pcs | Rear bumper side | @ S\$153.20 |
| 2 pcs | Rear bumper reflector | @ S\$141.10 |
| 1 pc | Rear w/s glass moulding | |
| 1 pc | Rear end panel | |
| 1 pc | End panel top garnish | |
| 1 pc | End panel outer antenel sensor | |
| 1 pc | Tail gate closed pocket | |

<i>By</i>	975.50	<i>✓</i>
<i>By</i>	96.80	<i>50% ✓</i>
<i>By</i>	177.10	<i>✓</i>
<i>By</i>	43.00	<i>✓</i>
	589.20	<i>?</i>
<i>By</i>	463.50	<i>✓</i>
<i>By</i>	306.40	<i>X</i>
<i>By</i>	282.20	<i>X</i>
<i>By</i>	128.00	<i>✓</i>
	411.90	<i>?</i>
	92.30	<i>?</i>
	95.00	<i>?</i>
<i>By</i>	35.00	<i>X</i>

3,695.90

Less 20% : 739.18

- | | | |
|------|--------------------------------|--|
| 1 pc | Rear w/s glass sealant | |
| 1 pc | Rear bumper reverse sensor(set | |
| 1 pc | Rear no.plate with box | |

<i>By</i>	2,956.72	
<i>By</i>	60.00	<i>sn</i>
<i>Shot</i>	300.00	<i>sn</i>
<i>By</i>	50.00	<i>sn X</i>

To remove & refix rear windscreen
glass and conduct water leak test.

120
150.00

To remove roof lining, front and
rear seats, trim board and carpet

120.00 *60*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHA7234X

Page : 2

To apply undersealing

60.00 ?

To putty and spray replaced parts

4401 900.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1,000.00 ?

Total : S\$ 5,596.72
=====

Singapore Dollars Five Thousand Five Hundred
and Ninety Six and Cents Seventy Two Only