



FALCON-AIR

AIG ASIA PACIFIC INSURANCE PTE LTD  
AIG Building 78 Shenton Way #07-16  
079120

Attention : Motor Claim Department  
Contact : 6419 3000

*Not Authorized*  
*2 hrs*  
*4/5 #4500*  
*day.*  
*Whop. of the rep-*  
*13/2/19*

Estimate : ES707284

Date : 12/02/2019  
Vehicle Num. : SME 9371P  
Make/Model : TOYOTA VIOS  
Chassis/Eng# :  
Accident Date : 12/02/2019  
Claim No. :  
Reference :  
Policy No. :

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1PC	REAR BUMPER <i>DD 427.90</i>		485.00
2.	2PCS	REAR BUMPER SIDE RETAINER <i>bet</i>	35.00	70.00
3.	10PCS	REAR BUMPER CLIP <i>bet</i>	6.80	68.00
4.	2PCS	TAILLAMP <i>one</i>	398.40	796.80
5.	2PCS	TAILLAMP PANEL <i>one nls to 015 R</i>	184.40	368.80
6.	2PCS	TAILLAMP PANEL CLIP <i>11</i>	12.00	24.00
7.	1PC	REAR END PANEL <i>body to 539.13</i>		765.00
8.	1PC	REAR END PANEL GARNISH <i>fin</i>		75.50
9.	1PC	BOOT LID <i>bet/one</i>		755.00
10.	1PC	BOOT LID LOCK <i>two</i>		120.00
11.	1PC	BOOT LID WEATHERSTRIP <i>two</i>		125.00
12.	2PCS	BOOT LID HINGE <i>bet nls</i>	110.00	220.00
13.	1PC	BOOT LID CABLE <i>one</i>		130.00
14.	1PC	BOOT LID LOGO <i>one</i>		45.00
15.	1PC	BOOT LID 1.5 EMBLEM <i>one</i>		35.00
16.	1PC	BOOT LID E EMBLEM <i>one</i>		35.00
17.	1PC	BOOT LID VVTI EMBLEM <i>one</i>		50.00
18.	1PC	BOOT LID VIOS EMBLEM <i>one</i>		30.00
19.	1PC	BOOT LID GARNISH <i>one</i>		135.00
20.	1PC	RR NUMBER PLATE LAMP ASSY <i>one</i>		95.00
21.	2PCS	REAR FENDER INNER TRIMS <i>nls total</i>	255.00	510.00
22.	20PCS	REAR FENDER INNER TRIM CLIPS <i>one</i>	6.80	136.00

CONTINUE / ...


FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

AIG ASIA PACIFIC INSURANCE PTE LTD  
AIG Building 78 Shenton Way #07-16  
079120

Attention : Motor Claim Department  
Contact : 6419 3000

Estimate : ES707284

Date : 12/02/2019  
Vehicle Num. : SME 9371P  
Make/Model : TOYOTA VIOS  
Chassis/Eng# :  
Accident Date : 12/02/2019  
Claim No. :  
Reference :  
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1PC	SPARE TYRE BOARD		295.00 ✓
24.	1PC	N/S REAR FENDER		979.00 x
25.	1SET	REAR WS MLDING		124.00 x
26.	1SET	SEALANT N INNER SEAL		100.00 x
List TotalS\$ :				6,572.10
25.00% Discount S\$ :				1,643.03
				4,929.07
SPECIAL NETT ITEMS :				
1.	1PC	REAR NUMBER PLATE		45.00 40
2.	1PC	BOOT LID SEALANT		80.00 50
3.	1SET	BOOT LID STICKER		80.00 30
4.	1PC	BREAKDOWN SIGN		100.00 x
Special Nett Total S\$ :				305.00
LABOUR :				
TO CHECK LIGHT SYSTEM AND WIRING				50.00 30
TO REMOVE/REFIT INNER TRIMS AND GARNISHES				150.00 80
TRANSFER BOOT LID PARTS				100.00 50
INSTALL REVERSE SENSOR IN NEW BUMPER				100.00 50
ANTI-RUST				120.00 60

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

1-4183-73  
3137-79


**FALCON-AIR AUTO SERVICES PTE LTD**

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

AIG ASIA PACIFIC INSURANCE PTE LTD  
AIG Building 78 Shenton Way #07-16  
079120

Attention : Motor Claim Department  
Contact : 6419 3000

Estimate : ES707284

Date : 12/02/2019  
Vehicle Num. : SME 9371P  
Make/Model : TOYOTA VIOS  
Chassis/Eng# :  
Accident Date : 12/02/2019  
Claim No. :  
Reference :  
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		TO APPLY BODY SEALANT ON BODY JOINTS		120.00 120
		TO REMOVE/REFIT FUEL TANK TO FACILITATE REPAIRS		150.00 60
		TO REMOVE/REFIT SPEAKERBOARD, SEATS TO FAC REPAIRS		180.00 180
		TO RNR REAR WS		120.00 120
		LABOUR/PANEL BEATING		1,600.00 100
		SPRAY PAINTING		1,400.00 110
		Labour Total S\$ :		4,090.00

2400

E. & O.E.	Total S\$ :	9,324.07
-----------	-------------	----------

for FALCON AIR AUTO SERVICES PTE LTD

(TAMPINES BRANCH)

4737.79

4590.

**FALCON-AIR AUTO SERVICES PTE LTD**

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg