

15/5/2010

INS. CASE OWNER:

CC 3/AIG1900

North, J...
d 93
J...
LKK:
IDAC:

Surveyor:

MJ

DOE:

2/7/19

Date / Time:

7/1/19

Registered in Merimen:

17/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SUR 7754A

Claim No.:

915741545154

Name of Insured:

ANGK VITAMENH KAWAN

Policy No.:

H0004429-01

Insured Tel No.:

HP:

Make / Model:

SUBARU

Excess Sec II :SS

D.O.A.:

2/7/19

Place of Accident:

UE

Is driver the owner? (YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SUR 7754A

SMB 50573

SUP 53AL



INSRS:
WSP:
Tel:
Liability:
RMKS:

01



INSRS:
WSP:
Tel:
Liability:
RMKS:

SMKT

TP



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
14/3/19	Call OE: CELVIA 14/3/19	
18/3/19	After call ltr to OE: CELVIA 18/3/19 VIC-OL	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
	After call ltr to OE:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
	PIR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/> <input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: \$\$ (days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: 14/1/20 Confirm with: Tan Lee Goh Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 28 If NO or B 28, Ass. Lia.: 100% (3 VEH. C.C., OI LATER CASE)

Repair Cost: \$\$ 8184.49

Loss of Rental (LOR): \$\$ 1182.40 (10 days) x \$118.24

Loss of Use (LOU): \$\$ - (\$ x days)

Loss of Income (LOI): \$\$ 500.00 (\$ 50 x 10 days)

LOR only LOU only LOR + LOU LOR + LO [Tick only one]

GIALTA Search: \$\$ 7.00

Medical: \$\$ -

Disbursement: \$\$ - (e.g. Tow/ Independent)

Legal Cost: \$\$ -

Total: \$\$ 9873.89 Global Sum SS: 9870.00

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: \$\$ 9870.00 Name 1: SMART Taxis Pte Ltd

Payee 2: (Strike if N.A.) \$\$ Name 2:

Payee 3: (Strike if N.A.) \$\$ Name 3:

COPY SENT
16/1/2020

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$320


Hand Jia

REF: AIG

cheese
Colours

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT





Veh No: SHB 50572 Yr Regn: 1 Nov 2017
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Tr / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Prius CC: 1798
 Colour: maroon A/C: Insured / Std / NI / NA
 Sp Reading: _____ T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JT DKB3FU 103573180
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or westlake
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 2/2/19 D.O.I. 7/2/19
 Survey held at Smt
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	P/P - \$8184.49 (Red \$32017.19 [80%])
	02/19/2010
	SLR 7754A
	SLR 539L

Date/Time File Pass to? : Preli. Report
 : Final Report
 Date/Time File Return to? _____
 Days Of Repair: _____
 Resurvey No. of Trip: _____
 Survey Fee: _____
 Transportation: _____
 Add Fee: Site Insp. \$
 Interview \$
 Tech. Invs \$
 Weekend \$
 Report Format: _____
 Lump Sum / I.B.I: \$ _____
 TOTAL _____

Jia Le

Section A - Accident Details	
Registration Number	SHB5057Z
Case Reference Number	TAX/02/19/2010
Registration Date	1/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TOH KHENG CHAI CHARLIE
Type of Accident	Head to Rear
Accident Date and Time	2/2/2019 10:45 PM
Accident Reported Date and Time	4/2/2019 11:50 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24099993
Special Instruction to ARC, if any	DROVE IN /TP
Prepared Date and Time	7/2/2019 9:26 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



l/r

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,535.00	\$1,000.00
Total Spray Cost	\$3,348.00	\$900.00
Total Spare Part Cost	\$32,558.68	\$6,174.49
Total Other Cost	\$1,760.00	\$110.00
TOTAL COST	\$40,201.68	\$8,184.49 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	17.0	6.0
Prepared / Adjusted By	Kim Ming Chin	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	08/02/2019 12:09 AM	08/02/2019 11:43 AM
Signature		
Remarks		p/p repair, photo before paint.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0203	Invoice Number	
Quotation Date	16.08.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$1,690.00	\$600.00
TO REPAIR REAR PORTION	\$845.00	\$400.00
Total Labour	\$2,535.00	\$1,000.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO REPSRAY FRONT HOOD	\$378.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$3,348.00	\$900.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$40.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$0.00
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$250.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$40.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO TOP UP AC GAS	\$120.00	\$0.00
TO CONDUCT RADIATOR PRESSURE CHECK	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,760.00	\$110.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119479 62	COVER, FR BUMPER		\$495.50	25.00	\$371.63	Replace	Replace

DEF



SMRT Accident Vehicle Repair Estimates

SMRT Automobile Services Pte Ltd
 50 Woodlands Industrial Park East, Singapore
 FAX Number: 63645500
 Estimator Telephone Number: 66622623
 Accident Reporting Number: 68662672

Date Generated: 16/05/2019
 User ID: PuhDuan

52115470 50	SUPPORT, FR BUMPER RH	0.00	\$76.90	0.00	\$0.00	Replace	Check	X	
52118470 50	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Check	X	
52127479 07	COVER, FR BUMPER RH	0.00	\$28.10	0.00	\$0.00	Replace	Not Given	X	NN
52128479 06	COVER, FR BUMPER LH	0.00	\$28.10	0.00	\$0.00	Replace	Not Given	X	NN
52114471 90	BRACKET, FR BUMPER	1.00	\$99.80	25.00	\$74.85	Replace	Replace		CRA
	NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace		MIS
	NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace		CRA
53395470 40	SEAL, HOOD TO FR END	0.00	\$24.40	0.00	\$0.00	Replace	Not Given	X	MIV
75310470 60	EMBLEM ASSY FRONT	1.00	\$87.10	25.00	\$65.33	Replace	Replace		NEL
53112472 40	GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Not Given	X	NN
53101470 80	GRILLE SUB-ASSY	1.00	\$335.60	25.00	\$251.70	Replace	Replace		BVC
52161180 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace		NEL
52535500 80	RETAINER, FR BUMPER, LH & RH	0.00	\$8.50	0.00	\$0.00	Replace	Check	X	
52021471 10	REINFORCEMENT FRONT UPPER	0.00	\$891.10	0.00	\$0.00	Replace	Check	X	
52611471 40	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Check	X	
52132470 10	REINFORCEMENT FRONT LOWER	0.00	\$238.50	0.00	\$0.00	Replace	Check	X	
52618470 90	ABSORBER, FR BUMPER LOWER	0.00	\$117.00	0.00	\$0.00	Replace	Check	X	
52103470 10	EXTENSION SUB-ASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Check	X	
52102470 20	EXTENSION SUB-ASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Check	X	
53289470 72	COVER, RADIATOR	0.00	\$227.80	0.00	\$0.00	Replace	Check	X	
53203479 01	SUPPORT S/A LH	0.00	\$237.00	0.00	\$0.00	Replace	Check	X	
53028470 10	SUPPORT SUB-ASSY LOWER	0.00	\$397.40	0.00	\$0.00	Replace	Check	X	
53213470 50	SUPPORT, RADIATOR UPPER RH	0.00	\$76.70	0.00	\$0.00	Replace	Check	X	
53214470 50	SUPPORT, RADIATOR UPPER LH	0.00	\$76.70	0.00	\$0.00	Replace	Check	X	
80541150 37	CUSHION HOOD BUMPER	0.00	\$8.50	0.00	\$0.00	Replace	Check	X	
16592370 20	GUIDE, RADIATOR AIR	0.00	\$93.90	0.00	\$0.00	Replace	Check	X	
53217470 30	BRACE, HOOD LOCK SUPPORT	0.00	\$76.20	0.00	\$0.00	Replace	Not Given	X	
53510471 40	LOCK ASSY, HOOD	0.00	\$131.10	0.00	\$0.00	Replace	Check	X	NN
53630470 90	CABLE ASSY, HOOD	0.00	\$53.20	0.00	\$0.00	Replace	Check	X	
16562370 10	SEAL, RADIATOR TO RH	0.00	\$24.80	0.00	\$0.00	Replace	Check	X	
16563370 10	SEAL, RADIATOR TO LH	0.00	\$24.80	0.00	\$0.00	Replace	Check	X	
16593370 40	GUIDE, RADIATOR AIR, RH	0.00	\$54.60	0.00	\$0.00	Replace	Check	X	
16595370 50	GUIDE, RADIATOR AIR, LH	0.00	\$58.80	0.00	\$0.00	Replace	Check	X	
90480400 21	GROMMET (FOR RADIATOR LOWER	0.00	\$12.70	0.00	\$0.00	Replace	Check	X	
16523370 10	CUSHION, (FOR RADIATOR UPPER	0.00	\$9.80	0.00	\$0.00	Replace	Check	X	
16594370 10	GUIDE, RADIATOR AIR, UPPER	0.00	\$44.70	0.00	\$0.00	Replace	Check	X	
16400373 10	RADIATOR ASSY	0.00	\$1,841.10	0.00	\$0.00	Replace	Check	X	
	COOLANT	0.00	\$12.30	0.00	\$0.00	Replace	Check	X	
16361370 60	FAN RADIATOR, LH	0.00	\$181.80	0.00	\$0.00	Replace	Check	X	
16361370 70	FAN RADIATOR, RH	0.00	\$233.00	0.00	\$0.00	Replace	Check	X	
16711371 80	FAN SHROUD RADIATOR	0.00	\$219.30	0.00	\$0.00	Replace	Check	X	
16363361 60	MOTOR, COOLING FAN, RH	0.00	\$443.40	0.00	\$0.00	Replace	Check	X	
16363370 80	MOTOR, COOLING FAN, LH	0.00	\$543.50	0.00	\$0.00	Replace	Check	X	
16571372 10	HOSE, RADIATOR, NO.1	0.00	\$42.60	0.00	\$0.00	Replace	Check	X	
16572372 10	HOSE, RADIATOR, NO.2	0.00	\$40.20	0.00	\$0.00	Replace	Check	X	



SMRT Accident Vehicle Repair Estimates

SMRT Automobile Services Pte Ltd
 90 Westlands Industrial Park East, Singapore
 FAX Number 63685592
 Estimator Telephone Number 68662623
 Accident Reporting Number 68662672

Date Generated 18/08/2018
 User ID J. PanSuan

16264371 20	HOSE, WATER BY-PASS , NO.2	0.00	\$37.40	0.00	\$0.00	Replace	Check	X
16267370 80	HOSE, WATER BY-PASS , NO.3	0.00	\$20.10	0.00	\$0.00	Replace	Check	X
16261371 00	HOSE, WATER BY-PASS , NO.4	0.00	\$13.20	0.00	\$0.00	Replace	Check	X
16261371 50	HOSE, WATER BY-PASS , NO.1	0.00	\$37.40	0.00	\$0.00	Replace	Check	X
86510470 50	HORN ASSY, HIGH	0.00	\$112.80	0.00	\$0.00	Replace	Check	X
86520470 30	HORN ASSY, LOW	0.00	\$112.80	0.00	\$0.00	Replace	Check	X
88460103 20	AIR CON CONDENSER ASSY	0.00	\$1,317.70	0.00	\$0.00	Replace	Check	X
88710471 60	TUBE & ACCESSORY	0.00	\$574.40	0.00	\$0.00	Replace	Check	X
88703470 80	HOSE SUB-ASSY, DISCHARGE	0.00	\$337.10	0.00	\$0.00	Replace	Check	X
G922E470 10	HOSE, HV WATER PUMP INLET	0.00	\$37.90	0.00	\$0.00	Replace	Check	X
G9040470 40	INVERTER WATER PUMP ASSY	0.00	\$432.00	0.00	\$0.00	Replace	Check	X
G922F470 10	HOSE, HV WATER PUMP OUTLET	0.00	\$29.60	0.00	\$0.00	Replace	Check	X
G922H47 010	HOSE, INVERTER RADIATOR INLET	0.00	\$40.70	0.00	\$0.00	Replace	Check	X
17753370 10	INLET, AIR CLEANER, NO 3	0.00	\$35.30	0.00	\$0.00	Replace	Check	X
17751371 10	INLET, AIR CLEANER, NO 1	0.00	\$130.50	0.00	\$0.00	Replace	Check	X
17700373 30	AIR CLEANER ASSY	0.00	\$956.20	0.00	\$0.00	Replace	Check	X
8211147J 21	WIRE, ENGINE ROOM MAIN	0.00	\$6,138.00	0.00	\$0.00	Replace	Check	X
53301471 10	HOOD SUB-ASSY	0.00	\$938.40	0.00	\$0.00	Replace	Check	X
53410471 30	HINGE ASSY, HOOD, RH	0.00	\$57.00	0.00	\$0.00	Replace	Check	X
53420471 30	HINGE ASSY, HOOD, LH	0.00	\$17.00	0.00	\$0.00	Replace	Check	X
53341470 40	INSULATOR, HOOD	0.00	\$393.90	0.00	\$0.00	Replace	Check	X
90467090 50	INSULATOR, HOOD CLIP	0.00	\$2.30	0.00	\$0.00	Replace	Check	X
55708472 30	WIPER GARNISH LOUVER SUB-ASSY	0.00	\$686.80	0.00	\$0.00	Replace	Check	X
53802471 00	FENDER SUB-ASSY, FR , LH	1.00	\$933.10	100.00	\$0.00	Replace	Repair	R
81185476 91	UNIT, HEADLAMP , LH	0.00	\$2,558.90	0.00	\$0.00	Replace	Check	X
75374471 40	EMBLEM, SIDE PANEL (HYBRID)	0.00	\$52.90	0.00	\$0.00	Replace	Not Given	X
81056476 90	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check	X
53801470 80	FENDER SUB-ASSY, FR , RH	1.00	\$933.10	100.00	\$0.00	Replace	Repair	R
81145476 91	UNIT, HEADLAMP , RH	0.00	\$2,558.90	0.00	\$0.00	Replace	Check	X
75374471 40	EMBLEM, SIDE PANEL (HYBRID)	0.00	\$52.90	0.00	\$0.00	Replace	Not Given	X
81016476 90	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check	X
52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace	DEF
52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace	BU C

NN

NN

NN

NN

DEF

BU C



Case Details

Case Reference Number : TAX/02/19/2010
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5057Z

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-5619-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 02/02/2019 02:45 PM
 Vehicle Age(In Months) : 15

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Quantity	Surveyor Approval		Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)			Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace	DEF
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Check	X N/A
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Check	X N/A
One Time Key In	Main			COVER, FR BUMPER RH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Give	X N/A
One Time Key In	Main			COVER, FR BUMPER LH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BRACKET, FR BUMPER	1	99.80	99.80	25.00	74.85	Replace	1	74.85	Replace	/ CRA
One Time Key In	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	1	25.00	Replace	/ MIS
One Time Key In	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	1	35.00	Replace	/ CRA
One Time Key In	Main			SEAL, HOOD TO FR END	1	24.40	24.40	25.00	18.30	Replace	0	0	Not Give	X N/A
One Time Key In	Main			EMBLEM ASSY FRONT	1	87.10	87.10	25.00	65.32	Replace	1	65.32	Replace	/ NEC

Total Spare Part Cost 29,977.43

Surveyor Total 1,848.88

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 29,977.43

Final Sur Total 1,848.88

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	0	0	Not Givr	* X N/A
One Time Key In	Main			GRILLE SUB-ASSY	1	335.60	335.60	25.00	251.70	Replace	1	251.70	Replace	* / PUC
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	* / NEC
One Time Key In	Main			RETAINER, FR BUMPER, LH & RH	2	8.60	17.00	25.00	12.75	Replace	0	0	Check	* X N/A
One Time Key In	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	0	0	Check	* X N/A
One Time Key In	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0	Check	* X N/A
One Time Key In	Main			REINFORCEMENT FRONT LOWER	1	238.50	238.50	25.00	178.88	Replace	0	0	Check	* X N/A
One Time Key In	Main			ABSORBER, FR BUMPER LOWER	1	117.00	117.00	25.00	87.75	Replace	0	0	Check	* X N/A
One Time Key In	Main			EXTENSION SUB-ASSY, LH	1	116.30	116.30	25.00	87.22	Replace	0	0	Check	* X N/A
One Time Key In	Main			EXTENSION SUB-ASSY, RH	1	116.30	116.30	25.00	87.22	Replace	0	0	Check	* X N/A
One Time Key In	Main			COVER, RADIATOR	1	227.80	227.80	25.00	170.85	Replace	0	0	Check	* X N/A
One Time Key In	Main			SUPPORT S/A UPPER	1	364.90	364.90	25.00	273.67	Replace	0	0	Check	* X N/A
One Time Key In	Main			SUPPORT S/A RH	1	237.00	237.00	25.00	177.75	Replace	0	0	Check	* X N/A
One Time Key In	Main			SUPPORT S/A LH	1	237.00	237.00	25.00	177.75	Replace	0	0	Check	* X N/A
One Time Key In	Main			SUPPORT SUB-ASSY LOWER	1	397.40	397.40	25.00	298.05	Replace	0	0	Check	* X N/A

Total Spare Part Cost 29,977.43
 Lump Sum Discount (%) 0.00
 Final Spare Part Cost 29,977.43

Surveyor Total 1,946.88
 Lump Sum Dis (%) 0
 Final Sur Total 1,946.88

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SUPPORT, RADIATOR UPPER RH	1	76.70	76.70	25.00	57.53	Replace	0	0	Check	* X N/A
One Time Key In	Main			SUPPORT, RADIATOR UPPER LH	1	76.70	76.70	25.00	57.53	Replace	0	0	Check	* X N/A
One Time Key In	Main			CUSHION HOOD BUMPER	2	8.50	17.00	25.00	12.75	Replace	0	0	Check	* X N/A
One Time Key In	Main			GUIDE, RADIATOR AIR,	1	93.90	93.90	25.00	70.43	Replace	0	0	Check	* X N/A
One Time Key In	Main			BRACE, HOOD LOCK SUPPORT	1	76.20	76.20	25.00	57.15	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			LOCK ASSY, HOOD	1	131.10	131.10	25.00	98.32	Replace	0	0	Check	* X N/A
One Time Key In	Main			CABLE ASSY, HOOD	1	53.20	53.20	25.00	39.90	Replace	0	0	Check	* X N/A
One Time Key In	Main			SEAL, RADIATOR TO RH	1	24.80	24.80	25.00	18.60	Replace	0	0	Check	* X N/A
One Time Key In	Main			SEAL, RADIATOR TO LH	1	24.80	24.80	25.00	18.60	Replace	0	0	Check	* X N/A
One Time Key In	Main			GUIDE, RADIATOR AIR , RH	1	54.60	54.60	25.00	40.95	Replace	0	0	Check	* X N/A
One Time Key In	Main			GUIDE, RADIATOR AIR , LH	1	58.80	58.80	25.00	44.10	Replace	0	0	Check	* X N/A
One Time Key In	Main			GROMMET (FOR RADIATOR LOWER SUPPORT)	2	12.70	25.40	25.00	19.05	Replace	0	0	Check	* X N/A
One Time Key In	Main			CUSHION, (FOR RADIATOR UPPER SUPPORT)	2	9.90	19.80	25.00	14.70	Replace	0	0	Check	* X N/A
One Time Key In	Main			GUIDE, RADIATOR AIR , UPPER	1	44.70	44.70	25.00	33.53	Replace	0	0	Check	* X N/A
One Time Key In	Main			RADIATOR ASSY	1	1,841.10	1,841.10	25.00	1,380.82	Replace	0	0	Check	* X N/A

Total Spare Part Cost 29,977.43

Surveyor Total 1,848.88

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 29,977.43

Final Sur Total 1,848.88

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COOLANT	4	12.30	49.20	0.00	49.20	Replace	0	0	Check	* X N/A
One Time Key In	Main			FAN RADIATOR , LH	1	181.80	181.80	25.00	136.35	Replace	0	0	Check	* X N/A
One Time Key In	Main			FAN RADIATOR , RH	1	233.00	233.00	25.00	174.75	Replace	0	0	Check	* X N/A
One Time Key In	Main			FAN SHROUD RADIATOR	1	219.30	219.30	25.00	164.48	Replace	0	0	Check	* X N/A
One Time Key In	Main			MOTOR, COOLING FAN , RH	1	443.40	443.40	10.00	399.06	Replace	0	0	Check	* X N/A
One Time Key In	Main			MOTOR, COOLING FAN , LH	1	543.50	543.50	10.00	489.15	Replace	0	0	Check	* X N/A
One Time Key In	Main			HOSE, RADIATOR , NO.1	1	42.60	42.60	25.00	31.95	Replace	0	0	Check	* X N/A
One Time Key In	Main			HOSE, RADIATOR , NO.2	1	40.20	40.20	25.00	30.15	Replace	0	0	Check	* X N/A
One Time Key In	Main			HOSE, WATER BY-PASS , NO.2	1	37.40	37.40	25.00	28.05	Replace	0	0	Check	* X N/A
One Time Key In	Main			HOSE, WATER BY-PASS , NO.3	1	20.10	20.10	25.00	15.08	Replace	0	0	Check	* X N/A
One Time Key In	Main			HOSE, WATER BY-PASS , NO.4	1	13.20	13.20	25.00	9.90	Replace	0	0	Check	* X N/A
One Time Key In	Main			HOSE, WATER BY-PASS , NO.1	1	37.40	37.40	25.00	28.05	Replace	0	0	Check	* X N/A
One Time Key In	Main			HORN ASSY, HIGH	1	112.80	112.80	25.00	84.60	Replace	0	0	Check	* X N/A
One Time Key In	Main			HORN ASSY, LOW	1	112.80	112.80	25.00	84.60	Replace	0	0	Check	* X N/A
One Time Key In	Main			AIR CON CONDENSER ASSY	1	1,317.70	1,317.70	25.00	988.28	Replace	0	0	Check	* X N/A

Total Spare Part Cost 29,977.43

Surveyor Total 1,848.88

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 29,977.43

Final Sur Total 1,848.88

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TUBE & ACCESSORY	1	574.40	574.40	25.00	430.80	Replace	0	0	Check	X N/A
One Time Key In	Main			HOSE SUB-ASSY, DISCHARGE	1	337.10	337.10	25.00	252.83	Replace	0	0	Check	X N/A
One Time Key In	Main			HOSE, HV WATER PUMP INLET	1	37.90	37.90	25.00	28.42	Replace	0	0	Check	X N/A
One Time Key In	Main			INVERTER WATER PUMP ASSY	1	432.00	432.00	10.00	388.80	Replace	0	0	Check	X N/A
One Time Key In	Main			HOSE, HV WATER PUMP OUTLET	1	29.60	29.60	25.00	22.20	Replace	0	0	Check	X N/A
One Time Key In	Main			HOSE, INVERTER RADIATOR INLET	1	40.70	40.70	25.00	30.53	Replace	0	0	Check	X N/A
One Time Key In	Main			INLET, AIR CLEANER, NO 3	1	35.30	35.30	25.00	26.47	Replace	0	0	Check	X N/A
One Time Key In	Main			INLET, AIR CLEANER, NO 2	1	93.90	93.90	25.00	70.43	Replace	0	0	Check	X N/A
One Time Key In	Main			INLET, AIR CLEANER, NO 1	1	130.50	130.50	25.00	97.88	Replace	0	0	Check	X N/A
One Time Key In	Main			AIR CLEANER ASSY	1	956.20	956.20	25.00	717.15	Replace	0	0	Check	X N/A
One Time Key In	Main			WIRE, ENGINE ROOM MAIN	1	6,138.00	6,138.00	10.00	5,524.20	Replace	0	0	Check	X N/A
One Time Key In	Main			HOOD SUB-ASSY	1	938.40	938.40	25.00	703.80	Replace	0	0	Check	X N/A
One Time Key In	Main			HINGE ASSY, HOOD, RH	1	57.00	57.00	25.00	42.75	Replace	0	0	Check	X N/A
One Time Key In	Main			HINGE ASSY, HOOD, LH	1	57.00	57.00	25.00	42.75	Replace	0	0	Check	X N/A
One Time Key In	Main			INSULATOR, HOOD	1	393.90	393.90	25.00	295.42	Replace	0	0	Check	X N/A

Total Spare Part Cost 29,977.43

Surveyor Total 1,848.88

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 29,977.43

Final Sur Total 1,848.88

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			INSULATOR, HOOD CLIP	6	2.30	13.80	25.00	10.35	Replace	0	0	Check	* X N/A
One Time Key In	Main			WIPER GARNISH LOUVER SUB-ASSY	1	666.90	666.90	25.00	500.17	Replace	0	0	Check	* X N/A
One Time Key In	Main			FENDER SUB-ASSY, FR , LH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair	* X N/A
One Time Key In	Main			UNIT, HEADLAMP , LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Check	* X N/A
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0	Check	* X N/A
One Time Key In	Main			FENDER SUB-ASSY, FR , RH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair	* X N/A
One Time Key In	Main			UNIT, HEADLAMP , RH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Check	* X N/A
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0	Check	* X N/A
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace	* / DEF
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace	* / BUC
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	1	11.10	Replace	* / SCR
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95	Replace	* / NEC
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	* / NEC

Total Spare Part Cost	29,977.43	Surveyor Total	1,848.88
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	29,977.43	Final Sur Total	1,848.88

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	* / NEC
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	* / NEC
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace	* / NEC
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check	* X N/A
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check	* X N/A
One Time Key In	Main			STOPPER, RR BUMPER, RH & LH	2	4.30	8.60	25.00	6.45	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			SEAL, RR BUMPER, RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Check	* X N/A
One Time Key In	Main			SEAL, RR BUMPER, LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Check	* X N/A
One Time Key In	Main			RETAINER, OUTSIDE, RH & LH	2	3.30	6.60	25.00	4.95	Replace	0	0	Check	* X N/A
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	* / NEC
One Time Key In	Main			FILLER, RR BUMPER, RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Check	* X N/A
One Time Key In	Main			FILLER, RR BUMPER, LH	1	119.90	119.90	25.00	89.93	Replace	0	0	Check	* X N/A
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, RH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, RH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Give	* X N/A

Total Spare Part Cost 29,977.43

Surveyor Total 1,848.88

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 29,977.43

Final Sur Total 1,848.88

SMRT Recommendation											Surveyor Approval			
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Givt	* X M/I
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Check	* X M/I
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Check	* X M/I
One Time Key In	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	0	0	Check	* X M/I
One Time Key In	Main			COVER, REAR FLOOR UNDER, RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Not Givt	* X M/I
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Not Givt	* X M/I
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.90	222.90	25.00	186.95	Replace	0	0	Not Givt	* X M/I
One Time Key In	Main			TAIL GATE PANEL, SUB-ASSY, BACK DOOR	1	929.50	929.50	25.00	697.20	Replace	0	0	Not Givt	* X M/I
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	1	0	Repair	* X R
One Time Key In	Main			STICKER SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	* / NEC
One Time Key In	Main			STICKER DECAL 8555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	* / NEC
One Time Key In	Main			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	* / NEC
One Time Key In	Main			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	* / NEC
Total Spare Part Cost									29,977.43			Surveyor Total	1,848.88	
Lump Sum Discount (%)									0.00			Lump Sum Dis (%)	0	
Final Spare Part Cost									29,977.43			Final Sur Total	1,848.88	

Labour's Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			2,535.00	1,000.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	1,690.00	600	
2	Main	TO REPAIR REAR PORTION	845.00	400	
Total:			2,535.00	1,000.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
3	Main	TO REPSRAY FRONT HOOD	378.00	0	
4	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
5	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
6	Main	TO REPSRAY REAR BUMPER	378.00	200	
7	Main	TO RESPRAY BUMPER BEAM	180.00	0	
8	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	0	
9	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	0	
10	Main	TO RESPRAY REAR PANEL	180.00	0	
11	Main	TO RESPRAY TAIL GATE	378.00	0	
12	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100	
Total:			3,348.00	900.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	40	
3	Main	TO CHECK & REBET SYSTEM FUNCTION	350.00	0	
Total:			1,760.00	110.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
4	Main	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	0	
5	Main	TO REMOVE AND REFIT WIRE HARDESS	250.00	0	
6	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
7	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	40	
8	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	
9	Main	TO TOP UP A/C GAS	120.00	0	
10	Main	TO CONDUCT RADIATOR PRESSURE CHECK	120.00	0	
11	Main	TO REPLACE SUNDRY PARTS	100.00	0	
12	Main	TO WASH AND VACUUM	90.00	0	
Total:			1,760.00	110.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	29,977.43	1,848.88
Total Labour Cost	2,535.00	1,000.00
Total Spray Painting	3,348.00	900.00
Other	1,760.00	110.00
Overall Total	37,620.43	3,858.88
Lump Sum Repair Option		
Lump Sum Total	0.00	3,858.88
Surveyor Approved Amount		3,858.88
No of Repair Days*	17	6
Remarks	-	p/p repair, photo before paint.
Surveyor Name		Heee je

Estimator Assessment(\$)

Surveyor Assessment(\$)

Signature

d

Save Clear

Survey Date

08/02/2019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLEMENT PARTS

Contractor		Date of Collection	1 / 1
Accident Case Number	TAX/02/19/2010	Date of Request	12/02/2019
Vehicle No	SUB 5057 2	Number of Days to Extend (if any)	2
Vehicle Model	TOYOTA PRINS 4		

S/N	Part Number	Part Description	Quantity	Unit Price	
		TAILGATE BACK DOOR OUTER GARNISH	1pc	✓	CRA \$608.40
		REAR BUMPER REINFORCEMENT	1pc	DD	\$239.10
		FRONT BUMPER FOAM	1pc	✓ CRA	\$52.73
		INLET AIR CLEANER NO.2	1pc	✓ BVC	\$70.43
		HEAD LAMP RH	1pc	✓ CRA	\$2,303.01
		SUPPORT S/A UPPER	1pc	DD	\$273.68

<< Please submit photographs for damaged parts >>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
(to be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the appropriate penalties.

For SMRT Head Office

Acknowledge By	ARC Executive / Supervisor / SA	
Approved By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YRS / NO.	Date of submission

Pg 1/2

REQUEST FOR SUPPLEMENT PARTS

Contractor:		Date of Collection:	1 / 1
Account No. / Number:	TAX / 02/19/2010	Date of Request:	12 / 02 / 2019
Vehicle No. / Make:	SUB 5057 2	Number of Days to extend (if any):	3 2
Vehicle Model:	TOYOTA PRIUS 4		

SN	Number	Part Description	Quantity	Unit Price	
		SUPPORT S/A RH	1pc	✓ DD	\$177.75
		REVERSE SENSOR	1 SET	✓ Shorted	\$180
		FILLER / REAR BUMPER LH	1pc	✓ DEF	\$89.93
		TAILGATE WEATHERSTRIP	1pc	✓ CUT	\$170.53
		Request ADDITIONAL REPAIR PARTS			

Please submit photographs for damaged parts

13/2/19

[Signature]

I hereby declare that:- Supplementary Parts are raised for replacement for the aforesaid

Signature of person making this declaration
(to be signed in front of an authorised witness)

I am a true and correct copy, and I make it with the understanding and belief that a person who makes false declaration is

ARC Executive / Supervisor / SA	
Surveyor / In-house Staff	
MRT Stars / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
YES / NO	Date of submission

P 1/2

Case Details

Case Reference Number : TAX/02/19/2010
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5057Z

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-5619-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 02/02/2019 02:45 PM
 Vehicle Age(In Months) : 15

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Approval		Remarks	
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)		Repair/Replace
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace	DEF
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Check	
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Check	
One Time Key In	Main			COVER, FR BUMPER RH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Give	
One Time Key In	Main			COVER, FR BUMPER LH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Give	
One Time Key In	Main			BRACKET, FR BUMPER	1	99.80	99.80	25.00	74.85	Replace	1	74.85	Replace	CRA
One Time Key In	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	1	25.00	Replace	MIS
One Time Key In	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	1	35.00	Replace	CRA
One Time Key In	Main			SEAL, HOOD TO FR END	1	24.40	24.40	25.00	18.30	Replace	0	0	Not Give	
One Time Key In	Main			EMBLEM ASSY FRONT	1	87.10	87.10	25.00	65.32	Replace	1	65.32	Replace	NEC

Total Spare Part Cost 29,977.43

Surveyor Total 1,848.88

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 29,977.43

Final Sur Total 1,848.88

BOM Type	Costing Type	Portion	Material Number	Part Name	SMRT Recommendation						Surveyor Approval			Remarks
					Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	0	0	Not Give	
One Time Key In	Main			GRILLE SUB-ASSY	1	335.60	335.60	25.00	251.70	Replace	1	251.70	Replace	BUC
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	NEC
One Time Key In	Main			RETAINER, FR BUMPER, LH & RH	2	8.50	17.00	25.00	12.75	Replace	0	0	Check	
One Time Key In	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	0	0	Check	
One Time Key In	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0	Check	
One Time Key In	Main			REINFORCEMENT FRONT LOWER	1	238.50	238.50	25.00	178.88	Replace	0	0	Check	
One Time Key In	Main			ABSORBER, FR BUMPER LOWER	1	117.00	117.00	25.00	87.75	Replace	0	0	Check	
One Time Key In	Main			EXTENSION SUB-ASSY, LH	1	116.30	116.30	25.00	87.22	Replace	0	0	Check	
One Time Key In	Main			EXTENSION SUB-ASSY, RH	1	116.30	116.30	25.00	87.22	Replace	0	0	Check	
One Time Key In	Main			COVER, RADIATOR	1	227.80	227.80	25.00	170.85	Replace	0	0	Check	
One Time Key In	Main			SUPPORT S/A UPPER	1	364.90	364.90	25.00	273.67	Replace	0	0	Check	
One Time Key In	Main			SUPPORT S/A RH	1	237.00	237.00	25.00	177.75	Replace	0	0	Check	
One Time Key In	Main			SUPPORT S/A LH	1	237.00	237.00	25.00	177.75	Replace	0	0	Check	
One Time Key In	Main			SUPPORT SUB-ASSY LOWER	1	397.40	397.40	25.00	298.05	Replace	0	0	Check	

Total Spare Part Cost	29,977.43	Surveyor Total	1,848.88
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	29,977.43	Final Sur Total	1,848.88

BOM Type	Posting Type	Portion	Material Number	Part Name	SMRT Recommendation						Surveyor Approval			Remarks
					Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			SUPPORT, RADIATOR UPPER RH	1	76.70	76.70	25.00	57.53	Replace	0	0	Check	▼
One Time Key In	Main			SUPPORT, RADIATOR UPPER LH	1	76.70	76.70	25.00	57.53	Replace	0	0	Check	▼
One Time Key In	Main			CUSHION HOOD BUMPER	2	8.50	17.00	25.00	12.75	Replace	0	0	Check	▼
One Time Key In	Main			GUIDE, RADIATOR AIR,	1	93.90	93.90	25.00	70.43	Replace	0	0	Check	▼
One Time Key In	Main			BRACE, HOOD LOCK SUPPORT	1	76.20	76.20	25.00	57.15	Replace	0	0	Not Give	▼
One Time Key In	Main			LOCK ASSY, HOOD	1	131.10	131.10	25.00	98.32	Replace	0	0	Check	▼
One Time Key In	Main			CABLE ASSY, HOOD	1	53.20	53.20	25.00	39.90	Replace	0	0	Check	▼
One Time Key In	Main			SEAL, RADIATOR TO RH	1	24.80	24.80	25.00	18.60	Replace	0	0	Check	▼
One Time Key In	Main			SEAL, RADIATOR TO LH	1	24.80	24.80	25.00	18.60	Replace	0	0	Check	▼
One Time Key In	Main			GUIDE, RADIATOR AIR , RH	1	54.60	54.60	25.00	40.95	Replace	0	0	Check	▼
One Time Key In	Main			GUIDE, RADIATOR AIR , LH	1	58.80	58.80	25.00	44.10	Replace	0	0	Check	▼
One Time Key In	Main			GROMMET (FOR RADIATOR LOWER SUPPORT)	2	12.70	25.40	25.00	19.05	Replace	0	0	Check	▼
One Time Key In	Main			CUSHION, (FOR RADIATOR UPPER SUPPORT)	2	9.80	19.60	25.00	14.70	Replace	0	0	Check	▼
One Time Key In	Main			GUIDE, RADIATOR AIR , UPPER	1	44.70	44.70	25.00	33.53	Replace	0	0	Check	▼
One Time Key In	Main			RADIATOR ASSY	1	1,841.10	1,841.10	25.00	1,380.82	Replace	0	0	Check	▼

Total Spare Part Cost 29,977.43

Surveyor Total 1,848.88

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 29,977.43

Final Sur Total 1,848.88