



Section A - Accident Details	
Registration Number	SHB5057Z
Case Reference Number	TAXI02/19/2910
Registration Date	1/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PROUS4
Name of Driver	TOH KHENG CHAI CHARLIE
Type of Accident	Head to Rear
Accident Date and Time	2/2/2019 10:45 PM
Accident Reported Date and Time	4/2/2019 11:50 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24099093
Special Instruction to ARC, if any	DROVE IN /TP
Prepared Date and Time	7/2/2019 9:26 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



h/h

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,535.00	\$1,000.00
Total Spray Cost	\$3,348.00	\$900.00
Total Spare Part Cost	\$32,556.68	\$6,174.49
Total Other Cost	\$1,700.00	\$110.00
TOTAL COST	\$40,201.68	\$8,184.49 (PIP)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	17.0	6.0
Prepared / Adjusted By	Kim Ming Chin	Hwee Jie (LRK) / AIG
ARC / Surveyor Sign Off Date	08/02/2019 12:09 AM	08/02/2019 11:43 AM
Signature		
Remarks		p/p repair, photo before paint.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
10 Woodlands Industrial Park 2A, Singapore
FAE Number: 0502552
Customer Telephone Number: 68922023
Accident Handling Number: 0442072

Date Generated: 16/08/2019
User ID: Pethuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0203	Invoice Number	
Quotation Date	16.08.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$1,690.00	\$900.00
TO REPAIR REAR PORTION	\$845.00	\$400.00
Total Labour	\$2,535.00	\$1,000.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO REPSRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO REPSRAY FRONT HOOD	\$378.00	\$0.00
TO REPSRAY FRONT FENDER LH	\$378.00	\$200.00
TO REPSRAY FRONT FENDER RH	\$378.00	\$200.00
TO REPSRAY REAR BUMPER	\$378.00	\$200.00
TO REPSRAY BUMPER BEAM	\$180.00	\$0.00
TO REPSRAY FILLER RR BUMPER LH	\$180.00	\$0.00
TO REPSRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO REPSRAY REAR PANEL	\$180.00	\$0.00
TO REPSRAY TAIL GATE	\$378.00	\$0.00
TO REPSRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$3,348.00	\$900.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$40.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$0.00
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$250.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$40.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO TOP UP A/C GAS	\$120.00	\$0.00
TO CONDUCT RADIATOR PRESSURE CHECK	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$80.00	\$0.00
Total Other Costs	\$1,760.00	\$110.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Description	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		62119479 B2	COVER, FR BUMPER	1	\$495.50	25.00	\$371.63	Replace	Replace




SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
31 Woodlands Industrial Park 2A, Singapore
Tel Number: 6388522
Estimate Telephone Number: 3866203
Accident Reporting Number: 4888272

Date Generated: 16/03/2018

Sheet No: 1 of 2

Table with columns for Part Number, Description, Quantity, Unit Price, Total Price, Labor Price, Material Price, Action, and Status. Rows include parts like SUPPORT, FR BUMPER RH, SEAL, HOOD TO FR END, EMBLEM ASSY FRONT, GRILLE, RADIATOR, CLIPS PIECE, FRT & RR BUMPER, RETAINER, FR BUMPER, LH & RH, REINFORCEMENT FRONT UPPER, ABSORBER, FR BUMPER, REINFORCEMENT FRONT LOWER, ABSORBER, FR BUMPER LOWER, EXTENSION SUB-ASSY, LH, EXTENSION SUB-ASSY, RH, COVER, RADIATOR, SUPPORT SIA LH, SUPPORT SUB-ASSY LOWER, SUPPORT, RADIATOR UPPER RH, SUPPORT, RADIATOR UPPER LH, CUSHION HOOD BUMPER, GUIDE, RADIATOR AIR, BRACE, HOOD LOCK SUPPORT, LOCK ASSY, HOOD, CABLE ASSY, HOOD, SEAL, RADIATOR TO RH, SEAL, RADIATOR TO LH, GUIDE, RADIATOR AIR, RH, GUIDE, RADIATOR AIR, LH, GROMMET (FOR RADIATOR LOWER CUSHION, (FOR RADIATOR UPPER), GUIDE, RADIATOR AIR UPPER, RADIATOR ASSY, COOLANT, FAN RADIATOR, LH, FAN RADIATOR, RH, FAN SHROUD RADIATOR, MOTOR, COOLING FAN, RH, MOTOR, COOLING FAN, LH, HOSE, RADIATOR, NO.1, HOSE, RADIATOR, NO.2.




SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 30 Woodlands Industrial Park East, Singapore
 Tel: 6500 0000
 Estimate Tracking Number: 9880202
 Accident Reporting Number: 18880272

Date Generated: 18/05/2014
 Sheet 10 of 10 Pages

16264371 20	HOSE, WATER BY-PASS NO.2	0.00	\$37.40	0.00	\$0.00	Replace	Check	X
16267370 80	HOSE, WATER BY-PASS NO.3	0.00	\$20.10	0.00	\$0.00	Replace	Check	X
16261371 00	HOSE, WATER BY-PASS NO.4	0.00	\$13.20	0.00	\$0.00	Replace	Check	X
16261371 50	HOSE, WATER BY-PASS NO.1	0.00	\$37.40	0.00	\$0.00	Replace	Check	X
86510470 50	HORN ASSY, HIGH	0.00	\$112.80	0.00	\$0.00	Replace	Check	X
86520470 30	HORN ASSY, LOW	0.00	\$112.80	0.00	\$0.00	Replace	Check	X
89460103 20	AIR CON CONDENSER ASSY	0.00	\$1,317.70	0.00	\$0.00	Replace	Check	X
88710471 50	TUBE & ACCESSORY	0.00	\$574.40	0.00	\$0.00	Replace	Check	X
88703470 80	HOSE SUB-ASSY, DISCHARGE	0.00	\$337.10	0.00	\$0.00	Replace	Check	X
G922E470 10	HOSE, HV WATER PUMP INLET	0.00	\$37.90	0.00	\$0.00	Replace	Check	X
G9040470 40	INVERTER WATER PUMP ASSY	0.00	\$432.00	0.00	\$0.00	Replace	Check	X
G922F470 10	HOSE, HV WATER PUMP OUTLET	0.00	\$29.80	0.00	\$0.00	Replace	Check	X
G922H47 010	HOSE, INVERTER RADIATOR INLET	0.00	\$40.70	0.00	\$0.00	Replace	Check	X
17753370 10	INLET, AIR CLEANER, NO 3	0.00	\$35.30	0.00	\$0.00	Replace	Check	X
17751371 10	INLET, AIR CLEANER, NO 1	0.00	\$130.50	0.00	\$0.00	Replace	Check	X
17700373 30	AIR CLEANER ASSY	0.00	\$908.20	0.00	\$0.00	Replace	Check	X
8211147J 21	WIRE, ENGINE ROOM MAIN	0.00	\$6,138.00	0.00	\$0.00	Replace	Check	X
53301471 10	HOOD SUB-ASSY	0.00	\$938.40	0.00	\$0.00	Replace	Check	X
53410471 30	HINGE ASSY, HOOD, RH	0.00	\$57.00	0.00	\$0.00	Replace	Check	X
53420471 30	HINGE ASSY, HOOD, LH	0.00	\$37.00	0.00	\$0.00	Replace	Check	X
53341470 40	INSULATOR, HOOD	0.00	\$383.90	0.00	\$0.00	Replace	Check	X
90467090 50	INSULATOR, HOOD CLIP	0.00	\$2.30	0.00	\$0.00	Replace	Check	X
52708472 30	WIPER GARNISH LOUVER SUB-ASSY	0.00	\$685.90	0.00	\$0.00	Replace	Check	X
53802471 00	FENDER SUB-ASSY, FR., LH	1.00	\$933.10	100.00	\$0.00	Replace	Repair	L
81185476 91	UNIT, HEADLAMP, LH	0.00	\$2,558.90	0.00	\$0.00	Replace	Check	X
75374471 40	EMBLEM, SIDE PANEL (HYBRID)	0.00	\$52.90	0.00	\$0.00	Replace	Not Given	X
81055476 90	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check	X
53801470 80	FENDER SUB-ASSY, FR., RH	1.00	\$933.10	100.00	\$0.00	Replace	Repair	L
81145476 91	UNIT, HEADLAMP, RH	0.00	\$2,558.90	0.00	\$0.00	Replace	Check	X
75374471 40	EMBLEM, SIDE PANEL (HYBRID)	0.00	\$52.90	0.00	\$0.00	Replace	Not Given	X
81016470 90	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check	X
52189479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace	✓
52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace	✓



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 30 Woodlands Industrial Park EA, Singapore
 Tax Number: 13022562
 Company Registration Number: 19902223
 Accident Reporting Number: 19902071

Date Generated: 19/02/2018
 User ID: j. Pothan

	52189470 20	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	Replace	Replace	✓
	52481470 10	PAD, RR BUMPER, CTR	3.00	\$2.20	25.00	\$4.95	Replace	Replace	✓
	52462470 30	PAD, RR BUMPER, RH & LH_1	2.00	\$3.80	25.00	\$5.70	Replace	Replace	✓
	52462470 20	PAD, RR BUMPER, RH & LH_2	2.00	\$3.80	25.00	\$5.70	Replace	Replace	✓
	52462470 10	PAD, RR BUMPER, RH & LH_3	2.00	\$3.80	25.00	\$5.70	Replace	Replace	✓
	52191470 30	SEAL, RR BUMPER ARM, RH & LH	2.00	\$11.00	25.00	\$18.50	Replace	Replace	✓
	5259680 30	STOPPER, RR BUMPER, RH & LH	0.00	\$4.30	0.00	\$0.00	Replace	Not Given	✗
	52591470 50	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Check	✗
	52592470 40	SEAL, RR BUMPER, LH	0.00	\$85.20	0.00	\$0.00	Replace	Check	✗
	75302352 20	RETAINER, OUTSIDE, RH & LH	0.00	\$3.30	0.00	\$0.00	Replace	Check	✗
		PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	✓
	52565479 00	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Check	✗
	81501470 10	LENS & BODY ASSY, RR BUMPER, RH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	✗
	81591470 10	LENS & BODY ASSY, RR BUMPER, LH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	✗
	81551472 81	LENS & BODY, REAR COMBINATION LAMP, RH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	✗
	81561471 51	LENS & BODY, REAR COMBINATION LAMP, LH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	✗
	52575470 40	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Check	✗
	52576470 40	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Check	✗
	58307470 90	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$829.80	0.00	\$0.00	Replace	Check	✗
	58398470 50	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	✗
	58386470 30	COVER, REAR FLOOR UNDER, LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given	✗
	66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given	✗
	67005474 40	TAIL GATE PANEL SUB-ASSY, BACK DOOR	0.00	\$929.80	0.00	\$0.00	Replace	Not Given	✗
		STICKER SMART LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓
		STICKER DECAL 6555 8888	1.00	\$21.00	0.00	\$21.00	Replace	Replace	✓
	75141470 90	NAME PLATE (HYBRID), LUGGAGE	1.00	\$52.30	25.00	\$39.23	Replace	Replace	✓
	75442471 30	NAME PLATE (PRUS), LUGGAGE	1.00	\$52.30	25.00	\$39.23	Replace	Replace	✓
Total				\$34,322.70		\$1,848.93			

6174.49
 +1000.00
 +1010.00

 8184.49

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (I)	ARC Check	Surveyor Check
		53205470 00	SUPPORT SIA UPPER	1.00	\$364.90	25.00	\$273.68	Replace	Replace
		53202479 01	SUPPORT SIA RH	1.00	\$237.00	25.00	\$177.75	Replace	Replace
		17752371 21	INLET, AIR CLEANER, NO 2	1.00	\$93.90	25.00	\$70.43	Replace	Replace
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
		82023470 30	REAR BUMPER REINFORCEMENT	1.00	\$318.80	25.00	\$239.10	Replace	Replace
		52568470 00	FILLER, RR BUMPER, LH	1.00	\$119.90	25.00	\$89.93	Replace	Replace
		76801471 1051	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$861.20	25.00	\$646.40	Replace	Replace
		52611471 40	ABSORBER, FR BUMPER	1.00	\$70.30	25.00	\$52.73	Replace	Replace
		81145478 81	UNIT, HEADLAMP, RH	1.00	\$2,358.90	25.00	\$2,303.01	Replace	Replace
		87881470 50	TAIL GATE WEATHERSTRIP, BACK	1.00	\$360.70	25.00	\$270.53	Replace	Replace
Total					5,195.60		4,325.56		



Case Details

Case Reference Number : TAX/02/19/2010
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5057Z

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-5619-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 02/02/2019 02:45 PM
 Vehicle Age(In Months) : 15

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SOH Type	Coating Type	Partion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Approval			Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace	DEF
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Check	X NMI
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Check	X NMI
One Time Key In	Main			COVER, FR BUMPER RH	1	23.10	23.10	25.00	21.08	Replace	0	0	Not Give	X NMI
One Time Key In	Main			COVER, FR BUMPER LH	1	23.10	23.10	25.00	21.08	Replace	0	0	Not Give	X NMI
One Time Key In	Main			BRACKET, FR BUMPER	1	99.80	99.80	25.00	74.85	Replace	1	74.85	Replace	/ CRA
One Time Key In	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	1	25.00	Replace	/ M13
One Time Key In	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	1	35.00	Replace	/ CRA
One Time Key In	Main			SEAL, HOOD TO FR END	1	24.40	24.40	25.00	18.30	Replace	0	0	Not Give	X NMI
One Time Key In	Main			EMBLEM ASSY FRONT	1	87.10	87.10	25.00	65.22	Replace	1	65.22	Replace	/ NEC
Total Spare Part Cost						29,977.43			Surveyor Total	1,848.88				
Lump Sum Discount (%)						0.00			Lump Sum Dis (%)	0				
Final Spare Part Cost						29,977.43			Final Sur Total	1,848.88				

SMRT Recommendation											Surveyor Approval			
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	0	0	Not Givn	* X N/A
One Time Key In	Main			GRILLE SUB-ASSY	1	335.60	335.60	25.00	251.70	Replace	1	251.70	Replace	/ PUC
One Time Key In	Main			CLIPS PIECE, FRIT & RR BUMPER	10	1.00	15.00	25.00	11.25	Replace	10	11.25	Replace	/ HEC
One Time Key In	Main			RETAINER, FR BUMPER, LH & RH	2	8.00	17.00	25.00	12.75	Replace	0	0	Check	* X N/A
One Time Key In	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	0	0	Check	* X N/A
One Time Key In	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0	Check	* X N/A
One Time Key In	Main			REINFORCEMENT FRONT LOWER	1	238.50	238.50	25.00	178.58	Replace	0	0	Check	* X N/A
One Time Key In	Main			ABSORBER, FR BUMPER LOWER	1	117.00	117.00	25.00	87.75	Replace	0	0	Check	* X N/A
One Time Key In	Main			EXTENSION SUB-ASSY, LH	1	116.30	116.30	25.00	87.22	Replace	0	0	Check	* X N/A
One Time Key In	Main			EXTENSION SUB-ASSY, RH	1	116.30	116.30	25.00	87.22	Replace	0	0	Check	* X N/A
One Time Key In	Main			COVER, RADIATOR	1	227.80	227.80	25.00	170.85	Replace	0	0	Check	* X N/A
One Time Key In	Main			SUPPORT S/A UPPER	1	304.90	304.90	25.00	227.87	Replace	0	0	Check	* X N/A
One Time Key In	Main			SUPPORT S/A RH	1	237.00	237.00	25.00	177.75	Replace	0	0	Check	* X N/A
One Time Key In	Main			SUPPORT S/A LH	1	237.00	237.00	25.00	177.75	Replace	0	0	Check	* X N/A
One Time Key In	Main			SUPPORT SUB-ASSY LOWER	1	307.40	307.40	25.00	229.35	Replace	0	0	Check	* X N/A

Total Spare Part Cost 26,977.43

Surveyor Total 1,848.88

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 26,977.43

Final Sur Total 1,848.88

SMART Recommendation											Surveyor Approval			
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SUPPORT, RADIATOR UPPER RH	1	76.70	76.70	25.00	57.53	Replace	0	0	Check	X N/A
One Time Key In	Main			SUPPORT, RADIATOR UPPER LH	1	76.70	76.70	25.00	57.53	Replace	0	0	Check	X N/A
One Time Key In	Main			CUSHION HOOD BUMPER	2	8.50	17.00	25.00	12.75	Replace	0	0	Check	X N/A
One Time Key In	Main			GUIDE, RADIATOR AIR,	1	93.90	93.90	25.00	70.43	Replace	0	0	Check	X N/A
One Time Key In	Main			BRACE, HOOD LOCK SUPPORT	1	76.20	76.20	25.00	57.15	Replace	0	0	Not Give	X N/A
One Time Key In	Main			LOCK ASSY, HOOD	1	121.10	121.10	25.00	96.32	Replace	0	0	Check	X N/A
One Time Key In	Main			CABLE ASSY, HOOD	1	53.20	53.20	25.00	39.90	Replace	0	0	Check	X N/A
One Time Key In	Main			SEAL, RADIATOR TO RH	1	24.80	24.80	25.00	18.60	Replace	0	0	Check	X N/A
One Time Key In	Main			SEAL, RADIATOR TO LH	1	24.80	24.80	25.00	18.60	Replace	0	0	Check	X N/A
One Time Key In	Main			GUIDE, RADIATOR AIR, RH	1	54.60	54.60	25.00	40.95	Replace	0	0	Check	X N/A
One Time Key In	Main			GUIDE, RADIATOR AIR, LH	1	58.80	58.80	25.00	44.10	Replace	0	0	Check	X N/A
One Time Key In	Main			GROMET (FOR RADIATOR LOWER SUPPORT)	2	12.70	25.40	25.00	18.00	Replace	0	0	Check	X N/A
One Time Key In	Main			CUSHION, (FOR RADIATOR UPPER SUPPORT)	2	8.00	16.00	25.00	14.75	Replace	0	0	Check	X N/A
One Time Key In	Main			GUIDE, RADIATOR AIR, UPPER	1	44.70	44.70	25.00	33.53	Replace	0	0	Check	X N/A
One Time Key In	Main			RADIATOR ASSY	1	1,841.10	1,841.10	25.00	1,380.83	Replace	0	0	Check	X N/A

Total Spare Part Cost 25,977.43

Surveyor Total 1,548.88

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 25,977.43

Final Sur Total 1,548.88

SMRT Recommendation											Surveyor Approval			
ROM Type	Casting Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(S)	List Price(S)	Dis(%)	Final Price(S)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(S)	Repair/Replace	Remarks
One Time Key In	Main			COOLANT	4	12.30	49.20	0.00	49.20	Replace	0	0	Check	X N/A
One Time Key In	Main			FAN RADIATOR , LH	1	181.80	181.80	25.00	136.35	Replace	0	0	Check	X N/A
One Time Key In	Main			FAN RADIATOR , RH	1	233.00	233.00	25.00	174.75	Replace	0	0	Check	X N/A
One Time Key In	Main			FAN SHROUD RADIATOR	1	219.20	219.20	25.00	164.48	Replace	0	0	Check	X N/A
One Time Key In	Main			MOTOR, COOLING FAN , RH	1	443.40	443.40	10.00	399.06	Replace	0	0	Check	X N/A
One Time Key In	Main			MOTOR, COOLING FAN , LH	1	543.50	543.50	10.00	489.15	Replace	0	0	Check	X N/A
One Time Key In	Main			HOSE, RADIATOR , NO.1	1	42.80	42.80	25.00	32.05	Replace	0	0	Check	X N/A
One Time Key In	Main			HOSE, RADIATOR , NO.2	1	40.20	40.20	25.00	30.15	Replace	0	0	Check	X N/A
One Time Key In	Main			HOSE, WATER BY-PASS , NO.2	1	37.40	37.40	25.00	28.05	Replace	0	0	Check	X N/A
One Time Key In	Main			HOSE, WATER BY-PASS , NO.3	1	20.10	20.10	25.00	15.08	Replace	0	0	Check	X N/A
One Time Key In	Main			HOSE, WATER BY-PASS , NO.4	1	13.20	13.20	25.00	9.90	Replace	0	0	Check	X N/A
One Time Key In	Main			HOSE, WATER BY-PASS , NO.1	1	27.40	27.40	25.00	20.55	Replace	0	0	Check	X N/A
One Time Key In	Main			HORN ASSY, HIGH	1	112.80	112.80	25.00	84.60	Replace	0	0	Check	X N/A
One Time Key In	Main			HORN ASSY, LOW	1	112.80	112.80	25.00	84.60	Replace	0	0	Check	X N/A
One Time Key In	Main			AIR CON CONDENSER ASSY	1	1,317.70	1,317.70	25.00	988.28	Replace	0	0	Check	X N/A
Total Spare Part Cost						29,877.43							Surveyor Total	1,848.88
Lump Sum Discount (%)						0.00							Lump Sum Dis (%)	0
Final Spare Part Cost						29,877.43							Final Sur Total	1,848.88

SMRT Recommendation											Surveyor Approval			
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TUBE & ACCESSORY	1	374.40	374.40	25.00	430.80	Replace	0	0	Check	X N/A
One Time Key In	Main			HOSE SUB-ASSY, DISCHARGE	1	337.10	337.10	25.00	252.83	Replace	0	0	Check	X N/A
One Time Key In	Main			HOSE, HV WATER PUMP INLET	1	37.90	37.90	25.00	28.42	Replace	0	0	Check	X N/A
One Time Key In	Main			INVERTER WATER PUMP ASSY	1	432.00	432.00	10.00	388.80	Replace	0	0	Check	X N/A
One Time Key In	Main			HOSE, HV WATER PUMP OUTLET	1	23.60	23.60	25.00	17.70	Replace	0	0	Check	X N/A
One Time Key In	Main			HOSE, INVERTER RADIATOR INLET	1	40.70	40.70	25.00	30.52	Replace	0	0	Check	X N/A
One Time Key In	Main			INLET, AIR CLEANER, NO 2	1	35.30	35.30	25.00	26.47	Replace	0	0	Check	X N/A
One Time Key In	Main			INLET, AIR CLEANER, NO 2	1	93.90	93.90	25.00	70.42	Replace	0	0	Check	X N/A
One Time Key In	Main			INLET, AIR CLEANER, NO 1	1	130.00	130.00	25.00	97.50	Replace	0	0	Check	X N/A
One Time Key In	Main			AIR CLEANER ASSY	1	958.20	958.20	25.00	718.65	Replace	0	0	Check	X N/A
One Time Key In	Main			WIRE, ENGINE ROOM MAIN	1	6,138.00	6,138.00	10.00	5,524.20	Replace	0	0	Check	X N/A
One Time Key In	Main			HOOD SUB-ASSY	1	938.40	938.40	25.00	703.80	Replace	0	0	Check	X N/A
One Time Key In	Main			HINGE ASSY, HOOD, RH	1	57.00	57.00	25.00	42.75	Replace	0	0	Check	X N/A
One Time Key In	Main			HINGE ASSY, HOOD, LH	1	57.00	57.00	25.00	42.75	Replace	0	0	Check	X N/A
One Time Key In	Main			INSULATOR, HOOD	1	393.90	393.90	25.00	295.42	Replace	0	0	Check	X N/A

Total Spare Part Cost	29,977.43	Surveyor Total	1,848.88
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	29,977.43	Final Sur Total	1,848.88

SMART Recommendation											Surveyor Approval			
BOM Type	Coating Type	Partion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			INSULATOR, HOOD CLIP	6	2.30	13.80	25.00	10.35	Replace	0	0	Check	* X N/A
One Time Key In	Main			WIPER GARNISH LOUVER SUB-ASSY	1	666.90	666.90	25.00	506.17	Replace	0	0	Check	* X N/A
One Time Key In	Main			FENDER SUB-ASSY, FR, LH	1	933.10	933.10	25.00	698.83	Replace	1	0	Repair	* X N/A
One Time Key In	Main			UNIT, HEADLAMP, LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Check	* X N/A
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	32.90	32.90	25.00	24.67	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1	496.40	496.40	10.00	437.76	Replace	0	0	Check	* X N/A
One Time Key In	Main			FENDER SUB-ASSY, FR, RH	1	933.10	933.10	25.00	698.83	Replace	1	0	Repair	* X N/A
One Time Key In	Main			UNIT, HEADLAMP, RH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Check	* X N/A
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	32.90	32.90	25.00	24.67	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	1	496.40	496.40	10.00	437.76	Replace	0	0	Check	* X N/A
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.82	Replace	1	317.83	Replace	* / DEF
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.73	Replace	* / BUL
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	11.80	14.80	25.00	11.10	Replace	1	11.10	Replace	* / SCR
One Time Key In	Main			PAD, RR BUMPER, CTR	2	2.20	4.40	25.00	4.95	Replace	2	4.95	Replace	* / NEC
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 2	2	3.85	7.60	25.00	5.70	Replace	2	5.70	Replace	* / NEC

Total Spare Part Cost	29,877.43	Surveyor Total	1,948.88
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	29,877.43	Final Sur Total	1,948.88

SMART Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	/ NEC
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	/ NEC
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace	/ NEC
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check	X N/A
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	238.10	Replace	0	0	Check	X N/A
One Time Key In	Main			STOPPER, RR BUMPER, RH & LH	2	4.30	8.60	25.00	6.45	Replace	0	0	Not Give	X N/A
One Time Key In	Main			SEAL, RR BUMPER, RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Check	X N/A
One Time Key In	Main			SEAL, RR BUMPER, LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Check	X N/A
One Time Key In	Main			RETAINER, OUTSIDE, RH & LH	2	2.35	4.70	25.00	4.95	Replace	0	0	Check	X N/A
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	/ NEC
One Time Key In	Main			FILLER, RR BUMPER, RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Check	X N/A
One Time Key In	Main			FILLER, RR BUMPER, LH	1	119.90	119.90	25.00	89.93	Replace	0	0	Check	X N/A
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, RH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give	X N/A
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give	X N/A
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, RH	1	428.10	428.10	10.00	385.29	Replace	0	0	Not Give	X N/A

Total Spare Part Cost	29,977.43	Surveyor Total	1,848.88
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	29,977.43	Final Sur Total	1,848.88

SMRT Recommendation											Surveyor Approval			
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Check	* X N/A
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.00	111.00	25.00	83.53	Replace	0	0	Check	* X N/A
One Time Key In	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	609.90	609.90	25.00	472.35	Replace	0	0	Check	* X N/A
One Time Key In	Main			COVER, REAR FLOOR UNDER, RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.00	222.00	25.00	168.95	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	1	0	Repair	* X R
One Time Key In	Main			STICKER SMRT LOGO	1	7.90	7.90	0.00	7.90	Replace	1	7.90	Replace	* / NEC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	* / NEC
One Time Key In	Main			NAME PLATE (RR/RD), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	* / NEC
One Time Key In	Main			NAME PLATE (RR/L), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	* / NEC
Total Spare Part Cost									29,977.43	Surveyor Total		1,848.88		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									29,977.43	Final Sur Total		1,848.88		

Labour's Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1			2,536.00	1,000.00	

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Man	TO REPAIR FRONT PORTION	1,090.00	600	
2	Man	TO REPAIR REAR PORTION	845.00	400	
Total:			2,585.00	1,000.00	

Spray Coat Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Man	TO RESPRAY FRONT BUMPER	375.00	200	
2	Man	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
3	Man	TO RESPRAY FRONT HOOD	375.00	0	
4	Man	TO RESPRAY FRONT FENDER LH	375.00	200	
5	Man	TO RESPRAY FRONT FENDER RH	375.00	200	
6	Man	TO RESPRAY REAR BUMPER	375.00	200	
7	Man	TO RESPRAY BUMPER BEAM	180.00	0	
8	Man	TO RESPRAY FILLER RR BUMPER LH	180.00	0	
9	Man	TO RESPRAY FILLER RR BUMPER RH	180.00	0	
10	Man	TO RESPRAY REAR PANEL	180.00	0	
11	Man	TO RESPRAY TAIL GATE	575.00	0	
12	Man	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100	
Total:			3,345.00	900.00	

Other Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Man	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
2	Man	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	40	
3	Man	TO CHECK & RESET SYSTEM FUNCTION	350.00	0	
Total:			1,760.00	110.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
4	Man	TO REMOVE & REPAIR FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	0	
5	Man	TO REMOVE AND REFIT WIRE HARNESS	200.00	0	
6	Man	TO TEST AND REPAIR REVERSE SENSOR SYSTEM	120.00	0	
7	Man	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	40	
8	Man	TO INSPECT RR LIGHTING MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	
9	Man	TO TOP UP A/C GAS	120.00	0	
10	Man	TO CONDUCT RADIATOR PRESSURE CHECK	120.00	0	
11	Man	TO REPLACE SUNDRY PARTS	100.00	0	
12	Man	TO WASH AND VACUUM	80.00	0	
Total:			1,760.00	110.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	29,577.43	1,848.88
Total Labour Cost	2,326.00	1,000.00
Total Spray Painting	3,348.00	900.00
Other	1,760.00	110.00
Overall Total	37,620.43	3,858.88
Lump Sum Repair Option		
Lump Sum Total	0.00	3,858.88
Surveyor Approved Amount		3,858.88
No. of Repair Days*	17	0
Remarks		p/p repair, photo before paint.
Surveyor Name		Heen Jc

Estimator Assessment(1)

Surveyor Assessment(1)

Signature



Save Clear

Survey Date:

08/02/2019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

REQUEST FOR SUPPLEMENT PARTS

Contractor		Date of Collection	1 / 1
Accident Case Number	TAX/02/19/2010	Date of Request	12/02/2019
Vehicle No	SUB 5057 2	Number of Days to Extend (if any)	2
Vehicle Model	TOYOTA PRIUS 4		

S/N	Part Number	Part Description	Quantity	Unit Price
		TAILGATE BACK DOOR OUTER GARISH	1pc	✓
		REAR BUMPER REINFORCEMENT	1pc	✓ DD
		FRONT BUMPER FOAM	1pc	✓ CRA
		INLET AIR CLEANER NOZ	1pc	✓ BVC
		HEAD LAMP RH	1pc	✓ CRA
		SUPPORT S/A UPPER	1pc	✓ .00

CRA \$608.40
 \$239.10
 \$52.73
 \$70.43
 \$2,303.01
 \$273.68

Contractor must submit photographs for damaged parts

I, (Name) _____
 (Position) _____
 do solemnly and sincerely declare that: Supplementary Parts are listed for replacement for the aforesaid vehicle.

Signature of person making this declaration
(to be signed in front of an authorized witness)

I declare under penalty of perjury that the information is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to criminal prosecution.

Approved By	ARC Executive / Supervisor / SA	
Approved By	Surveyor / In-house Staff	
Parts Ordered	SMART Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of Submission

REQUEST FOR SUPPLEMENTARY PARTS

Contractor:		Date of Collection:	1 / 1
Acq. Inv. Case Number:	TAX/02/19/2010	Date of Request:	12/02/2019
Vehicle #:	SUB 5057 2	Number of Days to Extend (If any):	3 2
Vehicle Model:	TORIDA PRUS 4		

Item Number	Part Description	Quantity	Unit Price
	SUPPORT SFA RH	1pc	✓ DD
	REVERSE SENSOR	1 Set	✓ Shorted
	FILLER, REAR BUMPER LH	1pc	✓ DEF
	TARGATE WEATHERSTRIP	1pc	✓ CUT
	Request ADDITIONAL REPAIR DAYS		

\$177.75
 \$160
 \$89.93
 \$770.53

Please submit photographs for damaged parts

12/2/19

I hereby declare that: Supplementary Parts are used for replacement for the aforesaid

Signatures of person making this declaration
 (who signed in front of an authorized witness)

APR: Executive / Supervisor / SA	
Surveyor / In-house Staff	
APR: Stars / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Executive / Member
YES / NO	Date of submission

Pg 2/2