

## Case Details

Case Reference Number : TAX/02/19/2010  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHB5057Z

Company Type : SMRT Taxis Pte Ltd  
 Estimation ID : EST-5619-ID  
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd  
 Accident Date and Time : 02/02/2019 02:45 PM  
 Vehicle Age(In Months) : 15

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation					Surveyor Approval			Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace	DEF
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Check	
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Check	
One Time Key In	Main			COVER, FR BUMPER RH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Give	
One Time Key In	Main			COVER, FR BUMPER LH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Give	
One Time Key In	Main			BRACKET, FR BUMPER	1	99.80	99.80	25.00	74.85	Replace	1	74.85	Replace	CRA
One Time Key In	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	1	25.00	Replace	MIS
One Time Key In	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	1	35.00	Replace	CRA
One Time Key In	Main			SEAL, HOOD TO FR END	1	24.40	24.40	25.00	18.30	Replace	0	0	Not Give	
One Time Key In	Main			EMBLEM ASSY FRONT	1	87.10	87.10	25.00	65.32	Replace	1	65.32	Replace	NEC
<b>Total Spare Part Cost</b>									29,977.43	<b>Surveyor Total</b>		1,848.88		
<b>Lump Sum Discount (%)</b>									0.00	<b>Lump Sum Dis (%)</b>		0		
<b>Final Spare Part Cost</b>									29,977.43	<b>Final Sur Total</b>		1,848.88		

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	0	0	Not Give	
One Time Key In	Main			GRILLE SUB-ASSY	1	335.60	335.60	25.00	251.70	Replace	1	251.70	Replace	BUC
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	NEC
One Time Key In	Main			RETAINER, FR BUMPER, LH & RH	2	8.50	17.00	25.00	12.75	Replace	0	0	Check	
One Time Key In	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	0	0	Check	
One Time Key In	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0	Check	
One Time Key In	Main			REINFORCEMENT FRONT LOWER	1	238.50	238.50	25.00	178.88	Replace	0	0	Check	
One Time Key In	Main			ABSORBER, FR BUMPER LOWER	1	117.00	117.00	25.00	87.75	Replace	0	0	Check	
One Time Key In	Main			EXTENSION SUB-ASSY, LH	1	116.30	116.30	25.00	87.22	Replace	0	0	Check	
One Time Key In	Main			EXTENSION SUB-ASSY, RH	1	116.30	116.30	25.00	87.22	Replace	0	0	Check	
One Time Key In	Main			COVER, RADIATOR	1	227.80	227.80	25.00	170.85	Replace	0	0	Check	
One Time Key In	Main			SUPPORT S/A UPPER	1	364.90	364.90	25.00	273.67	Replace	0	0	Check	
One Time Key In	Main			SUPPORT S/A RH	1	237.00	237.00	25.00	177.75	Replace	0	0	Check	
One Time Key In	Main			SUPPORT S/A LH	1	237.00	237.00	25.00	177.75	Replace	0	0	Check	
One Time Key In	Main			SUPPORT SUB-ASSY LOWER	1	397.40	397.40	25.00	298.05	Replace	0	0	Check	

Total Spare Part Cost 29,977.43

Surveyor Total 1,848.88

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 29,977.43

Final Sur Total 1,848.88

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SUPPORT, RADIATOR UPPER RH	1	76.70	76.70	25.00	57.53	Replace	0	0	Check	
One Time Key In	Main			SUPPORT, RADIATOR UPPER LH	1	76.70	76.70	25.00	57.53	Replace	0	0	Check	
One Time Key In	Main			CUSHION HOOD BUMPER	2	8.50	17.00	25.00	12.75	Replace	0	0	Check	
One Time Key In	Main			GUIDE, RADIATOR AIR,	1	93.90	93.90	25.00	70.43	Replace	0	0	Check	
One Time Key In	Main			BRACE, HOOD LOCK SUPPORT	1	76.20	76.20	25.00	57.15	Replace	0	0	Not Give	
One Time Key In	Main			LOCK ASSY, HOOD	1	131.10	131.10	25.00	98.32	Replace	0	0	Check	
One Time Key In	Main			CABLE ASSY, HOOD	1	53.20	53.20	25.00	39.90	Replace	0	0	Check	
One Time Key In	Main			SEAL, RADIATOR TO RH	1	24.80	24.80	25.00	18.60	Replace	0	0	Check	
One Time Key In	Main			SEAL, RADIATOR TO LH	1	24.80	24.80	25.00	18.60	Replace	0	0	Check	
One Time Key In	Main			GUIDE, RADIATOR AIR , RH	1	54.60	54.60	25.00	40.95	Replace	0	0	Check	
One Time Key In	Main			GUIDE, RADIATOR AIR , LH	1	58.80	58.80	25.00	44.10	Replace	0	0	Check	
One Time Key In	Main			GROMMET (FOR RADIATOR LOWER SUPPORT)	2	12.70	25.40	25.00	19.05	Replace	0	0	Check	
One Time Key In	Main			CUSHION, (FOR RADIATOR UPPER SUPPORT)	2	9.80	19.60	25.00	14.70	Replace	0	0	Check	
One Time Key In	Main			GUIDE, RADIATOR AIR , UPPER	1	44.70	44.70	25.00	33.53	Replace	0	0	Check	
One Time Key In	Main			RADIATOR ASSY	1	1,841.10	1,841.10	25.00	1,380.82	Replace	0	0	Check	
<b>Total Spare Part Cost</b>									29,977.43	<b>Surveyor Total</b>		1,848.88		
<b>Lump Sum Discount (%)</b>									0.00	<b>Lump Sum Dis (%)</b>		0		
<b>Final Spare Part Cost</b>									29,977.43	<b>Final Sur Total</b>		1,848.88		

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COOLANT	4	12.30	49.20	0.00	49.20	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Check ▾	
One Time Key In	Main			FAN RADIATOR , LH	1	181.80	181.80	25.00	136.35	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Check ▾	
One Time Key In	Main			FAN RADIATOR , RH	1	233.00	233.00	25.00	174.75	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Check ▾	
One Time Key In	Main			FAN SHROUD RADIATOR	1	219.30	219.30	25.00	164.48	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Check ▾	
One Time Key In	Main			MOTOR, COOLING FAN , RH	1	443.40	443.40	10.00	399.06	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Check ▾	
One Time Key In	Main			MOTOR, COOLING FAN , LH	1	543.50	543.50	10.00	489.15	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Check ▾	
One Time Key In	Main			HOSE, RADIATOR , NO.1	1	42.60	42.60	25.00	31.95	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Check ▾	
One Time Key In	Main			HOSE, RADIATOR , NO.2	1	40.20	40.20	25.00	30.15	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Check ▾	
One Time Key In	Main			HOSE, WATER BY-PASS , NO.2	1	37.40	37.40	25.00	28.05	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Check ▾	
One Time Key In	Main			HOSE, WATER BY-PASS , NO.3	1	20.10	20.10	25.00	15.08	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Check ▾	
One Time Key In	Main			HOSE, WATER BY-PASS , NO.4	1	13.20	13.20	25.00	9.90	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Check ▾	
One Time Key In	Main			HOSE, WATER BY-PASS , NO.1	1	37.40	37.40	25.00	28.05	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Check ▾	
One Time Key In	Main			HORN ASSY, HIGH	1	112.80	112.80	25.00	84.60	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Check ▾	
One Time Key In	Main			HORN ASSY, LOW	1	112.80	112.80	25.00	84.60	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Check ▾	
One Time Key In	Main			AIR CON CONDENSER ASSY	1	1,317.70	1,317.70	25.00	988.28	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Check ▾	
<b>Total Spare Part Cost</b>									29,977.43	<b>Surveyor Total</b>		1,848.88		
<b>Lump Sum Discount (%)</b>									0.00	<b>Lump Sum Dis (%)</b>		<input type="text" value="0"/>		
<b>Final Spare Part Cost</b>									29,977.43	<b>Final Sur Total</b>		1,848.88		

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TUBE & ACCESSORY	1	574.40	574.40	25.00	430.80	Replace	0	0	Check	
One Time Key In	Main			HOSE SUB-ASSY, DISCHARGE	1	337.10	337.10	25.00	252.83	Replace	0	0	Check	
One Time Key In	Main			HOSE, HV WATER PUMP INLET	1	37.90	37.90	25.00	28.42	Replace	0	0	Check	
One Time Key In	Main			INVERTER WATER PUMP ASSY	1	432.00	432.00	10.00	388.80	Replace	0	0	Check	
One Time Key In	Main			HOSE, HV WATER PUMP OUTLET	1	29.60	29.60	25.00	22.20	Replace	0	0	Check	
One Time Key In	Main			HOSE, INVERTER RADIATOR INLET	1	40.70	40.70	25.00	30.53	Replace	0	0	Check	
One Time Key In	Main			INLET, AIR CLEANER, NO 3	1	35.30	35.30	25.00	26.47	Replace	0	0	Check	
One Time Key In	Main			INLET, AIR CLEANER, NO 2	1	93.90	93.90	25.00	70.43	Replace	0	0	Check	
One Time Key In	Main			INLET, AIR CLEANER, NO 1	1	130.50	130.50	25.00	97.88	Replace	0	0	Check	
One Time Key In	Main			AIR CLEANER ASSY	1	956.20	956.20	25.00	717.15	Replace	0	0	Check	
One Time Key In	Main			WIRE, ENGINE ROOM MAIN	1	6,138.00	6,138.00	10.00	5,524.20	Replace	0	0	Check	
One Time Key In	Main			HOOD SUB-ASSY	1	938.40	938.40	25.00	703.80	Replace	0	0	Check	
One Time Key In	Main			HINGE ASSY, HOOD, RH	1	57.00	57.00	25.00	42.75	Replace	0	0	Check	
One Time Key In	Main			HINGE ASSY, HOOD, LH	1	57.00	57.00	25.00	42.75	Replace	0	0	Check	
One Time Key In	Main			INSULATOR, HOOD	1	393.90	393.90	25.00	295.42	Replace	0	0	Check	
<b>Total Spare Part Cost</b>									<b>29,977.43</b>	<b>Surveyor Total</b>		<b>1,848.88</b>		
<b>Lump Sum Discount (%)</b>									<b>0.00</b>	<b>Lump Sum Dis (%)</b>		<b>0</b>		
<b>Final Spare Part Cost</b>									<b>29,977.43</b>	<b>Final Sur Total</b>		<b>1,848.88</b>		

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			INSULATOR, HOOD CLIP	6	2.30	13.80	25.00	10.35	Replace	0	0	Check	
One Time Key In	Main			WIPER GARNISH LOUVER SUB-ASSY	1	666.90	666.90	25.00	500.17	Replace	0	0	Check	
One Time Key In	Main			FENDER SUB-ASSY, FR , LH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair	
One Time Key In	Main			UNIT, HEADLAMP , LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Check	
One Time Key In	Main			EMBLEM, SIDE PANEL ( HYBRID)	1	52.90	52.90	25.00	39.67	Replace	0	0	Not Give	
One Time Key In	Main			COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0	Check	
One Time Key In	Main			FENDER SUB-ASSY, FR , RH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair	
One Time Key In	Main			UNIT, HEADLAMP , RH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Check	
One Time Key In	Main			EMBLEM, SIDE PANEL ( HYBRID)	1	52.90	52.90	25.00	39.67	Replace	0	0	Not Give	
One Time Key In	Main			COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0	Check	
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace	DEF
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace	BUL
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	1	11.10	Replace	SCR
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95	Replace	NEC
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	NEC

Total Spare Part Cost 29,977.43

Surveyor Total 1,848.88

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 29,977.43

Final Sur Total 1,848.88

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	NEC
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	NEC
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace	NEC
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check	
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check	
One Time Key In	Main			STOPPER, RR BUMPER, RH & LH	2	4.30	8.60	25.00	6.45	Replace	0	0	Not Give	
One Time Key In	Main			SEAL, RR BUMPER , RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Check	
One Time Key In	Main			SEAL, RR BUMPER , LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Check	
One Time Key In	Main			RETAINER, OUTSIDE , RH & LH	2	3.30	6.60	25.00	4.95	Replace	0	0	Check	
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	NEC
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Check	
One Time Key In	Main			FILLER, RR BUMPER , LH	1	119.90	119.90	25.00	89.93	Replace	0	0	Check	
One Time Key In	Main			LENS & BODY ASSY , RR BUMPER , RH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give	
One Time Key In	Main			LENS & BODY ASSY , RR BUMPER , LH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give	
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , RH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Give	

Total Spare Part Cost 29,977.43

Surveyor Total 1,848.88

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 29,977.43

Final Sur Total 1,848.88

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , LH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Give	
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Check	
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Check	
One Time Key In	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	0	0	Check	
One Time Key In	Main			COVER, REAR FLOOR UNDER , RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Not Give	
One Time Key In	Main			COVER, REAR FLOOR UNDER , LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Not Give	
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Not Give	
One Time Key In	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20	Replace	0	0	Not Give	
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	1	0	Repair	
One Time Key In	Main			STICKER SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	NEC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	NEC
One Time Key In	Main			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	NEC
One Time Key In	Main			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	NEC
<b>Total Spare Part Cost</b>									<b>29,977.43</b>	<b>Surveyor Total</b>		<b>1,848.88</b>		
<b>Lump Sum Discount (%)</b>									<b>0.00</b>	<b>Lump Sum Dis (%)</b>		<b>0</b>		
<b>Final Spare Part Cost</b>									<b>29,977.43</b>	<b>Final Sur Total</b>		<b>1,848.88</b>		

**Labour's Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
<b>Total:</b>			<b>2,535.00</b>	<b>1,000.00</b>	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	1,690.00	600	
2	Main	TO REPAIR REAR PORTION	845.00	400	
<b>Total:</b>			<b>2,535.00</b>	<b>1,000.00</b>	

**Spray Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
3	Main	TO REPSRAY FRONT HOOD	378.00	0	
4	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
5	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
6	Main	TO REPSRAY REAR BUMPER	378.00	200	
7	Main	TO RESPRAY BUMPER BEAM	180.00	0	
8	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	0	
9	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	0	
10	Main	TO RESPRAY REAR PANEL	180.00	0	
11	Main	TO RESPRAY TAIL GATE	378.00	0	
12	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100	
<b>Total:</b>			<b>3,348.00</b>	<b>900.00</b>	

**Other Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	40	
3	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	0	
<b>Total:</b>			<b>1,760.00</b>	<b>110.00</b>	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
4	Main	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	0	
5	Main	TO REMOVE AND REFIT WIRE HARDESS	250.00	0	
6	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
7	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	40	
8	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	
9	Main	TO TOP UP A/C GAS	120.00	0	
10	Main	TO CONDUCT RADIATOR PRESSURE CHECK	120.00	0	
11	Main	TO REPLACE SUNDRY PARTS	100.00	0	
12	Main	TO WASH AND VACUUM	60.00	0	
<b>Total:</b>			<b>1,760.00</b>	<b>110.00</b>	

## Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	29,977.43	1,848.88
Total Labour Cost	2,535.00	1,000.00
Total Spray Painting	3,348.00	900.00
Other	1,760.00	110.00
Overall Total	37,620.43	3,858.88
Lump Sum Repair Option	<input type="checkbox"/>	<input type="checkbox"/>
Lump Sum Total	0.00	3,858.88
Surveyor Approved Amount		3,858.88
No of Repair Days*	17	6
Remarks	-	p/p repair, photo before paint.
Surveyor Name		Hwee jie

Estimator Assesment(\$)

Surveyor Assesment(\$)

Signature



Save Clear

Survey Date

08/02/2019

**LKK Auto Consultants hence notify  
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

**Acknowledged by Repairer**

Signature:

Date: