

Survivor:

KSL

DOI:

ASSIGNMENT

17/2/19

Date / Time:

17/2/19

Registered in Merimen:

Pre-assign / CCU / FTE

GT 2359 P



Insured Vehicle No.:

Claim No.:

Name of Insured:

VO KLEENPLUS SERVICES PTE LTD

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :S\$

D.O.A.:

11/2/19

Place of Accident:

Is driver the owner?

( YES NO )

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES NO )

Insured Liability: %

Final ? Yes / No

SMF 568T



INSRS:

WSP:

Tel:

Liability:

RMKS:

Man's United



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE:

After call ltr to OE:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GLA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

27/6/19

Called OE to inform TP claim

6/9/19 - FILE PASD TO TYPE MANDATE

19/1/2020 - FILE PASD TO LMLL TO CLOSURE

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No. : 27

If NO or B 28, Ass. Lia:

Repair Cost: (w/loss)

S\$ 4457.30

Loss of Rental (LOR):

S\$ 700.00

(

7

days) x \$100

Loss of Use (LOU):

S\$ -

(\$

x

days)

Loss of Income (LOI):

S\$ -

(\$

x

days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 5159.30

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 5159.30

Name 1:

Alan's United Auto Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT  
19/3/2020

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$400

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMF-5687 Yr Regn: 10.18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Cerato c.c. 1591

Colour: N.P. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 7929 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNAI-3416MK 5019293

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 205/55R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 11/2/19

Rear

R/Bal. 9 mm

L/Bal. 9 mm

D.O.I. 12/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

P/P - \$4165.70 (Red \$3536 / 467)

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:  
\$ - R/S. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) \_\_\_\_\_



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA  
Our ref: CC6/CTI19002625/Kea3

Date: 15.02.2019

The Motor Claims Department  
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SMF 568T**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12.02.2019 at the premises of M/s Alan's United Auto Pte Ltd - Sin Ming and have the following to report:-

|                               |       |          |
|-------------------------------|-------|----------|
| Workshop Estimate Amount      | : S\$ | 7,701.70 |
| Revised Estimate Amount       | : S\$ | 2,757.00 |
| "Check" Items Amount          | : S\$ | 2,085.30 |
| Total (Including Check Items) | : S\$ | 4,842.30 |

|                         |       |   |        |
|-------------------------|-------|---|--------|
| Market Value            | : S\$ | - | (est.) |
| LTA Reimbursement Value | : S\$ | - | (est.) |
| Nett Value              | : S\$ | - | (est.) |

**Description of Damage:**

The vehicle sustained damages at the  
Rear Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 5.0 days

Yours faithfully,

KENNETH KONG  
Licensed Appraiser

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05923

Vehicle Insured : GT2359P

Accident Date : 11-Feb-2019

Date : 12-Feb-2019

Our Ref : 219020 (CHINA) / CHAN

PAGE : 1

KOH WEE HOCK  
716 WOODLANDS DRIVE 70  
#11-120  
Singapore 730716

*Not Authorized*

*Recovery B6001M*

*5 days*

## ESTIMATED COST OF REPAIR FOR KIA CERATO 1.6A SMF568T

|       |                                |             |           |            |        |
|-------|--------------------------------|-------------|-----------|------------|--------|
| 1 pc  | Boot lid                       |             | <i>B</i>  | 1,297.00   | —      |
| 1 pc  | Boot lid "CERATO" emblem       |             | <i>re</i> | 28.00      | —      |
| 1 pc  | Boot lid logo                  |             | <i>re</i> | 32.00      | —      |
| 1 pc  | Boot lid reflector centre      |             | <i>re</i> | 47.00      | X      |
| 2 pcs | Boot lid lamp                  | @ S\$608.00 | <i>re</i> | 1,216.00   | X      |
| 1 pc  | Rear bumper fascia             |             | <i>re</i> | 688.00     | ✓      |
| 2 pcs | Rear bumper side lamp          | @ S\$181.00 | <i>re</i> | 362.00     | X      |
| 2 pcs | Rear bumper side lamp cover    | @ S\$ 19.00 | <i>re</i> | 38.00      | ✓      |
| 1 pc  | Rear bumper spoiler            |             | <i>re</i> | 197.00     | ✓      |
| 1 pc  | Rear bumper reinforcement      |             |           | 318.00     | ?      |
| 2 pcs | Bumper reinforcement bracket-T | @ S\$ 65.00 |           | 130.00     | ?      |
| 3 pcs | Bumper reinforcement bracket-L | @ S\$ 65.00 |           | 195.00     | ?      |
| 1 pc  | End panel                      |             |           | 274.00     | ?      |
| 1 pc  | End panel top garnish          |             | <i>re</i> | 41.00      | X      |
| 2 pcs | Taillamp                       | @ S\$675.00 | <i>re</i> | 1,350.00   | X      |
|       |                                |             |           | 6,213.00   |        |
|       |                                |             |           | Less 10% : | 621.30 |

1 pc Rear bumper reverse sensor  
1 pc Rear no.plate with box

*re* 5,591.70  
300.00 sn ?  
451.50 50.00 sn

To apply undersealing

60.00 ?

To putty and spray replaced parts

800.00 *6601*

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GT2359P

Page : 2

To remove, cut-out damaged parts,  
panel beating, welding, align,  
refix and to renew above parts

900.00 ?

Total : S\$ 7,701.70  
=====

Singapore Dollars Seven Thousand Seven Hundred  
and One and Cents Seventy Only

LKK Auto Consultants hence notify  
the Repairer of the following:

- To ensure before/after safety pinning
- To supply damaged parts/ being necessary
- Paint gun/gun, not to be used
- Third party approval is not shown/available
- Insurance Institution is advised
- Supplementary remarks must be mentioned/added  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GT2359P  
Accident Date : 11-Feb-2019

No. : 05923

Date : 12-Feb-2019

Our Ref : 219020 (CHINA) / CHAN

PAGE : 1

KOH WEE HOCK  
716 WOODLANDS DRIVE 70  
#11-120  
Singapore 730716

*Not Authorized*  
*Recovery B4PAM*

## ESTIMATED COST OF REPAIR FOR KIA CERATO 1.6A SMF568T

*5 days*

- 1 pc Boot lid
- 1 pc Boot lid "CERATO" emblem
- 1 pc Boot lid logo
- 1 pc Boot lid reflector centre
- 2 pcs Boot lid lamp
- 1 pc Rear bumper fascia
- 2 pcs Rear bumper side lamp
- 2 pcs Rear bumper side lamp cover
- 1 pc Rear bumper spoiler
- 1 pc Rear bumper reinforcement
- 2 pcs Bumper reinforcement bracket-T @ S\$ 65.00
- 3 pcs Bumper reinforcement bracket-L @ S\$ 65.00
- 1 pc End panel
- 1 pc End panel top garnish
- 2 pcs Taillamp

|             |            |                  |            |
|-------------|------------|------------------|------------|
|             | <i>R</i>   | 1,297.00         | —          |
|             | <i>mc</i>  | 28.00            | —          |
|             | <i>ndc</i> | <del>32.00</del> | <i>X</i>   |
|             | <i>sn</i>  | 47.00            | <i>X</i>   |
| @ S\$608.00 | <i>sn</i>  | 1,216.00         | <i>X</i>   |
|             | <i>sn</i>  | 688.00           | <i>✓</i>   |
| @ S\$181.00 | <i>sn</i>  | 362.00           | <i>X</i>   |
| @ S\$ 19.00 | <i>ndc</i> | 38.00            | <i>✓</i>   |
|             | <i>ndc</i> | 197.00           | <i>✓</i>   |
|             | <i>cm</i>  | 318.00           | <i>✓</i>   |
| @ S\$ 65.00 | <i>cm</i>  | 130.00           | <i>✓</i>   |
| @ S\$ 65.00 | <i>cm</i>  | 195.00           | <i>✓</i>   |
|             | <i>R</i>   | 274.00           | <i>X R</i> |
|             | <i>sn</i>  | 41.00            | <i>X</i>   |
| @ S\$675.00 | <i>sn</i>  | 1,350.00         | <i>X</i>   |
|             |            | 6,213.00         |            |
| Less 10% :  |            | 621.30           |            |

*2923.00*  
*292.30*  
*2630.70*  
*Short 200* 5,591.70  
*ndc* 300.00 *sn* *✓*  
*ndc* 45 *sn* 50.00 *sn*

- 1 pc Rear bumper reverse sensor
- 1 pc Rear no.plate with box

To apply undersealing

To putty and spray replaced parts

60.00 *730* *✓*

800.00 *660*

Con't Page 2 ...

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GT2359P

Page : 2

To remove, cut-out damaged parts,  
panel beating, welding, align,  
refix and to renew above parts

600 ✓ 900.00 ?

Total : S\$ 7,701.70  
=====

Singapore Dollars Seven Thousand Seven Hundred  
and One and Cents Seventy Only

P 2630.70

SN 245

L 1290.00

4165.70 ✓

↑  
KENNEDY PUS COMPANY  
THS.

## Hsiao Tong (LKKAUTO)

---

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Monday, 24 June 2019 8:42 AM  
**To:** claims@cartimes.com.sg  
**Cc:** Kenneth Kong (LKKAUTO); Admin A  
**Subject:** RE: ACCIDENT INVOLVING SLN 8639P(AXA) / GBF 2079E/ OTHERS ON 02/10/2018  
\*LKK REF: CC4/ASM18018391/Kpa3

Without Prejudice  
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

|                                   |                    |
|-----------------------------------|--------------------|
| 1. Cost of Repair (w/GST)         | \$ 4,494.00        |
| 2. Loss of Use (10days x \$80.00) | \$ 800.00          |
| 3. LTA/ GIA Search Fee            | \$ 7.45            |
| <b>Total</b>                      | <b>\$ 5,301.45</b> |

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** claims@cartimes.com.sg <claims@cartimes.com.sg>  
**Sent:** Monday, 17 June 2019 2:32 PM  
**To:** Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>  
**Cc:** Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>; Admin A <admin-a@lkkauto.com>  
**Subject:** Re: ACCIDENT INVOLVING SLN 8639P(AXA) / GBF 2079E/ OTHERS ON 02/10/2018 \*LKK REF: CC4/ASM18018391/Kpa3

Dear Hsiao Tong,

Attached is the LOD, LTA Search, Discharge Voucher and Letter of Authorization.

Regards,

Yuki Peck

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19002625/Kda3n2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 20-03-2020



Code : CTI

**1. Policy Particulars :- THIRD PARTY CLAIM**

|              |                  |                |            |
|--------------|------------------|----------------|------------|
| Insured Veh. | GT 2359P         | Veh. Inspected | SMF 568T   |
| Policy No.   | DMCVSN1771531700 | Coverage (\$)  | 0.00       |
| Claim No.    | SNM19D200740     | Excess (\$)    | 0.00       |
| Assign From  |                  | Assign Date    | 12/02/2019 |

**2. Vehicle Particulars & Condition**

|              |                   |              |                    |
|--------------|-------------------|--------------|--------------------|
| Make & Model | KIA CERATO (A)    | c.c          | 1591               |
| Engine No.   | HIDDEN            | Year of Reg. | 2018               |
| Chassis No.  | KNAF3416MK5019293 | Colour       | METALLIC PEARL RED |
| Odometer     | 7929              | Steering     | IN ORDER           |
| Brakes       | IN ORDER          | Modification | STANDARD ALLOY RIM |
| General      | GOOD              |              |                    |

**3. Conditions of Tyres**

|                | Size       | Make  | Balance |
|----------------|------------|-------|---------|
| R/H Front Tyre | 205/55 R16 | KUMHO | 9 mm    |
| L/H Front Tyre | 205/55 R16 | KUMHO | 9 mm    |
| R/H Rear Tyre  | 205/55 R16 | KUMHO | 9 mm    |
| L/H Rear Tyre  | 205/55 R16 | KUMHO | 9 mm    |

**4. Description of Damages**

|                                                                            |
|----------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS. |
|----------------------------------------------------------------------------|

**5. General Information**

|                |                                                                                              |                 |            |
|----------------|----------------------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 11/02/2019                                                                                   | Inspection Date | 12/02/2019 |
| Survey held at | ALAN'S UNITED AUTO PTE LTD<br>BLK 7 SIN MING INDUSTRIAL ESTATE<br>#01-76<br>SINGAPORE 575642 |                 |            |

**5a. Remarks**

|                                                                                                                                           |
|-------------------------------------------------------------------------------------------------------------------------------------------|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|-------------------------------------------------------------------------------------------------------------------------------------------|

**5b. Estimate Days of Repair**

|                                     |                       |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | <b>5 Working Days</b> |
|-------------------------------------|-----------------------|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 568T

| Qty                         | Description of Parts                                                                                                                  | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                                                                                                                       |                      |                           |                   |
| 1                           | BOOT LID                                                                                                                              | BENT                 | 1,297.00                  | 1,297.00          |
| 1                           | BOOT LID 'CERATO' EMBLEM                                                                                                              | NECESSARY            | 28.00                     | 28.00             |
| 1                           | BOOT LID LOGO                                                                                                                         | NECESSARY            | 32.00                     | 32.00             |
| 1                           | BOOT LID REFLECTOR CENTRE                                                                                                             | SERVICEABLE          | 47.00                     | -                 |
| 2                           | BOOT LID LAMP @\$608.00                                                                                                               | SERVICEABLE          | 1,216.00                  | -                 |
| 1                           | REAR BUMPER FASCIA                                                                                                                    | BUCKLED              | 688.00                    | 688.00            |
| 2                           | REAR BUMPER SIDE LAMP @\$181.00                                                                                                       | SERVICEABLE          | 362.00                    | -                 |
| 2                           | REAR BUMPER SIDE LAMP COVER @\$19.00                                                                                                  | DENTED               | 38.00                     | 38.00             |
| 1                           | REAR BUMPER SPOILER                                                                                                                   | DENTED / CUT         | 197.00                    | 197.00            |
| 1                           | REAR BUMPER REINFORCEMENT                                                                                                             | CRACKED              | 318.00                    | 318.00            |
| 2                           | BUMPER REINFORCEMENT BRACKET -T @\$65.00                                                                                              | CRACKED              | 130.00                    | 130.00            |
| 3                           | BUMPER REINFORCEMENT BRACKET -L @\$65.00                                                                                              | CRACKED              | 195.00                    | 195.00            |
| 1                           | END PANEL                                                                                                                             | TO REPAIR SEE LABOUR | 274.00                    | -                 |
| 1                           | END PANEL TOP GARNISH                                                                                                                 | SERVICEABLE          | 41.00                     | -                 |
| 2                           | TAILLAMP @\$675.00                                                                                                                    | SERVICEABLE          | 1,350.00                  | -                 |
|                             | LESS 10% DISCOUNT                                                                                                                     |                      | -621.30                   | -292.30           |
|                             |                                                                                                                                       |                      | 5,591.70                  | 2,630.70          |
| <b>SPECIAL NETT ITEMS</b>   |                                                                                                                                       |                      |                           |                   |
| 1                           | REAR BUMPER REVERSE SENSOR (SN)                                                                                                       | SHORTED              | 300.00                    | 200.00            |
| 1                           | REAR NO.PLATE WITH BOX (SN)                                                                                                           | DENTED               | 50.00                     | 45.00             |
|                             |                                                                                                                                       |                      | 350.00                    | 245.00            |
| <b>LABOUR</b>               |                                                                                                                                       |                      |                           |                   |
|                             | TO APPLY UNDERSEALING .                                                                                                               |                      | 60.00                     | 30.00             |
|                             | TO PUTTY AND SPRAY REPLACED PARTS.                                                                                                    |                      | 800.00                    | 660.00            |
|                             | TO REMOVE,CUT-OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS.INCLUSIVE OF THE REPAIR OF END PANEL . |                      | 900.00                    | 600.00            |
|                             |                                                                                                                                       |                      | 1,760.00                  | 1,290.00          |
| <b>GRAND TOTAL</b>          |                                                                                                                                       |                      | <b>7,701.70</b>           | <b>4,165.70</b>   |

Report Ref No. CC6/CT119002625/Kda3n2



|                             |  |  |          |
|-----------------------------|--|--|----------|
| RECOMMENDED COST OF REPAIRS |  |  | 4,165.70 |
|-----------------------------|--|--|----------|

Report Ref No. CC6/CTI19002625/Kda3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.