

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHC 5957X

AAD1902-062

Not Notified
U/Sing @ 2650h

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHC 5957X
 VF1ABL15AUC281474
 RENAULT
 LATITUDE
 8.2.2019
AIG
 23/3/2015

PART		LIST	
1	BUMPER COVER FRT	\$	<i>As</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>Sm</i> 181.75 X
1	BUMPER ABSORBER FRT	\$	<i>Sm</i> 394.68 X
1	BUMPER RETAINER FRT LH	\$	<i>Di</i> 151.41 ✓
1	BUMPER SUPPORT FRT	\$	<i>Sm</i> 123.88
1	BUMPER RETAINER FRT RH	\$	<i>Sm</i> 150.77
1	BUMPER SUPPORT FRT	\$	<i>Sm</i> 123.88
1	BUMPER UNDERTRAY FRT	\$	<i>Sm</i> 472.83
1	BUMPER GRILLE LOWER FRT	\$	<i>Sm</i> 266.80
1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sm</i> 207.21
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sm</i> 207.21
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08
1	TOW COVER FRT	\$	<i>Sm</i> 28.61
1	HEADLAMP LH	\$	<i>Sm</i> 1,184.43
1	HEADLAMP HARNESS	\$	<i>Sm</i> 928.29
1	FENDER PANEL FRT LH	\$	<i>R</i> 783.83 ✓
1	WHEELARCH FRT LH	\$	<i>Sm</i> 278.84
1	FENDER BRACKET LOWER LH	\$	<i>Sm</i> 15.79
1	FENDER INSULATOR LH	\$	<i>Sm</i> 130.84
1	DOOR PANEL FRT LH	\$	<i>R</i> 2,844.66
1	DOOR HINGE UPPER LH	\$	<i>R</i> 261.28
1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55
1	DOOR CHECK FRT LH	\$	<i>Sm</i> 194.77
1	DOOR LOCK FRT LH	\$	<i>R</i> 908.75
1	DOOR CATCH FRT LH	\$	<i>R</i> 131.23
1	DOOR HANDLE OUTER FRT LH	\$	<i>Sm</i> 477.76
1	DOOR HANDLE COVER FRT LH	\$	<i>Sm</i> 13.22
1	DOOR HANDLE MODULE FRT LH	\$	<i>Sm</i> 133.60
1	DOOR REGULATOR FRT LH	\$	<i>Sm</i> 505.19
1	DOOR REGULATOR MOTOR FRT LH	\$	<i>Sm</i> 796.46
1	DOOR REGULATOR GUIDE FRT LH	\$	<i>Sm</i> 120.97

Trans-cab Auto Services Pte Ltd

AAD1902-062

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5957X

	\$ 14,493.02
10%	\$ 1,449.30
	\$ 13,043.72

Special Nett

1SET	BUMPER CLIP FRT	\$	<i>nc</i>	66.00	✓
1	BUMPER BRACKET CLIP FRT LH	\$	<i>nn</i>	12.00	}
1	BUMPER SUPPORT CLIP FRT LH	\$	<i>nn</i>	10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>nn</i>	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>nn</i>	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>nn</i>	20.00	}
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>nn</i>	30.00	
1SET	WHEELARCH CLIP FRT LH	\$	<i>nn</i>	30.50	}
1	FRONT DOOR STICKER 'Trans-cab'	\$	<i>nc</i>	80.00	
1	FRONT DOOR STICKER 'Chassis'	\$	<i>nn</i>	50.00	<i>15mm</i>
1	DOOR CHECK BOLT	\$	<i>nn</i>	22.69	}
1	DOOR GUIDE SCREW	\$	<i>nn</i>	10.85	
1	DOOR HINGE BOLT	\$	<i>nn</i>	10.85	
1	DOOR HINGE NUT RH	\$	<i>nn</i>	14.60	
1	DOOR CHECK BOLT	\$	<i>nn</i>	22.69	
1	DOOR CHECK NUT	\$	<i>nn</i>	3.75	
1	DOOR LOCK SCREW L70Y	\$	<i>nn</i>	6.12	
1	DOOR CATCH SCREW L70Y	\$	<i>nn</i>	10.06	X

TOTAL \$ 539.63

TOTAL PARTS \$ 13,583.35

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00	<i>500l</i>
To apply paint protection system (PPS) maintain and enhancement	\$	380.00	<i>nn X</i>
Putty and spray painting of the affected portion.	\$	4,200.00	<i>660l</i>

Trans-cab Auto Services Pte Ltd

AAD1902-062

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5957X

To rust-proofing of the affected areas.	\$	170.00	<i>30/</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>20/</i>
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00	<i>X</i>
To replace, refix and top up coolant for radiator	\$	<i>nn</i> 170.00	<i>X</i>
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>nn</i> 170.00	<i>X</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00	<i>X</i>

TOTAL \$ 10,780.00

Over All Total \$ 24,363.35

LUMP SUM(REPAIR DAY)

~~20 DAYS~~

2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: