

INS. CASE OWNER:

CC 3, LPL 1900 2627, Kph3n2

LKK:
IDAC:

ASSIGNMENT

Surveyor:

KSC

DOI:

1/12/19

Date / Time:

1/12/19

Registered in Merimen:

Pre-assign / CCU / FTE

X06433P



Insured Vehicle No.

Name of Insured

The Global Resources P/L

Insured Tel No.

HP:

Excess See II :SS

D.O.A:

9/2/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

18/19/19/1205/021410

Policy No.:

Make / Model:

Place of Accident:

Smy Ave

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHB9762U



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans. Car



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

20/12
SmySHB9762U-CC/FULL/019986/Kph3n2; P/L: 18/12/19
X06433P-X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

04/10/19

- MINAURED
- ORIGINAL TP LOD IN
- FILE REVIEWED. OLD ROAD-ENDED TP.

07/12/19

10/12/19

11/12/19

20/12/19

- TYPE REPORT FOR MANDATE APPROVAL
- REPORT DONE
- OFFER MANDATE APPROVAL TO LPL BY EMAIL
- LPL APPROVED MANDATE.
- SEND 1st OFFER TO TP.
- TP ACCEPTED OFFER.
- ALL DONE IN ORDER.
- TO CLOSE.

PRELIMINARY ADVICE Date/Time: 15/02/19

Sent By: a3

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: L16

S\$ 13,500.00 (14 days) Reduction: 73 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lin:

Repair Cost: (w/curr)

S\$ 14,445.00

COLO ROAD-ENDED TP)

Loss of Rental (LOR):

S\$ 1,502.78 (18 days) X 83.46

Loss of Use (LOU):

S\$ - (\$ x days)

Loss of Income (LOI):

S\$ 900.00 (\$50 x 18 days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☒ [Tick only one]

GIA/LTA Search

S\$ 7.49

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

2450.00

Total: S\$ 16,854.77 Global Sum S\$: 16,850.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$ 16,850.00

Name 1:

TRANS-CAR AUTO SERVICES PTB LTD

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

-

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

-

COPY SENT
20/12/19

ASS. REC. BY:

REF: LPC /Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Cab

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHB 9762U Yr Regn: 07.13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Perant Latitude c.c. 1995Colour: M. White / Red A/C: Insured / Std / NI / NASp. Reading: 566047 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VI-1ABL15AUC 273251Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front

R/Bal. 0 mmL/Bal. 0 mmD.O.A. 9/2/19

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass toL/G \$15,500.00CRAP: \$36,533.30 (73%)

Date/Time. File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time. File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Fikros

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/LPC19002627/Kja3

Date: 15/02/2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB 9762U

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12/02/2019 at the premises of M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio and have the following to report:-

Workshop Estimate Amount	: S\$	49,653.30
Revised Estimate Amount	: S\$	16,875.66
"Check" Items Amount	: S\$	4,818.19
Total (Including Check Items)	: S\$	21,693.85
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Rear O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 14.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHB9762U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	11 Feb 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000389
Chassis No.:	VF1ABL15AUC273251
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	31 Jul 2013
First Registration Date:	31 Jul 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jul 2021
PARF Rebate Amount:	\$8,748.00

Intended COE Rebate Details

COE Expiry Date:	30 Jul 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$51,810.00
COE Rebate Amount:	\$15,981.00
Total Rebate Amount:	\$24,729.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Feb 2019

OK

Mei Kwan (LKKAUTO)


From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 19 February, 2019 5:40 PM
To: Mei Kwan (LKKAUTO); MT_Claim_SG
Cc: CS A Team; Admin A; Joy Irene (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving XD6433P (OI : LPC - 18/19/19/VC05/021410) and SHB9762U (TP : LKK REF - CC3/LPC19002627/Kja3) on 09/02/2019 [External General]
Attachments: XD6433P 090219.PDF
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Lonpac External - General

Dear Mei Kwan

Please see attached for our Insured's GIA report.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Tuesday, 19 February, 2019 2:14 PM
To: MT_Claim_SG
Cc: GERALD POH WEE BIN; ONG LI LI; CS A Team; Admin A; Joy Irene (LKKAUTO)
Subject: Direct Settlement - Accident Involving XD6433P (OI : LPC - TBA) and SHB9762U (TP : LKK REF - CC3/LPC19002627/Kja3) on 09/02/2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SHB 9762U at M/s Trans-cab Auto Services Pte Ltd (Ang Mo Kio).

Kindly verify validity of our insured's policy and let us have a copy of insured's accident report for our necessary action.

Enclosed for your perusal is:

- TP's GIA report

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9762U**AAD1902-065***Not Authored
C/Smp &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB 9762U

VF1ABL15AUC273251

RENAULT

LATITUDE

9.2.2019

LONPAC

31/7/2013

PART**LIST**

1	1 BUMPER COVER REAR	\$	<i>Tn</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>CM</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47	X
4	1 BUMPR BRACKET SIDE RH REAR	\$	<i>CM</i> 135.97	—
5	1 BUMPR RETAINER RH REAR	\$	<i>CM</i> 44.99	✓
6	1 BUMPER REFLECTOR RH	\$	<i>CM</i> 43.61	—
7	1 BUMPR BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97	X
8	1 BUMPR RETAINER LH REAR	\$	<i>SL</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61	X
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52	X
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	X
13	1 BOOT REAR	\$	<i>R</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>SL</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>DIS/SL</i> 323.05	✓
16	1 BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35	X
17	1 BOOT REFLECTOR LAMP RH	\$	<i>CM</i> 493.35	✓
18	1 BOOT BADGE 'RENAULT'	\$	<i>R</i> 225.36	—
19	1 BOOT BADGE	\$	<i>R</i> 225.36	—
20	1 BOOT STRUT LH	\$	<i>SL</i> 276.08	X
21	1 BOOT STRUT RH	\$	<i>SL</i> 276.08	X
22	1 BOOT HINGE LH	\$	<i>D.Y</i> 367.84	—
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	—
24	1 BOOT INNER TRIM	\$	<i>Return</i> 586.45	✓
25	1 BOOT SWITCH	\$	<i>SL</i> 168.13	} X
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>SL</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>SL</i> 221.81	

Trans-cab Auto Services Pte Ltd

AAD1902-065

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9762U

30	1 FENDER PANEL REAR RH	\$	Ry 3,299.13	✓
31	1 WHEELARCH REAR RH	\$	Sm 543.47	X
32	1 FENDER PANEL INNER TRIM REAR RH	\$	GNC 671.45	?X
33	1 WHEEL HOUSING PANEL REAR RH	\$	GNC 4,682.09	?X
34	1 TAILLAMP LH	\$	Sm 552.55	X
35	1 TAILLAMP PANEL LH	\$	R 986.70	X
36	1 TAILLAMP RH	\$	Bu 552.55	—
37	1 TAILLAMP PANEL RH	\$	Ry 986.70	—
38	1 OUTER PANEL REAR (End Panel)	\$	Ry 1,471.77	✓
39	1 OUTER PANEL REAR (End Panel)TRIM	\$	Dij/Lm 404.56	✓
40	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R 2,189.88	X
41	1 SPARE WHEEL PANEL TRIM	\$	Sm 612.21	X
42	1 EXHAUST REAR	\$	R 7,489.05	X
43	1 EXHAUST CAP REAR	\$	R 230.49	X

TOTAL	\$	36,036.98
10%	\$	3,603.70
	\$	32,433.28

Special Nett

1	1SET PARKING AID	\$	Shat 700.00	Goan
2	1SET REAR BUMPER CLIP	\$	na 66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	na 33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na 10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na 20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na 10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na 20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na 22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na 66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sm 17.82	X
11	1SET BOOT FINISHER CLIP	\$	na 24.20	X
12	1 REAR BOOT STICKER 'Trans-cab'	\$	na 80.00	Goan
13	1 REAR BOOT STICKER '6555-3333'	\$	na 80.00	13Sm
14	1 REAR BOOT ADVERTISEMENT STICKER	\$	na 300.00	Goan

Trans-cab Auto Services Pte Ltd**AAD1902-065**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9762U

16	1SET FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	X
17	1SET FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	X
18	1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
19	1 FENDER INNER TRIM CLIP RH	\$	nn	28.00	X
20	1 TAILLAMP CLIP RH	\$	nn	5.00	✓
21	1 TAILLAMP CLIP LH	\$	nn	5.00	X
22	2 REAR WINDSCREEN SELANT	\$	nn	80.00	40.00
23	1 WINDSCREEN MOULDING	\$	nn	100.00	—
24	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	—
25	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	nn	385.00	X
26	1 SPARE TYRE	\$	nn	330.00	X
27	1 REAR FENDER ADVERTISEMENT STICKER	\$	nn	300.00	to 150.00

TOTAL \$ 2,880.02**TOTAL PARTS \$ 35,313.30****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	1100
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	1200
To Rust-Proofing Of The Affected Areas.	\$	170.00	90
To reinstall rear bumper parking sensor.	\$	170.00	60
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X

Trans-cab Auto Services Pte Ltd

AAD1902-065

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9762U

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 100/
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	na 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	na 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	120/
To check steering geometry and computer wheel alignment	\$	na 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	na 380.00	X
TOTAL	\$	14,340.00	14320
Over All Total	\$	49,653.30	50033.28

(PART-BY-PART)

Repair Days

20 DAYS

14 days

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC3/LPC19002627/Kha3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 23-12-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 6433P	Veh. Inspected	SHB 9762U
Policy No.	Z18VC05000848	Coverage (\$)	0.00
Claim No.	18/19/19/VC05/021410	Excess (\$)	0.00
Assign From		Assign Date	12/02/2019

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	VF1ABL15AUC273251	Colour	METALLIC WHITE / RED
Odometer	566047	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	8 mm
L/H Front Tyre	215/60 R16	GITI	8 mm
R/H Rear Tyre	215/60 R16	GITI	8 mm
L/H Rear Tyre	215/60 R16	GITI	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	09/02/2019	Inspection Date	12/02/2019
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	14 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607196-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9762U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	TORN	1,108.46	1,108.46
1	BUMPER LOWER REAR	CRACKED	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	CRACKED	135.97	135.97
1	BUMPER RETAINER RH REAR	CRACKED	44.99	44.99
1	BUMPER REFLECTOR RH	CRACKED	43.61	43.61
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BOOT REAR	BENT	2,872.68	2,872.68
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	DISTORTED / CUT	323.05	323.05
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	CRACKED	493.35	493.35
1	BOOT BADGE 'RENAULT'	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	DISTORTED	367.84	367.84
1	BOOT HINGE RH	BENT	367.84	367.84
1	BOOT INNER TRIM	DEFORMED	586.45	586.45
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-

Report Ref No. CC3/LPC19002627/Kha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	FENDER PANEL REAR RH	BENT	3,299.13	3,299.13
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	WHEEL HOUSING PANEL REAR RH	SERVICEABLE	4,682.09	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP RH	BROKEN	552.55	552.55
1	TAILLAMP PANEL RH	BENT	986.70	986.70
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	DISTORTED / CUT	404.56	404.56
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
	LESS 10% DISCOUNT		-3,603.70	-1,427.85
			32,433.26	12,850.66
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SHORTED	700.00	600.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER LH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-

Report Ref No. CC3/LPC19002627/Kha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOT STICKER 'TRANS-CAB' (SN)	NECESSARY	80.00	60.00
1	REAR BOOT STICKER '6555-3333' (SN)	NECESSARY	80.00	15.00
1	REAR BOOT ADVERTISEMENT STICKER (SN)	NECESSARY	300.00	60.00
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NECESSARY	5.00	5.00
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	100.00
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)	NOT NECESSARY	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
1	REAR FENDER ADVERTISEMENT STICKER (SN)	NECESSARY	300.00	150.00
			2,880.02	1,295.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	1,100.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM REAR, BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, BOOT LOCK, BOOT LOCK CATCH, TAILLAMP PANEL LH, SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL), EXHAUST REAR AND EXHAUST CAP REAR.		6,000.00	1,200.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	90.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.)		170.00	100.00

Report Ref No. CC3/LPC19002627/Kha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.)		170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	120.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			14,720.00	2,730.00
GRAND TOTAL			50,033.28	16,875.66
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,500.00

Report Ref No. CC3/LPC19002627/Kha3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.