

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SJK 6573Y
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/WL

Claim Type: Third Party

Accident Date: 03/02/2019

TP Veh Reg No: SLG8744E

Estimate No: ES1991192/WL

Date: 25 Feb 2019

Policy No: GA309820

Veh Reg No: SJK6573Y

Make/Model: HONDA FREED 1.5G A

Chassis No: GB31010114

Engine No: L15A2310183

Reg. Date: 29/10/2008

Estimate Repair Cost to Vehicle No :SJK6573Y

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	695.50	1 PC	695.50	
2 REAR BUMPER CLIPS	3.70	6 PCS	22.20	
3 REAR TAILGATE	1,247.30	1 PC	1,247.30	
4 TAILGATE LOGO	27.40	1 PC	27.40	
5 TAILGATE EMBLEM (FREED)	54.20	1 PC	54.20	
			2,046.60	
		Less 25%	511.65	1,534.95
Special Net				
6 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	40.00
Labour				
7 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	
8 PANEL BEATING	600.00	1 LA	600.00	
9 PUTTY & RESPRAY ON REAR AFFECTED AREAS	700.00	1 LA	700.00	
			1,420.00	1,420.00
Total				S\$ 2,994.95
Add GST @ 7%				209.65
Total Amount Payable				S\$ 3,204.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE