



Case Details

Case Reference Number : TAX/02/19/2043
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5112Y

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-5656-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 08/02/2019 01:50 PM
 Vehicle Age(In Months) : 15

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR RH	1	1,249.60	1,249.60	25.00	937.20	Replace	1	0	Repair	
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	NEC
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	89.50	89.50	25.00	67.13	Replace	1	0	Repair	
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR, RH	1	1,243.90	1,243.90	25.00	932.93	Replace	1	932.93	Replace	BUC
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL, RH	1	576.00	576.00	25.00	432.00	Replace	1	0	Repair	
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	25.00	618.60	Replace	1	0	Repair	
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	0	0	Not Give	
One Time Key In	Main			FILLER, RR BUMPER, RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Give	
One Time Key In	Main			CAP SUB-ASSY, WHEEL	1	175.80	175.80	25.00	131.85	Replace	0	0	Not Give	
One Time Key In	Main			WHEEL, DISC	1	1,555.10	1,555.10	25.00	1,166.32	Replace	1	0	Repair	

Total Spare Part Cost 4,873.88

Surveyor Total 1,112.93

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 4,873.88

Final Sur Total 1,112.93

BOM Type	Costing Type	Portion	SMRT Recommendation								Surveyor Approval			
			Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	NEC
Total Spare Part Cost									4,873.88					
Lump Sum Discount (%)									0.00					
Final Spare Part Cost									4,873.88					
										Surveyor Total		1,112.93		
										Lump Sum Dis (%)		0		
										Final Sur Total		1,112.93		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	1,014.00	750	
Total:			1,014.00	750.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT DOOR RH	378.00	200	
2	Main	RESPRAY MIRROR COVER RH	180.00	50	
3	Main	TO RESPRAY REAR DOOR RH	378.00	200	
4	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	100	
5	Main	TO RESPRAY REAR FENDER RH	378.00	200	
6	Main	TO REPSRAY REAR BUMPER	378.00	0	
7	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	0	
Total:			2,052.00	750.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE AND REFIX VIEW MIRROR	120.00	0	
2	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			760.00	50.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
5	Main	TO WASH AND VACUUM	60.00	0	
6	Main	TO TRANSFER DOOR MECHANISM	240.00	50	
Total:			760.00	50.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,873.88	1,112.93
Total Labour Cost	1,014.00	750.00
Total Spray Painting	2,052.00	750.00
Other	760.00	50.00
Overall Total	8,699.88	2,662.93
Lump Sum Repair Option		
Lump Sum Total	0.00	2,662.93
Surveyor Approved Amount		2,662.93
No of Repair Days*	7	4
Remarks		P/P REPAIR, PHOTO BEFORE PAINT
Surveyor Name		Hwee jie
Signature		
Survey Date	11/02/2019	

Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: