

ASS. REC BY:

REF CS/CT119002635/ Usd3ⁿ²

Special Instruction

Customer's

Signature

From (Person)

Manus
Ongehlin Kiat

ASSIGNMENT (Office)

CT1

Date/Time

12/2/19 @ 5:12pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLT 313A

Insured:

SGF 7973G

at Workshop m/s

Euro Success

Tel:

G7 426231

of

1 kaki Bukit Ave 6 # 02-03

Policy No.

DMPCSN 3029191022

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05/02/2019

CA / REV / REP. / REV 24 HRS

up

14/2/19

H.O.D. Endorsement:

Date/Time:

12:22pm @ 13/2/19

Person Contacted:

Ah Huan

Vehicle IN/OUT

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

Repairer Request Manus. Due to unavailability for manus today
as he went for Court case, Repairer arrange on 14/2/19

SLT 313A - X

SGF 7973G - X

REF: CTI

VEHICLE

Date: 14/01/19

Estimated Cost

OD / ☒ WS / TP RES / OD RES / LYA / INV / MY

Vehicle No: SLT 313A

at Workshop: Euro Success

at 1 kaki Bkt Ave 6 # 02-03

Insured

Policy No

Claim No

Sum Insured

Excess

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLT 313A Reg: 1217

Type: ☒ Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or ☒ CA

Make: mer Benz C200 AMG cc 1991

Colour: white AC: Insured / Std / NI / NA

Sp Reading: 18352 TA Radio: Insured / Std / NI / NA

Eng No

C No: WDD2050422R325877

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SDR / STD A/Rim or

Tyre Size: F: 225/40 R19

R: 255/35 R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SOMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. 5/2/19 D.O.I. 14/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/2/19 LTA 81428
H/S 6800 confirmed with AH Insur.
(\$ 13,303.00 - Rd - 66%)

RECEIVED 26 FEB 2019

Date/Time: File Pass to?

26/02/19
Typist

Date/Time: File Return to?

5

Report Format

Lump Sum / LB 6.800/- H/S

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp. (\$

☐ Interview (\$

☐ Tech Insp. (\$

☐ Weekend (\$

Survey Fee

Transportation

1. 10.00

2. Photos

3. Other

4. Total

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Feb 2019 17:10		12 Feb 2019 17:12 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LIM TEOW SEN, ID: S6915484J			
Main Claimant:	FLORENCE SOH MEE NIAN, ID: S2625929J			
Vehicle Reg. No.:	SLT313A	Date of Loss:	05/02/2019 21:00 - :59 [51 Months and 27 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP	Policy/Cover Note No.:	DMPCSN30291918022 (Comprehensive) Coverage: 24/04/2018 - 23/04/2019	
Vehicle Reg. No. (Insured):	SGF7973G	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY, 417883 Kaki Bukit - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/02/2019]			
Adj Asg. Remarks:	workshop request Marcus to conduct the Pre-repair inspection, thank you.			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Ong Chin Kiat

From: Ruby Ong <ruby@htapartners.com.sg>
Sent: Tuesday, 12 February, 2019 4:10 PM
To: Ong Chin Kiat
Subject: RE: REMINDER : REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLT 313A [OUR REF. TCL.GCN.RO.50044.19.ESS]
Attachments: 0144_001.pdf
Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Chin Kiat

We refer to our telephone conversation a while ago. Enclosed please find our client's Traffic Police Report for your kind attention.

Our client is agreeable to appoint Marcus of LKK as the single joint expert to carry out the pre-repair survey for SLT 313A.

Please make the necessary arrangements with the contact person. The details are as follows :

Venue : **EURO SUCCESS SERVICES PTE LTD**
1 Kaki Bukit Avenue 6
#02-03 Autobay
Singapore 417883

Contact Person : Ah Huat (Tel. 9828 9277 / 6742 6231)

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our client's right to claim for compensation for loss of use for your current request for re-survey.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 278
Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

From: Ruby Ong
Sent: Tuesday, February 12, 2019 3:19 PM
To: 'Ong Chin Kiat' <chinkiat.ong@sg.cntaiping.com>
Subject: REMINDER : REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLT 313A [OUR REF. TCL.GCN.RO.50044.19.ESS]
Importance: High

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8527K
Vehicle Details	
Vehicle No.:	SLT313A
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Feb 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C200 AMG LINE AUTO
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	27492031122471
Chassis No.:	WDD2050422R325877
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$46,383.00
Original Registration Date:	15 Dec 2017
First Registration Date:	15 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$51,937.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Dec 2027
PARF Rebate Amount:	\$38,952.00
Intended COE Rebate Details	
COE Expiry Date:	14 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,109.00
COE Rebate Amount:	\$42,476.00
Total Rebate Amount:	\$81,428.00

The information contained herein is correct as at 15 Feb 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/02/2019 16:11
Date Of Accident	05/02/2019 21:15
Exact Location Of Accident	870 YISHUN STREET 81 CP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT313A
Insured/Policyholder	
Name Of Registered Owner	SPRINGLIFE MAINTENANCE SERVICE PTE LTD
Co Reg No	201118527K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97893540
Alternative Phone No	OFFICE-97893540

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C200 AMG LINE AUTO

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	AVPPSB0551721800
Cover Note Number	

Driver

Name of Driver	FLORENCE SOH MEE NIAN
NRIC No	S2625929J
Date Of Birth	26/02/1966
Occupation	INDOOR
Date Of Driving Pass	05/02/2013
Driving Experience	6 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97893540
Fax Number	
Contact Number	
Email Address	FLORENCE@SUMMERPOND.COM

Address	278 BELGRAVIA DRIVE
Postcode	804644
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN:

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGF7973G
Vehicle Make/Model/Colour	TOYOTA COROLLA 1.6
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ANDY LIM
NRIC/Passport Number	
Contact Number	96429161
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan Pg. 1

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: 020719
1.00 pm

Driver's Signature
(if driver is not the policyholder)
Date & Time: 020719
1.00 pm


IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4

Singapore 415933
Tel: 67446697
Fax: 67492305
Email: vackb@singnet.com.sg
NRIC/FIN No.

SPARMC Sketch Plan Form_V2

07 FEB 2013

Accident Sketch Plan Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

MY CAR WAS PARKED AT 870 YISHUN STREET 81 CARPARK AT

AROUND 1300 ON 05/02/19 I WENT TO COLLECT MY CAR AT 2115

WHEN I SAW A PAPER ON MY CAR WINDSCREEN AND SCRATCH

AT THE LEFT FRONT PORTION OF MY CAR.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time: 020719
 1.00pm
 IDAC/VAC Sketch Plan Form_V3

Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 020719
 1.00pm

IDAC KAKI BUKIT(VAC)
 23 KAKI BUKIT AVE 4
 Reporting Centre Singapore 435933
 Name: Tel: 67416697
 NRIC/FIN No.: Fax: 67492305
 Email: vackb@singnet.com.sg

07 FEB 2019

Accident Sketch Plan Pg. 1

Hi, I'm very sorry for causing such accident on a day I am really sincerely
sorry as I have been driving for whole day and manage ~~the~~ my turn that has
cause the incident and scratches on your car. I'm willing to take full responsibility for
the incident i've cause upon your Chinese New Year. You can contact me at ~~4602 0111~~
(Andy Lim) 9642 9161

Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

H/P: 98289277 (AH HUAT)

Model: **MERCEDES C200**

NSF Authority
date
2/5/19 68001
14/1/19
Theodore H. Hargrave
H. Hargrave

QTY	List Items	Price \$
1	Front bonnet	2500.00 X
1	Front bumper 1645.10	1650.00 ✓
1	Front bumper lower kit 645.10	770.00 ✓
1	Front L/H grill	188.00 ✓
1	Front bumper reinforcement	700.00 X
1	Front bumper top seal	110.00 ✓
2	Front bumper L-R retainer @130	260.00 X
1	Front bumper inner sponge	195.00 X
1	Front bumper inner frame pad	300.00 X
1	Front L/H head lamp assy 2825.00	3850.00 ✓
1	Front L/H head lamp panel	190.00 X
1	Front L/H head lamp bracket	185.00 X
1	Front L/H sport rim 12005.~	1950.00 ✓
1	Front L/H tyre	500.00 X
1	Front L/H shock absorber	750.00 X
1	Front L/H lower arm	650.00 X
1	Front L/H knuckle arm with bearing 1215.	1350.00 ✓
1	Front L/H upper arm	620.00 X
10	Front bonnet insulator clip @5.50	55.00 X
20	Front bumper clip @5.50 60	110.00 ✓

6688-2
p-6019-38
S.N-1200.20
inter-1340-2

8559-38
6847.

I hereby acknowledge and agree to the following:
 • I understand and agree with the painting
 • I understand (Lampoon paint) during resurvey
 • I understand the warranty information
 • Third party claims on a "Without Prejudice" basis
 • No legal action (suits) is allowed
 • Suspectatory claims must be resurveyed and
 is subject to local approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Labour cost

Price\$

To remove,refix front undercarriage

250.00 120

To check front electrical wiring

120.00 20

To check wheel alignment

150.00 80

To diagnos,ease fault memory after repair

11 400.00 X

To apply putty,respray painting etc

1000.00 600

To panel beating,cut,weld,remove replacing front bonnet,fender,bumper above parts

1300.00 520

Total

\$3,220.00

1340

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$20,103.00

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119002635/USD3N2

Date: 28/02/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30291918022	
Claimant Vehicle No :	SLT313A	Insured Vehicle No :	SGF7973G	
Date of Loss:	05/02/2019	Nature of Claim:	TP	Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT313A		
Make & Model:	MERCEDES-BENZ C200 AMG LINE (R18 LED), 2.0 (A)	Engine No:	27492031122471
Reg. Date:	15/12/2017 (Man. Year: 2017)	Chassis No:	WDD2050422R325877
Colour:	White	Odometer:	18352 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40R19	Rear Tyre Size:	255/35R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	16,883.00	7,219.38	9,663.62	57.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,220.00	1,340.00	1,880.00	58.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,103.00	8,559.38	11,543.62	57.42
Approved Total (Overridden) (S\$)		6,800.00		
Nett Amount (S\$)	20,103.00	6,800.00	13,303.00	66.17

INSPECTION

Date of Assignment:	12/02/2019	
Date Inspected:	14/02/2019 Inspected At:	Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 Feb 2019)	
Parts:	N/A	MERCEDES-BENZ C200 AMG LINE (R18 LED) 2.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT313A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	2,500.00 F	*- FL
2	1		*FRONT BUMPER	Deformed/Warped	1,650.00 F	*1,645.10 FL
3	1		*FRONT BUMPER LOWER KIT	Cut	770.00 F	*645.10 FL
4	1		*FRONT L/H GRILL	Scratched	188.00 F	*188.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Repair	700.00 F	*- FL
6	1		*FRONT BUMPER TOP SEAL	Necessary	110.00 F	*110.00 FL
7	2		*FRONT BUMPER L-R RETAINER	Not Necessary	260.00 F	*- FL
8	1		*FRONT BUMPER INNER SPONGE	Not Necessary	195.00 F	*- FL
9	1		*FRONT BUMPER INNER FRAME PAD	Not Necessary	300.00 F	*- FL
10	1		*FRONT L/H HEAD LAMP ASSY	Cracked	3,850.00 F	*2,825.00 FL
11	1		*FRONT L/H HEAD LAMP PANEL	Repair	190.00 F	*- FL
12	1		*FRONT L/H HEAD LAMP BRACKET	Not Necessary	185.00 F	*- FL
13	1		*FRONT L/H TYRE	Serviceable	500.00 F	*- FL
14	1		*FRONT L/H SHOCK ABSORBER	Not Necessary	750.00 F	*- FL
15	1		*FRONT L/H LOWER ARM	Not Necessary	650.00 F	*- FL
16	1		*FRONT L/H KNUCKLE ARM WITH BEARING	Bent/Damaged	1,350.00 F	*1,215.00 FL
17	1		*FRONT L/H UPPER ARM	Not Necessary	620.00 F	*- FL
18	10		*FRONT BONNET INSULATOR CLIPS	Not Necessary	55.00 F	*- FL
19	20		*FRONT BUMPER CLIP	Necessary	110.00 F	*60.00 FL
20	1		*FRONT L/H SPORT RIM	Cut	1,950.00 FS	*1,200.00 FS

F=Franchise part. S=SpccNett. L=ListItemDisc.

Sub Total (\$\$)	16,883.00	7,888.20
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	668.82
Total Parts (\$\$)	16,883.00	7,219.38

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REFIX FRONT UNDERCARRIAGE	New	250.00	120.00
2	TO CHECK FRONT ELECTRICAL WIRING	New	120.00	20.00
3	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
4	TO DIAGNOS,ERASE FAULT MEMORY AFTER REPAIR	New	400.00	0.00
5	TO APPLY PUTTY,RESPRAY PAINTING ETC	New	1,000.00	600.00
6	TO PANEL BEATING,CUT,WELD,REMOVE REPLACING FRONT BONNET,FENDER,BUMPER ABOVE PARTS	New	1,300.00	520.00
Gross Labour Cost (\$\$)			3,220.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >