

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 50063
Date Estimated : 11/02/2019
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Sime Darby Services Private Limited
305 Alexandra Road
#02-01 Vantage Automotive Centre
Singapore 159942

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SLZ81L	G460039	02/04/2018	540iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front LH fender and attachments, front LH wing mirror assembly, front LH door side window include making good the front bumper, rear LH fender and knocking out dents caused by the accident	2975.00		2,975.00	
To spray paint front bumper, front LH fender, LH wingmirror cover and rear LH fender	2594.00		2,594.00	
To carry out body cavity preservation (Per panel)	100.00		100.00	
To check electrical wiring systems at the front section for proper function	150.00		150.00	
# *To conduct water leak tests	75.00		75.00	
Sundries	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# ADJUSTABLE BLIND RIVET *	3.15	4.00		12.60
3M PLATINUM FRONT SIDE DOOR	252.34	1.00		252.34
FRT LH SIDE PANEL ALUMINIUM	929.15	1.00		929.15
# RIVET *	0.45	4.00		1.80
LH COVER CAP PRIMED	153.20	1.00		153.20
LH HEATED OUTSIDE MIRROR MEMORY BUS	998.90	1.00		998.90
FRT LH DOOR SIDE WINDOW GREEN (ESG)	363.20	1.00		363.20

SUPPLEMENTARY ITEMS

Total Labour :	5,974.00
Total Parts :	2,711.19
Total Labour & Parts :	8,685.19
Deduction for Excess :	3,000.00
Total Repair Costs less Excess:	5,685.19
GST @7%:	397.96
Grand Total :	6,083.15

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 50063
Date Estimated : 11/02/2019
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Sime Darby Services Private Limited
305 Alexandra Road
#02-01 Vantage Automotive Centre

Singapore 159942

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SLZ81L	G460039	02/04/2018	540iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# *To conduct water leak tests	75.00		75.00 (K)

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# ADJUSTABLE BLIND RIVET *	3.15	4.00		12.60 (K)
# RIVET *	0.45	4.00		1.80 (K)

Total Labour :	75.00
Total Parts :	14.40
Total Labour & Parts :	89.40