

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 4346X (Supplementary)

DATE : 13.02.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rocker Panel Outer Garnish, RH <i>namby barker</i>			\$ 341.40 ✓
	SUB TOTAL			\$ 341.40
	LESS 20%			\$ 68.28
	DISCOUNTED TOTAL			\$ 273.12
	<p>13/02/2019</p> <p><i>[Signature]</i></p> <p>2KK Auto</p> <p><i>[Signature]</i></p>			
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				