

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9797U**AAD1902-068***Not Notarised
1/12/19 @ 2800/-*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB 9797U

VF1ABL15AUC273417

RENAULT

LATITUDE

11.2.2019

AXA

31/7/2013

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75 X
1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68 X
1	BUMPER RETAINER FRT RH	\$	<i>Dir</i> 150.77 ✓
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80 } X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08
1	HEADLAMP RH	\$	<i>Sn</i> 1,184.43
1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15
1	FENDER PANEL FRT RH	\$	<i>R</i> 783.83 ✓
1	WHEELARCH FRT RH	\$	<i>Mir</i> 278.84 ✓
1	FENDER BRACKET LOWER RH	\$	<i>Sn</i> 15.79
1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84
1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66
1	WIPER RESERVOIR	\$	<i>Sn</i> 348.25 } X
1	WIPER RESERVOIR NECK	\$	<i>Sn</i> 136.11
1	WIPER RESERVOIR MOTOR	\$	<i>Sn</i> 270.06
1	RADIATOR GRILL	\$	<i>Sn</i> 1,707.78
TOTAL		\$	11,824.17
10%		\$	1,182.42
		\$	10,641.75

Special Nett

1SET	BUMPER CLIP FRT	\$	<i>nn</i> 66.00 ✓
1	BUMPER BRACKET CLIP FRT RH	\$	<i>nn</i> 12.00 X
1	BUMPER SUPPORT CLIP FRT RH	\$	<i>nn</i> 10.50 X
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>nn</i> 69.00 X

Trans-cab Auto Services Pte Ltd**AAD1902-068**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9797U

1	FRONT RIGHT DOOR STICKER 'TRANS-CAB'	\$	<i>nn</i> 80.00 <i>605n</i>
1	FRONT RIGHT DOOR STICKER 'CHASSIS'	\$	<i>nn</i> 50.00 <i>155n</i>
		<u>\$</u>	<u>157.50</u>
TOTAL		<u>\$</u>	<u>10,799.25</u>

TOTAL PARTS**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00 <i>400l</i>
Putty and spray painting of the affected portion.	\$	3,000.00 <i>660l</i>
To rust-proofing of the affected areas.	\$	170.00 <i>30l</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>20l</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00 <i>X</i>
To replace, refix and top up coolant for radiator	\$	<i>nn</i> 170.00 <i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1902-068**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9797UTo vacuum, replace, refix and recharge Air
Intercooler

\$

nn 170.00 *X***TOTAL \$ 8,210.00****Over All Total \$ 19,009.25****LUMP SUM (REPAIR DAY)****10 DAYS***2 1/2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: