

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

11-Feb-19

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8473 K

1 pc	O/s headlamp ✓	\$	1,028.00
1 pc	Front bumper <i>X 1402</i>	\$	531.00
1 pc	Front bumper emblem ✓	\$	44.00
1 pc	Front bumper <del>n/s</del> o/s protector ✓	\$	51.00
1 pc	Front bumper <del>n/s</del> o/s fog lamp cover ✓	\$	66.00
1 pc	Front bumper o/s <del>n/s</del> side retainer <i>X</i>	\$	16.00
		\$	<u>1,736.00</u>
		Less 10%	\$ 173.60
		\$	<u>1,562.40</u>

### S/NETT

1 set	Front bumper clips <i>X</i>	\$	48.00
	Sundry	\$	<del>50.00</del> <i>20</i>
	To check wiring for headlamp	\$	<del>40.00</del> <i>20</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of same, etc	\$	<del>200</del> <i>200</i>
	To putty and spray painting on bonnet grille, front bumper <i>X</i>	\$	<del>180</del> <i>180</i>
		\$	<u>350.00</u>
		\$	<u>2,600.40</u>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

*Kalvin 16/1/19*  
*12/2/19 1640h*  
*2 days*  
*45*  
*After Repairing*

... after to hence notify  
... the following:  
... after spray painting  
... (ed parts) during reassembly  
... to confirm  
... on a "no-fault" basis  
... and  
... from insurance company

Acknowledged by Repairer  
Signature:  
Date: