

1/20/2002

ASS. REC. BY:

REF:

es/FCI19002659/Jsd3

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

CWS

From (Person):

May chun

of

FCI

Date/Time:

5.50pm @ 12/2/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKE 30SP

Insured:

3HC 8140R

at Workshop m/s

Tech Choon Automotive

Tel:

96713577

of

60 Jalan Temburong #05-45

Policy No:

Claim No:

D19000932MFstH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

5/2/2019

(Client's Record)

14/2/19

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

(up)

Date/Time:

14/2/2019 @ 13/2/19

Person Contacted:

Mr. Wong

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKE 30SP - X
	3HC8140R - CS/KM019002257/Dtd3 Don: 5/2/2019
22/02/19	@ 11:19 a.m. revised PA to May chun via email.

Hwee J.e

Date: 14/2/19
 Estimated Cost:
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Insured Vehicle No: SKE 305P
 at Workshop n/s: Tech Choon
 Insured: Gajalen Lam Hnat # 05-45
 Policy No: (Nearby Kunji)
 Claim No:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh:
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value:
 IDAC Accident Rpt. Consistent? : Yes or No
 GIA / PR Seen Consistent? : Yes or No
 Est. Repairs: days Res.: Yes or No
 Lum Sum: % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS (up)
 Date: Person Contacted:
 Vehicle: IN / OUT

Ch No: SKE 305P
 Type: MC / MCycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: honda Jazz
 Colour: Blue
 Sp. Reading: 317479
 Eng. No.:
 C. No.: JHM6017507S232235
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/50R15
 R:
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Hankook
 Front: Rear:
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 2 mm
 D.O.A: 5/2/19 D.O.I: 14/2/19
 Survey held at: Tech Choon
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time	Action / Instruction
5/4/19	Confirmed L/s \$2,550/- 5 days of repair with repairer. (\$3,394.40 Rod - 57%) MV - \$20000 LTA - \$15164 NV - \$4836

RECEIVED 05 APR 2019

Date/Time: File Pairs to? ☐ : Prelim. Report
 1) *cs/04/1a* ☒ : Final Report
Typist
 Date/Time: File Return to?

Days Of Repair: 5
Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp. (\$
☐ Interview (\$
☐ Tech. Invs (\$
☐ Weekend (\$

Survey Fee:
Transportation:

☐ 5 + PS = 5P
☐ Photos
☐ Photos

Report Format

Lump Sum / L.B.B. (₹) 2,550/- H/S

140
50
$50 + 50$
38
328



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000932MFSH

Date: 22 February 2019

Our Ref: CS/FCI19002659/Jsd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKE 305P

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/02/2019 at the premises of M/s Tech Choon Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 5,944.40
Revised Estimate Amount	: S\$ 2,387.60
"Check" Items Amount	: S\$ 1,480.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 5 Days

Yours faithfully,
Hwee Jie
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	09-02-2019	Our Ref No. D19000932MFSH
Accident Date	05-02-2019	Claim Type. Third Party
Insured Vehicle	SHC8140R	Third Party Vehicle. SKE305P
Survey Location	60 JALAN LAM HUAT#05-45 CARROS CENTRE	
Contact Person.	MR WONG	
Contact No.	0/ 96713577	Fax No. 65073849
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TECH CHOON AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	VISION LAW LLC	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 22 February 2019 11:19 AM
To: 'May Chua Hui Chin'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19000932MFSH/1
Attachments: SKE 305P - Preli Advise.pdf

Dear May,

Enclosed preliminary revised of vehicle SKE 305P.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 13 February 2019 12:58 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000932MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 12 February 2019 5:50 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000932MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9155C
Vehicle Details	
Vehicle No.:	SKE305P
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.4M
Primary Colour:	Blue
Secondary Colour:	Black
Manufacturing Year:	2007
Engine No.:	L13A54003355
Chassis No.:	JHMGD17507S232235
Maximum Power Output:	60.0 kW (80 bhp)
Open Market Value:	\$13,768.00
Original Registration Date:	16 Nov 2007
First Registration Date:	16 Nov 2007
Transfer Count:	2
Actual ARF Paid:	\$15,145.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Nov 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$20,997.00
COE Rebate Amount:	\$15,164.00
Total Rebate Amount:	\$15,164.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 05 Apr 2019

OK

Tokio Marine Insurance Singapore Ltd.

(Company Reg. No.: 192300014M) (GST Reg No.: M2-0000023-4)
 20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046
 T: (65) 6221 6111 F: (65) 6221 4355 / (65) 6224 0895 E: tms@tokiomarine.com.sg W: www.tokiomarine.com

A member of the
Tokio Marine Group



TOKIO MARINE
INSURANCE GROUP

Certificate of Insurance

FORM MX4

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Policy No.: MT109794 (Private Car)

- | | | |
|--|---|--------------------------------|
| 1. Index Mark and Registration Number of Vehicle | SKE305P | Chassis No.: JHMGD17507S232235 |
| 2. Name of Policyholder | ICON ENGINEERING SERVICES PTE LTD | |
| 3. Effective date of the Commencement of Insurance for the purposes of the Act | 16/11/2018 (00:00:00) | |
| 4. Date of Expiry of Insurance | 15/11/2019 | |
| 5. Persons or Class of Persons entitled to drive* | Any person who is driving on the policyholder's order or with their permission. | |

* Provided that the Person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

IMPORTANT NOTICE

This Certificate is not transferable. During its currency, if the insurance is cancelled for whatsoever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days thereof or, if the Certificate has been lost destroyed, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189).

ADDITIONAL INFORMATION

Account No: 2397DDA

Insurance Plan:	Comprehensive Approved Workshop Plan		
Limit for total loss or theft:	Prevailing Market Value		
Policy Excess:	Own Damage Claims	SGD 600.00	(Original Excess : SGD 600.00)
	Additional Excess for Unnamed Driver(s)	SGD 500.00	
	Additional Excess for Young or Inexperience Driver(s)	SGD 3,500.00	
	WindScreen Excess	SGD 100.00	
Financial Interest:	EFIZZIG CREDIT PTE LTD		
Additional Terms:	Waiver of excess is not applicable.		

TOKIO MARINE INSURANCE SINGAPORE LTD.

Authorised Signature



TECH CHOON AUTOMOTIVE PTE. LTD.

60 JALAN LAM HUAT #05-45, CARROS CENTRE, SINGAPORE 737869

TEL: 6367 0710 FAX: 6368 8025 Email: tcawtl@singnet.com.sg

Business Reg No : 200311178 N GST Reg No. 200311178N

ICON ENGINEERING SERVICES PTE LTD

55 SUNGEI KADUT DRIVE

(REG NO: 200719155C) (SINGAPORE) 729563

(C1264) ATTN: CHUA KHENG TONG

Attention: Motor Claim Department

Contact: 63698468 Hp 96559765 Fax No.: 63698469

Tax Invoice : ES000252

Date: 14.02.2019

Vehicle Num: SKE305P

Make/Model: HONDA JAZZ GD1-1.4 A-2006

Chassis/Eng#: JHMGD175078232235

Accident Date: 05/02/2019

Claim No:

Reference:

Policy No.: MT109794 (TOKIO MARINE)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS:				
1.	1 PC	BUMPER REAR <i>DEP</i>		578.40 /
2.	2 PCS	BUMPER RETAINER <i>BUC</i>	15.80	31.60 /
3.	2 PCS	BUMPER SIDE BRACKET <i>NN</i>	8.90	17.80 X
4.	1 PC	TAILLAMP LH <i>CRA</i>		275.40 /
5.	2 PCS	REAR ENG PANEL OUTSIDE STOPPER <i>NN</i>	38.10	76.20 X
6.	1 PC	NUMBER PLATE GARNISH REAR <i>NN</i>		137.80 X
7.	1 PC	BOOT LID TRIM BOARD <i>NN</i>		135.70 X
8.	1 PC	REAR END PANEL GARNISH <i>NN</i>		81.60 X
9.	1 SET	BOOT LID GLASS MOUNDING <i>HEC</i>		20.30 /
10.	1 SET	WINDSCREEN SEALANT <i>HEC</i>		48.00 /
11.	1 PC	REAR END PANEL <i>DD</i>		296.60 /
12.	1 PC	BOOT LID <i>BUC</i>	7.00	7.00 /
13.	1 PC	BOOT LID RUBBER <i>NN</i>		148.80 X
14.	1 PC	BOOT LID LOCK <i>SVC</i>		123.80 X
15.	1 PC	BOOT LID LOCK CATCH <i>NN</i>		30.30 X
16.		BOOT LID LOCK VACCU PUMP <i>NN</i>		
17.	1 SET	REVERSE SENSOR <i>shorted</i>		200.00 /

List Total S\$:

20% Discount on parts

3,424.40

LABOUR:

(LABOUR CHARGES)

TO SPRAY PAINTING AT EFFECTED PORTION

TO SPRAY UNDERCOAT

2011-10

600.00 /
80.00 /

CONTINUE / ...



TECH CHOON AUTOMOTIVE PTE. LTD.

60 JALAN LAM HUAT #05-45, CARROS CENTRE, SINGAPORE 737869

TEL: 6367 0710 FAX: 6368 8025 Email: tcawtl@singnet.com.sg

Business Reg No : 200311178 N GST Reg No. 200311178N

ICON ENGINEERING SERVICES PTE LTD

55 SUNGEI KADUT DRIVE

(REG NO: 200719155C) (SINGAPORE) 729563

(C1864) ATTN: CHUA KHENG TONG

Attention : Motor Claim Department

Contact : 63698468 Hp 96589785; Fax No. : 63698469

Tax Invoice : ES000252

Date : 14.02.2019

Vehicle Num : SKE305P

Make/Model : HONDA JAZZ GD1-1.4 A-2005

Chassis/Eng# : JHMGD175073232235

Accident Date : 05/02/2019

Claim No. :

Reference :

Policy No. : MT109794 (TOKIO MARINE)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

TO REMOVE & REINSTALL REAR WINDSCREEN GLASS.
TO REPLACE REVERSE SENSOR & TESTING.
TO CHANGE REAR BOOT LID, BUMPER, REAR END PANEL.
WELDING, ADJUSTMENT & WATER TEST FOR WATER LEAKING.

Q
Q
Q

120 120.00
30 30.00
600 1,050.00

TO REMOVE & REINSTALL BOOT LID INTERNAL LOCK, WIRING
NUMBER PLATE LAMP & OPER HANDER & KEY LOCK

50 150.00

Labour Total S\$:

2,520.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SingDollars : Six Thousand Three Hundred Sixty & Cents Fifty-One Only

E. & O.E.

Total S\$

5,844.40

GST 7% S\$

416.11

Amount Due S\$

6,360.51

Total - \$2550

for TECH CHOON AUTOMOTIVE PTE LTD

Cheque should be made payable to : TECH CHOON AUTOMOTIVE PTE LTD

ANY DISPUTE MUST BE COMMUNICATED TO US IN WRITING WITHIN SEVEN DAYS FROM THE INVOICE DATE.

25/2/19
14/2/19
Hwee Jie - LKK

4/5 5 days

91803151



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19002659/Jsd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 08-04-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8140R	Veh. Inspected	SKE 305P
Policy No.		Coverage (\$)	0.00
Claim No.	D19000932MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	12/02/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA JAZZ	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JHMGD17507S232235	Colour	BLUE
Odometer	317479	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/50 R15	HANKOOK	6 mm
L/H Front Tyre	195/50 R15	HANKOOK	6 mm
R/H Rear Tyre	195/50 R15	HANKOOK	6 mm
L/H Rear Tyre	195/50 R15	HANKOOK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	05/02/2019	Inspection Date	14/02/2019
Survey held at	60 JALAN LAM HUAT #05-45		
Repairer	TECH CHOON AUTOMOTIVE PTE LTD		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 305P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER REAR	DEFORMED	578.40	578.40
2	BUMPER RETAINER @\$15.80	BUCKLED	31.60	31.60
2	BUMPER SIDE BRACKET @\$8.80	NOT NECESSARY	17.60	-
1	TAILLAMP LH	CRACKED	275.40	275.40
2	REAR ENG PANEL OUTSIDE STOPPER @\$38.10	NOT NECESSARY	76.20	-
1	NUMBER PLATE GARNISH REAR	NOT NECESSARY	137.80	-
1	BOOT LID TRIM BOARD	NOT NECESSARY	135.70	-
1	REAR END PANEL GARNISH	NOT NECESSARY	81.60	-
1	SET BOOT LID GLASS MOULDING	NECESSARY	29.30	29.30
1	SET WINDSCREEN SEALANT	NECESSARY	48.00	48.00
1	REAR END PANEL	DENTED	296.60	296.60
1	BOOT LID	BUCKLED	928.30	700.00
1	BOOT LID RUBBER	NOT NECESSARY	148.80	-
1	BOOT LID LOCK	SERVICEABLE	123.80	-
1	BOOT LID LOCK CATCH	NOT NECESSARY	30.30	-
1	BOOT LID LOCK VACCUM PUMP (NPA)	NOT NECESSARY	-	-
1	SET REVERSE SENSOR	SHORTED	485.00	200.00
	LESS 20% DISCOUNT		-	-431.86
			3,424.40	1,727.44
LABOUR				
	TO SPRAY PAINTING AT EFFECTED PORTION.		950.00	600.00
	TO SPRAY UNDERCOAT.		150.00	80.00
	TO REMOVE & REINSTALL REAR WINDSCREEN GLASS.		185.00	120.00
	TO REPLACE REVERSE SENSOR & TESTING.		85.00	30.00
	TO CHANGE REAR BOOT LID BUMPER, REAR END PANEL, WELDING ADJUSTMENT & WATER TEST FOR WATER LEAKING.		1,000.00	600.00
	TO REMOVE & REINSTALL BOOT LID INTERNAL LOCK, WIRING NUMBER PLATE LAMP & OPER HANDER & KEY LOCK.		150.00	50.00
			2,520.00	1,480.00

Report Ref No. CS/FC119002659/Jsd3n2



GRAND TOTAL		5,944.40	3,207.44
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,550.00

Report Ref No. CS/FCI19002659/Jsd3n2

MARKET VALUE: \$20,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$15,164.00=NETT VALUE: \$4,836.00

ONG HWEE JIE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.