

CS/CTI19002666/Gvd342

Sub Veyor

## ASSIGNMENT (Office)

From (Person): chung Buon Sen

of CTI

Date/Time: 13/2/19 @ 1.40pm

Estimated Cost:

Bill to:

OD / TP RES / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ7787K

Insured:

SKV9271D

at Workshop m/s

Ah Lim Motor

Tel:

64831244

of

No. 10 AMK Ind. Park 2A #01-09

Policy No:

Claim No:

SNM19D200762C02

Sum Insured:

DMPCSN 30270818066

Excess:

Make of Veh:

(Client's Record)

D.O.A. 31/01/2019

14/2/19 @ 11am (ow)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

2.40pm @ 13/2/19

Person Contacted:

Zila

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLQ7787K - X
	SKV9271D - X
29/4/19	@ 3.15pm Mui Hong Said TP Convert to OD claim
30/4/19	Submit preli report

XBL

REF: CT1

664364

## ASSIGNMENT

From: Date: 14/2/19

Estimated Cost:

OD: ☒ WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: SLQ 7787K

at Workshop no: Ah Lim Motor

of No. 10 Amk Ind. park 2A # 01-09

Insured:

Policy No:


Claim No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

~~Name~~  
owner waiting



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repair: days Res.: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLQ 7787K Date: 21 Jul 2017

Type: ☒ Car / ☐ Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover

Truck / Trailer or

Make: Honda Vezel CC: 1496

Colour: white A/C: Insured / Std / NI / NA

Sp Reading: 31662 T/Radio: Insured / Std / NI / NA

Eng No:

Ch No:

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215 / 60 R16

R: 11

BS / ☒ BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 6 mm

L/Bal: 6 mm

D.O.A.

Survey held at

Des. of Damages: ☒ Frt / ☒ Rea / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 30 APR 2019

Date/Time, File Pass to?



Preli. Report

D:



Final Report

Date/Time, File Return to?

30/4 - typist

Report Format:

Lump Sum / LB: / \$

Days Of Repair: 7

Resurvey No. of Trip: -

Add Fee:



Site Insp: (\$



Interview: (\$



Tech. Insp: (\$



Workshop: (\$

Survey Fee:

Transportation:

1. 5 + P. 5

1. Hotel

1. Other:

1. 100

1. 100

1. 100

1. 100

220

220

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Apr 2019		03 Apr 2019 15:32 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	THOR SHI HUA ANGELINE		
Vehicle Reg. No.:	SLQ7787K	Date of Loss:	31/01/2019 00:00 - :59
Claim Type:	TP / SNM19D200762C02	Policy/Cover Note No.:	DMPCSN30270818066
Vehicle Reg. No. (Insured):	SKV9271D	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 12/04/2019]		

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Shu Pei (LKKAuto) <shupe@lkkauto.com>  
**Sent:** Wednesday, 13 February 2019 1:40 PM  
**To:** assignments  
**Subject:** FW: TP / OUR CLIENT SLQ7787K DOA: 31/01/2019 POLICY NO. GA245240 YOUR INSURED SKV9271D

Best Regards,  
Shu Pei | Admin  
LKK Auto Consultants Pte Ltd  
Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Wednesday, 13 February 2019 1:23 PM  
**To:** zila <zila@ahlimmotor.com.sg>  
**Cc:** Admin A <admin-a@lkkauto.com>  
**Subject:** RE: TP / OUR CLIENT SLQ7787K DOA: 31/01/2019 POLICY NO. GA245240 YOUR INSURED SKV9271D

Without Prejudice

Dear Zila,

Will appoint accordingly.

Dear LKK,

Pls pri.

Regards,  
Chong Boon Sen  
Claims Executive  
Claims

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 63896171  
Fax: 62247175  
Email: boonsen.chong@sg.cntaiping.com  
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore)

Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

-----Original Message-----

From: zila [mailto:zila@ahlimmotor.com.sg]

Sent: Wednesday, 13 February, 2019 1:22 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: TP / OUR CLIENT SLQ7787K DOA: 31/01/2019 POLICY NO. GA245240 YOUR INSURED SKV9271D

Hi,

We choose Kenneth to be the surveyor.

Thanks.

Best Regards,

Zila

Ah Lim Motor

Tel: 64831244 Fax: 64836170

On 13/02/2019 1:10 PM, Chong Boon Sen wrote:

> Without Prejudice

> Dear Sirs

> We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

>

>

>

> Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

> You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

>

>

>

> Regards,

> Chong Boon Sen

> Claims Executive

> Claims

>

> China Taiping Insurance (Singapore) Pte. Ltd.

> 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Co. Reg. No.

> 200208384E

> DID: 63896171

> Fax: 62247175

> Email: boonsen.chong@sg.cntaiping.com

> Website: www.sg.cntaiping.com

>

>

> Disclaimer :

> This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore)

Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

>

> -----Original Message-----

> From: zila [mailto:zila@ahlimmotor.com.sg]

> Sent: Tuesday, 12 February, 2019 2:03 PM

> To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

> Subject: Re: TP / OUR CLIENT SLQ7787K DOA: 31/01/2019 POLICY NO.

> GA245240 YOUR INSURED SKV9271D

>

> Hi Boon Sen,

>

> Pls refer to the attached file.

>

>

> Best Regards,

>

>

> Zila

> Ah Lim Motor

> Tel: 64831244 Fax: 64836170

>

> On 12/02/2019 1:56 PM, Chong Boon Sen wrote:

>> Zila,

>>

>> Does not seem like insured under China Taiping?

>>

>> Got change vehicle and relevant change vehicle cert?

>>

>> Regards,

>> Chong Boon Sen

>> Claims Executive

>> Claims

>>

>> China Taiping Insurance (Singapore) Pte. Ltd.

>> 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Co. Reg. No.

>> 200208384E

>> DID: 63896171

>> Fax: 62247175

>> Email: boonsen.chong@sg.cntaiping.com

>> Website: www.sg.cntaiping.com

>>

>>

>> Disclaimer :

>> This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

>>

>> -----Original Message-----

>> From: zila [mailto:zila@ahlimmotor.com.sg]

>> Sent: Tuesday, 12 February, 2019 1:40 PM

>> To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chong Boon Sen

>> <boonsen.chong@sg.cntaiping.com>; Elaine Cheong

>> <elaine.cheong@sg.cntaiping.com>

>> Subject: TP / OUR CLIENT SLQ7787K DOA: 31/01/2019 POLICY NO. GA245240

>> YOUR INSURED SKV9271D

>> Importance: High

>>

>> Hi Claims Dept,

>>

>> Please kindly arrange survey.

>> Note: Vehicle is not in. – To be arrange

>>

>> Thanks.

>>

>>

>

>

>

> This email has been scanned by the Symantec Email Security.cloud service.

> For more information please visit <http://www.symanteccloud.com>

>

>

---

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

---

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6643H
Vehicle Details	
Vehicle No.:	SLQ7787K
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	L15B4404372
Chassis No.:	RU11204371
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,703.00
Original Registration Date:	21 Jul 2017
First Registration Date:	21 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$12,385.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jul 2027
PARF Rebate Amount:	\$9,288.00
Intended COE Rebate Details	
COE Expiry Date:	20 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$36,081.00
<b>Total Rebate Amount:</b>	<b>\$45,369.00</b>

The information contained herein is correct as at 15 Feb 2019

OK



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

6643H

### Vehicle Details

Vehicle No.:

SLQ7787K

Vehicle to be Exported:

No

Intended Deregistration Date:

01 Feb 2019

Vehicle Make:

HONDA

Vehicle Model:

VEZEL 1.5X CVT

Primary Colour:

White

Manufacturing Year:

2016

Engine No.:

L15B4404372

Chassis No.:

RU11204371

Maximum Power Output:

96.0 kW (128 bhp)

Open Market Value:

\$21,703.00

Original Registration Date:

21 Jul 2017

First Registration Date:

21 Jul 2017

Transfer Count:

0

Actual ARF Paid:

\$12,385.00

### Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

20 Jul 2027

PARF Rebate Amount:

\$9,288.00

### Intended COE Rebate Details

COE Expiry Date:

20 Jul 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$42,801.00

COE Rebate Amount:

\$36,242.00

**Total Rebate Amount:**

**\$45,530.00**

The information contained herein is correct as at 01 Feb 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	01/02/2019 16:56
Date Of Accident	31/01/2019 07:05
Exact Location Of Accident	PIE TOWARDS JURONG
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ7787K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	THOR SHI HUA ANGELINE
NRIC No	S8206643H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96828197
Alternative Phone No	OTHERS-91370072

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 X CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA245240
Cover Note Number	21/07/2018 - 20/07/2019

### Driver

Name of Driver	CHOO CHOW SENG
NRIC No	S7810387F
Date Of Birth	20/04/1978
Occupation	INDOOR
Date Of Driving Pass	06/06/2015
Driving Experience	3 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91370072
Fax Number	
Contact Number	OTHERS-96828197
Email Address	LANCECHOO@HOTMAIL.COM

Address	BLK 693A WOODLANDS AVE 6 #03-723
Postcode	731693
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO THE SKETCH PLAN BY DRIVER

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKW899Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKV9271D
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SKT2776X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**


**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan Pg. 2

## SKETCH PLAN

Date of Accident: 31-Jan-19 Time: 0706 hrs Location: PIE towards Jurong  
 My Vehicle A: SLQ 7787K Vehicle B: SKW 899Y Vehicle C: Others: SKV 9271 D



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

When travelling at PIE towards Jurong, SKW 899Y suddenly apply E-brake due to his front car also apply E-brake. Even though keeping at a safe distance, but my car cannot stop in time and hit the back of SKW 899Y. The car behind me also can't stop in time and hit my back.

(ARC - Ryan Hoon Tan Chong)  
 Signature

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop:

email address:

& myself:

email address: lancechoo@hotmail.com

Note: Please take note that your insurer have **14 days timeframe** for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:





THOR SHI HUA ANGELINE  
BLK 682D  
WOODLANDS DRIVE 73  
#11-237  
SINGAPORE 734682

**Renewal**

date  
**28/06/2019**

your servicing distributor  
**S & M ALLIANCE PTE LTD / 04066**

your servicing distributor contact  
**65425535**

## Policy Schedule

**Your SmartDrive Comprehensive Flexi**

### Your policy snapshot

Policyholder name	THOR SHI HUA ANGELINE	Policy number	VA1 / GA245240
Cover	Comprehensive	FIN / NRIC	S8206643H
Period of Insurance	from 21/07/2018 to 20/07/2019 (both dates inclusive)		

### Premium breakdown

Gross Premium after 20% NCD	SGD 1,468.95
Total Discounts	- SGD 265.81
7% GST	SGD 84.22
Final Premium	SGD 1,287.36

### Your benefits highlights

(refer to Policy Wording for full terms and conditions)

#### SmartDrive Comprehensive Flexi Benefits

- 24/7 Towing & Transportation in Singapore or Overseas
- Windscreen Replacement with Excess OR Repair your windscreen at your preferred location and get \$50 cash reward with no excess
- Loss or Damage
- Legal Liability
- Workshop of Your Choice
- Medical and dental expenses up to \$1,000 per person for you, your named drivers and your immediate family members
- Reimbursement of 110% of your car's market value in the event of total loss due to flood (without Basic Own Damage Excess)

#### Add-on Benefits

- Personal accident benefit of up to \$ 50,000.00 for you and your named drivers

### Vehicle details

Make & Model of Vehicle	HONDA VEZEL 1.5	Year of manufacture	2016
Vehicle registration number	SLQ7787K	Type of Use	Private use
Body type	SALOON	Engine capacity (c.c.)	1496
Seating capacity (excl driver)	4	Engine number	L15B4404372
Off-Peak car	No	Chassis number	RU11204371

Insured's Estimated Market Value	Market Value at the time of Loss (including accessories and spare parts)
Limitation to use	As per Certificate of Insurance
Finance Loan Company	MAYBANK

### Excess applicable (refer to Policy Wording for other applicable Excesses)

Basic Own Damage Excess	SGD 500.00
Windscreen Excess	SGD 100.00

AXA Insurance Pte Ltd (199903512M)  
8 Shenton Way, #24-01, AXA Tower,  
Singapore 068811  
Customer Centre, #B1-01

Sketch Plan Pg. 4

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S7810387F



Name  
CHOO CHOW SENG  
(ZHU CHAOSHENG)  
朱朝盛  
Race  
CHINESE  
Date of birth  
20-04-1978  
Sex  
M  
Country of birth  
SINGAPORE

57810387F

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: S7810387F

Name  
CHOO CHOW SENG  
ZHU CHAOSHENG

Valid Date: 20 Apr 1978  
Expiry Date: 06 Jun 2015



002435989F

SG 50

9137 0092 /

plc  
no money  
cur-clip  
1/2/17

9602 8197

4213141



NRIC No. S7810387F



Date of issue  
02-05-2008

APT BLK 693A WOODLANDS AVENUE 6 #03-723  
SINGAPORE 731693  
NRIC No: S7810387F Date: 25/12/2017

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

EFFECTIVE DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg

06 Jun 2015

NP 428A

License No: S7810387F





Sketch Plan Pg. 5



redefining / insurance

Date: 31/01/19

To: Owner of Vehicle Number: PLQ77715

The following has been advised to you via your workshop, Ah Lim Motor Company through their staff, Zila / Eileen / Mui Hong.

Please tick the applicable box if you had been advice on the content as seen below:

- ☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- ☐ You had been advised by the workshop on the liability and merits of the case accordingly.
- ☐ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- ☐ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- ☐ There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- ☐ The estimated waiting time for the spare parts to arrive is \_\_\_\_\_. The estimated arrival time does not include the repair period.
- ☐ You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.
- ☐ For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.
- For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using *any combination* of genuine original parts and/or original equipment manufacturer (OEM) parts.
- ☐ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- ☐ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.
- ☒ Others claim third party

Signed and acknowledge by:

Name and signature of policyholder/authorised driver

Zila

Name and signature of workshop personnel including company stamp



# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

**SURVEYOR COPY**

M/S : THOR SHI HUA ANGELINE  
BLK 682D WOODLANDS DRIVE 73  
#11-237  
SINGAPORE 734682  
TEL: 91370072  
ATTN:

Estimate No: MC1900112  
Date: 11 Feb 2019  
Policy No: GA245240  
Veh Reg No: SLQ7787K  
Make/Model: HONDA VEZEL 1.5X CVT

Your Ref No: SLQ7787K  
Claim Type: Third Party  
Accident Date: 31/01/2019  
TP Veh Reg No: SKV9271D

\* To decay damaged parts  
\* Parts prices are subject to  
\* Third party survey is on a "No Prejudice" basis  
\* No illegal modification(s) is allowed  
\* Supplementary item(s) must be submitted for final approval from insurance Company.

Acknowledged by Repairer  
Signature:  
Date:

## Estimate Repair Cost to Vehicle No :SLQ7787K

Description	Quantity	List Price SS	Amount SS
<b>SPARE PARTS</b>			
1 REAR WINDSCREEN MOULDING	1 PC	120.00	
2 TAILGATE	1 PC	972.50	
3 TAILGATE VEZEL LOGO	1 PC	43.00	
4 TAILGATE HINGE	2 PC	80.00	
5 TAILGATE ABSORBER	2 PC	360.00	
6 TAILGATE INNER LOCK	1 PC	157.00	
7 TAILGATE RUBBER	1 PC	96.80	
8 TAILGATE INNER TRIMBOARD	1 PC	153.40	
9 REAR BUMPER	1 PC	463.70	
10 REAR BUMPER SIDE RETAINERS	2 PC	41.40	
11 REAR BUMPER CLIPS	15 PC	52.50	
12 REAR BUMPER REFLECTOR	2 PC	282.20	
13 REAR BUMPER SIDE RH	1 PC	153.00	
14 REAR EXHAUST PIPE RH	1 PC	528.00	
15 REAR EXHAUST PIPE CHROME RH	1 PC	135.00	
16 REAR END PANEL	1 PC	411.90	
17 REAR END PANEL TOP GARNISH	1 PC	92.30	
18 SPARE TYRE PANEL LOWER COVER	1 PC	190.00	
19 FRONT BONNET	1 PC	892.30	
20 FRONT BONNET HINGE	2 PC	97.00	
21 FRONT BONNET RUBBER INNER	2 PC	46.00	
22 FRONT BONNET RUBBER CTR	2 PC	47.60	
23 FRONT BONNET RUBBER OUTER	2 PC	75.00	
24 FRONT BONNET INNER LOCK	1 PC	89.50	
25 FRONT GRILLE OUTER	1 PC	351.80	
26 FRONT GRILLE INNER	1 PC	385.00	
27 FRONT GRILLE EMBLEM	1 PC	23.90	
28 FRONT GRILLE CLIPS	8 PC	28.00	
29 FRONT GRILLE CHROME MOULDING	1 PC	77.50	
30 FRONT GRILLE INNER BRACKET CTR	1 PC	38.70	
31 FRONT GRILLE SIDE BRACKET	2 PC	39.20	
32 HEADLAMP	2 PC	3,420.00	
33 HEADLAMP LOWER BEAM	2 PC	70.00	
34 FRONT BUMPER	1 PC	801.70	
35 FRONT BUMPER SIDE RETAINER	2 PC	41.20	
36 FRONT BUMPER CLIPS	15 PC	58.50	
37 FRONT BUMPER LOWER AIR GRILLE	1 PC	77.50	



# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

**SURVEYOR COPY**

**M/S :** THOR SHI HUA ANGELINE  
BLK 682D WOODLANDS DRIVE 73  
#11-237  
SINGAPORE 734682  
**TEL:** 91370072  
**ATTN:**

**Estimate No:** MC1900112  
**Date:** 11 Feb 2019  
**Policy No:** GA245240  
**Veh Reg No:** SLQ7787K  
**Make/Model:** HONDA VEZEL 1.5X  
CVT

**Your Ref No:** SLQ7787K  
**Claim Type:** Third Party  
**Accident Date:** 31/01/2019  
**TP Veh Reg No:** SKV9271D

## Estimate Repair Cost to Vehicle No :SLQ7787K

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
38 FRONT BUMPER TOW COVER <i>x NN</i>	1 PC	14.50	
39 FRONT BUMPER LOWER GARNISH <i>?</i>	1 PC	195.60	
40 FRONT BUMPER REINFORCEMENT <i>?</i>	1 PC	321.00	
41 FRONT BUMPER REINFORCEMENT TOP MOULDING <i>?</i>	2 PC	48.40	
42 FOG LAMP <i>!</i>	2 PC	655.40	
43 FOG LAMP COVER <i>?</i>	2 PC	90.00	
44 RADIATOR SUPPORT PANEL <i>?</i>	1 PC	576.00	
45 AIR CON CONDENSER <i>?</i>	1 PC	568.10	
46 RADIATOR ASSY <i>?</i>	1 PC	1,280.00	
47 FRONT FENDER LH <i>x repair</i>	1 PC	580.00	
48 FRONT FENDER COWLING LH <i>x</i>	1 PC	130.00	
49 FRONT FENDER COWLING CLIPS <i>x NN</i>	8 PC	28.00	
		15,480.10	
	Less 20%	3,096.02	12,384.08
<b>Special Nett</b>			
50 FRONT BUMPER LOWER SPOILER - CHECK PRICE <i>?</i>	1 PC	0.0000	
51 NUMBER PLATE <i>- get</i>	2 PC	70.00	
52 RADIATOR COOLANT <i>?</i>	1 PC	30.00	
53 REVERSE SENSOR <i>?</i>	1 SET	200.00	
54 INNER SEAL <i>- m.c.</i>	1 PC	20.00	
55 WINDSCREEN SEALANT <i>- m.c.</i>	1 PC	40.00	
56 REAR BUMPER LOWER SPOILER - CHECK PRICE <i>?</i>	1 PC	0.00	
		360.00	360.00
<b>LABOUR</b>			
57 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	30
58 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00	?
59 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	80.00	60
60 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR FRT FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	900.00	400
61 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH, RADIATOR SUPPORT PANEL.	1 PC	900.00	600.



*+ fnt labour*

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimm@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : THOR SHI HUA ANGELINE  
BLK 682D WOODLANDS DRIVE 73  
#11-237  
SINGAPORE 734682  
TEL: 91370072  
ATTN:

Estimate No: MC1900112  
Date: 11 Feb 2019  
Policy No: GA245240  
Veh Reg No: SLQ7787K  
Make/Model: HONDA VEZEL 1.5X  
CVT

Your Ref No: SLQ7787K  
Claim Type: Third Party  
Accident Date: 31/01/2019  
TP Veh Reg No: SKV9271D

## Estimate Repair Cost to Vehicle No :SLQ7787K

Description	Quantity	List Price	Amount
		SS	SS
62 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	X NN
63 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	100
64 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	80.00	60
65 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	80.00	40.
66 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	40
67 TO REMOVE / REINSTALL REVERSE CAMERA	1 PC	80.00	40.
68 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	80.00	X NN
69 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	80.00	?
70 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD END PANEL TO KNOCK & REPAIR SPARE TYRE PANEL, REAR FENDER RH INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,000.00	400
71 TO SPRAY TAILGATE, REAR BUMPER RH, END PANEL, SPARE TYRE PANEL, REAR FENDER RH	1 PC	1,000.00	300
		4,640.00	4,640.00
		Total	SS 17,384.08
		Add GST @ 7%	1,216.89
		Total Amount Payable	SS 18,600.97

TOTAL: SINGAPORE DOLLAR EIGHTEEN THOUSAND SIX HUNDRED AND CENTS NINETY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.  
Thank You

7 Days.  
part by part.  
before paint photos.  
Cano King - 8288 0282  
14/2/19.

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Apr 2019		03 Apr 2019 15:32 <a href="#">Edit Adj Rpt</a>	<b>S\$6,318.88</b> <a href="#">Edit Estimates</a>	<b>S\$6,318.88</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

#### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured: -, ID: -

Main Claimant: **THOR SHI HUA ANGELINE**

Vehicle Reg. No.: **SLQ7787K**      Date of Loss: 31/01/2019 00:00 - :59  
[18 Months and 10 Days From LTA Reg Date (Man Yr)]

Claim Type: **TP / SNM19D200762C02**      Policy/Cover Note No.: **DMPCSN30270818066**

Vehicle Reg. No. (Insured): **SKV9271D**      Policy No. (Claimant):

Excess: **S\$0.00**

Repairer: **Ah Lim Motor Company (AMK)** 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, S68047 Ang Mo Kio - Tel: 6483 1244

Handling Insurer: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 ... [Handled by **Chong Boon Sen**]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **XING GUO QIANG**] ... [Final Rpt due 12/04/2019]

#### ASSOCIATED MAIL RECEIVED

[View All](#)   [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS

[View All](#)   [Search Tasks](#)   [Create New Task](#)   [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLQ7787K (SNM19D200762C02)

[SKV9271D]



TP

THOR SHI HUA ANGELINE

Jan 31 2019 12:00AM

[-]

Ah Lim Motor Company

Upload Documents		Upload Photos		Compose New Letter		<b>View</b> View in Browser <input type="button" value="v"/>	
<b>Photos/Images</b>						3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	30/04/19 13:43	General View				 Load PDF	
<b>Documentation</b>						1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail	Print
1	03/04/19 15:32	PRI CONTACT				 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div><div></div><div>^</div><div>v</div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19002666/GVD3E2  
Date: 23/05/2019

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30270818066  
 Claimant Vehicle No: SLQ7787K Insured Vehicle No: SKV9271D  
 Date of Loss: 31/01/2019 Nature of Claim: TP Claim No: SNM19D200762C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLQ7787K Engine No: L15B4404372  
 Make & Model: HONDA VEZEL, 1.5 (A) Chassis No: RU11204371  
 Reg. Date: 21/07/2017 (Man. Year: 2016) Odometer: 31662 km  
 Colour: White  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,744.08	4,248.88	8,495.20	66.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,640.00	2,070.00	2,570.00	55.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>17,384.08</b>	<b>6,318.88</b>	<b>11,065.20</b>	<b>63.65</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,216.89</b>	<b>442.32</b>	<b>774.57</b>	<b>63.65</b>
<b>Nett Amount (S\$)</b>	<b>18,600.97</b>	<b>6,761.20</b>	<b>11,839.77</b>	<b>63.65</b>

## INSPECTION

Date of Assignment: 03/04/2019  
 Date Inspected: 14/02/2019 Inspected At: Ah Lim Motor Company (AMK)  
 10 Ang Mo Kio Industrial Park 2A, #01-09  
 AMK Autopoint  
 Singapore 568047  
 Estimated Period of Repair: 7.0 days

**Adjuster:** XING GUO QIANG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$6,334.16 NETT)

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2019)
<b>Parts:</b> M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLQ7787K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
2	1		*TAILGATE	Buckled	972.50 FL	*972.50 FL
3	1		*TAILGATE VEZEL LOGO	Necessary	43.00 FL	*43.00 FL
4	2		*TAILGATE HINGE	Not Necessary	80.00 FL	*- FL
5	2		*TAILGATE ABSORBER	Not Necessary	360.00 FL	*- FL
6	1		*TAILGATE INNER LOCK	Not Necessary	157.00 FL	*- FL
7	1		*TAILGATE RUBBER	Torn	96.80 FL	*96.80 FL
8	1		*TAILGATE INNER TRIMBOARD	* Check	153.40 FL	*- FL
9	1		*REAR BUMPER	Deformed	463.70 FL	*463.70 FL
10	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	41.40 FL	*- FL
11	15		*REAR BUMPER CLIPS	Necessary	52.50 FL	*52.50 FL
12	2		*REAR BUMPER REFLECTOR	* Check	282.20 FL	*- FL
13	1		*REAR BUMPER SIDE RH	Not Necessary	153.00 FL	*- FL
14	1		*REAR EXHAUST PIPE RH	* Check	528.00 FL	*- FL
15	1		*REAR EXHAUST PIPE CHROME RH	Not Necessary	135.00 FL	*- FL
16	1		*REAR END PANEL	* Check	411.90 FL	*- FL
17	1		*REAR END PANEL TOP GARNISH	* Check	92.30 FL	*- FL
18	1		*SPARE TYRE PANEL LOWER COVER	* Check	190.00 FL	*- FL
19	1		*FRONT BONNET	Repair	892.30 FL	*- FL
20	2		*FRONT BONNET HINGE	Not Necessary	97.00 FL	*- FL
21	2		*FRONT BONNET RUBBER INNER	Not Necessary	46.00 FL	*- FL
22	2		*FRONT BONNET RUBBER CTR	Not Necessary	47.60 FL	*- FL
23	2		*FRONT BONNET RUBBER OUTER	Not Necessary	75.00 FL	*- FL
24	1		*FRONT BONNET INNER LOCK	Not Necessary	89.50 FL	*- FL
25	1		*FRONT GRILLE OUTER	Cracked	351.80 FL	*351.80 FL
26	1		*FRONT GRILLE INNER	Cracked	385.00 FL	*385.00 FL
27	1		*FRONT GRILLE EMBLEM	Necessary	23.90 FL	*23.90 FL
28	8		*FRONT GRILLE CLIPS	Necessary	28.00 FL	*28.00 FL
29	1		*FRONT GRILLE CHROME MOULDING	* Check	77.50 FL	*- FL
30	1		*FRONT GRILLE INNER BRACKET CTR	* Check	38.70 FL	*- FL
31	2		*FRONT GRILLE SIDE BRACKET	* Check	39.20 FL	*- FL
32	1		*HEADLAMP	N/S Broken / O/S * Check	3,420.00 FL	*1,710.00 FL
33	2		*HEADLAMP LOWER BEAM	* Check	70.00 FL	*- FL
34	1		*FRONT BUMPER	Deformed	801.70 FL	*801.70 FL
35	2		*FRONT BUMPER SIDE RETAINER	Deformed	41.20 FL	*41.20 FL
36	15		*FRONT BUMPER CLIPS	Necessary	58.50 FL	*58.50 FL
37	1		*FRONT BUMPER LOWER AIR GRILLE	* Check	77.50 FL	*- FL
38	1		*FRONT BUMPER TOW COVER	Not Necessary	14.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*FRONT BUMPER LOWER GARNISH	* Check	195.60 FL	*- FL
40	1		*FRONT BUMPER REINFORCEMENT	* Check	321.00 FL	*- FL
41	2		*FRONT BUMPER REINFORCEMENT TOP MOULDING	* Check	48.40 FL	*- FL
42	2		*FOGLAMP	* Check	655.40 FL	*- FL
43	2		*FOGLAMP COVER	* Check	90.00 FL	*- FL
44	1		*RADIATOR SUPPORT PANEL	* Check	576.00 FL	*- FL
45	1		*AIR CON CONDENSER	* Check	568.10 FL	*- FL
46	1		*RADIATOR ASSY	* Check	1,280.00 FL	*- FL
47	1		*FRONT FENDER LH	Repair	580.00 FL	*- FL
48	1		*FRONT FENDER COWLING LH	Not Necessary	130.00 FL	*- FL
49	8		*FRONT FENDER COWLING CLIPS	Not Necessary	28.00 FL	*- FL
50	1		*FRONT BUMPER LOWER SPOILER (NPA)	* Check	0.00 FS	*- FS
51	2		*NUMBER PLATE	Scratched	70.00 FS	*70.00 FS
52	1		*RADIATOR COOLANT	* Check	30.00 FS	*- FS
53	1		*SET REVERSE SENSOR	* Check	200.00 FS	*- FS
54	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
55	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
56	1		*REAR BUMPER LOWER SPOILER (NPA)	* Check	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>15,840.10</b>	<b>5,278.60</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>3,096.02</b>	<b>1,029.72</b>
<b>Total Parts (\$\$)</b>	<b>12,744.08</b>	<b>4,248.88</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	30.00
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS (* Check)	New	100.00	0.00
3	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR FRT FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME	New	900.00	400.00
4	TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH, RADIATOR SUPPORT PANEL	New	900.00	600.00
5	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	0.00
6	TO REMOVE AND REINSTALL / REPLACE FRONT / REAR WINDSCREEN	New	120.00	100.00
7	TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS	New	80.00	60.00
8	TO REMOVE AND REINSTALL / REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES	New	80.00	40.00
9	TO REMOVE AND REINSTALL / REPLACE FRONT / REAR BUMPER SENSORS	New	60.00	40.00
10	TO REMOVE / REINSTALL REVERSE CAMERA	New	80.00	40.00
11	TO REALIGN, DISMANTLE AND REINSTALL / REPLACE EXHAUST PIPE (* Check)	New	80.00	0.00
12	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL. TO KNOCK & REPAIR SPARE TYRE PANEL, REAR FENDER RH INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME	New	1,000.00	400.00
13	TO SPRAY TAILGATE, REAR BUMPER RH, END PANEL, SPARE TYRE PANEL, REAR FENDER RH	New	1,000.00	300.00
14	TO SPRY ANTI-RUST COATING ON AFFECTED AREAS	New	80.00	60.00
15	TO SPRY ANTI-RUST COATING ON AFFECTED AREAS	New	80.00	0.00
Gross Labour Cost (\$\$)			<b>4,640.00</b>	<b>2,070.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >