

ASS. REC. BY:

REF:

CS/FCI190002668/UVd3

n2

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

githorn

of

FCI

Date/Time:

9:25am 13/2/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8KX8299X

Insured:

SHB3713B

at Workshop m/s

Focus Auto

Tel:

68869097

of

11calci Bkt Ave 6 #02-50

Policy No:

Claim No:

D19000967MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

7/2/19

CA / REV / REP. / REV 24 HRS

KDS

H.O.D. Endorsement:

14/2/19

Date/Time:

12:49pm 13/2/19

Person Contacted:

Ms. Sin

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKX8299X-X

SHB3713B-GS/TMI18008824/KLSbnc Dwa: 11/5/18

15/2/19

Email preli revised to FCI

REF: FCI

DATE: 14/2/19

Name:
 Date: 14/2/19
 Estimated Cost:
 OD: ☒ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV
 To (Report Vehicle No): SKX 829AX
 at (Workshop No): Focus Auto
 of: 1 Kaki Bkt Ave 6 #02-50
 Insured:
 Policy No:
 Claim No:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh:



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Ball. or Market Value: 90
 IDAC Accident Report: Consistent?: Yes or No
 CA / PR Seen: Consistent?: Yes or No
 Est. Repairs: 3 days Res: Yes or No
 Lump Sum: 20 % 3 Val: Yes or No
 CA / REV / REP: / 24 HRS (DS)

Date: Person Contacted:

Vehicle: IN / OUT

Serial No: SKX 829AX or Reg: 12 15
 Type: ☒ Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
 Truck / Trailer or ☒ A1
 Make: Toyota harrier C.C. 1986
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 79252 T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: 254 60 0064459
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: ☒ Jammed / ☐ Leaked / ☐ Burnt or
 Brake: ☒ Jammed / ☐ Leaked / ☐ Burnt or
 Mod: ☒ H / ☐ S/Rim / ☐ STD A/Rim or
 Tyre Size: F:
 R: 235/55-28

☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /
 TOYO / YOKO or

Front		Rear
R/Bal: 7 mm		R/Bal: 7 mm
L/Bal: 7 mm		L/Bal: 7 mm
D.O.A: 7/2/19		D.O.I: 14/2/19

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/2/19 LIA 62865 confirmed r/s to 2200 with AH way (Red 2484.93, 539)

RECEIVED 21 FEB 2019

Date/Time: File Pass to? ☐ : Preli. Report

to: ☐ : Final Report

Date/Time: File Return to?

21/2 - typist

Report Format:

Lump Sum / L.B.E. (\$)

CWS
2200/2

Days Of Repair: 3

Resurvey No. of Trip: -

Add Fee: ☐ Site Insp. (\$)

☐ Interview (\$)

☐ Tech. Insp. (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

1. S. & P. (\$)

2. Hotel (\$)

3. Other (\$)

4. Total (\$)

TOTAL

135

50

44

229



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19000967MFSH

Our ref: CS/FCI19002668/Uvd3

DATE: 15/2/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. SKX 8299X


We thank for your instruction on 13/2/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 14/2/2019 at the premises of M/s FOCUS AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$4,684.93
Revised Estimate Amount	: S\$2,787.05
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	11-02-2019	Our Ref No. D19000967MFSH
Accident Date	07-02-2019	Claim Type. Third Party
Insured Vehicle	SHB3713B	Third Party Vehicle. SKX8299X
Survey Location	NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-50	
Contact Person.	SIN	
Contact No.	68869097/ 0	Fax No. 64819095
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FOCUS AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 15 February 2019 11:27 AM
To: 'CWS Motor Claims'
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000967MFSH/1, SKX 8299X
Attachments: SKX 8299X PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKX 8299X
Date of survey: 14/2/2019
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 13 February 2019 4:37 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000967MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 14/02/2019.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 13 February 2019 9:25 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000967MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



6303 8303



Wide selection of Inchcape Certified Pre-owned LEXUS & TOYOTA



2019



Interest Rate
1.98%
181 31 Jan 2019



Extended Warranty
1yr



Free Tyre & Service Credits
up to
\$3,000

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Wish 1.8A



2.38%p.a Lowest Interest@GV
Cars Financing \$2500
Downpayment Monthly From
\$638
GV Credit Pte Ltd StarAd

PRIME M01

ICHENG YONG CREDIT ENTERPRISES

With over 200 units of vehicle to choose from, ranging from all European to Japanese

Browse by Category

Sort by Date Posted

12 vehicles

harrier

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	harrier		Any	Any	2015	Any	Any	
	Toyota	Harrier 2.0A Premium Panoramic	\$86,688	\$10,950 /yr	08-Sep-2015	1,986 cc	32,460 km	
100% Accident Free, Underutilize By Expat Owners. Car Traded In For A Bigger Car. Car Interior Mint Condition Like New And Original P Our Cars Have Gone Through Complete Checks- No Repair...								
MV Auto								
Posted: 13-Feb-2019 Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota								
	Toyota	Harrier 2.0A Premium Panoramic	\$95,800	\$11,820 /yr	30-Dec-2015	1,986 cc	68,000 km	
Only \$11k Depreciation To Own The Best Looking And Performing Jap SUV In The Market! 1 Owner. Premium Package Unit With Electric Pano Roof! Classy White Exterior On Black Leather Interior Fl...								
Car Buyers Automotive Pte Ltd								
Posted: 13-Feb-2019 Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota								
	Toyota	Harrier 2.0A Elegance Panoramic	\$105,000	\$15,130 /yr	19-Jun-2015	1,986 cc	55,166 km	
Best Buy! 1 Owner Only! More Than \$20k Worth Of Upgrade To The Car! Sound System, Bodykit, Cool And Lite Window Tint, Titan Pack Forged Rim, Full Under Carriage Stable Bars, Brake Kit, Etc. Too...								
Posted: 12-Feb-2019 Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota								
	Toyota	Harrier 2.0A Elegance	\$81,800	\$11,830 /yr	28-Apr-2015	1,986 cc	-	
Very Good Condition. One Meticulous Owner, Low Mileage Hardly Driven, Comfortable And Spacious SUV With Panoramic Sunroof And Navigation System, Very Well Maintained, Please Call Anna To Make A Booking...								
Hua Yang Credit Pte Ltd								
Posted: 11-Feb-2019 Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota								

Turbo Toyota Harrier meets its matches

The Toyota Harrier namesake is a strong one in Singapore, but can the new turbocharged variant hold up against the Mazda CX-5 and the Tiguan?

[Read this article](#)

Compare

Toyota Harrier 2.0A Premium \$82,800 \$10,680 /yr 13-Aug-2015 1,986 cc 70,000 km

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 9848G

Vehicle Details

Vehicle No.: SKX8299X
Vehicle to be Exported: No
Intended Deregistration Date: 11 Feb 2019
Vehicle Make: TOYOTA
Vehicle Model: HARRIER PREMIUM 2.0 A
Primary Colour: White
Manufacturing Year: 2015
Engine No.: 3ZRB679926
Chassis No.: ZSU600064459
Maximum Power Output: 111.0 kW (148 bhp)
Open Market Value: \$29,849.00
Original Registration Date: 29 Dec 2015
First Registration Date: 29 Dec 2015
Transfer Count: 0
Actual ARF Paid: \$28,789.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Dec 2025
PARF Rebate Amount: \$21,591.00

Intended COE Rebate Details

COE Expiry Date: 28 Dec 2025
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$60,001.00
COE Rebate Amount: \$41,274.00
Total Rebate Amount: \$62,865.00

The information contained herein is correct as at 11 Feb 2019

OK

Reprint:1

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6886 9095 Email: focus.autopteltd@yahoo.com.sg

GST:201004495R RCB NO:20100495R

Administered by Repairs

Signature

Date

Not Affected
 4/5 @ 2200
 3 day
 14/2/19
 the photo attached

M/S: FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 6507 3848

FAX: 6507 3849

ATTN: Motor Claim Department

Your Ref No: SKX8299X

Claim Type: Third Party

Accident Date: 07-02-2019

TP Veh Reg No: SHB3713B

Estimate No: EST0000824

Date: 13 Feb 2019

Policy No: DMPHQ18-008655

Veh Reg No: SKX8299X

Make/Model: TOYOTA HARRIER

Chassis No: ZSU600064459

Engine No: 3ZRB679926

Reg. Date: 29-12-2015

Estimate Repair Cost for Vehicle No :SKX8299X

PAGE:1/1

Description	U/Price	Quantity	List Price SS	Amount SS
SKX8299X TOYOTA HARRIER				
List Price				
1 Rear Bumper	1,415.0000	1 PC	1,415.00	1381.10
2 Rear Bumper Inner Sponge	125.0000	2 PC	250.00	1 pc
3 Rear Bumper Side Retainer	151.9000	2 PC	303.80	X
4 Rear Bumper Lower Spoiler	520.2000	1 PC	520.20	—
5 Rear Bumper Clip	5.5000	4 PC	22.00	—
6 Rear End Panel	821.7000	1 PC	821.70	X
7 Rear Smart Sensor	207.2000	1 PC	207.20	—
			3,539.90	
	Less 25%		884.98	2,654.93
Special Net				
8 Rear Bumper Sensor	300.0000	1 set	300.00	200.00
			300.00	300.00
Labour				
9 Panel Beating	850.0000	1 PC	850.00	300
10 Check Wiring	60.0000	1 PC	60.00	20
11 Rust Proofing	60.0000	1 PC	60.00	X
12 To Remove & Replace Bumper Sensor	80.0000	1 PC	80.00	50
13 Spray Painting	680.0000	1 PC	680.00	500
			1,730.00	1,730.00
			Total	SS 4,684.93

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND SIX HUNDRED EIGHTY FOUR AND CENTS NINETY THREE ONLY

For FOCUS AUTO PTE LTD

AUTHORISED SIGNATURE

p-2255.50
 252
 1691.62
 2761.62
 2209.30



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19002668/Uvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 22-02-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3713B	Veh. Inspected	SKX 8299X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000967MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	13/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER (A)	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	ZSU600064459	Colour	WHITE	
Odometer	79252	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R18	BRIDGESTONE	7 mm	
L/H Front Tyre	235/55 R18	BRIDGESTONE	7 mm	
R/H Rear Tyre	235/55 R18	BRIDGESTONE	7 mm	
L/H Rear Tyre	235/55 R18	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/02/2019	Inspection Date	14/02/2019	
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 8299X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED / DEFORMED	1,415.00	1,381.10
2	REAR BUMPER INNER SPONGE @\$125.00	TORN (1 PC ONLY)	250.00	125.00
2	REAR BUMPER SIDE RETAINER @\$151.90	NOT NECESSARY	303.80	-
1	REAR BUMPER LOWER SPOILER	DEFORMED	520.20	520.20
4	REAR BUMPER CLIP @\$5.50	NECESSARY	22.00	22.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	821.70	-
1	REAR SMART SENSOR	CRACKED	207.20	207.20
	LESS 25% DISCOUNT		-884.97	-563.87
			2,654.93	1,691.63
SPECIAL NETT ITEMS				
1	SET REAR BUMPER SENSOR (SN)	SHORTED	300.00	200.00
			300.00	200.00
LABOUR				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		850.00	300.00
	CHECK WIRING.		60.00	20.00
	RUST PROOFING.	NOT NECESSARY	60.00	-
	TO REMOVE & REPLACE BUMPER SENSOR.		80.00	50.00
	SPRAY PAINTING.		680.00	500.00
			1,730.00	870.00
GRAND TOTAL			4,684.93	2,761.63
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,200.00

Report Ref No. CS/FC119002668/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.