

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050
 42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523
 (Email Adress : woonmeng @singnet.com.sg)
 Co Reg No. 200603678M GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : EQ Insurance Company Ltd
 Motor Claims Dept

Date : 12 Feb 2019

Dear Sirs :

Fax : 62234190
 62243903

RE : ESTIMATE COST FOR HONDA SHUTTLE 1.5G - SMA1099A ACCIDENT INVOLVING SMA1099A & FBJ9100J ON 09/02/2019

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear bumper	1pc	\$ 620.00 <i>de</i>
2	Rear bumper retainer @\$20ea.	2pcs	\$ 40.00 <i>new</i>
3	Towing cover.	1pc	\$ 18.00 <i>new</i>
4	Rear bootlid.	1pc	\$ 580.00 <i>Ry</i>
5	Rear end panel.	1pc	\$ 280.00 <i>Ry</i>
6	Shuttle.	1pc	\$ 38.00 <i>new</i>
7	Emblem.	1pc	\$ 25.00 <i>new</i>
			\$ 1,601.00
	Add 20%		\$ 320.20
			\$ 1,921.20
8	Rear sensor.	1set	\$ 220.00 <i>200 new</i>
	Sum Carried Forward		\$ 2,141.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Sum Carried Forward \$ 2,141.20

Labour Charge & Misc

To remove, repair, replace & install }
damaged parts. } \$ 750.00 *400*

To R & R sensor wiring \$ 60.00 *30*

To putty & spray painting. \$ 700.00 *450*

Total \$ 3,651.20

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

Taylor 97495749
wp
12/2/17 1650
Resuming before part
taylor@theauto.com
04 days