



## Case Details

Case Reference Number : TAX/02/19/2012  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHC4697C

Company Type : SMRT Taxis Pte Ltd  
 Estimation ID : EST-5618-ID  
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : EQ Insurance Company Ltd  
 Accident Date and Time : 02/02/2019 02:00 AM  
 Vehicle Age(In Months) : 53

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

| BOM Type                     | Costing Type | Portion | Material Number | Part Name                  | Qty | SMRT Recommendation     |                |        |                 | Repair/ Replace         | Surveyor Approval |                          |                | Remarks |
|------------------------------|--------------|---------|-----------------|----------------------------|-----|-------------------------|----------------|--------|-----------------|-------------------------|-------------------|--------------------------|----------------|---------|
|                              |              |         |                 |                            |     | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) |                         | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace |         |
| One Time Key In              | Main         |         |                 | BUMPER REAR                | 1   | 458.60                  | 458.60         | 25.00  | 343.95          | Replace                 | 1                 | 0                        | Repair         |         |
| One Time Key In              | Main         |         |                 | BUMPER CLIPS               | 10  | 1.61                    | 16.10          | 25.00  | 12.08           | Replace                 | 0                 | 0                        | Not Give       |         |
| One Time Key In              | Main         |         |                 | PIXEL STICKER              | 2   | 60.00                   | 120.00         | 0.00   | 120.00          | Replace                 | 2                 | 120.00                   | Replace        | NEC     |
| One Time Key In              | Main         |         |                 | BUMPER SIDE RETAINER RR/LH | 1   | 94.80                   | 94.80          | 25.00  | 71.10           | Replace                 | 0                 | 0                        | Not Give       |         |
| One Time Key In              | Main         |         |                 | BUMPER SEAL, RR LH         | 1   | 88.90                   | 88.90          | 25.00  | 66.68           | Replace                 | 0                 | 0                        | Not Give       |         |
| One Time Key In              | Main         |         |                 | DOOR RR/LH                 | 1   | 954.50                  | 954.50         | 25.00  | 715.88          | Replace                 | 1                 | 0                        | Repair         |         |
| One Time Key In              | Main         |         |                 | FENDER RR/LH               | 1   | 766.80                  | 766.80         | 25.00  | 575.10          | Replace                 | 1                 | 0                        | Repair         |         |
| One Time Key In              | Main         |         |                 | STICKER DECAL SMRT         | 1   | 7.80                    | 7.80           | 0.00   | 7.80            | Replace                 | 1                 | 7.80                     | Replace        | NEC     |
| One Time Key In              | Main         |         |                 | STICKER DECAL 6555 8888    | 1   | 21.60                   | 21.60          | 0.00   | 21.60           | Replace                 | 1                 | 21.60                    | Replace        | NEC     |
| One Time Key In              | Main         |         |                 | TYRE                       | 1   | 126.74                  | 126.74         | 0.00   | 126.74          | Replace                 | 0                 | 0                        | Not Give       |         |
| <b>Total Spare Part Cost</b> |              |         |                 |                            |     |                         |                |        | 3,174.08        | <b>Surveyor Total</b>   |                   | 149.40                   |                |         |
| <b>Lump Sum Discount (%)</b> |              |         |                 |                            |     |                         |                |        | 20.00           | <b>Lump Sum Dis (%)</b> |                   | 20                       |                |         |
| <b>Final Spare Part Cost</b> |              |         |                 |                            |     |                         |                |        | 2,539.26        | <b>Final Sur Total</b>  |                   | 119.52                   |                |         |

| SMRT Recommendation          |              |         |                 |            |     |                         |                |        |                 | Surveyor Approval       |                   |                          |                |         |
|------------------------------|--------------|---------|-----------------|------------|-----|-------------------------|----------------|--------|-----------------|-------------------------|-------------------|--------------------------|----------------|---------|
| BOM Type                     | Costing Type | Portion | Material Number | Part Name  | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace         | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In              | Main         |         |                 | WHEEL DISC | 1   | 1,484.20                | 1,484.20       | 25.00  | 1,113.15        | Replace                 | 1                 | 0                        | Repair         |         |
| <b>Total Spare Part Cost</b> |              |         |                 |            |     |                         |                |        | 3,174.08        | <b>Surveyor Total</b>   |                   | 149.40                   |                |         |
| <b>Lump Sum Discount (%)</b> |              |         |                 |            |     |                         |                |        | 20.00           | <b>Lump Sum Dis (%)</b> |                   | 20                       |                |         |
| <b>Final Spare Part Cost</b> |              |         |                 |            |     |                         |                |        | 2,539.26        | <b>Final Sur Total</b>  |                   | 119.52                   |                |         |

**Labour's Cost Detail**

| S.No.         | Costing Type | Job Scope            | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|--------------|----------------------|-------------------------|-------------------------|---------|
| 1             | Main         | TO REPAIR LH PORTION | 845.00                  | 600                     |         |
| <b>Total:</b> |              |                      | <b>845.00</b>           | <b>600.00</b>           |         |

**Spray Cost Detail**

| S.No.         | Costing Type | Job Scope                 | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|--------------|---------------------------|-------------------------|-------------------------|---------|
| 1             | Main         | TO REPSRAY REAR BUMPER    | 378.00                  | 200                     |         |
| 2             | Main         | TO REPSRAY REAR DOOR LH   | 378.00                  | 200                     |         |
| 3             | Main         | TO RESPRAY REAR FENDER LH | 378.00                  | 200                     |         |
| 4             | Main         | TO RESPRAY RIM            | 180.00                  | 50                      |         |
| <b>Total:</b> |              |                           | <b>1,314.00</b>         | <b>650.00</b>           |         |

**Other Cost Detail**

| S.No.         | Costing Type | Job Scope                               | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|--------------|---|-------------------------|-------------------------|---------|
| 1             | Main         | TOWING CHARGE                           | 56.00                   | 0                       |         |
| 2             | Main         | TO CHECK WIRING AND SYSTEM FUNCTION     | 80.00                   | 0                       |         |
| 3             | Main         | TO APPLY RUST-PROOFING ON AFFECTED AREA | 100.00                  | 20                      |         |
| 4             | Main         | TO DO WHEEL ALIGNMENT / TYRE BALANCING  | 120.00                  | 60                      |         |
| 5             | Main         | TO REPLACE SUNDRY PARTS                 | 100.00                  | 0                       |         |
| 6             | Main         | TO WASH AND VACUUM                      | 60.00                   | 0                       |         |
| <b>Total:</b> |              |   | <b>516.00</b>           | <b>80.00</b>            |         |

# Summary

|                          | Estimator Assesment(\$)             | Surveyor Assesment(\$)   |
|--------------------------|-------------------------------------|--|
| Total Spare Part Detail  | 2,539.26                            | 119.52   |
| Total Labour Cost        | 845.00                              | 600.00   |
| Total Spray Painting     | 1,314.00                            | 650.00   |
| Other                    | 516.00                              | 80.00  |
| Overall Total            | 5,214.26                            | 1,449.52   |
| Lump Sum Repair Option   | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/>  |
| Lump Sum Total           | 5,200.00                            | 1,450.00   |
| Surveyor Approved Amount |                                     | 1,450.00   |
| No of Repair Days*       | 6                                   | 3  |
| Remarks                  | -                                   | p/p repair, photo before paint.  |
| Surveyor Name            |                                     | Hwee jie   |
| Signature                |                                     |  |
| Survey Date              | 08/02/2019                          |  |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: