



ER

## ACKNOWLEDGMENTS

|                                       |          |
|---------------------------------------|----------|
| Page No.                              | Date     |
| Estimated cost                        |          |
| Cost of raw material for the material |          |
| Cost of labour for the                |          |
| Cost of overheads:                    | W.L.A.M. |
| Total                                 |          |
| Budgeted                              |          |
| Actual                                |          |
| Variance                              |          |
| Favourable                            |          |
| Unfavourable                          |          |
| Total incurred                        | Excess   |
| (Control - Revised)                   |          |
| Material cost                         |          |

**Remark:** The vehicle had commenced its repair at the time of inspection.

|                          |                          |
|--------------------------|--------------------------|
| Ref. or Market Value     | 9/45K                    |
| Basic Accident Prior     | Consistent? Yes or No    |
| GAZ / FH Taken           | Consistent? Yes or No    |
| Est. Repairs             | 6 days Yes or No         |
| Amount                   | 1-B-1 % 3 Vol. Yes or No |
| GAZ / REV / REP / 24 HRS |                          |

| Factor                   | Persons Considered  |
|--------------------------|---------------------|
| 1. Age                   | 18-24               |
| 2. Sex                   | Male                |
| 3. Education             | High school or less |
| 4. Income                | \$10,000 or less    |
| 5. Race                  | Black               |
| 6. Religion              | Protestant          |
| 7. Marital status        | Married             |
| 8. Political affiliation | Democrat            |
| 9. Geographic location   | Urban               |
| 10. Employment           | Unemployed          |
| 11. Health status        | Chronic illness     |
| 12. Social network       | Isolated            |
| 13. Cultural background  | Immigrant           |
| 14. Family structure     | Single parent       |
| 15. Life events          | Recent loss         |
| 16. Personality traits   | Introverted         |
| 17. Values               | Materialistic       |
| 18. Attitudes            | Pessimistic         |
| 19. Beliefs              | Religious           |
| 20. Interests            | None                |
| 21. Hobbies              | None                |
| 22. Skills               | None                |
| 23. Talents              | None                |
| 24. Abilities            | None                |
| 25. Strengths            | None                |
| 26. Weaknesses           | None                |
| 27. Challenges           | None                |
| 28. Opportunities        | None                |
| 29. Resources            | None                |
| 30. Support systems      | None                |
| 31. Coping mechanisms    | None                |
| 32. Resilience           | None                |
| 33. Adaptability         | None                |
| 34. Flexibility          | None                |
| 35. Creativity           | None                |
| 36. Innovation           | None                |
| 37. Problem-solving      | None                |
| 38. Decision-making      | None                |
| 39. Communication        | None                |
| 40. Leadership           | None                |
| 41. Teamwork             | None                |
| 42. Collaboration        | None                |
| 43. Networking           | None                |
| 44. Mentorship           | None                |
| 45. Guidance             | None                |
| 46. Inspiration          | None                |
| 47. Motivation           | None                |
| 48. Persistence          | None                |
| 49. Determination        | None                |
| 50. Commitment           | None                |
| 51. Dedication           | None                |
| 52. Passion              | None                |
| 53. Enthusiasm           | None                |
| 54. Optimism             | None                |
| 55. Positivity           | None                |
| 56. Hope                 | None                |
| 57. Faith                | None                |
| 58. Trust                | None                |
| 59. Respect              | None                |
| 60. Kindness             | None                |
| 61. Compassion           | None                |
| 62. Empathy              | None                |
| 63. Understanding        | None                |
| 64. Tolerance            | None                |
| 65. Open-mindedness      | None                |
| 66. Curiosity            | None                |
| 67. Wonder               | None                |
| 68. Awe                  | None                |
| 69. Amazement            | None                |
| 70. Surprise             | None                |
| 71. Excitement           | None                |
| 72. Joy                  | None                |
| 73. Happiness            | None                |
| 74. Contentment          | None                |
| 75. Satisfaction         | None                |
| 76. Fulfillment          | None                |
| 77. Purpose              | None                |
| 78. Meaning              | None                |
| 79. Significance         | None                |
| 80. Impact               | None                |
| 81. Legacy               | None                |
| 82. Influence            | None                |
| 83. Power                | None                |
| 84. Authority            | None                |
| 85. Control              | None                |
| 86. Dominance            | None                |
| 87. Supremacy            | None                |
| 88. Superiority          | None                |
| 89. Inferiority          | None                |
| 90. Equality             | None                |
| 91. Fairness             | None                |
| 92. Justice              | None                |
| 93. Equity               | None                |
| 94. Balance              | None                |
| 95. Harmony              | None                |
| 96. Unity                | None                |
| 97. Connection           | None                |
| 98. Relationship         | None                |
| 99. Bond                 | None                |
| 100. Link                | None                |

| Index | Time | Notes / Instructions      |
|-------|------|---------------------------|
| 1     | 0:00 | Start of the session      |
| 2     | 0:05 | Introduction to the topic |
| 3     | 0:10 | First question            |
| 4     | 0:15 | Second question           |
| 5     | 0:20 | Third question            |
| 6     | 0:25 | Fourth question           |
| 7     | 0:30 | Fifth question            |
| 8     | 0:35 | Sixth question            |
| 9     | 0:40 | Seventh question          |
| 10    | 0:45 | Eighth question           |
| 11    | 0:50 | Ninth question            |
| 12    | 0:55 | Tenth question            |
| 13    | 1:00 | End of the session        |

Vehicle: SLF4131E      VIN: 206      Date: Aug.  
Type: 4x4 Cycle / Bus / Van / Carry / Truck / Other: \_\_\_\_\_  
Truck / Trailer or \_\_\_\_\_

Date: *Land Rover Discovery Sport* Year: *1999*  
 Color: *A Grey.* RA: Insured / *500 / 10 / 10*  
 Sp/Decoding: *48347* (Radio: Insured / *500 / 10 / 10*)

SA LCA2A695 H566 213

Can / Cant / Can't / Fair / Poor / Guard

Showing: Ignored / Jammed / Leaked / Burnt - on

Broken / Broken / Jammed / Leaked / Burnt / ...

Mod. Nil / Prim / STD ARNm (c)

|           |    |          |
|-----------|----|----------|
| Typo Date | R: | 255/55K4 |
|           | R: | 2 4      |

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHYS / PRO / SUMI /  
TOYO / YOKO or

Good 6 mm. Poor 6 mm.

|       |   |    |       |   |    |
|-------|---|----|-------|---|----|
| 1.000 | 6 | mm | 1.000 | 6 | mm |
|-------|---|----|-------|---|----|

|     |      |                |
|-----|------|----------------|
| DOA | 0.01 | 4/3/19 e 250pm |
|-----|------|----------------|

Barney field at Waves 45 long Hae

Price of Damage(s):  Front  Rear  O/S  M/S  W/C  Rooftop

Rev N/S

The A/C / Chassis frame / Body Structure affected due to collision.

Rebate \$108,984

P/P 418,389.19

(Rid = \$18497.19 / 50%)

☐ Profit Report☐ Plant Report

Copyright © 2004 John Wiley & Sons, Ltd.

### Copyright Clearance

1. *Journal of Management Studies* 1990, 27, 103-117.

Days Of Repair:

Reentry No. of Trip.

Add Fee: ☐ Late Fee: ☐

**Figure 1**

TABLE 1. *Continued*

☐ **Wiederholungsfrage**

2. *How many times did you use the program?*

### References

張： 164 車

10.1186/1745-6215-10-10



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607188H

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC4/EQI19002683/T1jb3

Date: 05.03.2019

The Motor Claims Department  
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SLF4131E**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 04.03.2019 at the premises of M/s Wearnes Automotive Pte Ltd and have the following to report:-

|                          |       |           |
|--------------------------|-------|-----------|
| Workshop Estimate Amount | : S\$ | 35,654.80 |
| Revised Estimate Amount  | : S\$ | 17,312.50 |
| "Check" Items Amount     | : S\$ | 5,556.50  |
| Market Value             | : S\$ | -         |
| LTA Reimbursement Value  | : S\$ | -         |
| Nett Value               | : S\$ | -         |

Description of Damage:

The vehicle sustained damages at the  
Rear N/S portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6 days

Yours faithfully,

MOHD. RASUL  
**Licensed Appraiser**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                     |                           |            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------|---------------------------|------------|-------------------------------------------------------------------------------------|
| EQ INSURANCE COMPANY LTD                                                                                                               |                                                                     | Ref : CC4/EQI19002683/jb3 |            |                                                                                     |
| 5 MAXWELL ROAD<br>#17-00 TOWER BLOCK<br>MND COMPLEXSINGAPORE 069110                                                                    |                                                                     | Date : 13-02-2019         |            |  |
|                                                                                                                                        |                                                                     | Code : EQI                |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                     |                           |            |                                                                                     |
| Insured Veh.                                                                                                                           | GBG 1678C                                                           | Veh. Inspected            | SLF 4131E  |                                                                                     |
| Policy No.                                                                                                                             |                                                                     | Coverage (\$)             | 0.00       |                                                                                     |
| Claim No.                                                                                                                              |                                                                     | Excess (\$)               | 0.00       |                                                                                     |
| Assign From                                                                                                                            |                                                                     | Assign Date               | 13/02/2019 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                     |                           |            |                                                                                     |
| Make & Model                                                                                                                           |                                                                     | c.c                       | 0          |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                              | Year of Reg.              |            |                                                                                     |
| Chassis No.                                                                                                                            |                                                                     | Colour                    |            |                                                                                     |
| Odometer                                                                                                                               | -                                                                   | Steering                  |            |                                                                                     |
| Brakes                                                                                                                                 |                                                                     | Modification              |            |                                                                                     |
| General                                                                                                                                |                                                                     |                           |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                     |                           |            |                                                                                     |
|                                                                                                                                        | Size                                                                | Make                      | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                         |                                                                     |                           | mm         |                                                                                     |
| L/H Front Tyre                                                                                                                         |                                                                     |                           | mm         |                                                                                     |
| R/H Rear Tyre                                                                                                                          |                                                                     |                           | mm         |                                                                                     |
| L/H Rear Tyre                                                                                                                          |                                                                     |                           | mm         |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                     |                           |            |                                                                                     |
|                                                                                                                                        |                                                                     |                           |            |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                     |                           |            |                                                                                     |
| Accident Date                                                                                                                          | 01/02/2019                                                          | Inspection Date           |            |                                                                                     |
| Survey held at                                                                                                                         | WEARNES AUTOMOTIVE PTE LTD<br>45 LENG KEE ROAD<br>SINGAPORE 159103. |                           |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                     |                           |            |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                     |                           |            |                                                                                     |

# SERVICE ESTIMATE

86639 - C00001  
Mr Ho Chee Yon

SL: SERVICE SALES - PC

GST Reg.No:M28920628X  
Inv.No. : B8P 0 Page 1  
Inv.date. : 07/02/2019  
WIP No. : 52013  
Veh.In/Out:  
\*Tel.No. : Mobile: 93821919  
Reg.No. : SLF4131E  
Reg.date : 25/08/2018  
Mileage : 0  
Chassis No: SALCA2A69GH566213

Closed by : Paul Ong Qing Yong  
Svc Consultant :  
Remarks : Mr Ho Chee Yon

| Op.No                                  | Description                                                                             | Mech Qty | Price   | Disc% | Pkg | Amount   | B           |
|----------------------------------------|-----------------------------------------------------------------------------------------|----------|---------|-------|-----|----------|-------------|
| 802                                    | TO REPLACE REAR BUMPER,<br>REAR BOOTLID, REAR LH QTR PANEL,<br>REAR TAILLAMP, BOOT LAMP | 0        | 6000.00 | 0     |     | 6,000.00 | S 4800.00 L |
| 800                                    | TO PUTTY SPRAYPAINT ON<br>REAR BUMPER, REAR BOOTLID,<br>REAR QTR PANEL                  | 0        | 4000.00 | 0     |     | 4,000.00 | S 3000.00 L |
| 802                                    | TO TRANSFER REAR BOOTLID PARTS                                                          | 0        | 500.00  | 0     |     | 500.00   | S ✓ L       |
| 802                                    | TO REMOVE & REFIT INTERIOR PAR                                                          | 0        | 2400.00 | 0     |     | 2,400.00 | S X n       |
| 802                                    | TO REPLACE REAR WINDSCREEN                                                              | 0        | 1200.00 | 0     |     | 1,200.00 | S 600 L     |
| 802                                    | TO REPLACE REAR QTR GLASS                                                               | 0        | 600.00  | 0     |     | 600.00   | S X n       |
| 0080                                   | TO INSTALL REAR WINDSCREEN FIL                                                          | 0        | 280.00  | 0     |     | 280.00   | S ✓ L       |
| 0080                                   | TO INSTALL REAR QTR GLASS FILM                                                          | 0        | 280.00  | 0     |     | 280.00   | S X n       |
| 280                                    | TO CHECK WIRING INCLUDE                                                                 | 0        | 486.00  | 0     |     | 486.00   | S ✓ L       |
| RESETTING OF ALL ELECTRICAL<br>MODULES |                                                                                         |          |         |       |     |          |             |
| 802                                    | TO REPLACE REAR LH EXHAUST ASS                                                          | 0        | 2400.00 | 0     |     | 2,400.00 | S ?1200 X   |
| 0031                                   | TO REPLACE REAR LH RIM                                                                  | 0        | 50.00   | 0     |     | 50.00    | S X n.      |

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T +65 6430-4700 www.wearnesauto.com

Co reg no. 199501400R / GST reg no. M28920628X

Tan Jia 92495749

wp

4/3/19 @ 230pm

Review before paint.

o Gohys

tan jia @ lkkauto.com  
surv lkkauto.com

### SERVICE ESTIMATE

86639 - C00001  
Mr Ho Chee Yon

SL: SERVICE SALES - PC

GST Reg.No: H28920628X

Inv.No. : B&P 0 Page 2

Inv.date : 07/02/2019

WIP No. : 52013

Veh.In/Out:

\*Tel.No. : Mobile: 93821919

Reg.No. : SLF4131E

Reg.date : 25/08/2016

Mileage : 0

Chassis No: SALCA2AG9GH566213

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Ho Chee Yon

| Op.No | Description | Mech Qty | Price | Disc% | Pkg | Amount | G |
|-------|-------------|----------|-------|-------|-----|--------|---|
|-------|-------------|----------|-------|-------|-----|--------|---|

|     |                      |        |         |   |  |          |                 |
|-----|----------------------|--------|---------|---|--|----------|-----------------|
| 419 | WHEEL ALIGNMENT      | 0      | 280.00  | 0 |  | 280.00   | S ✓             |
|     | LLR075430/HUFFLER -  | 1.0 EA | 1669.90 |   |  | 1,669.90 | S ? X NN        |
|     | HUFFLER - REAR RH    | 1.0 EA | 1112.40 |   |  | 1,112.40 | S ? X NN        |
|     | INSULATOR - RUBBER   | 2.0 EA | 56.70   |   |  | 113.40   | S ? X NN        |
|     | CLAMP 60MM           | 1.0 EA | 75.80   |   |  | 75.80    | S ? X NN        |
|     | BUMPER COVER REAR DS | 1.0 EA | 1928.20 |   |  | 1,928.20 | S ✓ P 1735.38   |
|     | BRACKET - BUMPER MOU | 1.0 EA | 115.20  |   |  | 115.20   | S ? X NN        |
|     | TOW HOOK COVER REAR  | 1.0 EA | 27.40   |   |  | 27.40    | S X NY P 190.07 |
|     | MOULDING - REAR WHEE | 1.0 EA | 322.30  |   |  | 322.30   | S ✓ P 26.73     |
|     | TRIM CLIP BLUE EVOQU | 3.0 EA | 9.90    |   |  | 29.70    | S NE P 4.68     |
|     | TRIM CLIP WHITE EVOQ | 2.0 EA | 2.60    |   |  | 5.20     | S NE P 315.72   |
|     | GLASS - QUARTER WIND | 1.0 EA | 672.10  |   |  | 672.10   | S X NN          |
|     | FOG LAMP REAR LH DSP | 1.0 EA | 350.80  |   |  | 350.80   | S ✓ P 315.72    |
|     | LAMP - REAR, STOP AM | 1.0 EA | 585.60  |   |  | 585.60   | S ✓ P 581.76    |
|     | SEAL - REAR LAMP     | 1.0 EA | 37.80   |   |  | 37.80    | S ✓ P 219.78    |
|     | LAMP - REAR, STOP AM | 1.0 EA | 646.40  |   |  | 646.40   | S ✓ P 581.76    |
|     | *D* WINDSCREEN SEALA | 2.0 EA | 122.10  |   |  | 244.20   | S ✓ P 219.78    |

### SERVICE ESTIMATE

86639 - C00001  
Mr Ho Chee Yon

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 3

Inv.date. : 07/02/2019

WIP No. : 52013

Veh.In/Out:

\*Tel.No. : Mobile: 93821919

Reg.No. : SLF4131E

Reg.date. : 25/08/2016

Mileage : 0

Chassis No: SALCA2AG9GH566213

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Ho Chee Yon

| Op.No | Description | Mech Qty | Price | Disc% | Pkg | Amount | G |
|-------|-------------|----------|-------|-------|-----|--------|---|
|-------|-------------|----------|-------|-------|-----|--------|---|

|                                       |         |         |  |  |  |            |             |
|---------------------------------------|---------|---------|--|--|--|------------|-------------|
| *D* PRIMER GLASS & P                  | 1.0 EA  | 37.40   |  |  |  | 37.40 S    | ✓ P 33.46   |
| TAILGATE PANEL DSPOR <i>aluminium</i> | 1.0 EA  | 3281.50 |  |  |  | 3,281.50 S | ✓ P 3053.35 |
| TRIM CLIP WHITE EVO                   | 10.0 EA | 4.20    |  |  |  | 42.00 S    | ✓ P 39.80   |
| REAR WINDSCREEN DSPOR                 | 1.0 EA  | 1125.20 |  |  |  | 1,125.20 S | ✓ P 1012.68 |
| FENDER REAR LH DSPOR                  | 1.0 EA  | 3008.00 |  |  |  | 3,008.00 S | ✓ RY        |
| ALLOY WHEEL STYLE 52                  | 1.0 EA  | 1748.30 |  |  |  | 1,748.30 S | ✓ RY 9200   |

Gross Total. 35,654.80

Labour Total 18,476.00  
Parts Total 17,178.80  
Package Total 0.00

Net..... 35,654.80  
GST @ 7.0% 2,495.84  
Total..... 38,150.65  
Paid..... 0.00  
Please Pay.. 38,150.65

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

### SERVICE ESTIMATE

0 - E00004 SL: EQ INSURANCE COMPANY LTD

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD

#17-00 TOWER BLOCK

MND COMPLEX

SINGAPORE 069110

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 16/04/2019

WIP No. : 52013

Veh.In/Out: 04/03/2019 26/03/2019

\*Tel.No. : 62239433

Reg.No. : SLF4131E

Reg.date : 25/08/2016

Mileage : 49,347

Chassis No: SALCA2AG9GH566213

Closed by .... : Paul Ong Qing Yong

Svc Consultant : ACC

Remarks ..... : Mr Ho Chee Yon

| Op.No | Description                                                            | Mech Qty | Price   | Disc% | Pkg | Amount   | G |
|-------|------------------------------------------------------------------------|----------|---------|-------|-----|----------|---|
| 802   | TO REPLACE REAR BUMPER,<br>REAR BOOTLID,<br>REPAIR REAR LH QTR PANEL   | 0        | 4800.00 | 0     |     | 4,800.00 | S |
| 800   | TO PUTTY SPRAYPAINT ON<br>REAR BUMPER, REAR BOOTLID,<br>REAR QTR PANEL | 0        | 3000.00 | 0     |     | 3,000.00 | S |
| 802   | TO TRANSFER REAR BOOTLID PARTS                                         | 0        | 500.00  | 0     |     | 500.00   | S |
| 802   | TO REPLACE REAR WINDSCREEN                                             | 0        | 600.00  | 0     |     | 600.00   | S |
| 0080  | TO INSTALL REAR WINDSCREEN FIL                                         | 0        | 280.00  | 0     |     | 280.00   | S |
| 280   | TO CHECK WIRING INCLUDE<br>RESETTING OF ALL ELECTRICAL<br>MODULES      | 0        | 486.00  | 0     |     | 486.00   | S |
| 419   | WHEEL ALIGNMENT                                                        | 0        | 280.00  | 0     |     | 280.00   | S |
| 800   | TO PUTTY SPRAY PAINT<br>REAR LH RIM                                    | 0        | 200.00  | 0     |     | 200.00   | S |
|       | BUMPER COVER REAR DS                                                   | 1.0 EA   | 1928.20 | 10    |     | 1,735.38 | S |
|       | TRIM CLIP BLUE EVOQU                                                   | 3.0 EA   | 9.90    | 10    |     | 26.73    | S |



### SERVICE ESTIMATE

O - E00004      SL: EQ INSURANCE COMPANY LTD  
 EQ INSURANCE COMPANY LTD      GST Reg.No:M28920628X  
 5 MAXWELL ROAD      Inv.No. . : B&P      0 Page 2  
 #17-00 TOWER BLOCK      Inv.date. : 16/04/2019  
 MND COMPLEX      WIP No. . : 52013  
 SINGAPORE 069110      Veh.In/Out: 04/03/2019 26/03/2019  
                                          \*Tel.No. . : 62239433  
                                          Reg.No. . : SLF4131E  
 Closed by .... : Paul Ong Qing Yong      Reg.date. : 25/08/2016  
 Svc Consultant : ACC      Mileage . : 49,347  
 Remarks ..... : Mr Ho Chee Yon      Chassis No: SALCA2AG9GH566213

| Op.No | Description          | Hech Qty | Price   | Disc% | Pkg | Amount   | G |
|-------|----------------------|----------|---------|-------|-----|----------|---|
|       | TRIM CLIP WHITE EVOQ | 2.0 EA   | 2.60    | 10    |     | 4.68     | S |
|       | *D* PRIMER GLASS & P | 1.0 EA   | 37.40   | 10    |     | 33.66    | S |
|       | TAILGATE PANEL DSPOR | 1.0 EA   | 3281.50 | 10    |     | 2,953.35 | S |
|       | TRIM CLIP WHITE EVO  | 10.0 EA  | 4.20    | 10    |     | 37.80    | S |
|       | REAR WINDSCREEN DSPO | 1.0 EA   | 1125.20 | 10    |     | 1,012.68 | S |
|       | ADHESIVE AND SEALER  | 2.0 EA   | 122.10  | 10    |     | 219.78   | S |
|       | BUMPER - COVER       | 1.0 EA   | 432.10  | 10    |     | 388.89   | S |
|       | FOG LAMP REAR LH DSP | 1.0 EA   | 350.80  | 10    |     | 315.72   | S |
|       | LAMP - REAR, STOP AN | 1.0 EA   | 646.40  | 10    |     | 581.76   | S |
|       | D PILLAR FINISHER LH | 1.0 EA   | 109.30  | 10    |     | 98.37    | S |
|       | BADGE REAR "DISCO" D | 1.0 EA   | 172.20  | 10    |     | 154.98   | S |
|       | BADGE REAR "VERY" DS | 1.0 EA   | 154.50  | 10    |     | 139.05   | S |
|       | NAME PLATE - PLASTIC | 1.0 EA   | 186.40  | 10    |     | 167.76   | S |
|       | BADGE OVAL REAR RR3  | 1.0 EA   | 91.70   | 10    |     | 82.53    | S |
|       | MOULDING - REAR WHEE | 1.0 EA   | 322.30  | 10    |     | 290.07   | S |

Gross Total.      18,389.19

Labour Total      10,146.00  
 Parts Total      8,243.19  
 Package Total      0.00

Net.....      18,389.19  
 GST @ 7.0%      1,287.24  
 Total.....      19,676.43  
 Paid.....      0.00  
 Please Pay..      19,676.43

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Supp.

### SERVICE ESTIMATE

O - E00004      SL: EQ INSURANCE COMPANY LTD  
 EQ INSURANCE COMPANY LTD      GST Reg.No:M28920628X  
 5 MAXWELL ROAD      Inv.No. . : B&P      0 Page 1  
 #17-00 TOWER BLOCK      Inv.date. : 16/04/2019  
 MND COMPLEX      WIP No. . : 52013  
 SINGAPORE 069110      Veh.In/Out: 04/03/2019 26/03/2019  
                                          \*Tel.No. . : 62239433  
                                          Reg.No. . : SLF4131E  
 Closed by .... : Paul Ong Qing Yong      Reg.date .: 25/08/2016  
 Svc Consultant : ACC      Mileage ..: 49,347  
 Remarks ..... : Mr Ho Chee Yon      Chassis No: SALCA2AG9GH566213

| Op.No | Description | Mech Qty | Price | Disc% | Pkg | Amount | G |
|-------|-------------|----------|-------|-------|-----|--------|---|
|-------|-------------|----------|-------|-------|-----|--------|---|

|             |                      |        |        |    |  |          |  |
|-------------|----------------------|--------|--------|----|--|----------|--|
| 800         | TO PUTTY SPRAY PAINT | 0      | 200.00 | 0  |  | 200.00 S |  |
| REAR LH RIM |                      |        |        |    |  |          |  |
|             | BUMPER - COVER       | 1.0 EA | 432.10 | 10 |  | 388.89 S |  |
|             | D PILLAR FINISHER LH | 1.0 EA | 109.30 | 10 |  | 98.37 S  |  |
|             | BADGE REAR "DISCO" D | 1.0 EA | 172.20 | 10 |  | 154.98 S |  |
|             | BADGE REAR "VERY" DS | 1.0 EA | 154.50 | 10 |  | 139.05 S |  |
|             | NAME PLATE - PLASTIC | 1.0 EA | 186.40 | 10 |  | 167.76 S |  |
|             | BADGE OVAL REAR RR3  | 1.0 EA | 91.70  | 10 |  | 82.53 S  |  |

|               |          |              |          |
|---------------|----------|--------------|----------|
|               |          | Gross Total. | 1,231.58 |
| Labour Total  | 200.00   | Net.....     | 1,231.58 |
| Parts Total   | 1,031.58 | GST @ 7.0%   | 86.21    |
| Package Total | 0.00     | Total.....   | 1,317.79 |
|               |          | Paid.....    | 0.00     |
|               |          | Please Pay.. | 1,317.79 |

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Total = \$36886.38

### (PAYMENT BREAKDOWN)

|                  |   |           |       |   |        |
|------------------|---|-----------|-------|---|--------|
| Vehicle No       | : | SHF H131E | Model | : | D. SRT |
|                  | : | ABG 168C  |       |   |        |
| Date of Accident | : | 01/02/19  |       |   |        |

|                       |   |                              |                                        |
|-----------------------|---|------------------------------|----------------------------------------|
| Global Sum Settlement | : | <input type="checkbox"/> YES | <input checked="" type="checkbox"/> NO |
| Liability             | : | 100 %                        | (Agreed/Assessed)                      |

|                      |   |              |                                            |
|----------------------|---|--------------|--------------------------------------------|
| Repair Estimate      | : | \$ 38,150.65 |                                            |
| Final Repair Cost    | : | \$ 19,676.43 |                                            |
| Loss of Use          | : | \$           | days at \$ per day                         |
| Rental (if any)      | : | \$ 834.60    | 06 days at \$ 139.10 (incl of GST) per day |
| Others               | : | \$           |                                            |
|                      | : | \$           |                                            |
|                      | : | \$           |                                            |
|                      | : | \$           |                                            |
| Final Settlement Sum | : | \$ 20511.03  |                                            |

Remarks: \_\_\_\_\_

#### Payment Instruction: Payee's Breakdown

|    |                            |   |             |
|----|----------------------------|---|-------------|
| 1) | WEARNES AUTOMOTIVE PTE LTD | : | \$ 20511.03 |
| 2) |                            | : | \$          |
| 3) |                            | : | \$          |
| 4) |                            | : | \$          |

## WEARNES AUTO PROTECTOR (LAND ROVER) PRIVATE VEHICLE

Name of Policyholder : HO CHEE YON  
 Period of Insurance : 25 Aug 2018 To 24 Aug 2019  
 Engine No. : 01515922562204PT  
 Chassis No. : SALCA2AG9GH566213

Vehicle No. : SLF4131E  
 Policy No. : 2100480502-02  
 Endorsement No. :  
 Issued Date : 11 Aug 2018

## ABOUT THE COVER

Make/Model : LANDROVER DISCOVERY SPORT SI4 SE/HSE  
 Engine Capacity/Tonnage : 1,999.00 CC Sum Insured : Market Value First Year of Registration : 2016  
 Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes  
 Person or Classes of Persons Entitled to Drive\* :

a) The Policyholder  
 b) Any other person who is driving on the Policyholder's order or with his/her permission  
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 2000cc

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

## EXCESS

Section 1  
 Fire - \$0 Own Damage - \$900 Theft - \$0 Flood Cover - \$0

Section 2  
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

HO CHEE YON - \$900 (Own Damage)

## APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Wearn's Automotive Pte Ltd Add: 45 Leng Kee Road Singapore 159103 63789333

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

## IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0503486613

WEARNES AUTOMOTIVE - DJT (J)

45 LENG KEE ROAD

SINGAPORE 159103

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

*M. J. Tan*

AIG Asia Pacific Insurance Pte. Ltd.  
 AUTHORISED REPRESENTATIVE

ESP/ENC

## Nivitha (LKK Auto)

---

**From:** Shu Pei (LKKAuto) <shupeil@lkkauto.com>  
**Sent:** Monday, 11 February 2019 4:06 PM  
**To:** assignments  
**Subject:** FW: TP Claim - SLF4131E; TP Vehicle GBG1678C (EQ)  
**Attachments:** SAS2546097.pdf; 4993\_001.pdf; GBG1678C (01.02.19).pdf; SLF4131E.PDF

**Sensitivity:** Confidential

8:57am @ 12/2/19  
person @ participant  
vehicle not in

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Joel Goh <joel.goh@eqinsurance.com.sg>  
**Sent:** Monday, 11 February 2019 4:01 PM  
**To:** Admin A <admin-a@lkkauto.com>  
**Subject:** FW: TP Claim - SLF4131E; TP Vehicle GBG1678C (EQ)  
**Sensitivity:** Confidential

Dear LKK

Please assist on the following PRS.

Best Regards,

Joel Goh

Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)

 A Member of Citystate

*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify t*

---

**From:** Joel Goh  
**Sent:** Monday, February 11, 2019 3:58 PM  
**To:** 'Paul Ong Qing Yong'  
**Subject:** RE: TP Claim - SLF4131E; TP Vehicle GBG1678C (EQ)  
**Sensitivity:** Confidential

Without Prejudice

Dear Paul

We will assign LKK to handle this direct settlement.

Dear LKK

Please assist on the following direct settlement.

Best Regards,

Joel Goh

Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
dtd 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)

 A Member of Citystate

*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.*

---

**From:** Paul Ong Qing Yong [<mailto:paul.ong@wearnes.com>]

**Sent:** Monday, February 11, 2019 9:03 AM

**To:** EQI PRS

**Subject:** TP Claim - SLF4131E; TP Vehicle GBG1678C

**Importance:** High

**Sensitivity:** Confidential

Attached for TP Claim,

Please advise if we can settle direct.

**Paul Ong**

Service Consultant

Bodyshop & Paint



**Wearnes Automotive Pte Ltd**

249 Alexandra Road Singapore 159935

M (65) 8126 1237 D (65) 6378 9336

[www.wearnesauto.com](http://www.wearnesauto.com) [paul.ong@wearnes.com](mailto:paul.ong@wearnes.com)

*This email, including any attachment, is confidential and may also be privileged.  
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.  
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

## Cecilia Chong (LKK Auto)

**From:** Cecilia Chong (LKK Auto)  
**Sent:** Monday, 16 September 2019 4:39 PM  
**To:** Joel Goh  
**Subject:** RE: TP Claim - SLF4131E; TP Vehicle GBG1678C (EQ) (DM19HO00400-JG)  
**Attachments:** ADJUSTMENT REPORT.pdf; INSPECTION REPORT.pdf; LKK RESURVEY PHOTO.pdf; LKK SURVEY PHOTO.pdf; LOD AND OTHER DOCUMENTS.pdf

**Sensitivity:** Confidential

EQ ref : **GBG 1678C (DMCPHQ18-003625)**

LKK ref : CC4/EQI19002683/T1gb3q2

Dear Sirs/Madam,

### **ACCIDENT INVOLVING GBG 1678C(EQ-OI) AND SLF 4131E(TP) ON 01/02/2019**

We refer to the above matter.

OI HIT STATIONARY TP VEHICLE.

A letter was sent out to the Insured to notify Third Party claim and NCD issues. No further feedback till to date.

We seek your approval to offer Third Party repairer "**WEARNES AUTOMOTIVE PTE LTD**" at **20,318.43(all-in)**.

The summary is as follows: -

|                                            | Claimed Amount | Revised Amount               |
|--------------------------------------------|----------------|------------------------------|
| 1. Cost of Repair (w/GST)                  | \$ 35,654.80   | \$ 19,676.43                 |
| 2. Loss of Rental (6days x \$139.10) W/GST | \$ 834.60      | \$ 642.00 (6days x \$107.00) |
| 3. LTA/ GIA Search Fee                     | \$ 0           | \$ 0                         |
| Total                                      | \$ 36,489.40   | <b><u>\$ 20,318.43</u></b>   |

\*\*6days recommendation for repair

|              |                                    |
|--------------|------------------------------------|
| Market Value | : \$145,000.00 (est)               |
| LTA Rebate   | : \$108,984.00 (est)               |
| Nett Value   | : <b><u>\$ 36,016.00 (est)</u></b> |

Enclosed here with all the relevant documents for your perusal.

**Kindly let us have your approval/instruction.**

## Cecilia Chong (LKK Auto)

---

**From:** Joel Goh <joel.goh@eqinsurance.com.sg>  
**Sent:** Tuesday, 17 September 2019 9:08 AM  
**To:** Cecilia Chong (LKK Auto)  
**Subject:** RE: TP Claim - SLF4131E; TP Vehicle GBG1678C (EQ) (DM19HO00400-JG)

**Sensitivity:** Confidential

Dear Cecilia

Please proceed to resolve this matter up to \$20,318.43.

Best Regards,

Joel Goh  
Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)

 A Member of Citystate

*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the*

---

**From:** Cecilia Chong (LKK Auto) [mailto:CeciliaChong@lkkauto.com]  
**Sent:** Monday, September 16, 2019 4:39 PM  
**To:** Joel Goh  
**Subject:** RE: TP Claim - SLF4131E; TP Vehicle GBG1678C (EQ) (DM19HO00400-JG)  
**Sensitivity:** Confidential

EQ ref : **GBG 1678C (DMCPHQ18-003625)**

LKK ref : CC4/EQ119002683/T1gb3q2

Dear Sirs/Madam,

**ACCIDENT INVOLVING GBG 1678C(EQ-OI) AND SLF 4131E(TP) ON 01/02/2019**

We refer to the above matter.

OI HIT STATIONARY TP VEHICLE.



**From:** Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>  
**Sent:** Monday, February 18, 2019 11:29 AM  
**To:** Paul Ong Qing Yong  
**Cc:** Admin A  
**Subject:** RE: SLF 4131E GBG 1678C 01/02/2019

**WITHOUT PREJUDICE**

Dear Paul,

With reference to the subject.

Please be informed that basing on the accident statements submitted by parties involved and video, the liability is clear.

The final repair cost is subject to the consistency of the damages according to the nature of the accident and approval of our principal insurer.

The days for losses(use/income/rental) will be based on the number of days of repair recommended by our surveyor and our principal's approval.

Please note that this e-mail is on without prejudice basis and does not amount to an authorisation of repair to your client's vehicle. Contents herein should not be construed as an admission of any liability, confirmation of damages whatsoever to the insured/insurer's part.

Furthermore, this e-mail should not be regarded as a waiver by EQ Insurance of their rights to repudiate the claim should there be future discovery of any breach of policy terms and conditions committed by their driver or insured.

Best Regards,  
Joy Irene | Case Handler  
LKK Auto Consultants Pte Ltd  
DID: 6841-2409 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

**From:** Paul Ong Qing Yong [mailto:[paul.ong@wearnes.com](mailto:paul.ong@wearnes.com)]  
**Sent:** Monday, 18 February 2019 11:22 AM  
**To:** Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>

**Cc:** Admin A <admin-a@lkkauto.com>  
**Subject:** RE: SLF 4131E GBG 1678C 01/02/2019  
**Importance:** High

Hi Joy,

Received above.

Sending the video in a dropbox link below:

<https://www.dropbox.com/sh/a68i8evwsqoia4a/AACtvvFXbKXt50N7QZhi3YUua?dl=0>

please allow some time for the link to sync if there's an error message.

**Paul Ong**  
Service Consultant  
Bodyshop & Paint



**Wearnes Automotive Pte Ltd**  
249 Alexandra Road Singapore 159935  
M (65) 8126 1237 D (65) 6378 9335  
[www.wearnesauto.com](http://www.wearnesauto.com) [paul.ong@wearnes.com](mailto:paul.ong@wearnes.com)

*This email, including any attachment, is confidential and may also be privileged.  
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.  
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

---

**From:** Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>  
**Sent:** Monday, February 18, 2019 11:09 AM  
**To:** Paul Ong Qing Yong <[paul.ong@wearnes.com](mailto:paul.ong@wearnes.com)>  
**Cc:** Admin A <admin-a@lkkauto.com>  
**Subject:** SLF 4131E GBG 1678C 01/02/2019

WITHOUT PREJUDICE

Dear Paul,

We refer to our tele-con earlier.

Kindly send us the reported video of your client.

Our insured reported that your client SLF 4131E cut lane.



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 20/12/2019

**THIRD PARTY DIRECT SETTLEMENT**

|                  |           |            |                                        |
|------------------|-----------|------------|----------------------------------------|
| Vehicle No.      | GBG 1678C | (Insd Veh) | Your Ref. No. : DM19HO00400-JG         |
|                  | SLF 4131E | (TP Veh)   | Our Ref. No. : CC4/EQI19002683/T1gb3q2 |
| Date of Accident | 1/2/2019  |            |                                        |

|                      |                |        |
|----------------------|----------------|--------|
| Liability            | 100%           |        |
| Final Repair Cost    | : \$ 19,676.43 |        |
| Loss of Use          | : \$           | days   |
| Rental (If any)      | : \$ 834.60    | 6 days |
| Others:              | : \$           |        |
|                      | : \$           |        |
|                      | 20,511.03      |        |
| Final Settlement Sum | : \$ 20,511.03 |        |
| Remarks              | :              |        |
|                      |                |        |

**Payment Instruction: Payee's Breakdown**

|    |                             |                |
|----|-----------------------------|----------------|
| 1) | WEARNES AUTOMOTIVE PTE LTD. | : \$ 20,511.03 |
|    |                             | : \$           |
|    |                             |                |

JOANNE LEE

LKK Auto Consultants Pte Ltd



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQI19002683/T1gb3q2

5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEXSINGAPORE 069110

Date : 20-12-2019



Code : EQI

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                 |                |            |
|--------------|-----------------|----------------|------------|
| Insured Veh. | GBG 1678C       | Veh. Inspected | SLF 4131E  |
| Policy No.   | DMCPHQ18-003625 | Coverage (\$)  | 0.00       |
| Claim No.    | DM19HO00400-JG  | Excess (\$)    | 0.00       |
| Assign From  | JOEL            | Assign Date    | 11/02/2019 |

## 2. Vehicle Particulars & Condition

|              |                            |              |            |
|--------------|----------------------------|--------------|------------|
| Make & Model | LAND ROVER DISCOVERY SPORT | c.c          | 1999       |
| Engine No.   | HIDDEN                     | Year of Reg. | 2016       |
| Chassis No.  | SALCA2AG9GH566213          | Colour       | GREY       |
| Odometer     | 48347                      | Steering     | IN ORDER   |
| Brakes       | IN ORDER                   | Modification | SPORTS RIM |
| General      | GOOD                       |              |            |

## 3. Conditions of Tyres

|                | Size       | Make    | Balance |
|----------------|------------|---------|---------|
| R/H Front Tyre | 235/55 R19 | PIRELLI | 6 mm    |
| L/H Front Tyre | 235/55 R19 | PIRELLI | 6 mm    |
| R/H Rear Tyre  | 235/55 R19 | PIRELLI | 6 mm    |
| L/H Rear Tyre  | 235/55 R19 | PIRELLI | 6 mm    |

## 4. Description of Damages

|                                                                                |
|--------------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.<br>DAMAGES SEE DETAILS. |
|--------------------------------------------------------------------------------|

## 5. General Information

|                |                                                                     |                 |            |
|----------------|---------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 01/02/2019                                                          | Inspection Date | 04/03/2019 |
| Survey held at | WEARNES AUTOMOTIVE PTE LTD<br>45 LENG KEE ROAD<br>SINGAPORE 159103. |                 |            |

## 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

## 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 6 Working Days |
|-------------------------------------|----------------|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 4131E

| Qty                         | Description of Parts                   | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|----------------------------------------|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                        |                      |                           |                   |
| 1                           | LLR075430/MUFFLER (SN)                 | NOT NECESSARY        | 1,669.90                  | -                 |
| 1                           | MUFFLER -REAR RH (SN)                  | NOT NECESSARY        | 1,112.40                  | -                 |
| 2                           | INSULATOR -RUBBER (SN)                 | NOT NECESSARY        | 113.40                    | -                 |
| 1                           | CLAMP 60MM(SN)                         | NOT NECESSARY        | 75.80                     | -                 |
| 1                           | BUMPER COVER REAR DS (SN)              | DEFORMED             | 1,928.20                  | 1,735.38          |
| 1                           | BRACKET -BUMPER MOU (SN)               | NOT NECESSARY        | 115.20                    | -                 |
| 1                           | TOW HOOK COVER REAR (SN)               | NOT NECESSARY        | 27.40                     | -                 |
| 1                           | MOULDING ,REAR WHEE (SN)               | CUT                  | 322.30                    | 290.07            |
| 3                           | TRIM CLIP BLUE EVOQU (SN)              | NECESSARY            | 29.70                     | 26.73             |
| 2                           | TRIM CLIP WHITE EVOQ (SN)              | NECESSARY            | 5.20                      | 4.68              |
| 1                           | GLASS -QUARTER WIND (SN)               | NOT NECESSARY        | 672.10                    | -                 |
| 1                           | FOG LAMP REAR LH DSP (SN)              | CRACKED              | 350.80                    | 315.72            |
| 1                           | LAMP -REAR ,STOP AN (SN)               | NOT NECESSARY        | 585.60                    | -                 |
| 1                           | SEAL -REAR LAMP (SN)                   | NOT NECESSARY        | 37.80                     | -                 |
| 1                           | LAMP -REAR ,STOP AN (SN)               | CRACKED              | 646.40                    | 581.76            |
| 2                           | *D* WINDSCREEN SEALA (SN)              | NECESSARY            | 244.20                    | 219.78            |
| 1                           | *D* PRIMER GLASS & P (SN)              | NECESSARY            | 37.40                     | 33.66             |
| 1                           | TAILGATE PANEL DSPOR (ALUMINIUM) (SN)  | DENTED               | 3,281.50                  | 2,953.35          |
| 10                          | TRIM CLIP WHITE EVO (SN)               | NECESSARY            | 42.00                     | 37.80             |
| 1                           | REAR WINDSCREEN DSPO (SN)              | NECESSARY            | 1,125.20                  | 1,012.68          |
| 1                           | FENDER REAR LH DSPOR (SN)              | TO REPAIR SEE LABOUR | 3,008.00                  | -                 |
| 1                           | ALLOY WHEEL STYLE 52 (SN)              | TO REPAIR SEE LABOUR | 1,748.30                  | -                 |
| 1                           | BUMPER -COVER (SN) (ADDITIONAL)        | DEFORMED             | 388.89                    | 388.89            |
| 1                           | D PILLAR FINISHER LH (SN) (ADDITIONAL) | DEFORMED             | 98.37                     | 98.37             |
| 1                           | BADGE REAR 'DISCO' D (SN) (ADDITIONAL) | NECESSARY            | 154.98                    | 154.98            |
| 1                           | BADGE REAR 'VERY' DS (SN) (ADDITIONAL) | NECESSARY            | 139.05                    | 139.05            |
| 1                           | NAME PLATE -PLASTIC (SN) (ADDITIONAL)  | NECESSARY            | 167.76                    | 167.76            |
| 1                           | BADGE OVAL REAR RR3 (SN) (ADDITIONAL)  | NECESSARY            | 82.53                     | 82.53             |
|                             |                                        |                      | 18,210.38                 | 8,243.19          |

Report Ref No. CC4/EQ19002683/T1gb3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts                                                                                                                                       | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|     | <b>LABOUR</b>                                                                                                                                              |               |                           |                   |
|     | TO PUTTY SPRAY PAINT REAR LH RIM .(ADDITIONAL)                                                                                                             |               | 200.00                    | 200.00            |
|     | TO REPLACE REAR BUMPER ,REAR BOOTLID ,REAR LH QTR PANEL,REAR TAILLAMP,BOOT LAMP .INCLUSIVE OF THE REPAIR OF FENDER REAR LH DSPOR AND ALLOY WHEEL STYLE 52. |               | 6,000.00                  | 4,800.00          |
|     | TO PUTTY SPRAYPAINT ON REAR BUMPER ,REAR BOOTLID,REAR QTR PANEL.                                                                                           |               | 4,000.00                  | 3,000.00          |
|     | TO TRANSFER REAR BOOTLID PARTS.                                                                                                                            |               | 500.00                    | 500.00            |
|     | TO REMOVE & REFIT INTERIOR PAR.                                                                                                                            | NOT NECESSARY | 2,400.00                  | -                 |
|     | TO REPLACE REAR WINDSCREEN.                                                                                                                                |               | 1,200.00                  | 600.00            |
|     | TO REPLACE REAR QTR GLASS.                                                                                                                                 | NOT NECESSARY | 600.00                    | -                 |
|     | TO INSTALL REAR WINDSCREEN FIL.                                                                                                                            |               | 280.00                    | 280.00            |
|     | TO INSTALL REAR QTR GLASS FILM .                                                                                                                           | NOT NECESSARY | 280.00                    | -                 |
|     | TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.                                                                                               |               | 486.00                    | 486.00            |
|     | TO REPLACE REAR LH EXHAUST ASS .                                                                                                                           | NOT NECESSARY | 2,400.00                  | -                 |
|     | TO REPLACE REAR LH RIM .                                                                                                                                   | NOT NECESSARY | 50.00                     | -                 |
|     | WHEEL ALIGNMENT.                                                                                                                                           |               | 280.00                    | 280.00            |
|     |                                                                                                                                                            |               | 18,676.00                 | 10,146.00         |
|     | <b>GRAND TOTAL</b>                                                                                                                                         |               | <b>36,886.38</b>          | <b>18,389.19</b>  |
|     | <b>RECOMMENDED COST OF REPAIRS</b>                                                                                                                         |               |                           | <b>18,389.19</b>  |

Report Ref No. CC4/EQ19002683/T1gb3q2

MOHAMAD TAUFIKH  
M.MATAI, AMSAE-A  
Automotive Assessor

HO LEONG CHUAN  
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.