

SERVICE ESTIMATE

86639 - C00001
Mr Ho Chee Yon

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 07/02/2019

WIP No. : 52013

Veh.In/Out:

*Tel.No. : Mobile: 93821919

Reg.No. : SLF4131E

Reg.date : 25/08/2016

Mileage : 0

Chassis No: SALCA2AG9GH566213

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Ho Chee Yon

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR BUMPER, REAR BOOTLID, REAR LH QTR PANEL, REAR TAILLAMP, BOOT LAMP	0	6000.00	0		6,000.00 S	4800.
-----	---	---	---------	---	--	------------	-------

800	TO PUTTY SPRAYPAINT ON REAR BUMPER, REAR BOOTLID, REAR QTR PANEL	0	4000.00	0		4,000.00 S	3000.
-----	--	---	---------	---	--	------------	-------

802	TO TRANSFER REAR BOOTLID PARTS	0	500.00	0		500.00 S	✓
-----	--------------------------------	---	--------	---	--	----------	---

802	TO REMOVE & REFIT INTERIOR PAR	0	2400.00	0		2,400.00 S	X
-----	--------------------------------	---	---------	---	--	------------	---

802	TO REPLACE REAR WINDSCREEN	0	1200.00	0		1,200.00 S	600
-----	----------------------------	---	---------	---	--	------------	-----

802	TO REPLACE REAR QTR GLASS	0	600.00	0		600.00 S	X
-----	---------------------------	---	--------	---	--	----------	---

0080	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0		280.00 S	✓
------	--------------------------------	---	--------	---	--	----------	---

0080	TO INSTALL REAR QTR GLASS FILM	0	280.00	0		280.00 S	X
------	--------------------------------	---	--------	---	--	----------	---

280	TO CHECK WIRING INCLUDE	0	486.00	0		486.00 S	✓
-----	-------------------------	---	--------	---	--	----------	---

RESETTING OF ALL ELECTRICAL
MODULES

802	TO REPLACE REAR LH EXHAUST ASS	0	2400.00	0		2,400.00 S	?1200
-----	--------------------------------	---	---------	---	--	------------	-------

0031	TO REPLACE REAR LH RIM	0	50.00	0		50.00 S	X
------	------------------------	---	-------	---	--	---------	---

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T +65 6430 4700 www.wearnesauto.com

Co reg no. 199501400R / GST reg no. M28920628X

Tan Jiah 97495749
WP

4/3/19 @ 230 PM

Resurvey before paint.

o Gohys

Tan Jiah @ 11/11/2019
surv @ 11/11/2019

SERVICE ESTIMATE

86639 - C00001
Mr Ho Chee Yon

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 07/02/2019

WIP No. : 52013

Veh.In/Out:

*Tel.No. : Mobile: 93821919

Reg.No. : SLF4131E

Reg.date. : 25/08/2016

Mileage : 0

Chassis No: SALCA2AG9GH566213

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Ho Chee Yon

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

419	WHEEL ALIGNMENT	0	280.00	0		280.00	S ✓
	LLR075430/MUFFLER -	1.0 EA	1669.90			1,669.90	S ?
	MUFFLER - REAR RH	1.0 EA	1112.40			1,112.40	S ?
	INSULATOR - RUBBER	2.0 EA	56.70			113.40	S ?
	CLAMP 60MM	1.0 EA	75.80			75.80	S ?
	BUMPER COVER REAR DS	1.0 EA	1928.20			1,928.20	S de
	BRACKET - BUMPER MOU	1.0 EA	115.20			115.20	S ?
	TOW HOOK COVER REAR	1.0 EA	27.40			27.40	S X
	MOULDING - REAR WHEE	1.0 EA	322.30			322.30	S X
	TRIM CLIP BLUE EVOQU	3.0 EA	9.90			29.70	S ne ✓
	TRIM CLIP WHITE EVOQ	2.0 EA	2.60			5.20	S ne ✓
	GLASS - QUARTER WIND	1.0 EA	672.10			672.10	S X
	FOG LAMP REAR LH DSP	1.0 EA	350.80			350.80	S can ✓
	LAMP - REAR, STOP AN	1.0 EA	585.60			585.60	S can ?
	SEAL - REAR LAMP	1.0 EA	37.80			37.80	S ?
	LAMP - REAR, STOP AN	1.0 EA	646.40			646.40	S ?
	D WINDSCREEN SEALA	2.0 EA	122.10			244.20	S ne ✓

SERVICE ESTIMATE

86639 - C00001
Mr Ho Chee Yon

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 3

Inv.date. : 07/02/2019

WIP No. : 52013

Veh.In/Out:

*Tel.No. : Mobile: 93821919

Reg.No. : SLF4131E

Reg.date. : 25/08/2016

Mileage : 0

Chassis No: SALCA2AG9GH566213

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Ho Chee Yon

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

D PRIMER GLASS & P	1.0 EA	37.40				37.40 S	he /
TAILGATE PANEL DSPOR <i>aluminium</i>	1.0 EA	3281.50				3,281.50 S	HA /
TRIM CLIP WHITE EVO	10.0 EA	4.20				42.00 S	he /
REAR WINDSCREEN DSPOR	1.0 EA	1125.20				1,125.20 S	he /
FENDER REAR LH DSPOR	1.0 EA	3008.00				3,008.00 S	Ry
ALLOY WHEEL STYLE 52	1.0 EA	1748.30				1,748.30 S	Rx \$200

Gross Total. 35,654.80

Labour Total 18,476.00
Parts Total 17,178.80
Package Total 0.00

Net..... 35,654.80

GST @ 7.0% 2,495.84

Total..... 38,150.65

Paid..... 0.00

Please Pay.. 38,150.65

GST: S=StdRated; O=OutOfScope; Z=ZeroRated