

ASS. REC. BY:

REF: CS/TMI19002697/Dvd3

Special Instruction:

Surveyor:

Bryan

ASSIGNMENT (Office)

From (Person):

Ng Kwai Kay Francis

of

TMI

Date/Time:

13/2/19 @ 11:17 am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SH 7498J

Insured:

SME 9703R

at Workshop m/s

Chunni Motor

Tel:

65425119

of

Blk 10, Amk ~~Autopoint~~ #01-05/06

Policy No:

MT108717

Claim No:

M1900834

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/2/19

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

1:17 pm @ 13/2/19

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SH 7498J - CS/FCI 17023630 / Uqdzno

Dof: 3/12/17

SME 9703R - x ..



## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est. Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Feb 2019		13 Feb 2019 11:17 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	LIM KEE HUAT, ID: S1628828D								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SH7498J	Date of Loss:	10/02/2019 23:00 - :59						
Claim Type:	TP / M1900834	Policy/Cover Note No.:	MT108717 (Comprehensive) Coverage: 24/10/2018 - 23/10/2020						
Vehicle Reg. No. (Insured):	SME9703R	Policy No. (Claimant):							
		Excess:	S\$600.00						
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ng Kwai Kay Francis]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/02/2019]								
Adj Asg. Remarks:	WSHOP ESTIMATE IS HIGH-CHECK THKS								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a> <a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>				<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MC0619018959 / ComfortDelGro Engineering Pte Ltd - Leyang  
 ENTRY DATE & TIME: 11/02/2019 16:35  
 SUBMITTED BY: Jehel Lim Siong Gek

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/02/2019 16:35
Date Of Accident	10/02/2019 23:20
Exact Location Of Accident	BLK 120 YISHUN RING ROAD PARKING LOT 359
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH7498J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
<b>Vehicle Particulars</b>	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
<b>Driver</b>	
Name of Driver	LIM WAN CHYE
NRIC No	S1597595D
Date Of Birth	24/01/1963
Occupation	OUTDOOR
Date Of Driving Pass	16/03/1984
Driving Experience	34 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96680913
Fax Number	
Contact Number	
EMail Address	YUANCAI83@HOTMAIL.COM

Address BLK 120 YISHUN RING ROAD  
#09-425  
Postcode 760120  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
Insurance Company of Driver's Own Vehicle -  
-  
-

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
Weather Conditions CLEAR  
Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 2  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

**Circumstances of Accident**

REFER ATTACHED \* TYPE OF ACCIDENT :- 3P REVERSED

**Attachment(s)**

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SME9703R  
Vehicle Make/Model/Colour HONDA  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver LIM KEE HUAT  
NRIC/Passport Number S1628828D  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage REAR  
No. Of Passenger (Including Driver)

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
 CO-REG NO. 199303821R  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 11.02.2019 @ 1130HRS

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.: June Tan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 10.02.2019 @ 23:20hrs. My taxi (A) was parked at Blk 120 Yishun Ring Rd parking lot 359.

As my taxi engine was stationary. Veh (B) over reverse while parking his car due to his foot has stucked under the pedal causing lost of control.

My taxi (A) rear portion was damaged. No injury in this accident.

Photos taken at scene to support my claims.

Veh (B) SME 9703R. Mr Lim Kee Huat. Nric no: S 1628828D. Hp: 9783 2653.

DECLARATION

I/We declare the foregoing particulars are true in every respect.  
COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time: 11.02.2019

*Handwritten Signature*  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 11.02.2019@1130hrs

*Handwritten Signature*  
Reporting Centre Personnel's Signature  
Name: June Tan  
NRIC/FIN No.:



SH 7498J

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid Comfort Logo & Tel No. Sticker <i>HLC</i>			\$ 30.00
	Boot Lid Advertisement Logo <i>HLC</i>			\$ 100.00
	Rear No. Plate <i>HN</i>			\$ 25.00
	Rear Bumper Advertisement Logo <i>HLC</i>			\$ 50.00
	Rear Bumper Rubber Mat <i>HLC</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) <i>HLC</i>		\$ 100.00	\$ 200.00
	Rear Windscreen Sealant <i>HLC</i>			\$ 46.00
			<i>476.00</i>	
				<b>\$ 501.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ 2,000.00
	Spray Painting Charge			\$ 1,500.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 100.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Exhaust Pipe			\$ 300.00
			<i>2190.00</i>	
	<b>TOTAL LABOUR</b>			<b>\$ 4,220.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 19,950.08</b>
			<i>15227.92</i>	
			<i>4512000/-</i>	

Nett ✓  
 Nett ✓  
 Nett X  
 Nett ✓  
 Nett ✓  
 Nett ✓  
 Nett ✓  
 Nett ✓  
 1000/-  
 900/-  
 30/-  
 40/-  
 80/-  
 80/-  
 60/-

*13/02/2019 @ 1300ms  
 Kia Anthur  
 2/5 work 9 days.  
 Ryan  
 LKK Auto*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI19002697/DVD3N2

Date: 02/04/2019

#### REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MT108717
Claimant Vehicle No :	SH7498J	Insured Vehicle No :	SME9703R
Date of Loss:	10/02/2019	Nature of Claim:	TP
		Claim No:	M1900834

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH7498J	Engine No:	D4FDEU461779
Make & Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU085485
Reg. Date:	10/03/2016 (Man. Year: 2015)	Odometer:	582316 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	15,730.08	13,037.92	2,692.16	17.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,220.00	2,190.00	2,030.00	48.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>19,950.08</b>	<b>15,227.92</b>	<b>4,722.16</b>	<b>23.67</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>12,000.00</b>		
(S\$)	19,950.08	12,000.00	7,950.08	39.85
+ GST 7.00/7.00% (S\$)	1,396.51	840.00	556.51	39.85
<b>Nett Amount (S\$)</b>	<b>21,346.59</b>	<b>12,840.00</b>	<b>8,506.59</b>	<b>39.85</b>

#### INSPECTION

Date of Assignment:	13/02/2019	
Date Inspected:	13/02/2019	Inspected At: Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint Singapore 568047
Estimated Period of Repair:	9.0 days	

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 02 Apr 2019)
<b>Parts:</b> 143	HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SH7498J)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	2,174.90 FL	*2,174.90 FL
2	1		*BOOT LID RUBBER	Deformed	96.50 FL	*96.50 FL
3	2		*BOOT LID HINGE (LH/RH)	Repair	284.60 FL	*- FL
4	1		*BOOT LID LOCK UPPER	Bent	102.60 FL	*102.60 FL
5	1		*BOOT LID LOCK LOWER	Bent	31.70 FL	*31.70 FL
6	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
7	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
8	2		*BOOT LID LAMP (LH/RH)	Cracked/Broken	1,131.20 FL	*1,131.20 FL
9	1		*BOOT LID TRIMBOARD	Deformed	116.40 FL	*116.40 FL
10	10		*BOOT LID TRIMBOARD CLIPS	Necessary	11.00 FL	*11.00 FL
11	1		*BOOTLID MOULDING	Dented	85.00 FL	*85.00 FL
12	1		*BOOTLID I40 EMBLEM	Necessary	27.90 FL	*27.90 FL
13	1		*BOOTLID LOWER GARNISH	Dented	227.90 FL	*227.90 FL
14	1		*REAR BUMPER	Dented	553.00 FL	*553.00 FL
15	1		*REAR BUMPER REINFORCEMENT	Cracked/Broken	428.40 FL	*428.40 FL
16	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Not Necessary	160.60 FL	*- FL
17	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
18	1		*REAR BUMPER BRACKET	O/s Broken/N/s Not Necessary	71.20 FL	*35.60 FL
19	1		*REAR BUMPER SPONGE	Torn	118.40 FL	*118.40 FL
20	1		*REAR BUMPER UNDER COVER	Distorted	228.00 FL	*228.00 FL
21	2		*TAIL LAMP (LH/RH)	Cracked/Broken	1,395.60 FL	*1,395.60 FL
22	1		*TAIL LAMP QUARTER PANEL (RH)	Dented	226.50 FL	*226.50 FL
23	1		*REAR PANEL	Dented	526.70 FL	*526.70 FL
24	1		*REAR PANEL GARNISH	Mounting Deformed	57.70 FL	*57.70 FL
25	1		*REAR PANEL LOWER PANEL	Dented	495.50 FL	*495.50 FL
26	1		*SPARE TYRE HOLDER	Not Necessary	248.00 FL	*- FL
27	1		*TAIL LAMP PANEL TOP (RH)	Not Necessary	545.90 FL	*- FL
28	1		*SPARE TYRE PANEL	Dented	852.80 FL	*852.80 FL
29	1		*SPARE TYRE PANEL CUSHION	Not Necessary	209.05 FL	*- FL
30	1		*REAR TOWING HOOK	Not Necessary	94.60 FL	*- FL
31	1		*MEMBER ASSY-REAR FLOOR CENTRE	Not Necessary	570.40 FL	*- FL
32	2		*EXHAUST PIPE INSULATOR	Not Necessary	117.10 FL	*- FL
33	2		*EXHAUST SILENCER	Bent	1,935.40 FL	*1,935.40 FL
34	2		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
35	1		*EXHAUST PIPE CENTRE	Not Necessary	730.10 FL	*- FL
36	1		*REAR FENDER INNER LINING (RH)	Not Necessary	169.30 FL	*- FL
37	1		*REAR FENDER AIR-DUCT	Not Necessary	51.60 FL	*- FL
38	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
39	1		*REAR FENDER RH	Dented With Housing	4,736.80 FL	*4,736.80 FL
40	1		*BOOT LID COMFORT LOGO & TEL NO STICKER	Necessary	30.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*BOOT LID ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
42	1		*REAR NO PLATE	Not Necessary	25.00 FS	*- FS
43	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
44	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
45	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
46	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>19,537.35</b>	<b>16,178.40</b>
- List Item Discount on L Items 20.00/20.00% (S\$)	3,807.27	3,140.48
<b>Total Parts (S\$)</b>	<b>15,730.08</b>	<b>13,037.92</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	2,000.00	1,000.00
2	SPRAY PAINTING CHARGE	New	1,500.00	900.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
6	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
7	REMOVE/REFIX EXHAUST PIPE	New	300.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,220.00</b>	<b>2,190.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >