Payce 3: (Strike if N.A.)

SS

Name 3:

AND DESCRIPTIONS

KCE

Lumo Sum ! Lla I -

new beales

#### Performance Motors Limited

203, Alexandra bund Else Dathy Performance Centre Eleganore 18941 761. 4325/110 [Sales & Admin! 6328/111 [Afterdales] Fax. 4474775

180, Kampung Arang Kinad East Coast Centre Elogapore 476181 Tel. 43199888 (AfterSales) Pax. 43445771

115. Alexandra Broad Sine Dathy Business Centre Minappore 159845 Tel. 6139035 (AfterDales) 6319033/73E (Minorrad) Fas. 64796626 (Minorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

13 FEB 2019

Estimate No. : b1 50086 Page No. : 1 of 5 Date Estimated : 12/02/2019 Prepared By : Kevin Leong Wai Kit

- ESTIMATE REPAIR FOR -

Tan Wen Bin, Vincent (Chen Wenbin)

Blk 328 Sembawang Crescent

#14-08

ACCOUNT -121 AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way

#08-16 Chartis Building

Singapore 079120

Singapore 750328

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

2550 4250.00

3,257.00

SKS7295P

NS38396

30/04/2015

316iA/4

DESCRIPTION

To replace rear bumper, boot, reinforcement & all attachment cause by accident. To repair on rear end panel.

2621 934 796 668 Painting on rear bumper, boot, end panel & trunk floor

To remove and install boot compartment carpet and garnish to facilitate repairs.

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.

To check electrical wiring systems and lightings at the rear section for proper function.

To carry out body cavity preservation. (Per panel) Rear Boot

To supply rear emboss number plate.

Sundries.

150.00

Total Labour 1:

8,777.00

DESCRIPTION	QTY	PRIC	VALUE
TAILPIPE END PIECE ALU LOOK . A	1	107.85	107.85
BOOTLID POPUL 81	1	1,179.80	1,179.80~
RR BUMPER BOTTOM REINFORCEMENT	1	69.80	69.80
REAR BUMPER CENTRE GUIDE ? Cox	1	32.90	32.90 -
REAR BUMPER CARRIER (ECE)	1	467.95	467.95
REAR BUMPER PANEL PRIMED BASIS TO CRA	1	1,172.30	1,172.30
RR BUMPER FLAP TOWING EYE PRIMED MC	1	43.25	43.25 -
REAR PDC HOLDER SET A	1	24.60	24.60
REAR BUMPER LH SIDE GUIDE 27 VSVC	1	58.50	58.50
REAR BUMPER RH SIDE GUIDE 7. )	- 1	58.50	58.50

New Dealer

## Performance Motors Limited

A sember of the Rise Darby Group CO. Reg. No. 187401359% GDT Reg. No HG-0020081-K

PO3. Alexandra Road dies Dauby Performance Comtre Singapore 189941 Twl. 61306100 (Seles & Admin) 8130611 (AfterSales) Fax. 8474771

281, Emprouy Arang Soud East Count Destre Singapore 438280 Twl. 63198880 (AfterSales) Fax. 63448773

Grand Total

14,017.21



GST REG. NO : M2 - 0020081 - X

#### ESTIMATE

Date Estimated Prepared By	: b1 500 : 12/02/20 : Kevin Le				rage no.	e Eni	2 of 5
REGN. NO. SKS7295P	CHASSIS NO. NS38396	REGN. DATE 30/04/2015	MODEL 316iA/4				MILEAGE 0
PLAQUUNDEI UNDEI TRUNI RR BU RR BU DECO PDC S		TOR MISOTOR CANCELLA CONVERTE AND MEISS (A96) AND MEISS (A96)		QTY 1 1 1 1 1 1 1 4 2 1 Tota	71.25 38.40 37.25 76.40 36.80 36.80 5.05 368.80 53.05	*	VALU 71.2 38.4 37.2 76.4 36.8 20.2 737.6 53.0
Surveyors Hame Burveyor's Tal Authorised Date	162/19/0120U RASUL 90010668	Com No.  Excess 55  Sign  Authorised Yes / No.  Time.  OR Yes / No. Pag. Yes / No.					
Fegn for Oate & Time 22 Sonveyor's Hemb Eurosyon's Tel Authorised Oate HESURYET PARD Sonveyon's E-mail	162/19/0120U RASUL 90010668	Claim No	P/	abour 1 arts abour 2 xcess			8,777.0 4,323.2 0.0

<sup>&</sup>quot; THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY"

<sup>\*\*</sup> PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

A member of the Sime Darby Group Co. Ray, No. 197401559W. GST Reg. No. NO-0020061-X



#### FINAL REPORT

Estimate No.

b1 50086

Page No. :

Date Estimated :

12/02/2019

Prepared By

Kevin Leong Wai Kit

REPAIR FOR -

- ACCOUNT -

121

Tan Wen Bin, Vincent (Chen Wenbin)

AIG Asia Pacific Insurance Pte. Ltd.

Blk 328 Sembawang Crescent

#14-08

78 Shenton Way

#08-16 Chartis Building

Singapore 079120

Singapore 750328

REGN DATE MODEL MILEAGE REGN. NO. CHASSIS NO. SKS7295P NS38396 30/04/2015 3161A/4 DESCRIPTION ORIGINAL PRICE DISC. % NETT 2,550.00 To replace rear bumper and attachments, boot lid include 2550.00 making good the tail end panel and knocking out dents caused by the accident 2399.00 2,399.00 -To spray paint rear bumper, boot lid and tall end panel 230.00 To remove and install boot compartment carpet and 230.00 garnish to facilitate repairs To transfer lock mechanism from old to new boot lid 451.00 451.00 include conducting checks on new boot lid central locking system for proper function To check electrical wiring systems and lightings at the 150.00 150.00 rear section for proper function 100.00 100.00 To carry out body cavity preservation (Per panel) 83.00 83.00 To supply rear emboss number plate 150.00 150.00 Sundries

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,179.80	1.00		1,179.80
RR BUMPER BOTTOM REINFORCEMENT	69.80	1.00		69.80
REAR BUMPER CENTRE GUIDE	32.90	1.00		32.90-
REAR BUMPER CARRIER (ECE)	467.95	1.00		467.95
REAR BUMPER PANEL PRIMED BASIS	1,172.30	1.00		1,172.30
RR BUMPER FLAP TOWING EYE PRIMED	43.25	1.00		43.25
REAR PDC HOLDER SET	24.60	1.00		24.60
PLAQUE 74MM	71.25	1.00		71.25
# PLUG BLACK D=5MM *	0.90	10.00		9.00
RR BUMPER LH REFLECTOR	36.80	1.00		36.80
RR BUMPER RH REFLECTOR	36.80	1.00		36.80
DECOUPLING RING PDC TORQUE CONVERTE	5.05	4.00		20.20 -
PDC SENSOR MINERALWEISS (A96)	368.80	1.00		368.80

A member of the Sime Darby Group Co. Reg. No. 187401559W. GST Reg. No. MS-0020081-X



#### FINAL REPORT

PDC SENSOR MINERALWEISS (A96)
(DG/SL) ADHESIVE SET K6

368.80 1.00 53.05 1.00

368.80

# SUPPLEMENTARY ITEMS

 Total Labour :
 6,113.00

 Total Parts :
 3,955.30

 Total Labour & Parts :
 10,068.30

 Deduction for Excess :
 10,068.30

 Total Repair Costs less Excess :
 10,068.30

 Total Repair Costs less Excess:
 10,068.30

 GST @7%:
 704.78

 Grand Total:
 10,773.08

Amentor of the Sime Deby Group Co. Rep. No. 19740159W, GST Rep. No. M2-0020081-X



#### SUPPLEMENTARY

Estimate No.

b1 50086

Page No.:

Date Estimated :

12/02/2019

Prepared By Kevin Leong Wai Kit

REPAIR FOR -

- ACCOUNT -

121 AIG Asia Pacific Insurance Pte. Ltd.

Tan Wen Bin, Vincent (Chen Wenbin)

Blk 328 Sembawang Crescent #14-08

78 Shenton Way

#08-16 Chartis Building

Singapore 079120

Singapore 750328

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SKS7295P

DESCRIPTION

NS38396

30/04/2015

3161A/4

0

ORIGINAL PRICE DISC. % NETT

DISC. %

DESCRIPTION # PLUG BLACK D=5MM . N.C. UNIT PRICE 0.90

QTY 10.00

NETT 9.00

Total Labour:

Total Parts:

9.00

Total Labour & Parts:

9.00

BMN Dealer

## Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-a

301. Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel 6190100 (Hales & Admin) 63180111 (AfterBales) FAX. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180

Tel. 63190808 (AfterSales) Pax. 63449773

315. Alexandra Boad Sime Darby Business Centre Singapore 189944 Tel. 41190318 (AfterSales) 43190533/530 (Motorrad)

Fax 64796601 (AfterSales) 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

13 FEB 2019

Estimate No. : b1 50086 Page No. : 1 of 5

Date Estimated

: 12/02/2019

Prepared By

: Kevin Leong Wai Kit

RR BUMPER FLAP TOWING EYE PRIMED ML)

REAR PDC HOLDER SET M

REAR BUMPER LH SIDE GUIDE

REAR BUMPER RH SIDE GUIDE

- ESTIMATE REPAIR FOR -- ACCOUNT -121

Tan Wen Bin, Vincent (Chen Wenbin)

Blk 328 Sembawang Crescent

#14-08

AIG Asia Pacific Insurance Pte. Ltd.

43.25

24.60

58.50

58.50

43.25

24.60

58.50

58.50

78 Shenton Way

#08-16 Chartis Building

Singapore 079120

Singapore 750328

SKS7295P	NS38396	30/04/2015	316iA/4	0
REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE

							=
REGN. NO. SKS7295P	CHASSIS NO. NS38396	REGN. DATE 30/04/2015	MODEL 316iA/4			MILEAGE 0	
NAME OF THE PARTY		COALCOAL STATE OF	Services of the service				=
	DESCRIPTION	12 200				VAL	JΕ
	To replace rear bumper, boot, cause by accident. To repair o		chment			2550 4250.	00
	434 796	48 3421				- 44	/
	Painting on rear bumper, boot,					2398 3,497. 230 271. 230 271. 451 537. 150 127. 150 127.	00
	To some send install hand one		a a a faith			~ 2 c 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1
	To remove and install boot cor to facilitate repairs.	npartment carpet and g	arnish			250 91	UU
	STATES OF THE PROPERTY AND PROPERTY.					1200	,
	To transfer lock mechanism fro					45 ( 534.	бо
	including conduct checks on n system for proper function.	ew bootlid central locking	g				
	-/						
	To check electrical wiring syste					150 17	00
	rear section for proper function	lý.					
	To carry out body cavity prese	rvation.				100 118	60
	(Per panel) Rear Boot					100/	
	To supply rear emboss numbe	e piato				Y 02	00
	To supply real emboss number	plate.				/ 03.	00
	Sundries.					7 150.	
				Tot	tal Labour 1:	8,777.	00
	PROPERTY			command and	2270		
	TAILPIPE END PIECE ALU LO	OCK .		QTY	107.85	107.	
	BOOTLID POPULATE BY	A CONTRACTOR OF THE CONTRACTOR		1	1,179.80	1,179.	
	RR BUMPER BOTTOM REINE	ORCEMENT .		1	69.80	69.	
	REAR BUMPER CENTRE GU			1	32.90	32	
	REAR RUMPER CARRIER (E)	CE)		4	467.95	467.	
	REAR BUMPER PANEL PRIM	ED BASIS FICKA		4	1,172.30	1,172	
	RR BUMPER FLAP TOWING	EYE PRIMED ML)		- 4	43.25	43	



ember of the Sime Darby Group Beg. No. 197401555W SET Reg. No NG-00130881-x

303. Alexandra Road Sime Darby Performance Centre Singapore 159941

Tel 63190100 (Sales a Admin) 63190111 (AfterSales) Fax. 64767770

280, Eampong Arang Road

East Coast Centre Singapore 438180 Tel. 63190888 (AfterSales) Fax. 63449773



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.

50086 : b1

Date Estimated

: 12/02/2019

Prepared By

: Kevin Leong Wai Kit

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SKS7295P

NS38396

30/04/2015

316iA/4


0

Page No. : 2 of 5

VALUE DESCRIPTION PRIC QTY PLAQUE 74MM A. 71.25 71.25 UNDERBODY PANELLING REAR LH 38.40 38.40 UNDERBODY PANELLING REAR RH 37.25 37.25 TRUNK LID GASKET ALL 76.40 76.40 RR BUMPER LH REFLECTOR MID 36.80 36.80 RR BUMPER RH REFLECTOR CM 36.80 36.80 DECOUPLING RING PDC TORQUE CONVERTE \* 5.05 20.20 368.80 737.60 PDC SENSOR MINERALWEISS (A96) A-53.05 53.05 (DG/SL) ADHESIVE SET K6

Total Parts

4,323.20



Labour 1 8,777.00 : Parts 4,323.20 4 Labour 2 0.00 0.00 Excess 4 Total GST @ 7% 917.01 Grand Total : 14,017,21

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

<sup>\*\*</sup> PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*



#### Sompo Insurance Singapore Pte. Ltd.

50 Raffies Place, #05-01/06 Bingspore Land Yoser, Singspore 048029 Tel: 6461 6556 - Flac: 6221 3302 - Watsile: www.xxmpo.asmi.eg Ce. Reg. No.: 1889054906 - GST Reg. No. M200903196

#### Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No.

: D18MTPV01018367

Insured

: TAN WEN BIN VINCENT

Motor Car (Registration No.) : SKS7295P

Cover

: Comprehensive - ExcelDrive PRESTIGE

Policy Commencement Date : 06 NOVEMBER 2018 00:00

Policy Expiry Date

: 05 NOVEMBER 2019 23:59

Maximum Liability (Section I): Market value at time of loss

Excess\*

: \$500 - Section I

(Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim

per policy year)

Voluntary Excess\*

- NA

Windscreen Excess\*

: S\$100.00 - Waived if Repair at ExcelDrive Workshop

Loss of Use

: Per Policy Schedule

Persons or Classes of Persons entitled to drive\*

- The insured.
- 2. Any other person who is driving on the Insured's order or with his permission.

3. In the event of the death of the insured,

- a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
- b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the Insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car, And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

#### Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

#### ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323

UWe HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Thirti-Perty Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1967 (Malaysia); and (2) the Policy terms, conditions and exceptions of the Private Car Policy of MTP 27

Sompo Insurance Singapore Pte. Ltd.

#### **Authorised Signatory**

Date/Time of Issue: 01 NOVEMBER 2018 17:47

#### IMPORTANT NOTICE

Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unleadul for any person to use or cause to permit any other person to use a motor vehicle without a veiid policy of insurance under the Act;

On the sale of the Motor Car or if for any reason the insurance is terminated during its currency, the insured must surrender the Certificate of Insurance and the Policy to

the insurance company. If the Certificate of insurance has been lost or destroyed, a statutory declaration to that affect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 188);

This Policy will cause to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

Intermediary Code & Name 11729403 & THINKERS ALLIANCE PTE. LTD. CI Code: 22A LADZMK2P2YDMMKAJ

<sup>\*</sup> Subject to GST wherever applicable

#### Khanchna (LKK Auto)

From:

Khanchna (LKK Auto)

Sent:

Monday, 7 October 2019 10:30 AM

To:

PBSP

Cc:

Admin A

Subject:

RE: URGENT REMINDER - SKS7295P & SJN7724G ON 08/02/2019 \*\*\* LKK REF:

CC3/AIG19002701/R1kb3

Tracking:

Recipient

Delivery

PBSP

Admin A

Meikwan@lkkauto.com olivialau@lkkauto.com Delivered: 7/10/2019 10:30 AM

Delivered: 7/10/2019 10:30 AM

shupei@lkkauto.com

Delivered: 7/10/2019 10:30 AM

Without Prejudice (save as to costs)

Dear Sirs/Mdm.

We refer to the above matter.

We confirm settlement as follows: -

TOTAL	\$ 11,675.08
3. LTA/GIA Search Fee	\$ 2.00
2. Loss of Rental (9 days x \$100.00)	\$ 900.00
1. Cost of Repair (w/GST)	\$ 10,773.08

We will proceed to do the necessary promptly.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: <u>Khanchna@lkkauto.com</u> Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 5(408933)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Sent: Monday, 23 September 2019 6:21 PM

## Claim Audit

	13 Feb 2019 18:22	Cim Veh Mo	del Changed	(205082) BMW	3161 1.6 AT D/AB	4DR ABS HID (A	).		[A] Lau Shu Pei
	13 Feb 2019 15:22	Clm Creater	d	c Insurance Pte	95P. Acct Date: 26 b. Ltd. (SG). TP Instance Motors L	surer: Sampo Ins	urance Singapor	er: AIG Asia Pacifi re Pte. Ltd. (HQ).	[A] Lau Shu Pei
	13 Feb 2019 16:22	Adj Co Assi	gned	LKK Auto Consi	ultants Pte Ltd (HC	2):			(A) Lau Shi Pei
ı	13 Feb 2019 18:22	Adj Next R	ot Changed	Next Rpt:Final	Rpt.Due Date:201	9/02/22			(A) Lau Shi Pel
	13 Feb 2019 18:22	Adj Mandat	e Set	Approved:8000	pproved:8000.00.Reinsp:AdJ decides.				
	13 Feb 2019 18:22	Clm Ins Co		[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)				[1] Merimer Administrati	
7	13 Feb 2019 18:22	Label Adde	d	23):Express.				[A] Lau Shi Pei	
	13 Feb 2019 18:22	Adj Adjuste	r Assigned	None] -> MOHD TAUFIKH BIN HAMID					[A] Lau Sh Pei
į	28 Feb 2019 14:16	Adj Adjuste	r Assigned	MOHD TAUFIKH BIN HAMID -> MOHD RASUL					(A) Lau Sh Pei
	23 Sep 2019 10:00	Adj Rpt Init	tiated						(A) JOANN LEE KHANG MIN
1	23 Sep 2019 10:00	Cim Dti Mod	dified	JPJ Reg. Date:	-> 2015/04/30.				[A] JOANN LEE KHANG MIN
	23 Sep 2019 10:00	Clm Details	Notified						[A] JOANN LEE KHANG MIN
	23 Sep 2019 17:44	Adj Mandat			.08:L: 100% again				[A] Khanchi Pothuraj
	Date Fro	om	4 11	► Date To	4	■ ► Audit	Type None	*	Go
СТ	IVITY								
3 5	ecord								
e	rimen Billing	for this cas	e - Transacti	ion History					
		3 Sep 2019	OD/TP Case		LKK Auto	LKK Auto Consultants		5JN7724G	11.77

Alexander and the second		
TEAN		
1 1 1 1		

#### NOTE: TO BE COMPLETED BY SURVEYOR

## AIG THIRD PARTY EXPRESS SETTLEMENT FOR ACCIDENTS ON OR AFTER 1<sup>ST</sup> JUNE 2008 (PAYMENT BREAKDOWN)

Vehicle No:		SKS7	295P					***
Date of Accid	ent:	08/02/	2019				Mod	odel:
Global Sum S	Settle	ttlement: [ ] Yes [					No	
Repair Estim	ate			: 8	14,01	7.21		
Final Repair	Cost			: \$	10,77	3.08		
Loss of Use				: 8	100			days at \$ per day
Rental (if any	y)			: 8	900.0	0		09 days
LTA / GIA S	earch	Fee		: 8	2.00			
Others				: \$	**			
				: 8	124			
Final Settlen	ent S	Sum		: 8	11,67	5.08		
Is Third Party	y Wor	rkshop (	GIA F	legist	ered?	] YES	[ ]	NO (Kindly indicate below)
BOL	A Lia	egistere bility: _ .iability t			_(%)	Asse	LA Se	Application: Yes / No Scenario No:
Remarks								
Payment Inst	ructio	on: Pay	ee's B	reak	down			
1) Per	form	ance M	otor	Lim	ited		: 8	10,773.08
2) Per	form	ance M	otor	Lim	ited		: 8	2.00
3) Tan	Wen	Bin, V	incen	t			: 8	900.00
Signe								

Please attach all the supporting documents to the form. Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report / Bill (if any)

#### Asher Sng (LKKAuto)

From:

Asher Sng (LKKAuto)

Sent:

Wednesday, 20 February 2019 2:04 PM

To:

'GENEYOONG@HOTMAIL.COM'

Subject:

ACCIDENT INVOLVING SJN 7724G AND SKS 7295P ON 08/02/2019

Our Ref: CC3/AIG19002701/eb3

20 FEB 2019

#### YOONG CHON YEIN GENE

Dear Sir/Madam.

#### ACCIDENT INVOLVING SJN 7724G AND SKS 7295P ON 08/02/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher

Case Handler DID: 6841 6051 FAX: 6741 4108

Email: Ashersng@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd

(Motor Claims Dept)

# AUTHORISATION TO ACT

## (AIG Express Third Party Claim)

I, Tan Wen Bin Vincent (the third party claimant) of Bik 683C Edsolde
Plans #14-685 \$ ( \$23683 ) (address), owner of SKS 7275P (vehicle no.)
hereby authorizePerformance Motors Ltd ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SKS729SP that was damaged pursuant to the accident which occurred on 8/2/19/
(date) along 192 toward TP2 (location) involving vehicle no/s
SIN 77246 ("the accident").
I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this \_\_\_\_\_\_ 14 \_\_\_\_\_ (day) of \_\_\_\_\_\_ 10 \_\_\_\_\_ (month) 20\_\_\_\_19 (year)

Signed by "the third party claimant" (with chop if applicable) KEVIN LEONG WAI KIT
Performance Motors Limited
303 Alexandra Road
Since Darby Performance Centre
Sincepore 159941

Signed by "the workshop" (with chop)

# RELEASE VOUCHER (AIG Express Third Party Claim)

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I
have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK
AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for
SS 10, 773 cg(Repair Cost), SS 900-00 (Loss of rental/use), SS 2-00 (Disbursement), for vehicle no.
SKS7250 that was damaged pursuant to the accident which occurred on 8/2/19 (date) along
KPE Towards TPE (location) involving vehicle no/s SIN FRAG. This is
pursuant to the inspection conducted on 27/2/19 (date) at "the workshop".
We/I confirm that we/I are/am authorized by the owner Ten Nea Bin Vincent
("the third party claimant") of vehicle no. 3KS 729SP make the claim as set out in the above paragraph
and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I
enclose herein the letter of authority given by "the third party claimant".
We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss
and/or expense that they will or have already incurred in the event that "the third party claimant" after the
above said agreement lodges a further claim against the former for any loss and expenses suffered
pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKS7295P
(vehicle no.) as a result of the accident.
We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third
party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice
and without admission of liability basis.
This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive
jurisdiction over any dispute arising out of the same.
Dated this 14 (day) of 10 (month) 20 14 (year)
(manual) 20 - 1 (yout)
MEVIN LEONG WAI KIT

MRB

Signed by appointed surveyor

Signed by "the workshop" (with chop)

Paridhance Motors Limite 303 Alexandra Road Sime Darby Performance Centrol Singapore 159941



A member of the Sime Darby Group Co. Reg. No. 197481559W GST Reg. No M2-0020081-X

303. Alexandra Road Sime Datby Performance Centre Singapore 159941 Tel 6130000 (Sales & Admin) 1590111 (AfterSales) Pax. 66747770

280, Kampong Arang Road East Coast Centre Hingapore 438180

Tel. #3190888 (AfterSales) Fes. #3449773

015. Alexandra Road Sime Darby Business Centre Bingapore 18944 Tel. 63190528 (AfterSal 63190533/818 (Motorras Fax. 64796601 (AfterSal 64796604 (Motorras (Aftertales)



#### SERVICE TAX INVOICE

Repair Order No.

: B1 1341103 Page No.

Invoice By

: 1 of 2

: 27/02/2019

Invoice Number :

2106298 / WSB

Date IN

Invoice Date 12

04/06/2019 30 Days From Invoice

Motor Claim Advisor: Kevin Leong Wai Kit Payment Terms :

:: Toh Jing Xuan

CUSTOMER INFORMATION -

Mr Tan Wen Bin, Vincent (Chen Wenbin)

Blk 328 Sembawang Crescent

#14-08

INVOICE TO -121

AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way

#08-16 Chartis Building

Singapore 079120

Singapore 750328

DEGN NO SKS7295P CHASSIS NO. NS38396

REGN. DATE 30/04/2015

MODEL 316IA/4 MILEAGE 83859

----LABOUR 1----NETT To replace rear bumper and attachments, bootlid including 2.550.00 make good the tail end panel and knock out dented area caused by the accident. 2,399.00 To respray rear bumper, bootlid and tail end panel. To remove and install boot compartment carpet and garnish 230.00 to facilitate repairs. To transfer lock mechanism from old to new bootlid 451.00 including conduct checks on new bootlid central locking system for proper function. To check electrical wiring systems and lightings at the 150.00 rear section for proper function. To carry out body cavity preservation. 100.00 150.00 Sundries. INS CLAIMS: ACCIDENT REPAIR. DIRECT SETTLEMENT. 0.00 DATE OF ACCIDENT: 08.02.2019. 3RD PARTY CAR: SJN7724G. YOUR REF NO : NIL. VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO ON 27.02.2019 AT 12PM. AUTHORISED REPAIR BY MS ASHER SNG FROM LKK AUTO ON 20.02.2019 VIA EMAIL. PROPOSE CAR RENTAL = \$900.00. THE AMOUNT IS SUBJECTED 0.00 TO INSURANCE COMPANY CONFIRMATION. GIA SEARCH FEE = \$2.00. 0.00

Total Labour 1: 6,030.00

PARTS	Qty	Retail Price	NETT
BOOTLID	1	1,179.80	1,179.80
REAR BUMPER PANEL PRIMED BASIS	1	1,172.30	1,172.30
(DG/SL) ADHESIVE SET K6	1	53.05	53.05
REAR PDC HOLDER SET	1	24.60	24.60
PLAQUE 74MM	1	71.25	71.25
RR BUMPER LH REFLECTOR	1	36.80	36.80
RR BUMPER RH REFLECTOR	1	36.80	36.80
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
PDC SENSOR MINERALWEISS (A96)	1	368.80	368.80

A member of the Sime Darby Group Co. Reg. Mo. 197401559W GST Reg. No M2-0820881-x

Sime Darty Performance Centre Singapore 189941 Tel 62190200 (Sales & Admin) 61190211 (AfterSales) Fax. 64747770

280, Kampong Arang Hoad Kast Coast Centre Singapore 438185

Tel. 63190888 (AfterSales) Pas: 63449772

318, Alexandra Road Sime Darby Business Centra Singapore 159944 Tel. 53190538 (AtterSales 53190533/53E (Motorrad) 44796501 (AfterSales (Motorrad)



#### SERVICE TAX INVOICE

Repair Order No. : B1

1341103

: 2 of 2 Page No.

: 27/02/2019 Date IN

Invoice Number: 2106298 / WSB

Invoice Date : 04/06/2019 Motor Claim Advisor: Kevin Leong Wai Kit

Payment Terms : 30 Days From Invoice

Invoice By : Toh Jing Xuan

RR BUMPER FLAP TOWING EYE PRIMED	1 43.25	43.25
PDC SENSOR MINERALWEISS (A96)	1 368.80	368.80
RR BUMPER BOTTOM REINFORCEMENT	1 69.80	69.80
REAR BUMPER CENTRE GUIDE	1 32.90	32.90
REAR BUMPER CARRIER (ECE)	1 467.95	467.95
PLUG BLACK D=5MM	10 0.90	9.00
	Total Darts .	3 955 30

---- L A B O U R 2 ----To supply rear silver emboss lettering black base number

NETT 83.00

plate with bracket.

Total Labour 2: 83.00

Total Labour & Parts Charges Labour Charges 5,963.00 : S\$ 10,068.30 Parts Charges 3,955.30 Less Insurance Excess : SS 0.00 7.1 Invoice Total Amount Exclude GST : S\$ Lubricant/Misc : 150.00 10,068.30 GST @ 7% 704.78 Invoice Total Amount Include GST : S\$ 10,773.08

Computer generated invoice. No signature is required.

Amount Payable Include GST

S\$ 10,773.08

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service. No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





**CHAN'S & SONS ENTERPRISE** 

363 Sembawang Road, Goodlink Park, Singapore 758379.

Tel: 6753 2536 Fax: 6756 7565 Breakdown Recovery: 9742 9446

	201902-0246								
Hiror's Name	0. 1.	-		Date of Birth	Passport	and the latest the lat		lationality	
-/an W	en Bin. Vinc	cent		13 2 8	58	605	Z48B		
Blk 683	Man Wen Bin, Vincent Acidreas BIK 683C Edgedale Plains Postal Code			Occupation	Driving L	N/	no c	Date of Expliny	8
11 1 .	10 sugara	C 1	Postal Code	Contact No	Mobile P				
#14-	#14-685 823683				92	397	336		
roint Hirer's / Guarantor's Name			Date of Birth	Passpor	V Nnc N	a. A	vationality		
Address				Occupation	Driving L	icence l	No E	Date of Expiry	
			Postal Code	Contact No	Mobile P	honë N	0.		
								- 13	
CHECK OUT	71-7-19	Time	0 kg.	Mileage		$\cap$	1	1000	- 1
011501/111	-1-1		7-43am.		M E	1/4	1/2	3/4	F
CHECK IN	8 · 3 · 19	Tirne 1	2-30pm	Mileage	Flemarks M	1	J		
IMPORTANT NOTE	ES:-				UNIT		RATE (\$	B) TOTAL	(\$)
	SINGAPORE use. See clause 1		-compliance.	RATE	9	a	100	0 900	
8 Own Damage Liab	ven for vehicle that returns early lifty - First \$1500 for damage aged vehicle is under tepsir.		le plus loss of	DISCOUNT		П	( )		
II Third Party Liability	First \$2000 for any Third Par			GST @ 7%		П			
and/or less than 2yr	of \$3000 for drivers under 24 driving experience.	ein-	above 70ym	TOTAL				900	,
processed in	for all parking fines & traffic sur y's advance notice is required		e no extension	EXTENSION				V1013	376
Ill Vehicle should be	returned at the same time am time is before 10am.	as collect	ion except on			Ш		0 PI 0 C	3- 0
∀enicle returned after	er office hour will be charged to	the next	working day:	1				8	
All a series and a series of the series of t	charged at 1/5 of the daily rate.		200	DMIK					
Please check that y vehicle. Our comp	tenance, please check water & ou have not left any of your pe any and staff will not be resp vehicle is returned.	ersonal be	longings in the	SKS7295)	>	П			
	other users, please retrain to the car. A cleaning charge of \$ to vehicle.			DEPOSIT (refundat		1	× 5		-
minutes arrivally on the	ENGERS in commercial vehic covered under hirer's works			CHANGED OVER				DATE	

VEHICLE NO.	SMF 2085 G	MODEL	
FROM		RETURN	"Estimate Date. For actual return one CHECK IN

#### **CHAN'S & SONS ENTERPRISE**

363 Sembawang Road Singapore 758379 Tel: 67532536 Fax:67567565 GST Reg No: 51-936900-M



## TAX INVOICE

TAN WEN BIN, VINCENT

BLK 683C #14-685 EDGEDALE PLAINS SINGAPORE 823683

ATTN: TAN WEN BIN, VINCENT

INVOICE AR1903-0144

DATE 08/03/2019 **TERMS** C.O.D :

STAFF ID AMIRA

AGREEMENT NO. : HA201902-0246

DESCRIPTION AMOUNT (SGD)

Vehicle Reg No : SMF2085G 841.12

Make / Model

Rental Dates

: Rental Billing From 27/02/2019 To 08/03/2019 : 9 days

Rental Rate

Period

: S\$ 100.00 Per Day

(Including GST)

Reference No

: SKS7295P

AMOUNT: S\$ NINE HUNDRED DOLLARS ONLY NON-TAXABLE VALUE:

0.00

TAXABLE VALUE -GST 7%:

841.12 58.88

TOTAL S\$ :

900.00

Please make your cheques payable to : CHAN'S & SONS ENTERPRISE



For Official USe Only

Payment Date :	F / Amt
CS / CC /CH	
CS / CC /CH	

#### CHANS & SONS ENTERPRISE

363 Sembawang Road, Goodlink Park, Singapore 758379 Tel: 67532536 Fax:67567565 GST Reg No: 51-936900-M



Hirer

TAN WEN BIN, VINCENT

#### OFFICIAL RECEIPT

DESCRIPTION	BANGER AND DESCRIPTION OF THE PARTY OF THE P		AMOUNT	(SGD)
Official Receipt No Account of	201903-0070 TAN WEN BIN, VINCENT			
Date Issued	: 08/03/2019			
Vehicle Reg No.	: SMF2085G			
Rental Dates	27/02/2019			
Amount Received	S\$ 900.00			
Payment Type:	VISA	V101376	S\$	900.00
Payment for Invoice	: AR1903-0144			
Comments				
TOTAL AMOUNT RE	CEIVED		S\$	900.00



the own or steamen 10000

TO ANY MARKET THE WORK OF THE TAXABLE THE

SALE

Card No. 100 mm mm (ear fama)

HE NEWSTERN SECTION OF THE VEHICLE AND THE SECTION OF THE SECTION WHETHER STORY 

LOTOL: SOD

NO SIGNATURE REQUIRED

A fewer of the later between the artists. SCHOOL OF THE SAME DOOR BARREN

<sup>\*</sup> This is a computer generated document. No signature is required.





#### RECORDS MANAGEMENT CENTRE

## GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

## Third Party Insurer Enquiry

Our Ref No:

GR-19-021502

Date of Request:

11/02/2019

Your Ref No:

Online Purchase

Performance Motors Limited 303 Alexandra Road Sime Darby Performance Centre Singapore 159941

Dear Sir/Madam,

**Enquiry Date** 

11/02/2019

Enquiry By

Caroline Tan Shirui

TP Vehicle No.

SJN7724G

Accident Date

08/02/2019

**Enquiry Result** 

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJN7724G	AIG Asia Pacific Insurance Pte. Ltd.	26/02/2018-25/02/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



#### RECORDS MANAGEMENT CENTRE

## GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm GST Registration No: M400017735

#### TAX INVOICE

Our Ref No:

GR-19-021502

Date of Request:

11/02/2019

Your Ref No:

Online Purchase

Performance Motors Limited 303 Alexandra Road Sime Darby Performance Centre Singapore 159941

Dear Sir/Madam,

**Enquiry Date** 

11/02/2019

Enquiry By

Caroline Tan Shirui

TP Vehicle No.

SJN7724G

Accident Date

08/02/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque

## **Print Received Message**

This mail is associated with:

\*SKS7295P (9478391517SG) [SJN7724G] TP

TAN WEN BIN VINCENT Feb 8 2019 5:00PM [YOONG CHON YEIN GENE] Performance Motors Limited

From

AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 27/09/2019 08:25 AM.

To

LKK HQ

Subject

Alert - Adj Mandate Approved (S\$11675.08) - SKS7295P - Claim Handler: Syed-Yusoff, Saliha

Approved:11675.08:approval is subject to final repair bill & ATA

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Fst Submitted	Adj Assigned	Adj Rpt	Adi	Submitted	Ins Auth'ed	Status	
Main	14 Feb 2019 Edit Reg		27 Feb 2019 00:00 Edit Ad) Rpt	5\$10,068.30 Edit Estimati	COMPANY OF THE PARTY OF	0,068.30 ew Apt		Pending for Report Cancel Can	erine
	Main	R	eference	Claim	Details		Documents		Show All
CLAIM SI	JBFOLDER DI	TAILS				[Created	by adjuster]		
Insured	YOONG C	HON YEIN GENE	, ID: 57332219G						
Main Claimant:	TAN WEN	BIN VINCENT,	ID: S8605248B						
Vehicle Re No.:	SKS729	5P		Dat	e of Loss:		9 17:00 - :59 s and <b>9</b> Days Fron	n LTA Reg Date	(Man Yr)]
Claim Type	TP / 947	78391517SG			cy/Cover e Na.:	210040393	9 (Comprehensive	e)	
Vehicle Re No. (Insured):	S3N7724	G			cy No. iimant):				
					ess:				
Repairer:		nce Motors Limi /63190174	ted (Alexandra) 3	03 Alexandra Ro	ad, Sime I	Darby Perfor	mance Centre, 159	9941 Alexandra	- Tel:
Handling Insurer:	AIG Asia Yusoff@ai		e Pte. Ltd. (Expre	ss) - Tel: 65-64	19-3000	[Handled b	y Syed-Yusoff, S	Saliha] Saliha,S	yed-
Claimant's Insurer:	Sompo II	surance Singap	ore Pte. Ltd. (HQ)	- Tel: 6461 655	5				
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	S6-3561 [Ha	ndled by M	40HD RASU	L] [Final Rp	t due 22/02/	2019]
ASSOCIA	TED MAIL RE	CEIVED					Vie	w All Comp	ose Case Mai
<ul> <li>AIG_S0</li> </ul>	EXPRESS (27	/09/2019): Alert	- Adj Mandate App	proved (5\$116	75.08) - 1	SKS7295P -	Claim Handler:	Syed-Yusof	
ALL ASS	OCIATED TAS	sks=				View All	Search Tasks C	reate New Task	Complete
Due Da		Type Task	Group Subject	ct Handler	Assign	ned By	Completed On	Created (	On Done

#### Claim Documents

\*SKS7295P (94783915175G) [SJN7724G] TP TAN WEN BIN VINCENT Feb 8 2019 5:00PM [YOONG CHON YEIN GENE] Performance Motors Limited

Lett	ters/Corresponden	ces	1 per	page v	PC1
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit	
	tos/Images		3 per	page 🔽	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1300	Thumbnail	-
1	23/09/19 17:53	General View	0	Load JPG	M
2	23/09/19 17:53	Chassis Number	0	Load JPG	
3	23/09/19 17:53	General View	6	Load JPG	2
4	23/09/19 17:53	General View	0	Load JPG	2
5	23/09/19 17:53	General View	0	Load JPG	8
6	23/09/19 17:53	General View	0	Load JPG	100
7	23/09/19 17:53	General View	0	Load JPG	V
8	23/09/19 17:53	General View	0	Load JPG	12
9	23/09/19 17:53	General View	0	Load JPG	12
10	23/09/19 17:53	General View	0	Load 3PG	8
11	23/09/19 17:53	General View	0	Load JPG	Ø
12	23/09/19 17:53	General View	0	Load JPG	2
13	23/09/19 17:53	General View	0	Load JPG	2
14	23/09/19 17:53	General View	0	Load JPG	82
15	23/09/19 17:53	General View	6	Load JPG	120
16	23/09/19 17:53	General View	0	Load 3PG	Ø
17	23/09/19 17:53	General View	0	Load JPG	2
18	23/09/19 17:53	General View	0	Load JPG	2
19	23/09/19 17:53	General View	0	Load JPG	52
20	23/09/19 17:53	General View	0	Load JPG	12
21	23/09/19 17:53	General View	0	Load 3PG	V
22	23/09/19 17:53	General View	0	Load JPG	V
23	23/09/19 17:53	General View	0	Load JPG	R
24	23/09/19 17:53	General View	0	Load JPG	12
25	23/09/19 17:53	General View	0	Load JPG	V
26	23/09/19 17:53	General View	0	Load JPG	V
27	23/09/19 17:53	General View	0	Load JPG	V
28	23/09/19 17:53	General View	0	Load JPG	2
29	23/09/19 17:53	General View	0	Load JPG	V
30	23/09/19 17:53	General View	0	Load JPG	V
31	23/09/19 17:53	General View	0	Load JPG	V
32	23/09/19 17:53	General View	0	Load JPG	V
33	23/09/19 17:53	General View	0	Load 3PG	8
34	23/09/19 17:53	General View	0	Load JPG	82
35	23/09/19 17:53	General View	0	Load JPG	82
36	23/09/19 17:53	General View	6	Load JPG	82
37	23/09/19 17:53	General View	0	Load 3PG	V
38	23/09/19 17:53	General View	0	Load 3PG	V
39	23/09/19 17:53	General View	0	Load JPG	82
40	23/09/19 17:53	Reinspection Photo	0	Load 3PG	

Lett	ers/Corresponden	ces	1 per p	age v	V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	
					V
41	23/09/19 17:53	Reinspection Photo	0	Load JPG	☑
42	23/09/19 17:53	Reinspection Photo	0	Load JPG	V
43	23/09/19 17:53	Reinspection Photo	0	Lond JPG	V
44	23/09/19 17:53	Reinspection Photo	0	Load JPG	2
45	23/09/19 17:53	Reinspection Photo	0	Load JPG	2
46	23/09/19 17:53	Reinspection Photo	0	Load JPG	V
47	23/09/19 17:53	Reinspection Photo	0	Load 3PG	
48	23/09/19 17:53	Reinspection Photo	0	Load JPG	V
49	23/09/19 17:53	Reinspection Photo	0	Load JPG	V
7.0	22/09/19 17:35	Name postular i i i i i i i i i i i i i i i i i i i			
Doc	cumentation		1 per s	page 🔍	[2]
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	13/02/19 18:22	TP EST & GIA REPORT	0	Load PDF	
2	20/02/19 14:04	LETTER TO OI	0	Load PDF	
3	28/02/19 18:04	TP ESTIMATE- MARKED	0	Load PDF	
4	23/09/19 11:57	RENTAL RECEIPT	6	63 Load PDF	
5	23/09/19 11:57	GIA SEARCH	0	1 Load PDF	
6	23/09/19 11:57	LOD	0		
7	17/10/19 08:58	WORKSHOP INVOICE	0	Load PDF	
8	17/10/19 08:58	AUTHORISATION TO ACT FORM	0	Load PDF	
9	17/10/19 08:58	Release Voucher	0	Load PDF	_
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Prin
1	14/02/19 15:32	OI GIA REPORT	0	Load PDF	

#### **Documents Checklist**

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	ĵ.
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

NOTE: T	OBE	COMPL	ETED	BY	SURVEYOR
INCO I E	U D	COMMENT AND ADDRESS OF THE PARTY OF THE PART	the 1 hade		201115-1011

TEAM			
LEAM			_

## THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Global Sum Settlemen Repair Estimate Final Repair Cost Loss of Use Rental (if any) LTA / GIA Search Fee Others: Final Settlement Sum Is Third Party Works below) A) For Non GIA Reg B) For GIA Register BOLA Liability:	8/02/2 nt :		es : \$ : \$ : \$ : \$	[X] No 14,026.84 10,773.08	AB	S HID (	A)
Global Sum Settlemen Repair Estimate Final Repair Cost Loss of Use Rental (if any) LTA / GIA Search Fee Others: Final Settlement Sum Is Third Party Works below) A) For Non GIA Register BOLA Liability: * Assessed Liabili	nt :		: \$ : \$	14,026.84			
Repair Estimate Final Repair Cost Loss of Use Rental (if any) LTA / GIA Search Fee Others: Final Settlement Sum Is Third Party Works below) A) For Non GIA Reg B) For GIA Register BOLA Liability: * Assessed Liabilit		[ ] Y	: \$ : \$	14,026.84			
Repair Estimate Final Repair Cost Loss of Use Rental (if any) LTA / GIA Search Fee Others: Final Settlement Sum Is Third Party Works below) A) For Non GIA Reg B) For GIA Register BOLA Liability: * Assessed Liabilit		[ ] Y	: \$ : \$	14,026.84			
Final Repair Cost  Loss of Use  Rental (if any)  LTA / GIA Search Fee  Others:  Final Settlement Sum  Is Third Party Works below)  A) For Non GIA Reg  B) For GIA Register  BOLA Liability: * Assessed Liability			: \$	The CARRON TRANSCO			
Loss of Use Rental (if any) LTA / GIA Search Fee Others: Final Settlement Sum Is Third Party Works below) A) For Non GIA Reg B) For GIA Register BOLA Liability: * Assessed Liability			: \$	10,773.08			
Rental (if any)  LTA / GIA Search Fee Others:  Final Settlement Sum Is Third Party Works below)  A) For Non GIA Reg B) For GIA Register  BOLA Liability: * Assessed Liability							
CTA / GIA Search Fee Others:  Final Settlement Sum Is Third Party Works below)  A) For Non GIA Reg B) For GIA Register BOLA Liability:  * Assessed Liability			: \$			days a	at \$0.00 per day
Final Settlement Sum Is Third Party Works below) A) For Non GIA Reg B) For GIA Register BOLA Liability: * Assessed Liability				900.00	9	days	
Final Settlement Sum  Is Third Party Works below)  A) For Non GIA Reg  B) For GIA Register  BOLA Liability: * Assessed Liability			: \$	2.00			
Is Third Party Works below)  A) For Non GIA Reg  B) For GIA Register  BOLA Liability: * Assessed Liability			: \$	0.00			
Is Third Party Works below)  A) For Non GIA Reg  B) For GIA Register  BOLA Liability: * Assessed Liability			: S				
B) For GIA Register BOLA Liability: * Assessed Liability			: \$	11,675.08			
* Assessed Liabili			6)	BOLA Applicable27 Assessed Liabili			LA Scenario No:
Remarks		AND THE RESERVE OF THE PARTY OF		n collisions and for	United Michigan		Commence and Cold or many or many and
Payment Instruction:	: Paye	e's Break	down				
1) Performance Mot	tors Li	mited		: \$			11,675.0
2)		POTATE STATE		: \$			
3)				: \$			
JOANNE LEE	E KHA	NG MIN		17 Oct 2019			
LKK Auto Con		ts Pte Ltd	_	Date			

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25. Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19002701/R1KB3Q2

Date:

17/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100403939

Claimant Vehicle No:

SKS7295P

Insured Vehicle No: SJN7724G

Date of Loss:

08/02/2019

Nature of Claim:

TP

Claim No: 9478391517SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKS7295P

Make & Model:

BMW 316I, 1.6 AT D/AB 4DR ABS HID (A)

Engine No:

A550J805N13B16A

Reg. Date: Colour:

30/04/2015 (Man. Year: 2014) White

Chassis No: Odometer:

WBA3A16010NS38396 83859 km

Engine Capacity:

1598 cc

Market Value/New Car

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Yes Engine Modification:

No

205/60 R16

Front Tyre Size: Front Left Side:

205/60 R16

Rear Tyre Size:

Bridgestone 6 mm

Front Right Side:

Bridgestone 6 mm Bridgestone 6 mm Rear Left Side: Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,565.20	4,188.30	376.90	8.26
Miscellaneous Items		0.00	0.00	0.00	
Labour		8,544.00	5,880.00	2,664.00	31,18
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	13,109.20	10,068.30	3,040.90	23.20
	+ GST 7.00/7.00% (S\$)	917.64	704.78	212.86	23.20
	Nett Amount (S\$)	14,026.84	10,773.08	3,253.76	23.20
	+ Car Rental (9.0 x S\$	100.00/day) (S\$)	900.00		
	+ Doc	Search Fee (S\$)	2.00		
		lett Liability (S\$)	11,675.08		

INSPECTION

Date of Assignment:

27/02/2019

Date Inspected:

27/02/2019 inspected At:

Performance Motors Limited

(Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre Singapore 159941

Estimated Period of Repair:

7.0 days

Adjuster Report Page 2 of 4

Adjuster: MOHD RASUL Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

Recommend	ed Par	ts
-----------	--------	----

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	Control of the Contro	*REAR EMBOSS NUMBER PLATE	Scratched	83.00 FS	*83.00 FS
2	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
3	1		*TAILPIPE END PIECE ALU LOOK	Not Necessary	107.85 FS	*- FS
4	1		*BOOTLID	Bent	1,179.80 FS	*1,179.80 FS
5	1		*RR BUMPER BOTTOM REINFORCEMENT	Bent	69.80 FS	*69.80 FS
6	1		*REAR BUMPER CENTRE GUIDE	Cracked	32.90 FS	*32.90 FS
7	1		*REAR BUMPER CARRIER (ECE)	Bent	467.95FS	
8	1		*REAR BUMPER PANEL PRIMED BASIS	Cracked	1,172.30FS	*1,172.30 FS
9	1		*RR BUMPER FLAP TOWING EYE PRIMED	Missing	43.25FS	*43.25 FS
10	1		*SET REAR PDC HOLDER	Necessary	24.60 FS	*24.60 FS
11	1		*REAR BUMPER LH SIDE GUIDE	Serviceable	58.50 FS	*-FS
12	1		*REAR BUMPER RH SIDE GUIDE	Serviceable	58.50FS	*- FS
13	1		*PLAQUE 74MM	Necessary	71.25FS	*71.25 FS
14	1		*UNDERBODY PANELLING REAR LH	Not Necessary	38.40FS	*-FS
15	1		*UNDERBODY PANELLING REAR RH	Not Necessary	37.25FS	*- FS
16	1		*TRUNK LID GASKET	Not Necessary	76.40FS	*-FS
17	1		*RR BUMPER LH REFLECTOR	Missing	36.80 FS	*36.80 FS
18	1		*RR BUMPER RH REFLECTOR	Cracked	36.80 FS	*36.80 FS
19	4		*DECOUPLING RING PDC TORQUE CONVERTE	Necessary	20.20FS	*20.20 FS
20	2		*PDC SENSOR MINERALWEISS (A96)	Not Working	737.60FS	*737.60 FS
21	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
22	10		*PLUG BLACK D=5MM	Necessary	9.00FS	*9.00FS
F=Fn	anchise	part. S=Spo	Nett.	Total Parts (S\$)	4,565.20	4,188.30

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	pur Items			
1	TO REPLACE REAR BUMPER, BOOT, REINFORCEMENT & ALL ATTACHMENT CAUSE BY ACCIDENT .TO REPAIR ON REAR END PANEL	New	4,250.00	2,550.00
2	PAINTING ON REAR BUMPER ,BOOT ,END PANEL & TRUNK FLOOR	New	3,197.00	2,399.00
3	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
4	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	451.00
5	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
6	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL) REAR BOOT	New	118.00	100.00
	Gross Labor	ur Cost (S\$)	8,544.00	5,880.00
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >