

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

13 FEB 2019

E S T I M A T E

Estimate No. : b1 50086
Date Estimated : 12/02/2019
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Tan Wen Bin, Vincent (Chen Wenbin)
Blk 328 Sembawang Crescent
#14-08
Singapore 750328

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS7295P	NS38396	30/04/2015	316iA/4	0

DESCRIPTIONVALUE

To replace rear bumper, boot, reinforcement & all attachment
cause by accident. To repair on rear end panel.

2550 ~~4250.00~~

934 796 668 7451
Painting on rear bumper, boot, end panel & trunk floor

2398 ~~3197.00~~

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230 ~~271.00~~

To transfer lock mechanism from old to new bootlid
including conduct checks on new bootlid central locking
system for proper function.

451 ~~531.00~~

To check electrical wiring systems and lightings at the
rear section for proper function.

150 ~~177.00~~

To carry out body cavity preservation.
(Per panel) Rear Boot

100 ~~118.00~~

To supply rear emboss number plate.

X 83.00

Sundries.

? 150.00

Total Labour 1: **8,777.00**DESCRIPTIONQTYPRICVALUE

TAILPIPE END PIECE ALU LOOK ?

1 107.85 107.85

BOOTLID repair Bt

1 1,179.80 1,179.80

RR BUMPER BOTTOM REINFORCEMENT ?

1 69.80 69.80

REAR BUMPER CENTRE GUIDE ?

1 32.90 32.90

REAR BUMPER CARRIER (ECE) ?

1 467.95 467.95

REAR BUMPER PANEL PRIMED BASIS ~~ECRA~~

1 1,172.30 1,172.30

RR BUMPER FLAP TOWING EYE PRIMED ~~MC~~

1 43.25 43.25

REAR PDC HOLDER SET ~~MC~~

1 24.60 24.60

REAR BUMPER LH SIDE GUIDE ?

1 58.50 58.50

REAR BUMPER RH SIDE GUIDE ?

1 58.50 58.50

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 50086
Date Estimated : 12/02/2019
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS7295P	NS38396	30/04/2015	316iA/4	0

DESCRIPTION	QTY	PRIC	VALUE
PLAQUE 74MM <i>na</i>	1	71.25	71.25
UNDERBODY PANELLING REAR LH <i>?</i>	1	38.40	38.40
UNDERBODY PANELLING REAR RH <i>?</i>	1	37.25	37.25
TRUNK LID GASKET <i>na</i>	1	76.40	76.40
RR BUMPER LH REFLECTOR <i>mis</i>	1	36.80	36.80
RR BUMPER RH REFLECTOR <i>CR1</i>	1	36.80	36.80
DECOUPLING RING PDC TORQUE CONVERTE <i>na</i>	4	5.05	20.20
PDC SENSOR MINERALWEISS (A96) <i>na</i>	2	368.80	737.60
(DG/SL) ADHESIVE SET K6 <i>na</i>	1	53.05	53.05

Total Parts : 4,323.20

Claims OD / <u>Third Party</u> / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time <u>27/02/19 @ 1200</u>	Excess S\$ _____
Surveyor's Name <u>RASUL</u>	Sign _____
Surveyor's Tel <u>90010068</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>7 days</u>	

Labour 1	:	8,777.00
Parts	:	4,323.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	917.01
Grand Total	:	14,017.21

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **