

Asher

SMM Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 19740155W GST Reg. No. M2-0020081-X



105, Alexandra Road
Sime Darby Performance Centre
Singapore 119941
Tel. 43190120 (Sales & Admin)
43190111 (AfterSales)
Fax. 44747770

100, Selegie Road
East Coast Centre
Singapore 436186
Tel. 43190888 (AfterSales)
Fax. 43443773

110, Alexandra Road
Sime Darby Business Centre
Singapore 119944
Tel. 43190120 (AfterSales)
43190133/310 (Motorcycle)
Fax. 44746001 (AfterSales)
44746024 (Motorcycle)

GST REG. NO : M2 - 0020081 - X

13 FEB 2019

ESTIMATE

Estimate No. : b1 50086 Page No. : 1 of 5
Date Estimated : 12/02/2019
Prepared By : Kevin Leong Wai Kit

- ESTIMATE REPAIR FOR -

Tan Wen Bin, Vincent (Chen Wenbin)
Blk 328 Sembawang Crescent
#14-08

Singapore 750328

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS7295P	NS38396	30/04/2015	3161A/4	0

DESCRIPTION

To replace rear bumper, boot, reinforcement & all attachment
cause by accident. To repair on rear end panel.

Painting on rear bumper, boot, and panel & trunk floor

To remove and install boot compartment carpet and garnish
to facilitate repairs.

To transfer lock mechanism from old to new bootlid
including conduct checks on new bootlid central locking
system for proper function.

To check electrical wiring systems and lightings at the
rear section for proper function.

To carry out body cavity preservation.
(Per panel) Rear Boot

To supply rear emboss number plate.

Sundries.

VALUE

2550 4250.00

2399

2389 3397.00

230 271.00

451 531.00

150 177.00

100 118.00

50 83.00

7 150.00

Total Labour 1: 8,777.00

DESCRIPTION

TAILPIPE END PIECE ALU LOOK

BOOTLID

RR BUMPER BOTTOM REINFORCEMENT

REAR BUMPER CENTRE GUIDE

REAR BUMPER CARRIER (ECE)

REAR BUMPER PANEL PRIMED BASIS

RR BUMPER FLAP TOWING EYE PRIMED

REAR PDC HOLDER SET

REAR BUMPER LH SIDE GUIDE

REAR BUMPER RH SIDE GUIDE

QTY PRIC

1 107.85

1 1,179.80

1 69.80

1 32.90

1 467.95

1 1,172.30

1 43.25

1 24.60

1 58.50

1 58.50

VALUE

107.85

1,179.80

69.80

32.90

467.95

1,172.30

43.25

24.60

58.50

58.50

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559M GST Reg. No. M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

285, Kembangan Road
East Coast Centre
Singapore 438455
Tel. 63199896 (AfterSales)
Fax. 63449773

515, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190039 (AfterSales)
63190033/330 (MotorCRM)
Fax. 64794401 (AfterSales)
64794424 (MotorCRM)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.	: b1 50086	Page No. : 2 of 5
Date Estimated	: 12/02/2019	
Prepared By	: Kevin Leong Wai Kit	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS7295P	NS38396	30/04/2015	316ia/4	0

DESCRIPTION	QTY	PRIC	VALUE
PLAQUE 74MM <i>Ma</i>	1	71.25	71.25
UNDERBODY PANNELLING REAR LH <i>7.3 Xan</i>	1	38.40	38.40
UNDERBODY PANNELLING REAR RH	1	37.25	37.25
TRUNK LID GASKET <i>Ma Xan</i>	1	76.40	76.40
RR BUMPER LH REFLECTOR <i>Ma</i>	1	36.80	36.80
RR BUMPER RH REFLECTOR <i>Ma</i>	1	36.80	36.80
DECOUPLING RING PDC TORQUE CONVERTE <i>Ma</i>	4	5.05	20.20
PDC SENSOR MINERALWEISS (A86) <i>Ma</i>	2	368.80	737.60
(DG/SL) ADHESIVE SET K6 <i>Ma</i>	1	53.05	53.05

Total Parts : 4,323.20

Claims ID / <i>27/02/19</i> / Uninsured losses / Direct Settlement	
Regn No.	Claim No.
Date & Time <i>27/02/19 01200</i>	Excess \$
Surveyor's Name <i>Rasul</i>	Sign
Surveyor's Tel <i>90010068</i>	Authorized Yes / No
Authorized Date	Time
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No P&L Yes / No	
Surveyor's E-mail	
No. of Working Days Recommended <i>7 days</i>	

Labour 1	:	8,777.00
Parts	:	4,323.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	917.01
Grand Total	:	14,017.21

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401599N GST Reg. No. M3-0020081-X



FINAL REPORT

Estimate No. : b1 50086
Date Estimated : 12/02/2019
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Tan Wen Bin, Vincent (Chen Wenbin)
Blk 328 Sembawang Crescent
#14-08

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 750328

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS7295P	NS38396	30/04/2015	316iA/4	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments, boot lid include making good the tail end panel and knocking out dents caused by the accident	2550.00		2,550.00 ✓
To spray paint rear bumper, boot lid and tail end panel	2399.00		2,399.00 ✓
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00 ✓
To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	451.00		451.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00 ✓
To carry out body cavity preservation (Per panel)	100.00		100.00 ✓
* To supply rear emboss number plate	83.00		83.00 ✓
Sundries	150.00		150.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,179.80	1.00		1,179.80 ✓
RR BUMPER BOTTOM REINFORCEMENT	69.80	1.00		69.80 ✓
REAR BUMPER CENTRE GUIDE	32.90	1.00		32.90 ✓
REAR BUMPER CARRIER (ECE)	467.95	1.00		467.95 ✓
REAR BUMPER PANEL PRIMED BASIS	1,172.30	1.00		1,172.30 ✓
RR BUMPER FLAP TOWING EYE PRIMED	43.25	1.00		43.25 ✓
REAR PDC HOLDER SET	24.60	1.00		24.60 ✓
PLAQUE 74MM	71.25	1.00		71.25 ✓
# PLUG BLACK D=5MM *	0.90	10.00		9.00 ✓
RR BUMPER LH REFLECTOR	36.80	1.00		36.80 ✓
RR BUMPER RH REFLECTOR	36.80	1.00		36.80 ✓
DECOUPLING RING PDC TORQUE CONVERTE	5.05	4.00		20.20 ✓
PDC SENSOR MINERALWEISS (A96)	368.80	1.00		368.80 ✓

Performance Motors Limited

A member of the Sironi Group
Co. Reg. No. 19740155866 GST Reg. No. M3-0029081-X



FINAL REPORT

PDC SENSOR MINERALWEISS (A96)
(DG/SL) ADHESIVE SET K6

368.80 1.00
53.05 1.00

368.80 ✓
53.05 ✓

SUPPLEMENTARY ITEMS

Total Labour :	6,113.00
Total Parts :	3,955.30
Total Labour & Parts :	10,068.30
Deduction for Excess :	
Total Repair Costs less Excess:	10,068.30
GST @7%:	704.78
Grand Total :	10,773.08

Performance Motors Limited

A member of the Sincere Group
Co. Reg. No. 197401599N/ GST Reg. No. M3-0030081-X



SUPPLEMENTARY

Estimate No. : b1 50086
Date Estimated : 12/02/2019
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Tan Wen Bin, Vincent (Chen Wenbin)
Blk 328 Sembawang Crescent
#14-08

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 750328

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS7295P	NS38396	30/04/2015	316iA/4	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# PLUG BLACK D=5MM * <i>MC</i> ✓	0.90	10.00		9.00

Total Labour :	
Total Parts :	9.00
Total Labour & Parts :	9.00